































	<p>БПО-0001</p> <p> $F \text{ см}^2 = 27.590$ $Q \text{ кг.} = 7.477$ $D \text{ оп.мм} = 140.0$ $P \text{ н.мм} = 314.3$ Гр.сл. = II Точн. = Н </p>		<p>БПО-0006</p>
	<p>БПО-0002</p> <p> $F \text{ см}^2 = 1.22$ $Q \text{ кг.} = 0.331$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 190.9$ Гр.сл. = IV Точн. = П </p>		<p>БПО-0007</p> <p> $F \text{ см}^2 = 1.53$ $Q \text{ кг.} = 0.415$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 109.4$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-0003</p> <p> $F \text{ см}^2 = 0.723$ $Q \text{ кг.} = 0.196$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 138.0$ Гр.сл. = VI Точн. = П </p>		<p>БПО-0008</p> <p> $F \text{ см}^2 = 0.614$ $Q \text{ кг.} = 0.166$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 65.0$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-0004</p> <p> $F \text{ см}^2 = 0.640$ $Q \text{ кг.} = 0.173$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 67.4$ Гр.сл. = VI Точн. = П </p>		<p>БПО-0009</p> <p> $F \text{ см}^2 = 1.684$ $Q \text{ кг.} = 0.456$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 117.3$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-0005</p>		<p>БПО-0010</p> <p> $F \text{ см} = 6.456$ $Q \text{ кг.} = 1.750$ $D \text{ оп.мм} = 110$ $P \text{ н.мм} = 339$ Гр.сл. = VI Точн. = П </p>











	<p>БПО-0011</p> <p> $F \text{ см}^2 = 6.540$ $Q \text{ кг.} = 1.770$ $D \text{ оп.мм} = 110$ $P \text{ н.мм} = 364.9$ Гр.сл. = VI Точн. = II </p>		<p>БПО-0016</p> <p> $F \text{ см}^2 = 1.722$ $Q \text{ кг.} = 0.467$ $D \text{ оп.мм} = 71$ $P \text{ н.мм} = 255.4$ Гр.сл. = VI Точн. = H </p>
	<p>БПО-0012</p> <p> $F \text{ см}^2 = 1.772$ $Q \text{ кг.} = 0.480$ $D \text{ оп.мм} = 55$ $P \text{ н.мм} = 138.8$ Гр.сл. = V Точн. = H </p>		<p>БПО-0017</p> <p> $F \text{ см}^2 = 2.15$ $Q \text{ кг.} = 0.583$ $D \text{ оп.мм} = 113.0$ $P \text{ н.мм} = 290$ Гр.сл. = V Точн. = II </p>
	<p>БПО-0013</p> <p> $F \text{ см}^2 = 1.561$ $Q \text{ кг.} = 0.423$ $D \text{ оп.мм} = 48$ $P \text{ н.мм} = 128.6$ Гр.сл. = II Точн. = II </p>		<p>БПО-0018</p> <p> $F \text{ см}^2 = 2.06$ $Q \text{ кг.} = 0.558$ $D \text{ оп.мм} = 113.0$ $P \text{ н.мм} = 275$ Гр.сл. = V Точн. = II </p>
	<p>БПО-0014</p> <p> $F \text{ см}^2 = 1.837$ $Q \text{ кг.} = 0.498$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 118.2$ Гр.сл. = I Точн. = H </p>		<p>БПО-0019</p> <p> $F \text{ см}^2 = 1.680$ $Q \text{ кг.} = 0.455$ $D \text{ оп.мм} = 46$ $P \text{ н.мм} = 172.3$ Гр.сл. = VI Точн. = H </p>
	<p>БПО-0015</p> <p> $F \text{ см}^2 = 2.421$ $Q \text{ кг.} = 0.656$ $D \text{ оп.мм} = 68.9$ $P \text{ н.мм} = 238.7$ Гр.сл. = VI Точн. = H </p>		<p>БПО-0020</p> <p> $F \text{ см} = 0.899$ $Q \text{ кг.} = 0.244$ $D \text{ оп.мм} = 20.3$ $P \text{ н.мм} = 71.9$ Гр.сл. = IV Точн. = II </p>











	<p>БПО-0021</p> <p> $F \text{ см}^2 = 4.290$ $Q \text{ кг.} = 1.244$ $D \text{ оп.мм} = 66.2$ $P \text{ н.мм} = 295.9$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-0026</p> <p> $F \text{ см}^2 = 2.100$ $Q \text{ кг.} = 0.56$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 163.0$ $\text{Гр.сл.} = \text{VI}$ $\text{Точн.} = \text{H}$ </p>
	<p>БПО-0022</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$ </p>		<p>БПО-0027</p> <p> $F \text{ см} = 0.720$ $Q \text{ кг.} = 0.195$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 76.58$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>
	<p>БПО-0023</p> <p> $F \text{ см}^2 = 2.94$ $Q \text{ кг.} = 0.795$ $D \text{ оп.мм} = 42.5$ $P \text{ н.мм} = 110.4$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{II}$ </p>		<p>БПО-0028</p> <p> $F \text{ см}^2 = 2.046$ $Q \text{ кг.} = 0.554$ $D \text{ оп.мм} = 65.8$ $P \text{ н.мм} = 236$ $\text{Гр.сл.} = \text{V}$ $\text{Точн.} = \text{H}$ </p>
	<p>БПО-0024</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$ </p>		<p>БПО-0029</p> <p> $F \text{ см}^2 = 1.880$ $Q \text{ кг.} = 0.509$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 66$ $\text{Гр.сл.} = \text{I}$ $\text{Точн.} = \text{II}$ </p>
	<p>БПО-0025</p> <p> $F \text{ см}^2 = 4.921$ $Q \text{ кг.} = 1.328$ $D \text{ оп.мм} = 60.4$ $P \text{ н.мм} = 153.3$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-0030</p> <p> $F \text{ см} = 2.03$ $Q \text{ кг.} = 0.55$ $D \text{ оп.мм} = 114$ $P \text{ н.мм} = 273.7$ $\text{Гр.сл.} = \text{особ.}$ $\text{Точн.} = \text{П}$ </p>








	<p>БПО-0031</p> <p> $F \text{ см}^2 = 4.563$ $Q \text{ кг.} = 1.237$ $D \text{ оп.мм} = 141$ $P \text{ н.мм} = 537.6$ Гр.сл. = особ Точн. = П </p>		<p>БПО-0036</p> <p> $F \text{ см}^2 = 23.99$ $Q \text{ кг.} = 6.501$ $D \text{ оп.мм} = 72.0$ $P \text{ н.мм} = 198.3$ Гр.сл. = III Точн. = Н </p>
	<p>БПО-0032</p> <p> $F \text{ см}^2 = 2.955$ $Q \text{ кг.} = 0.801$ $D \text{ оп.мм} = 110$ $P \text{ н.мм} = 338.5$ Гр.сл. = особ Точн. = П </p>		<p>БПО-0037</p> <p> $F \text{ см} = 0.502$ $Q \text{ кг.} = 0.136$ $D \text{ оп.мм} = 8.0$ $P \text{ н.мм} = 25.13$ Гр.сл. = II Точн. = Н </p>
	<p>БПО-033</p> <p> $F \text{ см}^2 = 2.100$ $Q \text{ кг.} = 0.572$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 172.0$ Гр.сл. = V Точн. = Н </p>		<p>БПО-0038</p> <p> $F \text{ см}^2 = 1.131$ $Q \text{ кг.} = 0.307$ $D \text{ оп.мм} = 12.0$ $P \text{ н.мм} = 37.7$ Гр.сл. = II Точн. = Н </p>
	<p>БПО-0034</p> <p> $F \text{ см}^2 = 1.760$ $Q \text{ кг.} = 0.477$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 180$ Гр.сл. = IV Точн. = П </p>		<p>БПО-0039</p> <p> $F \text{ см}^2 = 1.247$ $Q \text{ кг.} = 0.338$ $D \text{ оп.мм} = 55.2$ $P \text{ н.мм} = 166.6$ Гр.сл. = особ Точн. = П </p>
	<p>БПО-0035</p> <p> $F \text{ см}^2 = 10.68$ $Q \text{ кг.} = 2.894$ $D \text{ оп.мм} = 182$ $P \text{ н.мм} = 542$ Гр.сл. = V Точн. = П </p>		<p>БПО-0040</p> <p> $F \text{ см} = 35.99$ $Q \text{ кг.} = 9.75$ $D \text{ оп.мм} = 62.5$ $P \text{ н.мм} = 298.3$ Гр.сл. = III Точн. = Н </p>











	<p>БПО-0041</p> <p> $F \text{ см}^2 = 11.000$ $Q \text{ кг.} = 2.98$ $D \text{ оп.мм} = 73.0$ $P \text{ н.мм} = 271.0$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-0046</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-0042</p> <p> $F \text{ см}^2 = 1.026$ $Q \text{ кг.} = 0.278$ $D \text{ оп.мм} = 28.7$ $P \text{ н.мм} = 121.8$ Гр.сл. = III Точн. = Н </p>		<p>БПО-0047</p> <p> $F \text{ см} =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-0043</p> <p> $F \text{ см}^2 = 4.70$ $Q \text{ кг.} = 1.274$ $D \text{ оп.мм} = 154.0$ $P \text{ н.мм} = 374.73$ Гр.сл. = V Точн. = Н </p>		<p>БПО-0048</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-0044</p> <p> $F \text{ см}^2 = 0.712$ $Q \text{ кг.} = 0.193$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 87.9$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-0049</p> <p> $F \text{ см}^2 = 1.023$ $Q \text{ кг.} = 0.277$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 119.3$ Гр.сл. = IV Точн. = Н </p>
	<p>БПО-0045</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-0050</p> <p> $F \text{ см} = 4.77$ $Q \text{ кг.} = 1.293$ $D \text{ оп.мм} = 71.0$ $P \text{ н.мм} = 195.7$ Гр.сл. = III Точн. = Н </p>









	<p>БПО-0051</p> <p> $F \text{ см}^2 = 2.8$ $Q \text{ кг.} = 0.759$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 156.8$ Гр.сл. = III Точн. = Н </p>		<p>БПО-0056</p> <p> $F \text{ см}^2 = 9.58$ $Q \text{ кг.} = 2.6$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 383.56$ Гр.сл. = III Точн. = Н </p>
	<p>БПО-0052</p> <p> $F \text{ см}^2 = 1.95$ $Q \text{ кг.} = 0.528$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 125.25$ Гр.сл. = I Точн. = Н </p>		<p>БПО-0057</p> <p> $F \text{ см} =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-0053</p> <p> $F \text{ см}^2 = 1.085$ $Q \text{ кг.} = 0.294$ $D \text{ оп.мм} = 37.3$ $P \text{ н.мм} = 128.2$ Гр.сл. = V Точн. = П </p>		<p>БПО-0058</p> <p> $F \text{ см}^2 = 1.44$ $Q \text{ кг.} = 0.403$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 80.0$ Гр.сл. = II Точн. = Н </p>
	<p>БПО-0054</p> <p> $F \text{ см}^2 = 0.894$ $Q \text{ кг.} = 0.242$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 122.2$ Гр.сл. = IV Точн. = ? </p>		<p>БПО-0059</p> <p> $F \text{ см}^2 = 4.863$ $Q \text{ кг.} = 1.318$ $D \text{ оп.мм} = 113.0$ $P \text{ н.мм} = 398.1$ Гр.сл. = VI Точн. = ? </p>
	<p>БПО-0055</p> <p> $F \text{ см}^2 = 0.282$ $Q \text{ кг.} = 0.076$ $D \text{ оп.мм} = 6.0$ $P \text{ н.мм} = 18.85$ Гр.сл. = I Точн. = Н </p>		<p>БПО-0060</p> <p> $F \text{ см} = 2.456$ $Q \text{ кг.} = 0.666$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 279.5$ Гр.сл. = VI Точн. = П </p>







	<p>БПО-0061</p> <p> $F \text{ см}^2 = 0.637$ $Q \text{ кг.} = 0.173$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 128.1$ Гр.сл. = VI Точн. = П </p>		<p>БПО-0066</p> <p> $F \text{ см}^2 = 1.299$ $Q \text{ кг.} = 0.352$ $D \text{ оп.мм} = 30.8$ $P \text{ н.мм} = 157.8$ Гр.сл. = V Точн. = П </p>
	<p>БПО-0062</p> <p> $F \text{ см}^2 = 0.817$ $Q \text{ кг.} = 0.221$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 162.6$ Гр.сл. = VI Точн. = П </p>		<p>БПО-0067</p> <p> $F \text{ см} = 6.79$ $Q \text{ кг.} = 1.84$ $D \text{ оп.мм} = 137$ $P \text{ н.мм} = 434$ Гр.сл. = V Точн. = П </p>
	<p>БПО-0063</p> <p> $F \text{ см}^2 = 0.755$ $Q \text{ кг.} = 0.205$ $D \text{ оп.мм} = 28.2$ $P \text{ н.мм} = 102.5$ Гр.сл. = VI Точн. = П </p>		<p>БПО-0068</p> <p> $F \text{ см}^2 = 6.996$ $Q \text{ кг.} = 1.9$ $D \text{ оп.мм} = 83.0$ $P \text{ н.мм} = 236.0$ Гр.сл. = I Точн. = П </p>
	<p>БПО-0064</p> <p> $F \text{ см}^2 = 1.53$ $Q \text{ кг.} = 0.415$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 195.2$ Гр.сл. = VI Точн. = П </p>		<p>БПО-0069</p> <p> $F \text{ см}^2 = 1.100$ $Q \text{ кг.} = 0.3$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 107.0$ Гр.сл. = III Точн. = H </p>
	<p>БПО-0065</p> <p> $F \text{ см}^2 = 1.89$ $Q \text{ кг.} = 0.512$ $D \text{ оп.мм} = 78.1$ $P \text{ н.мм} = 265.4$ Гр.сл. = VI Точн. = П </p>		<p>БПО-0070</p> <p> $F \text{ см} = 1.459$ $Q \text{ кг.} = 0.395$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 200.2$ Гр.сл. = IV Точн. = П </p>









	БПО-0071 $F \text{ см}^2 = 1.49$ $Q \text{ кг.} = 0.404$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 205.4$ Гр.сл. = IV Точн. = П		БПО-0076 $F \text{ см}^2 = 2.845$ $Q \text{ кг.} = 0.768$ $D \text{ оп.мм} = 141$ $P \text{ н.мм} = 277$ Гр.сл. = VI Точн. = П
	БПО-0072 $F \text{ см}^2 = 2.05$ $Q \text{ кг.} = 0.556$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 257.1$ Гр.сл. = IV Точн. = П		БПО-0077 $F \text{ см} = 1.295$ $Q \text{ кг.} = 0.351$ $D \text{ оп.мм} = 21.7$ $P \text{ н.мм} = 88.4$ Гр.сл. = II Точн. = Н
	БПО-0073 $F \text{ см}^2 = 3.56$ $Q \text{ кг.} = 0.965$ $D \text{ оп.мм} = 66$ $P \text{ н.мм} = 272$ Гр.сл. = V Точн. = Н		БПО-0078 $F \text{ см}^2 = 0.419$ $Q \text{ кг.} = 0.114$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 66.8$ Гр.сл. = IV Точн. = П
	БПО-0074 $F \text{ см}^2 = 0.314$ $Q \text{ кг.} = 0.085$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 52.8$ Гр.сл. = IV Точн. = ?		БПО-0079 $F \text{ см}^2 = 3.722$ $Q \text{ кг.} = 1.009$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 340.7$ Гр.сл. = ?6??. Точн. = Н
	БПО-0075 $F \text{ см}^2 = 3.977$ $Q \text{ кг.} = 1.078$ $D \text{ оп.мм} = 46.5$ $P \text{ н.мм} = 185.6$ Гр.сл. = VI Точн. = Н		БПО-0080 $F \text{ см} = 0.951$ $Q \text{ кг.} = 0.257$ $D \text{ оп.мм} = 39.2$ $P \text{ н.мм} = 174$ Гр.сл. = V Точн. = 0










	<p>БПО-0081</p> <p> $F \text{ см}^2 = 0.880$ $Q \text{ кг.} = 0.238$ $D \text{ оп.мм} = 34$ $P \text{ н.мм} = 161$ $\Gamma \text{р.сл.} = V$ $\text{Точн.} = 0$ </p>		<p>БПО-0086</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{р.сл.} =$ $\text{Точн.} =$ </p>
	<p>БПО-0082</p> <p> $F \text{ см}^2 = 0.87$ $Q \text{ кг.} = 0.238$ $D \text{ оп.мм} = 32.3$ $P \text{ н.мм} = 159.7$ $\Gamma \text{р.сл.} = V$ $\text{Точн.} = 0$ </p>		<p>БПО-0087</p> <p> $F \text{ см} =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{р.сл.} =$ $\text{Точн.} =$ </p>
	<p>БПО-0083</p> <p> $F \text{ см}^2 = 4.02$ $Q \text{ кг.} = 1.089$ $D \text{ оп.мм} = 139$ $P \text{ н.мм} = 434.2$ $\Gamma \text{р.сл.} = \text{особ}$ $\text{Точн.} = П$ </p>		<p>БПО-0088</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{р.сл.} =$ $\text{Точн.} =$ </p>
	<p>БПО-0084</p> <p> $F \text{ см}^2 = 0.973$ $Q \text{ кг.} = 0.264$ $D \text{ оп.мм} = 33.6$ $P \text{ н.мм} = 143.5$ $\Gamma \text{р.сл.} = VI$ $\text{Точн.} = H$ </p>		<p>БПО-0089</p> <p> $F \text{ см}^2 = 1.399$ $Q \text{ кг.} = 0.379$ $D \text{ оп.мм} = 38.5$ $P \text{ н.мм} = 121.1$ $\Gamma \text{р.сл.} = IV$ $\text{Точн.} = H$ </p>
	<p>БПО-0085</p> <p> $F \text{ см}^2 = 0.566$ $Q \text{ кг.} = 0.153$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 81$ $\Gamma \text{р.сл.} = V$ $\text{Точн.} = П$ </p>		<p>БПО-0090</p> <p> $F \text{ см} = 1.337$ $Q \text{ кг.} = 0.362$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 185.0$ $\Gamma \text{р.сл.} = VI$ $\text{Точн.} = П$ </p>







	<p>БПО-0091</p> <p> $F \text{ см}^2 = 0.954$ $Q \text{ кг.} = 0.259$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 117.0$ Гр.сл. = V Точн. = П </p>		<p>БПО-0096</p> <p> $F \text{ см}^2 = 0.6$ $Q \text{ кг.} = 0.163$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 77$ Гр.сл. = III Точн. = Н </p>
	<p>БПО-0092</p> <p> $F \text{ см}^2 = 3.100$ $Q \text{ кг.} = 0.840$ $D \text{ оп.мм} = 125.0$ $P \text{ н.мм} = 399.0$ Гр.сл. = V Точн. = П </p>		<p>БПО-0097</p> <p> $F \text{ см} = 2.01$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм} = 16.0$ $P \text{ н.мм} = 50.3$ Гр.сл. = II Точн. = Н </p>
	<p>БПО-0093</p> <p> $F \text{ см}^2 = 1.667$ $Q \text{ кг.} = 0.452$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 194.14$ Гр.сл. = VI Точн. = П </p>		<p>БПО-0098</p> <p> $F \text{ см}^2 = 2.115$ $Q \text{ кг.} = 0.573$ $D \text{ оп.мм} = 69.0$ $P \text{ н.мм} = 214.76$ Гр.сл. = IV Точн. = Н </p>
	<p>БПО-0094</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-0099</p> <p> $F \text{ см}^2 = 0.764$ $Q \text{ кг.} = 0.207$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 78.3$ Гр.сл. = III Точн. = Н </p>
	<p>БПО-0095</p> <p> $F \text{ см}^2 = 2.52$ $Q \text{ кг.} = 0.683$ $D \text{ оп.мм} = 85.1$ $P \text{ н.мм} = 197.5$ Гр.сл. = V Точн. = П </p>		<p>БПО-100</p> <p> $F \text{ см} = 1.010$ $Q \text{ кг.} = 0.275$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 98.66$ Гр.сл. = III Точн. = Н </p>








	<p>БПО-101</p> <p> $F \text{ см}^2 = 1.71$ $Q \text{ кг.} = 0.463$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 101.4$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-106</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-102</p> <p> $F \text{ см}^2 = 3.36$ $Q \text{ кг.} = 0.91$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 175.17$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-107</p> <p> $F \text{ см} = 2.01$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм} = 67.3$ $P \text{ н.мм} = 203.14$ Гр.сл. = IV Точн. = Н </p>
	<p>БПО-103</p> <p> $F \text{ см}^2 = 1.6$ $Q \text{ кг.} = 0.434$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 128.6$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-108</p> <p> $F \text{ см}^2 = 5.9$ $Q \text{ кг.} = 1.599$ $D \text{ оп.мм} = 76.0$ $P \text{ н.мм} = 208$ Гр.сл. = III Точн. = Н </p>
	<p>БПО-104</p> <p> $F \text{ см}^2 = 1.55$ $Q \text{ кг.} = 0.42$ $D \text{ оп.мм} = 25.6$ $P \text{ н.мм} = 71.6$ Гр.сл. = I Точн. = Н </p>		<p>БПО-109</p> <p> $F \text{ см}^2 = 173.16$ $Q \text{ кг.} = 46.93$ $D \text{ оп.мм} = 194.0$ $P \text{ н.мм} = 544.0$ Гр.сл. = I Точн. = Н </p>
	<p>БПО-105</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-110</p> <p> $F \text{ см} = 4.52$ $Q \text{ кг.} = 1.225$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 75.4$ Гр.сл. = II Точн. = Н </p>











	<p>БПО-111</p> <p> $F \text{ см}^2 = 1.183$ $Q \text{ кг.} = 0.321$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 84.3$ Гр.сл. = VI Точн. = Н </p>		<p>БПО-116</p> <p> $F \text{ см}^2 = 2.13$ $Q \text{ кг.} = 0.577$ $D \text{ оп.мм} = 42.4$ $P \text{ н.мм} = 182.2$ Гр.сл. = IV Точн. = П </p>
	<p>БПО-112</p> <p> $F \text{ см}^2 = 0.504$ $Q \text{ кг.} = 0.137$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 55.42$ Гр.сл. = III Точн. = Н </p>		<p>БПО-117</p> <p> $F \text{ см} = 1.64$ $Q \text{ кг.} = 0.444$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 191.1$ Гр.сл. = III Точн. = Н </p>
	<p>БПО-113</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-118</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-114</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-119</p> <p> $F \text{ см}^2 = 4.75$ $Q \text{ кг.} = 1.287$ $D \text{ оп.мм} = 65.2$ $P \text{ н.мм} = 280$ Гр.сл. = III Точн. = П </p>
	<p>БПО-115</p> <p> $F \text{ см}^2 = 2.52$ $Q \text{ кг.} = 0.683$ $D \text{ оп.мм} = 57.4$ $P \text{ н.мм} = 174$ Гр.сл. = III Точн. = Н </p>		<p>БПО-120</p> <p> $F \text{ см} =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>










	<p>БПО-121</p> <p> $F \text{ см}^2 = 1.919$ $Q \text{ кг.} = 0.52$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 223.1$ Гр.сл. = III Точн. = Н </p>		<p>БПО-126</p> <p> $F \text{ см}^2 = 0.766$ $Q \text{ кг.} = 0.208$ $D \text{ оп.мм} = 27.13$ $P \text{ н.мм} = 145.6$ Гр.сл. = IV Точн. = П </p>
	<p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-127</p> <p> $F \text{ см} = 1.09$ $Q \text{ кг.} = 0.295$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 74.2$ Гр.сл. = II Точн. = Н </p>
	<p>БПО-123</p> <p> $F \text{ см}^2 = 0.825$ $Q \text{ кг.} = 0.224$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 113$ Гр.сл. = V Точн. = Н </p>		<p>БПО-128</p> <p> $F \text{ см}^2 = 3.45$ $Q \text{ кг.} = 0.935$ $D \text{ оп.мм} = 74.3$ $P \text{ н.мм} = 230.14$ Гр.сл. = IV Точн. = Н </p>
	<p>БПО-124</p> <p> $F \text{ см}^2 = 1.943$ $Q \text{ кг.} = 0.527$ $D \text{ оп.мм} = 113.0$ $P \text{ н.мм} = 262$ Гр.сл. = V Точн. = П </p>		<p>БПО-129</p> <p> $F \text{ см}^2 = 1.168$ $Q \text{ кг.} = 0.317$ $D \text{ оп.мм} = 25.5$ $P \text{ н.мм} = 80.8$ Гр.сл. = VI Точн. = Н </p>
	<p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-130</p> <p> $F \text{ см} = 8.22$ $Q \text{ кг.} = 2.228$ $D \text{ оп.мм} = 94.0$ $P \text{ н.мм} = 438$ Гр.сл. = III Точн. = Н </p>








	<p>БПО-131</p> <p> $F \text{ см}^2 = 1.725$ $Q \text{ кг.} = 0.467$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 232.6$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-136</p> <p> $F \text{ см}^2 = 0.845$ $Q \text{ кг.} = 0.229$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 94.4$ Гр.сл. = III Точн. = Н </p>
	<p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-137</p> <p> $F \text{ см}^2 = 0.564$ $Q \text{ кг.} = 0.153$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 58.3$ Гр.сл. = III Точн. = Н </p>
	<p>БПО-133</p> <p> $F \text{ см}^2 = 3.457$ $Q \text{ кг.} = 0.937$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 176.6$ Гр.сл. = 2 Точн. = Н </p>		<p>БПО-138</p> <p> $F \text{ см}^2 = 1.16$ $Q \text{ кг.} = 0.314$ $D \text{ оп.мм} = 42.5$ $P \text{ н.мм} = 118.3$ Гр.сл. = II Точн. = Н </p>
	<p>БПО-134</p> <p> $F \text{ см}^2 = 0.810$ $Q \text{ кг.} = 0.220$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 57.24$ Гр.сл. = I Точн. = Н </p>		<p>БПО-139</p> <p> $F \text{ см}^2 = 2.82$ $Q \text{ кг.} = 0.764$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 143.9$ Гр.сл. = IV Точн. = Н </p>
	<p>БПО-135</p> <p> $F \text{ см}^2 = 3.16$ $Q \text{ кг.} = 0.856$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 103.6$ Гр.сл. = III Точн. = Н </p>		<p>БПО-140</p> <p> $F \text{ см}^2 = 4.21$ $Q \text{ кг.} = 1.141$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 264$ Гр.сл. = IV Точн. = Н </p>











	<p>БПО-141</p> <p> $F \text{ см}^2 = 3.857$ $Q \text{ кг.} = 1.045$ $D \text{ оп.мм} = 70.5$ $P \text{ н.мм} = 196.6$ Гр.сл. = II Точн. = Н </p>		<p>БПО-146</p> <p> $F \text{ см}^2 = 0.858$ $Q \text{ кг.} = 0.232$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 151$ Гр.сл. = VI Точн. = ОСО </p>
	<p>БПО-142</p> <p> $F \text{ см}^2 = 1.52$ $Q \text{ кг.} = 0.413$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 78$ Гр.сл. = ?6??. Точн. = Н </p>		<p>БПО-147</p> <p> $F \text{ см} = 2.3$ $Q \text{ кг.} = 0.52$ $D \text{ оп.мм} = 54$ $P \text{ н.мм} = 264$ Гр.сл. = VI Точн. = ОСО </p>
	<p>БПО-0143</p> <p> $F \text{ см}^2 = 4.430$ $Q \text{ кг.} = 1.201$ $D \text{ оп.мм} = 158.0$ $P \text{ н.мм} = 478.0$ Гр.сл. = V Точн. = П </p>		<p>БПО-0148</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-144</p> <p> $F \text{ см}^2 = 2.68$ $Q \text{ кг.} = 0.726$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 143$ Гр.сл. = V Точн. = Н </p>		<p>БПО-149</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-145</p> <p> $F \text{ см}^2 = 0.616$ $Q \text{ кг.} = 0.166$ $D \text{ оп.мм} = 23$ $P \text{ н.мм} = 109$ Гр.сл. = VI Точн. = ОСО </p>		<p>БПО-150</p> <p> $F \text{ см} =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = П </p>











			БПО-156 $F \text{ см}^2 = 0.777$ $Q \text{ кг.} = 0.211$ $D \text{ оп.мм} = 34.7$ $P \text{ н.мм} = 130.74$ $\text{Гр.сл.} = V$ $\text{Точн.} = H$
			БПО-157 $F \text{ см} = 0.732$ $Q \text{ кг.} = 0.198$ $D \text{ оп.мм} = 3.0$ $P \text{ н.мм} = 31.7$ $\text{Гр.сл.} = III$ $\text{Точн.} = H$
			БПО-158 $F \text{ см}^2 = 0.049$ $Q \text{ кг.} = 0.0133$ $D \text{ оп.мм} = 2.5$ $P \text{ н.мм} = 7.85$ $\text{Гр.сл.} = III$ $\text{Точн.} = H$
	БПО-154 $F \text{ см}^2 = 1.100$ $Q \text{ кг.} = 0.298$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 175.0$ $\text{Гр.сл.} = VI$ $\text{Точн.} = H$		БПО-159 $F \text{ см}^2 = 1.5$ $Q \text{ кг.} = 0.407$ $D \text{ оп.мм} = 61$ $P \text{ н.мм} = 260.1$ $\text{Гр.сл.} = IV$ $\text{Точн.} = H$
	БПО-155 $F \text{ см}^2 = 2.46$ $Q \text{ кг.} = 0.667$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 119.7$ $\text{Гр.сл.} = III$ $\text{Точн.} = H$		БПО-160 $F \text{ см} = 1.82$ $Q \text{ кг.} = 0.494$ $D \text{ оп.мм} = 40.5$ $P \text{ н.мм} = 111$ $\text{Гр.сл.} = II$ $\text{Точн.} = H$








	БПО-161 $F \text{ см}^2 = 2.414$ $Q \text{ кг.} = 0.654$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 157$ Гр.сл. = II Точн. = Н		БПО-166 $F \text{ см}^2 = 0.479$ $Q \text{ кг.} = 0.13$ $D \text{ оп.мм} = 18.6$ $P \text{ н.мм} = 49.7$ Гр.сл. = III Точн. = П
	БПО-162 $F \text{ см}^2 = 10.24$ $Q \text{ кг.} = 2.775$ $D \text{ оп.мм} = 150.0$ $P \text{ н.мм} = 463.8$ Гр.сл. = V Точн. = П		БПО-167 $F \text{ см} = 1.06$ $Q \text{ кг.} = 0.287$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 135.3$ Гр.сл. = IV Точн. = Н
	БПО-163 $F \text{ см}^2 = 0.194$ $Q \text{ кг.} = 0.052$ $D \text{ оп.мм} = 4.8$ $P \text{ н.мм} = 15.4$ Гр.сл. = I Точн. = Н		БПО-168 $F \text{ см}^2 = 1.535$ $Q \text{ кг.} = 0.416$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 205$ Гр.сл. = V Точн. = Н
	БПО-164 $F \text{ см}^2 = 6.0$ $Q \text{ кг.} = 1.626$ $D \text{ оп.мм} = 150.0$ $P \text{ н.мм} = 308$ Гр.сл. = II Точн. = Н		БПО-169 $F \text{ см}^2 = 2.9$ $Q \text{ кг.} = 0.786$ $D \text{ оп.мм} = 98.0$ $P \text{ н.мм} = 305$ Гр.сл. = VI Точн. = Н
	БПО-165 $F \text{ см}^2 = 1.76$ $Q \text{ кг.} = 0.477$ $D \text{ оп.мм} = 23.8$ $P \text{ н.мм} = 96$ Гр.сл. = II Точн. = Н		БПО-170 $F \text{ см} = 3.39$ $Q \text{ кг.} = 0.92$ $D \text{ оп.мм} = 59.0$ $P \text{ н.мм} = 160$ Гр.сл. = II Точн. = Н











	<p>БПО-171</p> <p> $F \text{ см}^2 = 0.617$ $Q \text{ кг.} = 0.167$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 102.0$ Гр.сл. = III Точн. = Н </p>		<p>БПО-176</p> <p> $F \text{ см}^2 = 2.07$ $Q \text{ кг.} = 0.561$ $D \text{ оп.мм} = 74.0$ $P \text{ н.мм} = 217.5$ Гр.сл. = IV Точн. = Н </p>
	<p>БПО-172</p> <p> $F \text{ см}^2 = 0.919$ $Q \text{ кг.} = 0.249$ $D \text{ оп.мм} = 19.8$ $P \text{ н.мм} = 138.3$ Гр.сл. = III Точн. = Н </p>		<p>БПО-177</p> <p> $F \text{ см} = 1.530$ $Q \text{ кг.} = 0.415$ $D \text{ оп.мм} = 24.5$ $P \text{ н.мм} = 238.4$ Гр.сл. = III Точн. = Н </p>
	<p>БПО-173</p> <p> $F \text{ см}^2 = 2.99$ $Q \text{ кг.} = 0.81$ $D \text{ оп.мм} = 81.6$ $P \text{ н.мм} = 388.3$ Гр.сл. = VI Точн. = П </p>		<p>БПО-178</p> <p> $F \text{ см}^2 = 10.98$ $Q \text{ кг.} = 2.976$ $D \text{ оп.мм} = 153.0$ $P \text{ н.мм} = 433$ Гр.сл. = IV Точн. = П </p>
	<p>БПО-174</p> <p> $F \text{ см}^2 = 0.957$ $Q \text{ кг.} = 0.259$ $D \text{ оп.мм} = 50.6$ $P \text{ н.мм} = 143.5$ Гр.сл. = III Точн. = Н </p>		<p>БПО-179</p> <p> $F \text{ см}^2 = 2.376$ $Q \text{ кг.} = 0.644$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 179.6$ Гр.сл. = V Точн. = П </p>
	<p>БПО-175</p> <p> $F \text{ см}^2 = 2.10$ $Q \text{ кг.} = 0.57$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 205.0$ Гр.сл. = V Точн. = Н </p>		<p>БПО-180</p> <p> $F \text{ см} =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>







	БПО-181 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$		БПО-186 $F \text{ см}^2 = 27.59$ $Q \text{ кг.} = 7.476$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 388$ $\text{Гр.сл.} = \text{II}$ $\text{Точн.} = \text{H}$
	БПО-182 $F \text{ см}^2 = 19.300$ $Q \text{ кг.} = 5.22$ $D \text{ оп.мм} = 145.0$ $P \text{ н.мм} = 394.0$ $\text{Гр.сл.} = \text{II}$ $\text{Точн.} = \text{H}$		БПО-187 $F \text{ см} = 18.23$ $Q \text{ кг.} = 4.94$ $D \text{ оп.мм} = 185.8$ $P \text{ н.мм} = 450.3$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
	БПО-183 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$		БПО-188 $F \text{ см}^2 = 32.068$ $Q \text{ кг.} = 8.69$ $D \text{ оп.мм} = 141.4$ $P \text{ н.мм} = 598.8$ $\text{Гр.сл.} = \text{V}$ $\text{Точн.} = \text{H}$
	БПО-184 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$		БПО-189 $F \text{ см}^2 = 1.620$ $Q \text{ кг.} = 0.439$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 245.6$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	БПО-185 $F \text{ см}^2 = 1.370$ $Q \text{ кг.} = 0.371$ $D \text{ оп.мм} = 93.0$ $P \text{ н.мм} = 206.6$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$		БПО-190 $F \text{ см} = 1.290$ $Q \text{ кг.} = 0.350$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 163$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{H}$








	БПО-191 $F \text{ см}^2 = 0.685$ $Q \text{ кг.} = 0.186$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 76.0$ Гр.сл. = особ Точн. = Н		БПО-196 $F \text{ см}^2 = 9.237$ $Q \text{ кг.} = 2.503$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 196.0$ Гр.сл. = II Точн. = Н
	БПО-192 $F \text{ см}^2 = 3.17$ $Q \text{ кг.} = 0.859$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 214$ Гр.сл. = IV Точн. = П		БПО-197 $F \text{ см} = 1.710$ $Q \text{ кг.} = 0.463$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 260.3$ Гр.сл. = III Точн. = Н
	БПО-193 $F \text{ см}^2 = 1.440$ $Q \text{ кг.} = 0.390$ $D \text{ оп.мм} = 93.0$ $P \text{ н.мм} = 218.0$ Гр.сл. = III Точн. = Н		БПО-198 $F \text{ см}^2 = 1.380$ $Q \text{ кг.} = 0.374$ $D \text{ оп.мм} = 81.0$ $P \text{ н.мм} = 208.5$ Гр.сл. = III Точн. = Н
	БПО-194 $F \text{ см}^2 = 2.64$ $Q \text{ кг.} = 0.715$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 261$ Гр.сл. = IV Точн. = П		БПО-199 $F \text{ см}^2 = 0.70$ $Q \text{ кг.} = 0.19$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 143$ Гр.сл. = особ Точн. = Н
	БПО-195 $F \text{ см}^2 = 3.515$ $Q \text{ кг.} = 0.953$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 159$ Гр.сл. = III Точн. = Н		БПО-200 $F \text{ см} = 7.960$ $Q \text{ кг.} = 2.15$ $D \text{ оп.мм} = 126.0$ $P \text{ н.мм} = 392.0$ Гр.сл. = IV Точн. = Н











	<p>БПО-201</p> <p> $F \text{ см}^2 = 2.032$ $Q \text{ кг.} = 0.551$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 202.13$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-206</p> <p> $F \text{ см}^2 = 1.269$ $Q \text{ кг.} = 0.344$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 90.5$ Гр.сл. = III Точн. = Н </p>
	<p>БПО-202</p> <p> $F \text{ см}^2 = 7.8$ $Q \text{ кг.} = 2.114$ $D \text{ оп.мм} = 42.5$ $P \text{ н.мм} = 160$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-207</p> <p> $F \text{ см}^2 = 1.67$ $Q \text{ кг.} = 0.455$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 155$ Гр.сл. = VI Точн. = Н </p>
	<p>БПО-203</p> <p> $F \text{ см}^2 = 1.77$ $Q \text{ кг.} = 0.479$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 95$ Гр.сл. = II Точн. = Н </p>		<p>БПО-208</p> <p> $F \text{ см}^2 = 2.157$ $Q \text{ кг.} = 0.5845$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 160$ Гр.сл. = VI Точн. = Н </p>
	<p>БПО-204</p> <p> $F \text{ см}^2 = 2.24$ $Q \text{ кг.} = 0.608$ $D \text{ оп.мм} = 44$ $P \text{ н.мм} = 128$ Гр.сл. = I Точн. = Н </p>		<p>БПО-209</p> <p> $F \text{ см}^2 = 3.11$ $Q \text{ кг.} = 0.843$ $D \text{ оп.мм} = 69.0$ $P \text{ н.мм} = 194$ Гр.сл. = IV Точн. = Н </p>
	<p>БПО-205</p> <p> $F \text{ см}^2 = 1.884$ $Q \text{ кг.} = 0.511$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 149$ Гр.сл. = III Точн. = Н </p>		<p>БПО-210</p> <p> $F \text{ см}^2 = 1.435$ $Q \text{ кг.} = 0.389$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 79.0$ Гр.сл. = IV Точн. = Н </p>

	БПО-211		БПО-216
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 1.630$ $Q \text{ кг.} = 0.442$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 247.1$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	БПО-212		БПО-217
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 1.370$ $Q \text{ кг.} = 0.371$ $D \text{ оп.мм} = 81.0$ $P \text{ н.мм} = 206.6$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	БПО-213		БПО-218
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 21.48$ $Q \text{ кг.} = 5.82$ $D \text{ оп.мм} = 80$ $P \text{ н.мм} = 334$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
	БПО-214		БПО-219
	$F \text{ см}^2 = 3.87$ $Q \text{ кг.} = 1.05$ $D \text{ оп.мм} = 46$ $P \text{ н.мм} = 225$ $\text{Гр.сл.} = \text{VI}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 2.48$ $Q \text{ кг.} = 0.67$ $D \text{ оп.мм} = 20$ $P \text{ н.мм} = 59$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	БПО-215		БПО-220
	$F \text{ см}^2 = 7.425$ $Q \text{ кг.} = 2.012$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 186$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 1.73$ $Q \text{ кг.} = 0.468$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 137$ $\text{Гр.сл.} = \text{II}$ $\text{Точн.} = \text{H}$









	<p>БПО-221</p> <p> $F \text{ см}^2 = 1.523$ $Q \text{ кг.} = 0.413$ $D \text{ оп.мм} = 46$ $P \text{ н.мм} = 123$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-226</p> <p> $F \text{ см}^2 = 1.600$ $Q \text{ кг.} = 0.434$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 244.2$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>
	<p>БПО-222</p> <p> $F \text{ см}^2 = 1.383$ $Q \text{ кг.} = 0.375$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 142.1$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-227</p> <p> $F \text{ см} = 1.0$ $Q \text{ кг.} = 0.271$ $D \text{ оп.мм} = 14.1$ $P \text{ н.мм} = 40.0$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>
	<p>БПО-223</p> <p> $F \text{ см}^2 = 2.084$ $Q \text{ кг.} = 0.565$ $D \text{ оп.мм} = 97.0$ $P \text{ н.мм} = 212.3$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-228</p> <p> $F \text{ см}^2 = 1.470$ $Q \text{ кг.} = 0.398$ $D \text{ оп.мм} = 91.0$ $P \text{ н.мм} = 223.8$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>
	<p>БПО-224</p> <p> $F \text{ см}^2 = 1.620$ $Q \text{ кг.} = 0.439$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 244.7$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-229</p> <p> $F \text{ см}^2 = 1.720$ $Q \text{ кг.} = 0.466$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 465.7$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>
	<p>БПО-225</p> <p> $F \text{ см}^2 = 1.360$ $Q \text{ кг.} = 0.369$ $D \text{ оп.мм} = 93.0$ $P \text{ н.мм} = 205.0$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-230</p> <p> $F \text{ см} = 6.65$ $Q \text{ кг.} = 1.802$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 108.0$ $\text{Гр.сл.} = \text{I}$ $\text{Точн.} = \text{H}$ </p>











	<p>БПО-231</p> <p> $F \text{ см}^2 = 1.013$ $Q \text{ кг.} = 0.275$ $D \text{ оп.мм} = 40.75$ $P \text{ н.мм} = 95.2$ Гр.сл. = III Точн. = Н </p>		<p>БПО-236</p> <p> $F \text{ см}^2 = 2.09$ $Q \text{ кг.} = 0.567$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 106.0$ Гр.сл. = I Точн. = Н </p>
	<p>БПО-232</p> <p> $F \text{ см}^2 = 0.604$ $Q \text{ кг.} = 0.164$ $D \text{ оп.мм} = 22.75$ $P \text{ н.мм} = 62.3$ Гр.сл. = II Точн. = Н </p>		<p>БПО-237</p> <p> $F \text{ см} =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-233</p> <p> $F \text{ см}^2 = 0.653$ $Q \text{ кг.} = 0.177$ $D \text{ оп.мм} = 25.2$ $P \text{ н.мм} = 59.0$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-238</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-234</p> <p> $F \text{ см}^2 = 2.670$ $Q \text{ кг.} = 0.724$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 154.5$ Гр.сл. = VI Точн. = Н </p>		<p>БПО-239</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-235</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-240</p> <p> $F \text{ см} = 4.83$ $Q \text{ кг.} = 1.309$ $D \text{ оп.мм} = 79.0$ $P \text{ н.мм} = 489.7$ Гр.сл. = VI Точн. = II </p>



	<p>БПО-241</p> <p> $F \text{ см}^2 = 19.635$ $Q \text{ кг.} = 5.321$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 157$ Гр.сл. = II Точн. = Н </p>		<p>БПО-246</p> <p> $F \text{ см}^2 = 2.62$ $Q \text{ кг.} = 0.71$ $D \text{ оп.мм} = 93.0$ $P \text{ н.мм} = 217.1$ Гр.сл. = IV Точн. = П </p>
	<p>БПО-242</p> <p> $F \text{ см}^2 = 5.3$ $Q \text{ кг.} = 1.44$ $D \text{ оп.мм} = 132.0$ $P \text{ н.мм} = 418$ Гр.сл. = VI Точн. = П </p>		<p>БПО-247</p> <p> $F \text{ см} = 3.37$ $Q \text{ кг.} = 0.913$ $D \text{ оп.мм} = 121.0$ $P \text{ н.мм} = 277.1$ Гр.сл. = IV Точн. = П </p>
	<p>БПО-243</p> <p> $F \text{ см}^2 = 1.340$ $Q \text{ кг.} = 0.363$ $D \text{ оп.мм} = 92.0$ $P \text{ н.мм} = 203.0$ Гр.сл. = III Точн. = Н </p>		<p>БПО-248</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-249</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-245</p> <p> $F \text{ см}^2 = 2.919$ $Q \text{ кг.} = 0.791$ $D \text{ оп.мм} = 71$ $P \text{ н.мм} = 197.4$ Гр.сл. = II Точн. = Н </p>		<p>БПО-250</p> <p> $F \text{ см} = 1.739$ $Q \text{ кг.} = 0.471$ $D \text{ оп.мм} = 72$ $P \text{ н.мм} = 225.9$ Гр.сл. = VI Точн. = Н </p>









	<p>БПО-251</p> <p> $F \text{ см}^2 = 0.820$ $Q \text{ кг.} = 0.22$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 82.0$ Гр.сл. = VI Точн. = Н </p>		<p>БПО-256</p> <p> $F \text{ см}^2 = 0.494$ $Q \text{ кг.} = 0.134$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 97.45$ Гр.сл. = IV Точн. = Н </p>
	<p>БПО-252</p> <p> $F \text{ см}^2 = 1.101$ $Q \text{ кг.} = 0.297$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 70.0$ Гр.сл. = VI Точн. = Н </p>		<p>БПО-257</p> <p> $F \text{ см}^2 = 1.150$ $Q \text{ кг.} = 0.312$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 107.0$ Гр.сл. = V Точн. = П </p>
	<p>БПО-253</p> <p> $F \text{ см}^2 = 48.600$ $Q \text{ кг.} = 13.17$ $D \text{ оп.мм} = 163.0$ $P \text{ н.мм} = 380.0$ Гр.сл. = I Точн. = Н </p>		<p>БПО-258</p> <p> $F \text{ см}^2 = 2.520$ $Q \text{ кг.} = 0.683$ $D \text{ оп.мм} = 107.0$ $P \text{ н.мм} = 307.0$ Гр.сл. = V Точн. = ? </p>
	<p>БПО-254</p> <p> $F \text{ см}^2 = 3.1121$ $Q \text{ кг.} = 0.843$ $D \text{ оп.мм} = 119$ $P \text{ н.мм} = 320.4$ Гр.сл. = VI Точн. = Н </p>		<p>БПО-259</p> <p> $F \text{ см}^2 = 3.64$ $Q \text{ кг.} = 0.987$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 128$ Гр.сл. = III Точн. = Н </p>
	<p>БПО-255</p> <p> $F \text{ см}^2 = 1.815$ $Q \text{ кг.} = 0.492$ $D \text{ оп.мм} = 56.3$ $P \text{ н.мм} = 238.6$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-260</p> <p> $F \text{ см}^2 = 3.205$ $Q \text{ кг.} = 0.868$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 242$ Гр.сл. = V Точн. = Н </p>










	<p>БПО-261</p> <p> $F \text{ см}^2 = 2.376$ $Q \text{ кг.} = 0.644$ $D \text{ оп.мм} = 77$ $P \text{ н.мм} = 288.1$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-266</p> <p> $F \text{ см}^2 = 1.87$ $Q \text{ кг.} = 0.507$ $D \text{ оп.мм} = 74$ $P \text{ н.мм} = 220$ Гр.сл. = V Точн. = П </p>
	<p>БПО-262</p> <p> $F \text{ см}^2 = 0.87$ $Q \text{ кг.} = 0.236$ $D \text{ оп.мм} = 22.67$ $P \text{ н.мм} = 64$ Гр.сл. = II Точн. = Н </p>		<p>БПО-267</p> <p> $F \text{ см} =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-263</p> <p> $F \text{ см}^2 = 11.69$ $Q \text{ кг.} = 3.168$ $D \text{ оп.мм} = 117.1$ $P \text{ н.мм} = 416.2$ Гр.сл. = VI Точн. = П </p>		<p>БПО-268</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-264</p> <p> $F \text{ см}^2 = 8.26$ $Q \text{ кг.} = 2.238$ $D \text{ оп.мм} = 79.6$ $P \text{ н.мм} = 306.8$ Гр.сл. = VI Точн. = П </p>		<p>БПО-269</p> <p> $F \text{ см}^2 = 1.640$ $Q \text{ кг.} = 0.444$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 189.0$ Гр.сл. = V Точн. = П </p>
	<p>БПО-265</p> <p> $F \text{ см}^2 = 2.090$ $Q \text{ кг.} = 0.566$ $D \text{ оп.мм} = 87.0$ $P \text{ н.мм} = 255.0$ Гр.сл. = V Точн. = П </p>		<p>БПО-270</p> <p> $F \text{ см} = 1.95$ $Q \text{ кг.} = 0.528$ $D \text{ оп.мм} = 41$ $P \text{ н.мм} = 131$ Гр.сл. = II Точн. = Н </p>










	БПО-271 $F \text{ см}^2 = 0.92$ $Q \text{ кг.} = 0.249$ $D \text{ оп.мм} = 16.0$ $P \text{ н.мм} = 124$ Гр.сл. = IV Точн. = Н		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. =
	БПО-272 $F \text{ см}^2 = 3.84$ $Q \text{ кг.} = 1.042$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 340$ Гр.сл. = VI Точн. = Н		БПО-277 $F \text{ см} = 1.18$ $Q \text{ кг.} = 0.32$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 69$ Гр.сл. = IV Точн. = Н
	БПО-273 $F \text{ см}^2 = 1.080$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 114.0$ Гр.сл. = V Точн. = П		БПО-278 $F \text{ см}^2 = 0.379$ $Q \text{ кг.} = 0.103$ $D \text{ оп.мм} = 6.9$ $P \text{ н.мм} = 21.98$ Гр.сл. = I Точн. = Н
	БПО-274 $F \text{ см}^2 = 2.94$ $Q \text{ кг.} = 0.796$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 168$ Гр.сл. = III Точн. = Н		БПО-279 $F \text{ см}^2 = 12.59$ $Q \text{ кг.} = 3.412$ $D \text{ оп.мм} = 152.7$ $P \text{ н.мм} = 492.7$ Гр.сл. = V Точн. = Н
	БПО-275 $F \text{ см}^2 = 2.057$ $Q \text{ кг.} = 0.557$ $D \text{ оп.мм} = 80$ $P \text{ н.мм} = 138.5$ Гр.сл. = IV Точн. = Н		БПО-280 $F \text{ см} =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. =

	<p>БПО-281</p> <p> $F \text{ см}^2 = 1.800$ $Q \text{ кг.} = 0.488$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 80.7$ Гр.сл. = III Точн. = Н </p>		<p>БПО-286</p> <p> $F \text{ см}^2 = 1.304$ $Q \text{ кг.} = 0.353$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 216.2$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-282</p> <p> $F \text{ см}^2 = 2.05$ $Q \text{ кг.} = 0.556$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 126$ Гр.сл. = IV Точн. = П </p>		<p>БПО-287</p> <p> $F \text{ см} = 0.429$ $Q \text{ кг.} = 0.116$ $D \text{ оп.мм} = 24.5$ $P \text{ н.мм} = 85.22$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-283</p> <p> $F \text{ см}^2 = 4.77$ $Q \text{ кг.} = 1.293$ $D \text{ оп.мм} = 72$ $P \text{ н.мм} = 172$ Гр.сл. = V Точн. = П </p>		<p>БПО-288</p> <p> $F \text{ см}^2 = 5.212$ $Q \text{ кг.} = 1.412$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 214.5$ Гр.сл. = V Точн. = П </p>
	<p>БПО-284</p> <p> $F \text{ см}^2 = 4.6$ $Q \text{ кг.} = 1.247$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 162.7$ Гр.сл. = VI Точн. = П </p>		<p>БПО-289</p> <p> $F \text{ см}^2 = 0.801$ $Q \text{ кг.} = 0.217$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 160.5$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-285</p> <p> $F \text{ см}^2 = 8.25$ $Q \text{ кг.} = 2.24$ $D \text{ оп.мм} = 102$ $P \text{ н.мм} = 415$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-290</p> <p> $F \text{ см} = 1.689$ $Q \text{ кг.} = 0.458$ $D \text{ оп.мм} = 61.36$ $P \text{ н.мм} = 238.0$ Гр.сл. = VI Точн. = П </p>








	БПО-291		БПО-296
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{ р.сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 1.100$ $Q \text{ кг.} = 0.298$ $D \text{ оп.мм} = 62.0$ $P \text{ н.мм} = 184.8$ $\Gamma \text{ р.сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-292		БПО-297
	$F \text{ см}^2 = 4.286$ $Q \text{ кг.} = 1.162$ $D \text{ оп.мм} = 51.3$ $P \text{ н.мм} = 205.5$ $\Gamma \text{ р.сл.} = \text{II}$ $\text{Точн.} = \text{П}$		$F \text{ см} =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{ р.сл.} =$ $\text{Точн.} =$
	БПО-293		БПО-298
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{ р.сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{ р.сл.} =$ $\text{Точн.} =$
	БПО-294		БПО-299
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{ р.сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{ р.сл.} =$ $\text{Точн.} =$
	БПО-295		БПО-300
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{ р.сл.} =$ $\text{Точн.} =$		$F \text{ см} =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{ р.сл.} =$ $\text{Точн.} =$











	БПО-301 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$		БПО-306 $F \text{ см}^2 = 1.974$ $Q \text{ кг.} = 0.535$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 267.9$ $\text{Гр.сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-302 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$		БПО-307 $F \text{ см} = 1.250$ $Q \text{ кг.} = 0.339$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 130$ $\text{Гр.сл.} = \text{особ}$ $\text{Точн.} = \text{Н}$
	БПО-303 $F \text{ см}^2 = 12.92$ $Q \text{ кг.} = 3.501$ $D \text{ оп.мм} = 148.0$ $P \text{ н.мм} = 381.6$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$		БПО-308 $F \text{ см}^2 = 0.927$ $Q \text{ кг.} = 0.251$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 91.75$ $\text{Гр.сл.} = \text{II}$ $\text{Точн.} = \text{Н}$
	БПО-304 $F \text{ см}^2 = 1.004$ $Q \text{ кг.} = 0.272$ $D \text{ оп.мм} = 25.7$ $P \text{ н.мм} = 128.7$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-309 $F \text{ см}^2 = 3.009$ $Q \text{ кг.} = 0.815$ $D \text{ оп.мм} = 90.3$ $P \text{ н.мм} = 401.4$ $\text{Гр.сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-305 $F \text{ см}^2 = 0.460$ $Q \text{ кг.} = 0.125$ $D \text{ оп.мм} = 12.0$ $P \text{ н.мм} = 49.38$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-310 $F \text{ см} = 8.72$ $Q \text{ кг.} = 2.363$ $D \text{ оп.мм} = 87.2$ $P \text{ н.мм} = 488.78$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$











	БПО-311 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 4.759$ $D \text{ оп.мм} = 0$ $P \text{ н.мм} = 0$ $\Gamma \text{ р.сл.} =$ $\text{Точн.} = \text{П}$		БПО-316 $F \text{ см}^2 = 0.12$ $Q \text{ кг.} = 0.033$ $D \text{ оп.мм} = 4.0$ $P \text{ н.мм} = 12$ $\Gamma \text{ р.сл.} = \text{II}$ $\text{Точн.} = \text{Н}$
	БПО-312 $F \text{ см}^2 = 0.48$ $Q \text{ кг.} = 0.13$ $D \text{ оп.мм} = 16.5$ $P \text{ н.мм} = 38$ $\Gamma \text{ р.сл.} = \text{I}$ $\text{Точн.} = \text{Н}$		БПО-317 $F \text{ см} = 4.297$ $Q \text{ кг.} = 1.164$ $D \text{ оп.мм} = 58.7$ $P \text{ н.мм} = 207.25$ $\Gamma \text{ р.сл.} = \text{II}$ $\text{Точн.} = \text{Н}$
	БПО-313 $F \text{ см}^2 = 0.9$ $Q \text{ кг.} = 0.244$ $D \text{ оп.мм} = 15.5$ $P \text{ н.мм} = 42$ $\Gamma \text{ р.сл.} = \text{I}$ $\text{Точн.} = \text{Н}$		БПО-318 $F \text{ см}^2 = 8.884$ $Q \text{ кг.} = 2.408$ $D \text{ оп.мм} = 128.0$ $P \text{ н.мм} = 860.2$ $\Gamma \text{ р.сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-314 $F \text{ см}^2 = 1.201$ $Q \text{ кг.} = 0.325$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 87.9$ $\Gamma \text{ р.сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$		БПО-319 $F \text{ см}^2 = 0.902$ $Q \text{ кг.} = 0.244$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 82.7$ $\Gamma \text{ р.сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-315 $F \text{ см}^2 = 1.6$ $Q \text{ кг.} = 0.434$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 107.7$ $\Gamma \text{ р.сл.} = \text{III}$ $\text{Точн.} = \text{Н}$		БПО-320 $F \text{ см} = 2.72$ $Q \text{ кг.} = 0.737$ $D \text{ оп.мм} = 42.4$ $P \text{ н.мм} = 166$ $\Gamma \text{ р.сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$











	<p>БПО-321</p> <p> $F \text{ см}^2 = 17.560$ $Q \text{ кг.} = 4.759$ $D \text{ оп.мм} = 144.1$ $P \text{ н.мм} = 610.6$ Гр.сл. = особ Точн. = П </p>		<p>БПО-326</p> <p> $F \text{ см}^2 = 10.85$ $Q \text{ кг.} = 2.94$ $D \text{ оп.мм} = 145.9$ $P \text{ н.мм} = 347$ Гр.сл. = IV Точн. = П </p>
	<p>БПО-322</p> <p> $F \text{ см}^2 = 1.248$ $Q \text{ кг.} = 0.338$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 97.8$ Гр.сл. = I Точн. = Н </p>		<p>БПО-327</p> <p> $F \text{ см} = 0.576$ $Q \text{ кг.} = 0.156$ $D \text{ оп.мм} = 19.0$ $P \text{ н.мм} = 54.4$ Гр.сл. = IV Точн. = П </p>
	<p>БПО-323</p> <p> $F \text{ см}^2 = 6.460$ $Q \text{ кг.} = 1.751$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 152.3$ Гр.сл. = III Точн. = П </p>		<p>БПО-328</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-324</p> <p> $F \text{ см}^2 = 1.129$ $Q \text{ кг.} = 0.306$ $D \text{ оп.мм} = 41.5$ $P \text{ н.мм} = 155.5$ Гр.сл. = V Точн. = П </p>		<p>БПО-329</p> <p> $F \text{ см}^2 = 24.145$ $Q \text{ кг.} = 6.543$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 196.3$ Гр.сл. = III Точн. = П </p>
	<p>БПО-325</p> <p> $F \text{ см}^2 = 6.86$ $Q \text{ кг.} = 1.859$ $D \text{ оп.мм} = 160.0$ $P \text{ н.мм} = 401$ Гр.сл. = V Точн. = Н </p>		<p>БПО-330</p> <p> $F \text{ см} = 2.550$ $Q \text{ кг.} = 0.691$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 349.1$ Гр.сл. = V Точн. = П </p>

	<p>БПО-331</p> <p> $F \text{ см}^2 = 5.2$ $Q \text{ кг.} = 1.41$ $D \text{ оп.мм} = 60$ $P \text{ н.мм} = 216.2$ Гр.сл. = особ Точн. = Н </p>		<p>БПО-336</p> <p> $F \text{ см}^2 = 15.9$ $Q \text{ кг.} = 4.3$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 141.4$ Гр.сл. = I Точн. = Н </p>
	<p>БПО-332</p> <p> $F \text{ см}^2 = 3.18$ $Q \text{ кг.} = 0.86$ $D \text{ оп.мм} = 81.0$ $P \text{ н.мм} = 303.4$ Гр.сл. = особ Точн. = Н </p>		<p>БПО-337</p> <p> $F \text{ см} = 3.580$ $Q \text{ кг.} = 0.969$ $D \text{ оп.мм} = 82$ $P \text{ н.мм} = 233$ Гр.сл. = IV Точн. = П </p>
	<p>БПО-333</p> <p> $F \text{ см}^2 = 1.66$ $Q \text{ кг.} = 0.45$ $D \text{ оп.мм} = 78.5$ $P \text{ н.мм} = 182.6$ Гр.сл. = VI Точн. = Н </p>		<p>БПО-338</p> <p> $F \text{ см}^2 = 5.740$ $Q \text{ кг.} = 1.55$ $D \text{ оп.мм} = 142.0$ $P \text{ н.мм} = 353$ Гр.сл. = IV Точн. = П </p>
	<p>БПО-334</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-339</p> <p> $F \text{ см}^2 = 2.47$ $Q \text{ кг.} = 0.669$ $D \text{ оп.мм} = 109.2$ $P \text{ н.мм} = 249.5$ Гр.сл. = V Точн. = Н </p>
	<p>БПО-335</p> <p> $F \text{ см}^2 = 8.04$ $Q \text{ кг.} = 2.17$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 100.5$ Гр.сл. = I Точн. = Н </p>		<p>БПО-340</p> <p> $F \text{ см} = 2.091$ $Q \text{ кг.} = 0.567$ $D \text{ оп.мм} = 90.2$ $P \text{ н.мм} = 211.5$ Гр.сл. = V Точн. = Н </p>











	БПО-341		БПО-346
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 1.399$ $Q \text{ кг.} = 0.379$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 191.3$ $\text{Гр.сл.} = V$ $\text{Точн.} = П$
	БПО-342		БПО-347
	$F \text{ см}^2 = 15.02$ $Q \text{ кг.} = 4.07$ $D \text{ оп.мм} = 133.5$ $P \text{ н.мм} = 393$ $\text{Гр.сл.} = IV$ $\text{Точн.} = П$		$F \text{ см} = 0.890$ $Q \text{ кг.} = 0.241$ $D \text{ оп.мм} = 28.1$ $P \text{ н.мм} = 135.7$ $\text{Гр.сл.} = V$ $\text{Точн.} = П$
	БПО-343		БПО-348
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 12.3$ $Q \text{ кг.} = 3.32$ $D \text{ оп.мм} = 125$ $P \text{ н.мм} = 879$ $\text{Гр.сл.} = IV$ $\text{Точн.} = H$
	БПО-344		БПО-349
	$F \text{ см}^2 = 3.0$ $Q \text{ кг.} = 0.813$ $D \text{ оп.мм} = 75.1$ $P \text{ н.мм} = 158$ $\text{Гр.сл.} = II$ $\text{Точн.} = H$		$F \text{ см}^2 = 40.47$ $Q \text{ кг.} = 10.97$ $D \text{ оп.мм} = 136$ $P \text{ н.мм} = 550$ $\text{Гр.сл.} = III$ $\text{Точн.} = П$
	БПО-345		БПО-350
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр.сл.} =$ $\text{Точн.} =$		$F \text{ см} = 2.92$ $Q \text{ кг.} = 0.792$ $D \text{ оп.мм} = 71$ $P \text{ н.мм} = 141.8$ $\text{Гр.сл.} = III$ $\text{Точн.} = H$











	<p>БПО-351</p> <p> $F \text{ см}^2 = 2.4$ $Q \text{ кг.} = 0.65$ $D \text{ оп.мм} = 38.4$ $P \text{ н.мм} = 118$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = ?$ </p>		<p>БПО-356</p> <p> $F \text{ см}^2 = 4.686$ $Q \text{ кг.} = 1.270$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 363.8$ $\text{Гр.сл.} = \text{VI}$ $\text{Точн.} = ?$ </p>
	<p>БПО-352</p> <p> $F \text{ см}^2 = 1.998$ $Q \text{ кг.} = 0.541$ $D \text{ оп.мм} = 77.0$ $P \text{ н.мм} = 272.0$ $\text{Гр.сл.} = \text{V}$ $\text{Точн.} = ?$ </p>		<p>БПО-357</p> <p> $F \text{ см} = 1.23$ $Q \text{ кг.} = 0.334$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 100$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = ?$ </p>
	<p>БПО-353</p> <p> $F \text{ см}^2 = 2.760$ $Q \text{ кг.} = 0.748$ $D \text{ оп.мм} = 92.0$ $P \text{ н.мм} = 408.6$ $\text{Гр.сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-358</p> <p> $F \text{ см}^2 = 1.023$ $Q \text{ кг.} = 0.277$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 100.0$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>
	<p>БПО-354</p> <p> $F \text{ см}^2 = 1.280$ $Q \text{ кг.} = 0.346$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 96.5$ $\text{Гр.сл.} = \text{особ}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-359</p> <p> $F \text{ см}^2 = 3.120$ $Q \text{ кг.} = 0.846$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 316.0$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{H}$ </p>
	<p>БПО-355</p> <p> $F \text{ см}^2 = 1.877$ $Q \text{ кг.} = 0.509$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 130.0$ $\text{Гр.сл.} = \text{особ}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-360</p> <p> $F \text{ см} = 1.754$ $Q \text{ кг.} = 0.475$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 233.7$ $\text{Гр.сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>








	<p>БПО-361</p> <p> $F \text{ см}^2 = 0.456$ $Q \text{ кг.} = 0.124$ $D \text{ оп.мм} = 23.6$ $P \text{ н.мм} = 65.2$ Гр.сл. = IV Точн. = П </p>		<p>БПО-366</p> <p> $F \text{ см}^2 = 7.38$ $Q \text{ кг.} = 2.0$ $D \text{ оп.мм} = 134.0$ $P \text{ н.мм} = 443.7$ Гр.сл. = IV Точн. = Н </p>
	<p>БПО-362</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-367</p> <p> $F \text{ см} = 1.850$ $Q \text{ кг.} = 0.501$ $D \text{ оп.мм} = 27.9$ $P \text{ н.мм} = 71.2$ Гр.сл. = II Точн. = Н </p>
	<p>БПО-363</p> <p> $F \text{ см}^2 = 1.980$ $Q \text{ кг.} = 0.537$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 312.4$ Гр.сл. = особ Точн. = П </p>		<p>БПО-368</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>
	<p>БПО-364</p> <p> $F \text{ см}^2 = 4.534$ $Q \text{ кг.} = 1.229$ $D \text{ оп.мм} = 187.0$ $P \text{ н.мм} = 480.2$ Гр.сл. = особ Точн. = П </p>		<p>БПО-369</p> <p> $F \text{ см}^2 = 0.926$ $Q \text{ кг.} = 0.251$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 97$ Гр.сл. = III Точн. = Н </p>
	<p>БПО-365</p> <p> $F \text{ см}^2 = 10.550$ $Q \text{ кг.} = 2.859$ $D \text{ оп.мм} = 109.8$ $P \text{ н.мм} = 248.5$ Гр.сл. = II Точн. = Н </p>		<p>БПО-370</p> <p> $F \text{ см} = 1.520$ $Q \text{ кг.} = 0.412$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 84.8$ Гр.сл. = III Точн. = ПН </p>











	<p>БПО-371</p> <p> $F \text{ см}^2 = 0.378$ $Q \text{ кг.} = 0.102$ $D \text{ оп.мм} = 19.5$ $P \text{ н.мм} = 44.9$ Гр.сл. = V Точн. = П </p>		<p>БПО-376</p> <p> $F \text{ см}^2 = 2.66$ $Q \text{ кг.} = 0.72$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 222.3$ Гр.сл. = IV Точн. = Н </p>
	<p>БПО-372</p> <p> $F \text{ см}^2 = 0.610$ $Q \text{ кг.} = 0.165$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 85.7$ Гр.сл. = V Точн. = П </p>		<p>БПО-377</p> <p> $F \text{ см}^2 = 0.570$ $Q \text{ кг.} = 0.154$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 114.0$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-373</p> <p> $F \text{ см}^2 = 0.762$ $Q \text{ кг.} = 0.207$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 153.5$ Гр.сл. = VI Точн. = ? </p>		<p>БПО-378</p> <p> $F \text{ см}^2 = 2.070$ $Q \text{ кг.} = 0.561$ $D \text{ оп.мм} = 42.4$ $P \text{ н.мм} = 180.0$ Гр.сл. = IV Точн. = ? </p>
	<p>БПО-374</p> <p> $F \text{ см}^2 = 2.237$ $Q \text{ кг.} = 0.606$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 176.9$ Гр.сл. = IV Точн. = П </p>		<p>БПО-379</p> <p> $F \text{ см}^2 = 5.38$ $Q \text{ кг.} = 1.458$ $D \text{ оп.мм} = 94.0$ $P \text{ н.мм} = 419.9$ Гр.сл. = IV Точн. = П </p>
	<p>БПО-375</p> <p> $F \text{ см}^2 = 0.730$ $Q \text{ кг.} = 0.198$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 136.2$ Гр.сл. = VI Точн. = Н </p>		<p>БПО-380</p> <p> $F \text{ см}^2 = 4.926$ $Q \text{ кг.} = 1.335$ $D \text{ оп.мм} = 91$ $P \text{ н.мм} = 378.3$ Гр.сл. = IV Точн. = П </p>










	<p>БПО-381</p> <p> $F \text{ см}^2 = 1.76$ $Q \text{ кг.} = 0.477$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 205.3$ Гр.сл. = IV Точн. = П </p>		<p>БПО-386</p> <p> $F \text{ см}^2 = 2.41$ $Q \text{ кг.} = 0.653$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 195.7$ Гр.сл. = IV Точн. = П </p>
	<p>БПО-382</p> <p> $F \text{ см}^2 = 0.585$ $Q \text{ кг.} = 0.159$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 99.5$ Гр.сл. = V Точн. = П </p>		<p>БПО-387</p> <p> $F \text{ см} = 3.654$ $Q \text{ кг.} = 0.990$ $D \text{ оп.мм} = 180.0$ $P \text{ н.мм} = 369.0$ Гр.сл. = особ Точн. = П </p>
	<p>БПО-383</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. = </p>		<p>БПО-388</p> <p> $F \text{ см}^2 = 3.237$ $Q \text{ кг.} = 0.877$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 341.0$ Гр.сл. = VI Точн. = ? </p>
	<p>БПО-384</p> <p> $F \text{ см}^2 = 1.803$ $Q \text{ кг.} = 0.489$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 185.1$ Гр.сл. = V Точн. = П </p>		<p>БПО-389</p> <p> $F \text{ см}^2 = 0.877$ $Q \text{ кг.} = 0.238$ $D \text{ оп.мм} = 19.0$ $P \text{ н.мм} = 77.4$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-385</p> <p> $F \text{ см}^2 = 17.97$ $Q \text{ кг.} = 4.871$ $D \text{ оп.мм} = 146$ $P \text{ н.мм} = 409$ Гр.сл. = III Точн. = Н </p>		<p>БПО-390</p> <p> $F \text{ см} = 0.261$ $Q \text{ кг.} = 0.071$ $D \text{ оп.мм} = 10.0$ $P \text{ н.мм} = 24.8$ Гр.сл. = III Точн. = Н </p>

	<p>БПО-391</p> <p> $F \text{ см}^2 = 3.394$ $Q \text{ кг.} = 0.920$ $D \text{ оп.мм} = 110.0$ $P \text{ н.мм} = 273.8$ Гр.сл. = V Точн. = П </p>		<p>БПО-396</p> <p> $F \text{ см}^2 = 2.453$ $Q \text{ кг.} = 0.665$ $D \text{ оп.мм} = 57.3$ $P \text{ н.мм} = 250.0$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-392</p> <p> $F \text{ см}^2 = 6.000$ $Q \text{ кг.} = 1.626$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 188.0$ Гр.сл. = II Точн. = П </p>		<p>БПО-397</p> <p> $F \text{ см}^2 = 2.775$ $Q \text{ кг.} = 0.752$ $D \text{ оп.мм} = 77.3$ $P \text{ н.мм} = 282.2$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-393</p> <p> $F \text{ см}^2 = 0.647$ $Q \text{ кг.} = 0.175$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 130.3$ Гр.сл. = VI Точн. = П </p>		<p>БПО-398</p> <p> $F \text{ см}^2 = 7.793$ $Q \text{ кг.} = 2.112$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 497.8$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-394</p> <p> $F \text{ см}^2 = 0.87$ $Q \text{ кг.} = 0.236$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 115$ Гр.сл. = VI Точн. = П </p>		<p>БПО-399</p> <p> $F \text{ см}^2 = 0.692$ $Q \text{ кг.} = 0.188$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 101.6$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-395</p> <p> $F \text{ см}^2 = 4.249$ $Q \text{ кг.} = 1.151$ $D \text{ оп.мм} = 175.0$ $P \text{ н.мм} = 396.7$ Гр.сл. = особ Точн. = П </p>		<p>БПО-400</p> <p> $F \text{ см}^2 = 0.855$ $Q \text{ кг.} = 0.232$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 145.5$ Гр.сл. = особ Точн. = П </p>









	<p>БПО-401</p> <p> $F \text{ см}^2 = 5.465$ $Q \text{ кг.} = 1.481$ $D \text{ оп.мм} = 180.0$ $P \text{ н.мм} = 534.3$ Гр.сл. = особ Точн. = П </p>		<p>БПО-406</p> <p> $F \text{ см}^2 = 0.437$ $Q \text{ кг.} = 0.118$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 83.7$ Гр.сл. = особ Точн. = П </p>
	<p>БПО-402</p> <p> $F \text{ см}^2 = 4.020$ $Q \text{ кг.} = 1.089$ $D \text{ оп.мм} = 110.0$ $P \text{ н.мм} = 353.2$ Гр.сл. = V Точн. = П </p>		<p>БПО-407</p> <p> $F \text{ см} = 1.430$ $Q \text{ кг.} = 0.388$ $D \text{ оп.мм} = 62.0$ $P \text{ н.мм} = 182.0$ Гр.сл. = V Точн. = П </p>
	<p>БПО-403</p> <p> $F \text{ см}^2 = 0.480$ $Q \text{ кг.} = 0.130$ $D \text{ оп.мм} = 10.0$ $P \text{ н.мм} = 28.0$ Гр.сл. = III Точн. = Н </p>		<p>БПО-408</p> <p> $F \text{ см}^2 = 0.758$ $Q \text{ кг.} = 0.205$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 71.6$ Гр.сл. = VI Точн. = П </p>
	<p>БПО-404</p> <p> $F \text{ см}^2 = 1.244$ $Q \text{ кг.} = 0.337$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 90.3$ Гр.сл. = IV Точн. = П </p>		<p>БПО-409</p> <p> $F \text{ см}^2 = 15.07$ $Q \text{ кг.} = 4.08$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 284$ Гр.сл. = II Точн. = Н </p>
	<p>БПО-405</p> <p> $F \text{ см}^2 = 0.772$ $Q \text{ кг.} = 0.209$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 128.9$ Гр.сл. = особ Точн. = П </p>		<p>БПО-410</p> <p> $F \text{ см} = 1.61$ $Q \text{ кг.} = 0.436$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 137$ Гр.сл. = VI Точн. = Н </p>










	<p>БПО-0412</p> <p> $F \text{ см}^2 = 3.218$ $Q \text{ кг.} = 0.872$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 281.3$ Гр. сл. = V Точн. = П </p>		<p>БПО-417</p> <p> $F \text{ см}^2 = 19.65$ $Q \text{ кг.} = 5.325$ $D \text{ оп.мм} = 78$ $P \text{ н.мм} = 336$ Гр. сл. = III Точн. = Т </p>
	<p>БПО-413</p> <p> $F \text{ см}^2 = 5.22$ $Q \text{ кг.} = 1.415$ $D \text{ оп.мм} = 137.5$ $P \text{ н.мм} = 333.1$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-418</p> <p> $F \text{ см}^2 = 4.22$ $Q \text{ кг.} = 1.144$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 198.9$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-414</p> <p> $F \text{ см}^2 = 2.15$ $Q \text{ кг.} = 0.583$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 170.9$ Гр. сл. = III Точн. = Н </p>		<p>БПО-418.01</p> <p> $F \text{ см}^2 = 3.867$ $Q \text{ кг.} = 1.048$ $D \text{ оп.мм} = 52.3$ $P \text{ н.мм} = 213.9$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-415</p> <p> $F \text{ см}^2 = 1.38$ $Q \text{ кг.} = 0.374$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 113$ Гр. сл. = III Точн. = Н </p>		











	<p>БПО-421</p> <p> $F \text{ см}^2 = 1.410$ $Q \text{ кг.} = 0.382$ $D \text{ оп.мм} = 13.3$ $P \text{ н.мм} = 42.1$ Гр. сл. = I Точн. = Н </p>		<p>БПО-426</p> <p> $F \text{ см}^2 = 5.4$ $Q \text{ кг.} = 1.463$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 357$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-0422</p> <p> $F \text{ см}^2 = 4.990$ $Q \text{ кг.} = 1.352$ $D \text{ оп.мм} = 190.0$ $P \text{ н.мм} = 599.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-427</p> <p> $F \text{ см}^2 = 4.77$ $Q \text{ кг.} = 1.29$ $D \text{ оп.мм} = 99.5$ $P \text{ н.мм} = 304$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-423</p> <p> $F \text{ см}^2 = 5.96$ $Q \text{ кг.} = 1.61$ $D \text{ оп.мм} = 54$ $P \text{ н.мм} = 226$ Гр. сл. = VI Точн. = Т </p>		<p>БПО-428</p> <p> $F \text{ см}^2 = 1.54$ $Q \text{ кг.} = 0.417$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 112.2$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-424</p> <p> $F \text{ см}^2 = 2.908$ $Q \text{ кг.} = 0.788$ $D \text{ оп.мм} = 34$ $P \text{ н.мм} = 163$ Гр. сл. = VI Точн. = Т </p>		<p>БПО-429</p> <p> $F \text{ см}^2 = 0.869$ $Q \text{ кг.} = 0.235$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 114.8$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-425</p> <p> $F \text{ см}^2 = 3.516$ $Q \text{ кг.} = 0.953$ $D \text{ оп.мм} = 115$ $P \text{ н.мм} = 334$ Гр. сл. = 0соб. Точн. = Т </p>		<p>БПО-430</p> <p> $F \text{ см}^2 = 3.26$ $Q \text{ кг.} = 0.883$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 188.6$ Гр. сл. = IV Точн. = П </p>











	<p>БПО-431</p> <p> $F \text{ см}^2 = 3.871$ $Q \text{ кг.} = 1.05$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 138$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-436</p> <p> $F \text{ см}^2 = 5.21$ $Q \text{ кг.} = 1.41$ $D \text{ оп.мм} = 56$ $P \text{ н.мм} = 214$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-432</p> <p> $F \text{ см}^2 = 2.062$ $Q \text{ кг.} = 0.559$ $D \text{ оп.мм} = 27.7$ $P \text{ н.мм} = 85$ Гр. сл. = VI Точн. = Н </p>		
	<p>БПО-433</p> <p> $F \text{ см}^2 = 0.507$ $Q \text{ кг.} = 0.137$ $D \text{ оп.мм} = 23.5$ $P \text{ н.мм} = 67.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-438</p> <p> $F \text{ см}^2 = 9.235$ $Q \text{ кг.} = 2.503$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 341.0$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-434</p> <p> $F \text{ см}^2 = 2.130$ $Q \text{ кг.} = 0.577$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 93.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-439</p> <p> $F \text{ см}^2 = 0.812$ $Q \text{ кг.} = 0.220$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 114.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-435</p> <p> $F \text{ см}^2 = 3.150$ $Q \text{ кг.} = 0.853$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 137.0$ Гр. сл. = V Точн. = Н </p>		<p>БПО-440</p> <p> $F \text{ см}^2 = 1.148$ $Q \text{ кг.} = 0.31$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 93.4$ Гр. сл. = VI Точн. = Н </p>

	<p>БПО-441</p> <p> $F \text{ см}^2 = 2.675$ $Q \text{ кг.} = 0.725$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 162.0$ Гр. сл. = V Точн. = Н </p>		<p>БПО-446</p> <p> $F \text{ см}^2 = 3.940$ $Q \text{ кг.} = 1.067$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 192.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-442</p> <p> $F \text{ см}^2 = 36.72$ $Q \text{ кг.} = 9.95$ $D \text{ оп.мм} = 156.0$ $P \text{ н.мм} = 354$ Гр. сл. = I Точн. = Н </p>		
	<p>БПО-443</p> <p> $F \text{ см}^2 = 1.860$ $Q \text{ кг.} = 0.504$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 136.0$ Гр. сл. = IV Точн. = Н </p>		
	<p>БПО-444</p> <p> $F \text{ см}^2 = 1.546$ $Q \text{ кг.} = 0.419$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 138.0$ Гр. сл. = III Точн. = Н </p>		
	<p>БПО-445</p> <p> $F \text{ см}^2 = 2.935$ $Q \text{ кг.} = 0.795$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 192.0$ Гр. сл. = III Точн. = Н </p>		











			БПО-456
			$F \text{ см}^2 = 23.400$ $Q \text{ кг.} = 6.341$ $D \text{ оп.мм} = 131.0$ $P \text{ н.мм} = 296.0$ Гр. сл. = I Точн. = Н
			БПО-457
			$F \text{ см}^2 = 13.2$ $Q \text{ кг.} = 3.58$ $D \text{ оп.мм} = 3.6$ $P \text{ н.мм} = 170.0$ Гр. сл. = I Точн. = Н
	БПО-453		БПО-458
	$F \text{ см}^2 = 12.04$ $Q \text{ кг.} = 3.262$ $D \text{ оп.мм} = 99$ $P \text{ н.мм} = 293.8$ Гр. сл. = VI Точн. = Н		$F \text{ см}^2 = 36.390$ $Q \text{ кг.} = 9.862$ $D \text{ оп.мм} = 99.0$ $P \text{ н.мм} = 260.0$ Гр. сл. = I Точн. = Н
	БПО-454		БПО-459
	$F \text{ см}^2 = 0.690$ $Q \text{ кг.} = 0.187$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 89.0$ Гр. сл. = III Точн. = Н		$F \text{ см}^2 = 6.275$ $Q \text{ кг.} = 1.7$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 144.0$ Гр. сл. = II Точн. = Н
	БПО-455		БПО-460
	$F \text{ см}^2 = 0.892$ $Q \text{ кг.} = 0.242$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 70.0$ Гр. сл. = II Точн. = Н		$F \text{ см}^2 = 4.160$ $Q \text{ кг.} = 1.127$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 206.0$ Гр. сл. = V Точн. = Н











	<p>БПО-461</p> <p> $F \text{ см}^2 = 2.088$ $Q \text{ кг.} = 0.566$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 138.0$ Гр. сл. = VI Точн. = Н </p>		
	<p>БПО-462</p> <p> $F \text{ см}^2 = 0.857$ $Q \text{ кг.} = 0.232$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 85.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-0467</p> <p> $F \text{ см}^2 = 1.133$ $Q \text{ кг.} = 0.307$ $D \text{ оп.мм} = 60.2$ $P \text{ н.мм} = 208.7$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-0463</p> <p> $F \text{ см}^2 = 0.470$ $Q \text{ кг.} = 0.127$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 92.2$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-468</p> <p> $F \text{ см}^2 = 1.515$ $Q \text{ кг.} = 0.41$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 125.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-0464</p> <p> $F \text{ см}^2 = 1.037$ $Q \text{ кг.} = 0.281$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 161.6$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-469</p> <p> $F \text{ см}^2 = 1.3$ $Q \text{ кг.} = 0.352$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 202.34$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-0465</p> <p> $F \text{ см}^2 = 2.335$ $Q \text{ кг.} = 0.633$ $D \text{ оп.мм} = 69.0$ $P \text{ н.мм} = 298.6$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-470</p> <p> $F \text{ см}^2 = 1.025$ $Q \text{ кг.} = 0.278$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 104.4$ Гр. сл. = II Точн. = Н </p>







	<p>БПО-471</p> <p> $F \text{ см}^2 = 3.410$ $Q \text{ кг.} = 0.924$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 293.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-476</p> <p> $F \text{ см}^2 = 5.130$ $Q \text{ кг.} = 1.390$ $D \text{ оп.мм} = 129.0$ $P \text{ н.мм} = 356.0$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-472</p> <p> $F \text{ см}^2 = 2.173$ $Q \text{ кг.} = 0.59$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 115.8$ Гр. сл. = III Точн. = Н </p>		<p>БПО-477</p> <p> $F \text{ см}^2 = 0.798$ $Q \text{ кг.} = 0.216$ $D \text{ оп.мм} = 19.0$ $P \text{ н.мм} = 74.0$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-473</p> <p> $F \text{ см}^2 = 2.950$ $Q \text{ кг.} = 0.8$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 367.2$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-478</p> <p> $F \text{ см}^2 = 5.940$ $Q \text{ кг.} = 1.610$ $D \text{ оп.мм} = 132.0$ $P \text{ н.мм} = 330.8$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-474</p> <p> $F \text{ см}^2 = 2.650$ $Q \text{ кг.} = 0.718$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 172.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-0479</p> <p> $F \text{ см}^2 = 0.702$ $Q \text{ кг.} = 0.190$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 98.9$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-0475</p> <p> $F \text{ см}^2 = 3.98$ $Q \text{ кг.} = 1.079$ $D \text{ оп.мм} = 100$ $P \text{ н.мм} = 475.9$ Гр. сл. = VI Точн. = П </p>		<p>БПО-480</p> <p> $F \text{ см}^2 = 1.620$ $Q \text{ кг.} = 0.439$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 130.0$ Гр. сл. = IV Точн. = Н </p>

	<p>БПО-481</p> <p> $F \text{ см}^2 = 2.040$ $Q \text{ кг.} = 0.553$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 144.0$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-486</p> <p> $F \text{ см}^2 = 1.515$ $Q \text{ кг.} = 0.411$ $D \text{ оп.мм} = 31.3$ $P \text{ н.мм} = 94.4$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-482</p> <p> $F \text{ см}^2 = 3.140$ $Q \text{ кг.} = 0.851$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 62.8$ Гр. сл. = II Точн. = П </p>		<p>БПО-487</p> <p> $F \text{ см}^2 = 0.707$ $Q \text{ кг.} = 0.192$ $D \text{ оп.мм} = 15.5$ $P \text{ н.мм} = 44.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-483</p> <p> $F \text{ см}^2 = 0.457$ $Q \text{ кг.} = 0.124$ $D \text{ оп.мм} = 12.5$ $P \text{ н.мм} = 36.4$ Гр. сл. = I Точн. = Н </p>		<p>БПО-488</p> <p> $F \text{ см}^2 = 2.400$ $Q \text{ кг.} = 0.650$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 146.0$ Гр. сл. = 0особ. Точн. = Н </p>
	<p>БПО-484</p> <p> $F \text{ см}^2 = 1.630$ $Q \text{ кг.} = 0.442$ $D \text{ оп.мм} = 31.3$ $P \text{ н.мм} = 92.4$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-489</p> <p> $F \text{ см}^2 = 3.475$ $Q \text{ кг.} = 0.942$ $D \text{ оп.мм} = 62$ $P \text{ н.мм} = 221$ Гр. сл. = III Точн. = Т </p>
	<p>БПО-485</p> <p> $F \text{ см}^2 = 1.351$ $Q \text{ кг.} = 0.366$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 78.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-490</p> <p> $F \text{ см}^2 = 0.814$ $Q \text{ кг.} = 0.22$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 82.0$ Гр. сл. = IV Точн. = Н </p>











	<p>БПО-491</p> <p> $F \text{ см}^2 = 3.330$ $Q \text{ кг.} = 0.903$ $D \text{ оп.мм} = 54.2$ $P \text{ н.мм} = 164.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-496</p> <p> $F \text{ см}^2 = 1.044$ $Q \text{ кг.} = 0.283$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 96.2$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-492</p> <p> $F \text{ см}^2 = 2.246$ $Q \text{ кг.} = 0.609$ $D \text{ оп.мм} = 47.5$ $P \text{ н.мм} = 133.2$ Гр. сл. = III Точн. = Н </p>		<p>БПО-497</p> <p> $F \text{ см}^2 = 0.675$ $Q \text{ кг.} = 0.183$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 71.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-493</p> <p> $F \text{ см}^2 = 0.536$ $Q \text{ кг.} = 0.145$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 46.1$ Гр. сл. = II Точн. = Н </p>		<p>БПО-498</p> <p> $F \text{ см}^2 = 4.125$ $Q \text{ кг.} = 1.12$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 178.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-494</p> <p> $F \text{ см}^2 = 0.765$ $Q \text{ кг.} = 0.21$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 73.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-499</p> <p> $F \text{ см}^2 = 0.723$ $Q \text{ кг.} = 0.196$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 71.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-495</p> <p> $F \text{ см}^2 = 1.325$ $Q \text{ кг.} = 0.36$ $D \text{ оп.мм} = 35.5$ $P \text{ н.мм} = 96.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-500</p> <p> $F \text{ см}^2 = 3.560$ $Q \text{ кг.} = 0.965$ $D \text{ оп.мм} = 65.8$ $P \text{ н.мм} = 208.6$ Гр. сл. = III Точн. = Н </p>










	<p>БПО-501</p> <p> $F \text{ см}^2 = 1.58$ $Q \text{ кг.} = 0.428$ $D \text{ оп.мм} = 41$ $P \text{ н.мм} = 133.6$ Гр.сл. = IV Точн. = Н </p>		<p>БПО-506</p> <p> $F \text{ см}^2 = 1.463$ $Q \text{ кг.} = 0.396$ $D \text{ оп.мм} = 35$ $P \text{ н.мм} = 105.9$ Гр.сл. = II Точн. = Н </p>
	<p>БПО-502</p> <p> $F \text{ см}^2 = 3.126$ $Q \text{ кг.} = 0.847$ $D \text{ оп.мм} = 45$ $P \text{ н.мм} = 252$ Гр.сл. = VI Точн. = Н </p>		<p>БПО-507</p> <p> $F \text{ см} = 0.57$ $Q \text{ кг.} = 0.155$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 58.5$ Гр.сл. = III Точн. = Н </p>
	<p>БПО-503</p> <p> $F \text{ см}^2 = 1.01$ $Q \text{ кг.} = 0.273$ $D \text{ оп.мм} = 29.5$ $P \text{ н.мм} = 98.6$ Гр.сл. = III Точн. = Н </p>		<p>БПО-508</p> <p> $F \text{ см}^2 = 1.730$ $Q \text{ кг.} = 0.468$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 140.0$ Гр.сл. = особ Точн. = Н </p>
	<p>БПО-504</p> <p> $F \text{ см}^2 = 0.65$ $Q \text{ кг.} = 0.177$ $D \text{ оп.мм} = 21$ $P \text{ н.мм} = 69.3$ Гр.сл. = III Точн. = Н </p>		<p>БПО-509</p> <p> $F \text{ см}^2 = 3.550$ $Q \text{ кг.} = 0.963$ $D \text{ оп.мм} = 29.6$ $P \text{ н.мм} = 80.0$ Гр.сл. = II Точн. = Н </p>
	<p>БПО-505</p> <p> $F \text{ см}^2 = 0.831$ $Q \text{ кг.} = 0.225$ $D \text{ оп.мм} = 23$ $P \text{ н.мм} = 79.7$ Гр.сл. = III Точн. = Н </p>		<p>БПО-510</p> <p> $F \text{ см} = 2.410$ $Q \text{ кг.} = 0.65$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 169.2$ Гр.сл. = VI Точн. = Н </p>









	<p>БПО-511</p> <p> $F \text{ см}^2 = 0.573$ $Q \text{ кг.} = 0.155$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 99.3$ Гр.сл. = особ Точн. = П </p>		<p>БПО-516</p> <p> $F \text{ см}^2 = 9.282$ $Q \text{ кг.} = 2.515$ $D \text{ оп.мм} = 141.0$ $P \text{ н.мм} = 395.7$ Гр.сл. = IV Точн. = П </p>
	<p>БПО-512</p> <p> $F \text{ см}^2 = 1.550$ $Q \text{ кг.} = 0.420$ $D \text{ оп.мм} = 33.8$ $P \text{ н.мм} = 252.5$ Гр.сл. = VI Точн. = П </p>		<p>БПО-517</p> <p> $F \text{ см} = 2.470$ $Q \text{ кг.} = 0.67$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 113.0$ Гр.сл. = II Точн. = П </p>
	<p>БПО-513</p> <p> $F \text{ см}^2 = 2.330$ $Q \text{ кг.} = 0.633$ $D \text{ оп.мм} = 43.6$ $P \text{ н.мм} = 198.6$ Гр.сл. = III Точн. = П </p>		<p>БПО-518</p> <p> $F \text{ см}^2 = 2.460$ $Q \text{ кг.} = 0.666$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 101.0$ Гр.сл. = III Точн. = П </p>
	<p>БПО-514</p> <p> $F \text{ см}^2 = 4.920$ $Q \text{ кг.} = 1.33$ $D \text{ оп.мм} = 121.0$ $P \text{ н.мм} = 346.5$ Гр.сл. = VI Точн. = П </p>		<p>БПО-519</p> <p> $F \text{ см}^2 = 15.770$ $Q \text{ кг.} = 4.274$ $D \text{ оп.мм} = 123.0$ $P \text{ н.мм} = 588.7$ Гр.сл. = VI Точн. = Н </p>
	<p>БПО-515</p> <p> $F \text{ см}^2 = 1.759$ $Q \text{ кг.} = 0.477$ $D \text{ оп.мм} = 52.7$ $P \text{ н.мм} = 288.0$ Гр.сл. = VI Точн. = П </p>		<p>БПО-520</p> <p> $F \text{ см} = 1.050$ $Q \text{ кг.} = 0.285$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 75.1$ Гр.сл. = II Точн. = Н </p>











	БПО-521 $F \text{ см}^2 = 1.840$ $Q \text{ кг.} = 0.5$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 86.0$ Гр.сл. = II Точн. = Н		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. =
	БПО-522 $F \text{ см}^2 = 2.665$ $Q \text{ кг.} = 0.722$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 202.5$ Гр.сл. = IV Точн. = Н		$F \text{ см} =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. =
	БПО-523 $F \text{ см}^2 = 4.070$ $Q \text{ кг.} = 1.102$ $D \text{ оп.мм} = 104.0$ $P \text{ н.мм} = 336.0$ Гр.сл. = VI Точн. = Н		БПО-528 $F \text{ см}^2 = 3.280$ $Q \text{ кг.} = 0.889$ $D \text{ оп.мм} = 95.0$ $P \text{ н.мм} = 461.4$ Гр.сл. = особ Точн. = П
	БПО-524 $F \text{ см}^2 = 3.097$ $Q \text{ кг.} = 0.839$ $D \text{ оп.мм} = 93.0$ $P \text{ н.мм} = 242.0$ Гр.сл. = VI Точн. = Н		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. =
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр.сл. = Точн. =		БПО-530 $F \text{ см} = 1.608$ $Q \text{ кг.} = 0.436$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 122.4$ Гр.сл. = IV Точн. = Н










	<p>БПО-531</p> <p> $F \text{ см}^2 = 7.826$ $Q \text{ кг.} = 2.121$ $D \text{ оп.мм} = 158.0$ $P \text{ н.мм} = 530$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p>		<p>БПО-536</p> <p> $F \text{ см}^2 = 0.819$ $Q \text{ кг.} = 0.222$ $D \text{ оп.мм} = 19.0$ $P \text{ н.мм} = 82$ $\text{Гр.сл.} = \text{II}$ $\text{Точн.} = \text{Н}$ </p>
	<p>БПО-532</p> <p> $F \text{ см}^2 = 4.55$ $Q \text{ кг.} = 1.233$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 309.7$ $\text{Гр.сл.} = \text{III}$ $\text{Точн.} = \text{Н}$ </p>		<p>БПО-537</p> <p> $F \text{ см} = 1.07$ $Q \text{ кг.} = 0.29$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 130.1$ $\text{Гр.сл.} = \text{V}$ $\text{Точн.} = \text{Н}$ </p>
	<p>БПО-533</p> <p> $F \text{ см}^2 = 3.93$ $Q \text{ кг.} = 1.065$ $D \text{ оп.мм} = 56$ $P \text{ н.мм} = 184.6$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p>		<p>БПО-538</p> <p> $F \text{ см}^2 = 3.249$ $Q \text{ кг.} = 0.88$ $D \text{ оп.мм} = 70.2$ $P \text{ н.мм} = 165.5$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p>
	<p>БПО-534</p> <p> $F \text{ см}^2 = 4.45$ $Q \text{ кг.} = 1.206$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 122$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p>		<p>БПО-539</p> <p> $F \text{ см}^2 = 3.33$ $Q \text{ кг.} = 0.902$ $D \text{ оп.мм} = 70.2$ $P \text{ н.мм} = 165.4$ $\text{Гр.сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p>
	<p>БПО-535</p> <p> $F \text{ см}^2 = 1.187$ $Q \text{ кг.} = 0.322$ $D \text{ оп.мм} = 30.8$ $P \text{ н.мм} = 86.5$ $\text{Гр.сл.} = \text{II}$ $\text{Точн.} = \text{Н}$ </p>		<p>БПО-540</p> <p> $F \text{ см} = 0.734$ $Q \text{ кг.} = 0.199$ $D \text{ оп.мм} = 17.0$ $P \text{ н.мм} = 70.0$ $\text{Гр.сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>










	<p>БПО-541</p> <p> $F \text{ см}^2 = 0.703$ $Q \text{ кг.} = 0.191$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 69.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-546</p> <p> $F \text{ см}^2 = 0.729$ $Q \text{ кг.} = 0.198$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 99.2$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-542</p> <p> $F \text{ см}^2 = 9.490$ $Q \text{ кг.} = 2.571$ $D \text{ оп.мм} = 115.0$ $P \text{ н.мм} = 385.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-547</p> <p> $F \text{ см}^2 = 6.91$ $Q \text{ кг.} = 1.873$ $D \text{ оп.мм} = 92.0$ $P \text{ н.мм} = 314.9$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-543</p> <p> $F \text{ см}^2 = 10.44$ $Q \text{ кг.} = 2.83$ $D \text{ оп.мм} = 150.0$ $P \text{ н.мм} = 584$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-548</p> <p> $F \text{ см}^2 = 0.655$ $Q \text{ кг.} = 0.178$ $D \text{ оп.мм} = 32.8$ $P \text{ н.мм} = 92.3$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-544</p> <p> $F \text{ см}^2 = 1.11$ $Q \text{ кг.} = 0.301$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 151.34$ Гр. сл. = VI Точн. = П </p>		<p>БПО-549</p> <p> $F \text{ см}^2 = 3.33$ $Q \text{ кг.} = 0.902$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 165$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-545</p> <p> $F \text{ см}^2 = 7.84$ $Q \text{ кг.} = 2.125$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 350.5$ Гр. сл. = VI Точн. = П </p>		<p>БПО-550</p> <p> $F \text{ см}^2 = 4.73$ $Q \text{ кг.} = 1.282$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 210.9$ Гр. сл. = III Точн. = П </p>











	<p>БПО-551</p> <p> $F \text{ см}^2 = 2.1$ $Q \text{ кг.} = 0.5$ $D \text{ оп.мм} = 35.5$ $P \text{ н.мм} = 82$ Гр. сл. = I Точн. = Н </p>		<p>БПО-556</p> <p> $F \text{ см}^2 = 0.914$ $Q \text{ кг.} = 0.248$ $D \text{ оп.мм} = 23.5$ $P \text{ н.мм} = 81.42$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-552</p> <p> $F \text{ см}^2 = 2.94$ $Q \text{ кг.} = 0.797$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 298.9$ Гр. сл. = VI Точн. = П </p>		<p>БПО-557</p> <p> $F \text{ см}^2 = 6.420$ $Q \text{ кг.} = 1.741$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 273.0$ Гр. сл. = III Точн. = П </p>
	<p>БПО-553</p> <p> $F \text{ см}^2 = 1.19$ $Q \text{ кг.} = 0.322$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 136.9$ Гр. сл. = V Точн. = П </p>		<p>БПО-558</p> <p> $F \text{ см}^2 = 2.330$ $Q \text{ кг.} = 0.63$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 126.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-554</p> <p> $F \text{ см}^2 = 1.66$ $Q \text{ кг.} = 0.45$ $D \text{ оп.мм} = 53.9$ $P \text{ н.мм} = 235.86$ Гр. сл. = VI Точн. = П </p>		
	<p>БПО-555</p> <p> $F \text{ см}^2 = 2.69$ $Q \text{ кг.} = 0.729$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 197.7$ Гр. сл. = V Точн. = Н </p>		<p>БПО-560</p> <p> $F \text{ см}^2 = 32.110$ $Q \text{ кг.} = 8.70$ $D \text{ оп.мм} = 188.0$ $P \text{ н.мм} = 790.0$ Гр. сл. = VI Точн. = Н </p>











	<p>БПО-0561</p> <p> $F \text{ см}^2 = 1.285$ $Q \text{ кг.} = 0.348$ $D \text{ оп.мм} = 45.4$ $P \text{ н.мм} = 194.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-566</p> <p> $F \text{ см}^2 = 1.715$ $Q \text{ кг.} = 0.465$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 124.4$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-562</p> <p> $F \text{ см}^2 = 0.738$ $Q \text{ кг.} = 0.2$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 77.7$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-567</p> <p> $F \text{ см}^2 = 3.140$ $Q \text{ кг.} = 0.851$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 173.9$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-563</p> <p> $F \text{ см}^2 = 1.19$ $Q \text{ кг.} = 0.322$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 121$ Гр. сл. = IV Точн. = П </p>		<p>БПО-568</p> <p> $F \text{ см}^2 = 0.656$ $Q \text{ кг.} = 0.178$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 33.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-0564</p> <p> $F \text{ см}^2 = 1.170$ $Q \text{ кг.} = 0.317$ $D \text{ оп.мм} = 41.3$ $P \text{ н.мм} = 178.4$ Гр. сл. = IV Точн. = П </p>		
	<p>БПО-565</p> <p> $F \text{ см}^2 = 1.780$ $Q \text{ кг.} = 0.482$ $D \text{ оп.мм} = 37.5$ $P \text{ н.мм} = 129.4$ Гр. сл. = IV Точн. = Н </p>		









	<p>БПО-571</p> <p> $F \text{ см}^2 = 2.394$ $Q \text{ кг.} = 0.65$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 124.0$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-576</p> <p> $F \text{ см}^2 = 1.345$ $Q \text{ кг.} = 0.364$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 97.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-572</p> <p> $F \text{ см}^2 = 2.394$ $Q \text{ кг.} = 0.65$ $D \text{ оп.мм} = 46.1$ $P \text{ н.мм} = 156.2$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-577</p> <p> $F \text{ см}^2 = 1.590$ $Q \text{ кг.} = 0.432$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 121.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-573</p> <p> $F \text{ см}^2 = 0.899$ $Q \text{ кг.} = 0.244$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 124.5$ Гр. сл. = VI Точн. = П </p>		<p>БПО-578</p> <p> $F \text{ см}^2 = 1.415$ $Q \text{ кг.} = 0.383$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 132.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-574</p> <p> $F \text{ см}^2 = 0.506$ $Q \text{ кг.} = 0.137$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 75.6$ Гр. сл. = VI Точн. = П </p>		<p>БПО-579</p> <p> $F \text{ см}^2 = 6.380$ $Q \text{ кг.} = 1.73$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 308.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-575</p> <p> $F \text{ см}^2 = 1.880$ $Q \text{ кг.} = 0.509$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 143.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-580</p> <p> $F \text{ см}^2 = 1.170$ $Q \text{ кг.} = 0.317$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 73.2$ Гр. сл. = II Точн. = Н </p>









	<p>БПО-581</p> <p> $F \text{ см}^2 = 1.660$ $Q \text{ кг.} = 0.450$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 158.3$ Гр. сл. = III Точн. = Н </p>		
	<p>БПО-582</p> <p> $F \text{ см}^2 = 0.615$ $Q \text{ кг.} = 0.167$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 78.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-587</p> <p> $F \text{ см}^2 = 2.290$ $Q \text{ кг.} = 0.62$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 102.0$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-0583</p> <p> $F \text{ см}^2 = 1.873$ $Q \text{ кг.} = 0.508$ $D \text{ оп.мм} = 71.1$ $P \text{ н.мм} = 246.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-588</p> <p> $F \text{ см}^2 = 0.522$ $Q \text{ кг.} = 0.141$ $D \text{ оп.мм} = 15.0$ $P \text{ н.мм} = 67.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-0584</p> <p> $F \text{ см}^2 = 1.220$ $Q \text{ кг.} = 0.331$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 140.8$ Гр. сл. = V Точн. = П </p>		<p>БПО-589</p> <p> $F \text{ см}^2 = 2.02$ $Q \text{ кг.} = 0.547$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 110.6$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-585</p> <p> $F \text{ см}^2 = 1.930$ $Q \text{ кг.} = 0.524$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 198.5$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-590</p> <p> $F \text{ см}^2 = 3.190$ $Q \text{ кг.} = 0.863$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 74.0$ Гр. сл. = I Точн. = Н </p>











	БПО-591 $F \text{ см}^2 = 0.746$ $Q \text{ кг.} = 0.202$ $D \text{ оп.мм} = 19.5$ $P \text{ н.мм} = 44.0$ Гр. сл. = I Точн. = Н		БПО-0596 $F \text{ см}^2 = 1.220$ $Q \text{ кг.} = 0.331$ $D \text{ оп.мм} = 65.1$ $P \text{ н.мм} = 205.2$ Гр. сл. = VI Точн. = П
			БПО-0597 $F \text{ см}^2 = 0.854$ $Q \text{ кг.} = 0.231$ $D \text{ оп.мм} = 39.2$ $P \text{ н.мм} = 144.8$ Гр. сл. = IV Точн. = Н
	БПО-593 $F \text{ см}^2 = 2.26$ $Q \text{ кг.} = 0.612$ $D \text{ оп.мм} = 90.1$ $P \text{ н.мм} = 247.8$ Гр. сл. = V Точн. = Н		БПО-598 $F \text{ см}^2 = 5.39$ $Q \text{ кг.} = 1.461$ $D \text{ оп.мм} = 86$ $P \text{ н.мм} = 381$ Гр. сл. = IV Точн. = П
	БПО-594 $F \text{ см}^2 = 0.625$ $Q \text{ кг.} = 0.169$ $D \text{ оп.мм} = 25.2$ $P \text{ н.мм} = 58.6$ Гр. сл. = IV Точн. = Н		БПО-599 $F \text{ см}^2 = 6.039$ $Q \text{ кг.} = 1.637$ $D \text{ оп.мм} = 78.0$ $P \text{ н.мм} = 315.1$ Гр. сл. = IV Точн. = П
	БПО-0595 $F \text{ см}^2 = 0.724$ $Q \text{ кг.} = 0.196$ $D \text{ оп.мм} = 52.9$ $P \text{ н.мм} = 120.3$ Гр. сл. = IV Точн. = П		БПО-600 $F \text{ см}^2 = 2.839$ $Q \text{ кг.} = 0.769$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 235.9$ Гр. сл. = IV Точн. = П




	<p>БПО-0601</p> <p>$F_{cm}^2 = 1.434$ $Q_{кз.} = 0.389$ $Доп. = 30.2$ $P_H = 128.9$ $\Gamma_{р.сл.} = V$ $Точн. = H$</p>		<p>БПО-0606</p> <p>$F_{cm}^2 = 11.7$ $Q_{кз.} = 3.17$ $Доп. = 152.7$ $P_H = 528$ $\Gamma_{р.сл.} = IV$ $Точн. = H$</p>
	<p>БПО-0602</p> <p>$F_{cm}^2 = 0.938$ $Q_{кз.} = 0.254$ $Доп. = 28.0$ $P_H = 147.0$ $\Gamma_{р.сл.} = IV$ $Точн. = H$</p>		<p>БПО-0607</p> <p>$F_{cm}^2 = 0.869$ $Q_{кз.} = 0.235$ $Доп. = 25.0$ $P_H = 109.0$ $\Gamma_{р.сл.} = IV$ $Точн. = H$</p>
	<p>БПО-0603</p> <p>$F_{cm}^2 = 1.094$ $Q_{кз.} = 0.296$ $Доп. = 56.2$ $P_H = 184.8$ $\Gamma_{р.сл.} = V$ $Точн. = H$</p>		<p>БПО-0608</p> <p>$F_{cm}^2 = 1.640$ $Q_{кз.} = 0.443$ $Доп. = 43.0$ $P_H = 212.0$ $\Gamma_{р.сл.} = Ocoд.$ $Точн. = H$</p>
	<p>БПО-0604</p> <p>$F_{cm}^2 =$ $Q_{кз.} =$ $Доп. =$ $P_H =$ $\Gamma_{р.сл.} =$ $Точн. =$</p>		<p>БПО-0609</p> <p>$F_{cm}^2 = 3.580$ $Q_{кз.} = 0.970$ $Доп. = 64.0$ $P_H = 256.0$ $\Gamma_{р.сл.} = V$ $Точн. = H$</p>
	<p>БПО-0605</p> <p>$F_{cm}^2 =$ $Q_{кз.} =$ $Доп. =$ $P_H =$ $\Gamma_{р.сл.} =$ $Точн. =$</p>		<p>БПО-0610</p> <p>$F_{cm}^2 = 1.207$ $Q_{кз.} = 0.327$ $Доп. = 30.0$ $P_H = 98.3$ $\Gamma_{р.сл.} = II$ $Точн. = H$</p>








	<p>БПО-611</p> <p> $F \text{ см}^2 = 1.6$ $Q \text{ кг.} = 0.434$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 164$ $\text{Гр. сл.} = \text{II}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-616</p> <p> $F \text{ см}^2 = 3.16$ $Q \text{ кг.} = 0.86$ $D \text{ оп.мм} = 75.5$ $P \text{ н.мм} = 280$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-612</p> <p> $F \text{ см}^2 = 0.820$ $Q \text{ кг.} = 0.222$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 81.0$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-617</p> <p> $F \text{ см}^2 = 5.667$ $Q \text{ кг.} = 1.536$ $D \text{ оп.мм} = 126.0$ $P \text{ н.мм} = 441.5$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$ </p>
	<p>БПО-613</p> <p> $F \text{ см}^2 = 2.546$ $Q \text{ кг.} = 0.69$ $D \text{ оп.мм} = 117.0$ $P \text{ н.мм} = 265.3$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-618</p> <p> $F \text{ см}^2 = 18.200$ $Q \text{ кг.} = 4.93$ $D \text{ оп.мм} = 94.0$ $P \text{ н.мм} = 281.0$ $\text{Гр. сл.} = \text{II}$ $\text{Точн.} = \text{H}$ </p>
	<p>БПО-614</p> <p> $F \text{ см}^2 = 1.081$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 146.9$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-619</p> <p> $F \text{ см}^2 = 11.200$ $Q \text{ кг.} = 3.04$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 193.0$ $\text{Гр. сл.} = \text{II}$ $\text{Точн.} = \text{T}$ </p>
	<p>БПО-615</p> <p> $F \text{ см}^2 = 0.876$ $Q \text{ кг.} = 0.237$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 111.4$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-0620</p> <p> $F \text{ см}^2 = 0.557$ $Q \text{ кг.} = 0.151$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 95.2$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$ </p>










	БПО-0621 $F \text{ см}^2 = 0.520$ $Q \text{ кг.} = 0.141$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 87.8$ Гр. сл. = IV Точн. = Н		БПО-626 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. =
	БПО-0622 $F \text{ см}^2 = 0.366$ $Q \text{ кг.} = 0.099$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 52.7$ Гр. сл. = IV Точн. = Н		БПО-627 $F \text{ см}^2 = 2.940$ $Q \text{ кг.} = 0.798$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 124.7$ Гр. сл. = II Точн. = Н
	БПО-0623 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. =		БПО-628 $F \text{ см}^2 = 11.610$ $Q \text{ кг.} = 3.145$ $D \text{ оп.мм} = 132.0$ $P \text{ н.мм} = 278.0$ Гр. сл. = III Точн. = Н
	БПО-624 $F \text{ см}^2 = 3.2$ $Q \text{ кг.} = 0.866$ $D \text{ оп.мм} = 92.6$ $P \text{ н.мм} = 257.8$ Гр. сл. = VI Точн. = Н		БПО-629 $F \text{ см}^2 = 3.830$ $Q \text{ кг.} = 1.037$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 248.0$ Гр. сл. = VI Точн. = Н
	БПО-625 $F \text{ см}^2 = 1.486$ $Q \text{ кг.} = 0.403$ $D \text{ оп.мм} = 26.5$ $P \text{ н.мм} = 212.5$ Гр. сл. = 0соб. Точн. = Н		БПО-630 $F \text{ см}^2 = 4.587$ $Q \text{ кг.} = 1.243$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 296.0$ Гр. сл. = VI Точн. = Н









	БПО-631 $F \text{ см}^2 = 4.587$ $Q \text{ кг.} = 1.124$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 296.0$ Гр. сл. = VI Точн. = Н		БПО-636 $F \text{ см}^2 = 3.310$ $Q \text{ кг.} = 0.897$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 166.0$ Гр. сл. = II Точн. = Н
	БПО-632 $F \text{ см}^2 = 3.340$ $Q \text{ кг.} = 0.897$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 198.0$ Гр. сл. = IV Точн. = Н		
	БПО-0633 $F \text{ см}^2 = 0.498$ $Q \text{ кг.} = 0.135$ $D \text{ оп.мм} = 19.4$ $P \text{ н.мм} = 72.0$ Гр. сл. = V Точн. = П		
	БПО-0634 $F \text{ см}^2 = 1.022$ $Q \text{ кг.} = 0.277$ $D \text{ оп.мм} = 40.1$ $P \text{ н.мм} = 136.9$ Гр. сл. = VI Точн. = П		БПО-639 $F \text{ см}^2 = 18.15$ $Q \text{ кг.} = 4.919$ $D \text{ оп.мм} = 128.0$ $P \text{ н.мм} = 446.5$ Гр. сл. = IV Точн. = П
	БПО-635 $F \text{ см}^2 = 6.580$ $Q \text{ кг.} = 1.783$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 164.0$ Гр. сл. = III Точн. = Н		БПО-640 $F \text{ см}^2 = 3.292$ $Q \text{ кг.} = 0.892$ $D \text{ оп.мм} = 88.0$ $P \text{ н.мм} = 331.7$ Гр. сл. = VI Точн. = Н











	БПО-641 $F \text{ см}^2 = 8.080$ $Q \text{ кг.} = 2.190$ $D \text{ оп.мм} = 162.0$ $P \text{ н.мм} = 676.0$ Гр. сл. = 0соб. Точн. = Н		БПО-646 $F \text{ см}^2 = 25.430$ $Q \text{ кг.} = 6.89$ $D \text{ оп.мм} = 180.0$ $P \text{ н.мм} = 1630.0$ Гр. сл. = 0соб. Точн. = Н
	БПО-642 $F \text{ см}^2 = 7.420$ $Q \text{ кг.} = 2.01$ $D \text{ оп.мм} = 68.0$ $P \text{ н.мм} = 260.0$ Гр. сл. = IV Точн. = Н		БПО-647 $F \text{ см}^2 = 8.380$ $Q \text{ кг.} = 2.27$ $D \text{ оп.мм} = 76.0$ $P \text{ н.мм} = 312.0$ Гр. сл. = V Точн. = Н
	БПО-643 $F \text{ см}^2 = 4.991$ $Q \text{ кг.} = 1.353$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 308.6$ Гр. сл. = I Точн. = Н		БПО-0648 $F \text{ см}^2 = 4.214$ $Q \text{ кг.} = 1.142$ $D \text{ оп.мм} = 94.0$ $P \text{ н.мм} = 489.0$ Гр. сл. = V Точн. = П
	БПО-644 $F \text{ см}^2 = 8.240$ $Q \text{ кг.} = 2.23$ $D \text{ оп.мм} = 174.0$ $P \text{ н.мм} = 541.0$ Гр. сл. = 0соб. Точн. = Н		БПО-649 $F \text{ см}^2 = 0.934$ $Q \text{ кг.} = 0.253$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 126.14$ Гр. сл. = IV Точн. = П
	БПО-645 $F \text{ см}^2 = 10.760$ $Q \text{ кг.} = 2.92$ $D \text{ оп.мм} = 122.0$ $P \text{ н.мм} = 357.5$ Гр. сл. = IV Точн. = Н		БПО-650 $F \text{ см}^2 = 9.568$ $Q \text{ кг.} = 2.593$ $D \text{ оп.мм} = 106.3$ $P \text{ н.мм} = 337.13$ Гр. сл. = V Точн. = Н











	<p>БПО-651</p> <p> $F \text{ см}^2 = 19.28$ $Q \text{ кг.} = 5.225$ $D \text{ оп.мм} = 130.8$ $P \text{ н.мм} = 449.1$ Гр. сл. = V Точн. = Н </p>		<p>БПО-656</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-652</p> <p> $F \text{ см}^2 = 1.25$ $Q \text{ кг.} = 0.339$ $D \text{ оп.мм} = 40.5$ $P \text{ н.мм} = 119$ Гр. сл. = V Точн. = П </p>		<p>БПО-657</p> <p> $F \text{ см}^2 = 0.58$ $Q \text{ кг.} = 0.157$ $D \text{ оп.мм} = 14.0$ $P \text{ н.мм} = 38$ Гр. сл. = III Точн. = П </p>
	<p>БПО-653</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-658</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-654</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-659</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-655</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-660</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>











	БПО-661 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$		БПО-666 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$
	БПО-662 $F \text{ см}^2 = 1.561$ $Q \text{ кг.} = 0.423$ $D \text{ оп.мм} = 115.0$ $P \text{ н.мм} = 171$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$		БПО-667 $F \text{ см}^2 = 6.770$ $Q \text{ кг.} = 1.835$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 361.0$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$
	БПО-663 $F \text{ см}^2 = 1.749$ $Q \text{ кг.} = 0.474$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 207.7$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		БПО-668 $F \text{ см}^2 = 4.95$ $Q \text{ кг.} = 1.3$ $D \text{ оп.мм} = 71.0$ $P \text{ н.мм} = 258.6$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
	БПО-664 $F \text{ см}^2 = 0.629$ $Q \text{ кг.} = 0.171$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 77.4$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		БПО-669 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$
	БПО-665 $F \text{ см}^2 = 1.92$ $Q \text{ кг.} = 0.52$ $D \text{ оп.мм} = 68.0$ $P \text{ н.мм} = 207$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$		БПО-670 $F \text{ см}^2 = 5.2$ $Q \text{ кг.} = 1.41$ $D \text{ оп.мм} = 106.0$ $P \text{ н.мм} = 438$ $\text{Гр. сл.} = \text{Особ.}$ $\text{Точн.} = \text{H}$








	<p>БПО-671</p> <p> $F \text{ см}^2 = 3.58$ $Q \text{ кг.} = 0.97$ $D \text{ оп.мм} = 106.5$ $P \text{ н.мм} = 316.0$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-676</p> <p> $F \text{ см}^2 = 0.713$ $Q \text{ кг.} = 0.193$ $D \text{ оп.мм} = 18.5$ $P \text{ н.мм} = 87.5$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-672</p> <p> $F \text{ см}^2 = 1.300$ $Q \text{ кг.} = 0.35$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 151.6$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-677</p> <p> $F \text{ см}^2 = 1.428$ $Q \text{ кг.} = 0.378$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 125.0$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-673</p> <p> $F \text{ см}^2 = 3.770$ $Q \text{ кг.} = 1.02$ $D \text{ оп.мм} = 65.2$ $P \text{ н.мм} = 244.5$ Гр. сл. = V Точн. = Н </p>		<p>БПО-678</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-674</p> <p> $F \text{ см}^2 = 5.040$ $Q \text{ кг.} = 1.36$ $D \text{ оп.мм} = 145.0$ $P \text{ н.мм} = 479.6$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-679</p> <p> $F \text{ см}^2 = 1.500$ $Q \text{ кг.} = 0.41$ $D \text{ оп.мм} = 31.5$ $P \text{ н.мм} = 70.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-675</p> <p> $F \text{ см}^2 = 1.630$ $Q \text{ кг.} = 0.442$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 162.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-0680</p> <p> $F \text{ см}^2 = 1.620$ $Q \text{ кг.} = 0.439$ $D \text{ оп.мм} = 26.4$ $P \text{ н.мм} = 93.9$ Гр. сл. = IV Точн. = П </p>











	<p>БПО-0681</p> <p> $F \text{ см}^2 = 6.998$ $Q \text{ кг.} = 1.896$ $D \text{ оп.мм} = 115.0$ $P \text{ н.мм} = 485.3$ Гр. сл. = 0соб. Точн. = П </p>		
	<p>БПО-0682</p> <p> $F \text{ см}^2 = 2.922$ $Q \text{ кг.} = 0.792$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 332.8$ Гр. сл. = VI Точн. = П </p>		
	<p>БПО-683</p> <p> $F \text{ см}^2 = 2.940$ $Q \text{ кг.} = 0.8$ $D \text{ оп.мм} = 52.5$ $P \text{ н.мм} = 190.9$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-688</p> <p> $F \text{ см}^2 = 1.812$ $Q \text{ кг.} = 0.491$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 115.9$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-684</p> <p> $F \text{ см}^2 = 11.31$ $Q \text{ кг.} = 3.065$ $D \text{ оп.мм} = 152.7$ $P \text{ н.мм} = 527.1$ Гр. сл. = III Точн. = Н </p>		<p>БПО-0689</p> <p> $F \text{ см}^2 = 1.473$ $Q \text{ кг.} = 0.399$ $D \text{ оп.мм} = 53.9$ $P \text{ н.мм} = 191.3$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-685-01</p> <p> $F \text{ см}^2 = 2.350$ $Q \text{ кг.} = 0.637$ $D \text{ оп.мм} = 43.2$ $P \text{ н.мм} = 208.0$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-690</p> <p> $F \text{ см}^2 = 1.412$ $Q \text{ кг.} = 0.383$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 113.4$ Гр. сл. = V Точн. = Н </p>










	БПО-691 $F \text{ см}^2 = 0.460$ $Q \text{ кг.} = 0.125$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 70.28$ Гр. сл. = IV Точн. = Н		БПО-696 $F \text{ см}^2 = 4.630$ $Q \text{ кг.} = 1.25$ $D \text{ оп.мм} = 134.0$ $P \text{ н.мм} = 414.56$ Гр. сл. = VI Точн. = П
	БПО-692 $F \text{ см}^2 = 1.330$ $Q \text{ кг.} = 0.360$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 164.0$ Гр. сл. = 0соб. Точн. = Н		БПО-697 $F \text{ см}^2 = 8.130$ $Q \text{ кг.} = 2.2$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 187.2$ Гр. сл. = V Точн. = Н
	БПО-693 $F \text{ см}^2 = 1.090$ $Q \text{ кг.} = 0.3$ $D \text{ оп.мм} = 18.5$ $P \text{ н.мм} = 143.5$ Гр. сл. = V Точн. = Н		БПО-698 $F \text{ см}^2 = 2.550$ $Q \text{ кг.} = 0.69$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 166.0$ Гр. сл. = IV Точн. = Н
	БПО-0694 $F \text{ см}^2 = 3.276$ $Q \text{ кг.} = 0.888$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 378.3$ Гр. сл. = 0соб. Точн. = П		БПО-699 $F \text{ см}^2 = 1.300$ $Q \text{ кг.} = 0.352$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 126.5$ Гр. сл. = II Точн. = Н
	БПО-695 $F \text{ см}^2 = 6.62$ $Q \text{ кг.} = 1.88$ $D \text{ оп.мм} = 118$ $P \text{ н.мм} = 703$ Гр. сл. = IV Точн. = П		БПО-700 $F \text{ см}^2 = 1.050$ $Q \text{ кг.} = 0.285$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 108.0$ Гр. сл. = V Точн. = Н










	<p>БПО-701</p> <p> $F \text{ см}^2 = 2.710$ $Q \text{ кг.} = 0.734$ $D \text{ оп.мм} = 50.5$ $P \text{ н.мм} = 183.5$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-706</p> <p> $F \text{ см}^2 = 1.970$ $Q \text{ кг.} = 0.534$ $D \text{ оп.мм} = 37.5$ $P \text{ н.мм} = 124.2$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-702</p> <p> $F \text{ см}^2 = 5.660$ $Q \text{ кг.} = 1.534$ $D \text{ оп.мм} = 121.5$ $P \text{ н.мм} = 350.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-707</p> <p> $F \text{ см}^2 = 2.500$ $Q \text{ кг.} = 0.7$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 227.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-703</p> <p> $F \text{ см}^2 = 1.950$ $Q \text{ кг.} = 0.528$ $D \text{ оп.мм} = 45.5$ $P \text{ н.мм} = 164.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-708</p> <p> $F \text{ см}^2 = 2.280$ $Q \text{ кг.} = 0.62$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 159.5$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-704</p> <p> $F \text{ см}^2 = 1.680$ $Q \text{ кг.} = 0.455$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 143.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-709</p> <p> $F \text{ см}^2 = 0.414$ $Q \text{ кг.} = 0.112$ $D \text{ оп.мм} = 12.0$ $P \text{ н.мм} = 29.2$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-705</p> <p> $F \text{ см}^2 = 2.030$ $Q \text{ кг.} = 0.550$ $D \text{ оп.мм} = 36.7$ $P \text{ н.мм} = 131.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-710</p> <p> $F \text{ см}^2 = 4.170$ $Q \text{ кг.} = 1.130$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 189.5$ Гр. сл. = VI Точн. = Н </p>





	БПО-711 $F \text{ см}^2 = 4.299$ $Q \text{ кг.} = 1.16$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 136.5$ Гр. сл. = V Точн. = Н		БПО-716 $F \text{ см}^2 = 2.110$ $Q \text{ кг.} = 0.572$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 207.5$ Гр. сл. = VI Точн. = П
	БПО-712 $F \text{ см}^2 = 0.820$ $Q \text{ кг.} = 0.222$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 91.9$ Гр. сл. = III Точн. = Н		БПО-0717 $F \text{ см}^2 = 1.656$ $Q \text{ кг.} = 0.449$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 220.7$ Гр. сл. = V Точн. = П
	БПО-713 $F \text{ см}^2 = 4.460$ $Q \text{ кг.} = 1.21$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 246.5$ Гр. сл. = III Точн. = Н		БПО-718 $F \text{ см}^2 = 1.19$ $Q \text{ кг.} = 0.322$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 179$ Гр. сл. = IV Точн. = Н
	БПО-714 $F \text{ см}^2 = 4.080$ $Q \text{ кг.} = 1.110$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 216.0$ Гр. сл. = III Точн. = Н		БПО-719 $F \text{ см}^2 = 1.31$ $Q \text{ кг.} = 0.355$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 195.8$ Гр. сл. = IV Точн. = П
	БПО-715 $F \text{ см}^2 = 2.33$ $Q \text{ кг.} = 0.63$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 139$ Гр. сл. = V Точн. = П		БПО-720 $F \text{ см}^2 = 3.416$ $Q \text{ кг.} = 0.926$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 400$ Гр. сл. = IV Точн. = П









	БПО-721 $F \text{ см}^2 = 2.29$ $Q \text{ кг.} = 0.621$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 306.7$ Гр. сл. = IV Точн. = П		БПО-726 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. =
	БПО-722 $F \text{ см}^2 = 0.455$ $Q \text{ кг.} = 0.123$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 84.53$ Гр. сл. = IV Точн. = П		БПО-0727 $F \text{ см}^2 = 0.964$ $Q \text{ кг.} = 0.261$ $D \text{ оп.мм} = 31.6$ $P \text{ н.мм} = 160.2$ Гр. сл. = VI Точн. = П
	БПО-0723 $F \text{ см}^2 = 2.170$ $Q \text{ кг.} = 0.588$ $D \text{ оп.мм} = 53.9$ $P \text{ н.мм} = 283.5$ Гр. сл. = V Точн. = П		БПО-728 $F \text{ см}^2 = 1.335$ $Q \text{ кг.} = 0.362$ $D \text{ оп.мм} = 69.0$ $P \text{ н.мм} = 158.6$ Гр. сл. = VI Точн. = Н
	БПО-724 $F \text{ см}^2 = 1.260$ $Q \text{ кг.} = 0.34$ $D \text{ оп.мм} = 27.5$ $P \text{ н.мм} = 89.5$ Гр. сл. = IV Точн. = П		БПО-0729 $F \text{ см}^2 = 22.306$ $Q \text{ кг.} = 6.045$ $D \text{ оп.мм} = 180.0$ $P \text{ н.мм} = 597.3$ Гр. сл. = VI Точн. = П
	БПО-725 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. =		БПО-730 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. =








	<p>БПО-731</p> <p> $F \text{ см}^2 = 1.0$ $Q \text{ кг.} = 0.27$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 101$ Гр. сл. = II Точн. = Т </p>		<p>БПО-736</p> <p> $F \text{ см}^2 = 13.920$ $Q \text{ кг.} = 3.77$ $D \text{ оп.мм} = 105.0$ $P \text{ н.мм} = 681.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-732</p> <p> $F \text{ см}^2 = 1.800$ $Q \text{ кг.} = 0.49$ $D \text{ оп.мм} = 74.0$ $P \text{ н.мм} = 185.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-737</p> <p> $F \text{ см}^2 = 17.9$ $Q \text{ кг.} = 4.85$ $D \text{ оп.мм} = 460.0$ $P \text{ н.мм} = 180.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-733</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-738</p> <p> $F \text{ см}^2 = 1.64$ $Q \text{ кг.} = 0.444$ $D \text{ оп.мм} = 76.0$ $P \text{ н.мм} = 212.3$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-734</p> <p> $F \text{ см}^2 = 1.250$ $Q \text{ кг.} = 0.33$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 72$ Гр. сл. = III Точн. = Н </p>		<p>БПО-739</p> <p> $F \text{ см}^2 = 2.39$ $Q \text{ кг.} = 0.648$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 274$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-735</p> <p> $F \text{ см}^2 = 1.957$ $Q \text{ кг.} = 0.53$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 135.4$ Гр. сл. = V Точн. = Н </p>		<p>БПО-740</p> <p> $F \text{ см}^2 = 2.56$ $Q \text{ кг.} = 0.694$ $D \text{ оп.мм} = 119.0$ $P \text{ н.мм} = 257.7$ Гр. сл. = VI Точн. = Н </p>









	БПО-741 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} =$		БПО-746 $F \text{ см}^2 = 1.552$ $Q \text{ кг.} = 0.421$ $D \text{ оп.мм} = 68.0$ $P \text{ н.мм} = 210$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-742 $F \text{ см}^2 = 1.89$ $Q \text{ кг.} = 0.512$ $D \text{ оп.мм} = 6.4$ $P \text{ н.мм} = 252$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$		БПО-747 $F \text{ см}^2 = 1.942$ $Q \text{ кг.} = 0.526$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 156.4$ $\Gamma \text{ р. сл.} = \text{0соб.}$ $\text{Точн.} = \text{П}$
	БПО-743 $F \text{ см}^2 = 2.066$ $Q \text{ кг.} = 0.56$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 204.7$ $\Gamma \text{ р. сл.} = \text{0соб.}$ $\text{Точн.} = \text{П}$		БПО-748 $F \text{ см}^2 = 1.080$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм} = 26.5$ $P \text{ н.мм} = 87.9$ $\Gamma \text{ р. сл.} = \text{II}$ $\text{Точн.} = \text{H}$
	БПО-744 $F \text{ см}^2 = 4.09$ $Q \text{ кг.} = 1.108$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 461$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		БПО-749 $F \text{ см}^2 = 1.76$ $Q \text{ кг.} = 0.477$ $D \text{ оп.мм} = 40.1$ $P \text{ н.мм} = 142.4$ $\Gamma \text{ р. сл.} = \text{II}$ $\text{Точн.} = \text{H}$
	БПО-745 $F \text{ см}^2 = 0.664$ $Q \text{ кг.} = 0.175$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 93.6$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$		БПО-750 $F \text{ см}^2 = 0.555$ $Q \text{ кг.} = 0.150$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 75.3$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$











	<p>БПО-751</p> <p> $F \text{ см}^2 = 0.920$ $Q \text{ кг.} = 0.25$ $D \text{ оп.мм} = 16.6$ $P \text{ н.мм} = 88.6$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-756</p> <p> $F \text{ см}^2 = 12.460$ $Q \text{ кг.} = 3.38$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 254.0$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-0752</p> <p> $F \text{ см}^2 = 0.769$ $Q \text{ кг.} = 0.208$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 54.2$ Гр. сл. = III Точн. = Н </p>		<p>БПО-757</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-753-01</p> <p> $F \text{ см}^2 = 1.815$ $Q \text{ кг.} = 0.492$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 98.6$ Гр. сл. = I Точн. = Н </p>		<p>БПО-758</p> <p> $F \text{ см}^2 = 1.327$ $Q \text{ кг.} = 0.36$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 150.6$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-754</p> <p> $F \text{ см}^2 = 5.200$ $Q \text{ кг.} = 1.4$ $D \text{ оп.мм} = 130.0$ $P \text{ н.мм} = 268.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-759</p> <p> $F \text{ см}^2 = 0.650$ $Q \text{ кг.} = 0.176$ $D \text{ оп.мм} = 9.0$ $P \text{ н.мм} = 28.3$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-755</p> <p> $F \text{ см}^2 = 0.552$ $Q \text{ кг.} = 0.141$ $D \text{ оп.мм} = 22.8$ $P \text{ н.мм} = 71.14$ Гр. сл. = III Точн. = Н </p>		<p>БПО-760</p> <p> $F \text{ см}^2 = 0.859$ $Q \text{ кг.} = 0.233$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 107.0$ Гр. сл. = II Точн. = Н </p>











	<p>БПО-761</p> <p> $F \text{ см}^2 = 1.082$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 83.1$ Гр. сл. = V Точн. = П </p>		<p>БПО-766</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-762</p> <p> $F \text{ см}^2 = 1.032$ $Q \text{ кг.} = 0.280$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 82.1$ Гр. сл. = V Точн. = П </p>		<p>БПО-767</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-763</p> <p> $F \text{ см}^2 = 0.850$ $Q \text{ кг.} = 0.230$ $D \text{ оп.мм} = 19.0$ $P \text{ н.мм} = 67.5$ Гр. сл. = III Точн. = Н </p>		<p>БПО-768</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-764/1</p> <p> $F \text{ см}^2 = 2.680$ $Q \text{ кг.} = 0.726$ $D \text{ оп.мм} = 45.4$ $P \text{ н.мм} = 133.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-769</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-765</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-770</p> <p> $F \text{ см}^2 = 5.81$ $Q \text{ кг.} = 1.575$ $D \text{ оп.мм} = 138.0$ $P \text{ н.мм} = 413.4$ Гр. сл. = IV Точн. = П </p>











	<p>БПО-771</p> <p> $F \text{ см}^2 = 6.670$ $Q \text{ кг.} = 1.81$ $D \text{ оп.мм} = 98.0$ $P \text{ н.мм} = 738.0$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-776</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-772</p> <p> $F \text{ см}^2 = 0.285$ $Q \text{ кг.} = 0.077$ $D \text{ оп.мм} = 10.0$ $P \text{ н.мм} = 39.23$ Гр. сл. = VI Точн. = П </p>		<p>БПО-777-01</p> <p> $F \text{ см}^2 = 2.05$ $Q \text{ кг.} = 0.556$ $D \text{ оп.мм} = 74.0$ $P \text{ н.мм} = 290.0$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-773</p> <p> $F \text{ см}^2 = 4.010$ $Q \text{ кг.} = 1.09$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 121.9$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-778</p> <p> $F \text{ см}^2 = 1.064$ $Q \text{ кг.} = 0.288$ $D \text{ оп.мм} = 12.8$ $P \text{ н.мм} = 38.4$ Гр. сл. = III Точн. = П </p>
	<p>БПО-774</p> <p> $F \text{ см}^2 = 3.965$ $Q \text{ кг.} = 1.075$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 514$ Гр. сл. = VII Точн. = П </p>		<p>БПО-779-01</p> <p> $F \text{ см}^2 = 15.770$ $Q \text{ кг.} = 4.274$ $D \text{ оп.мм} = 130.0$ $P \text{ н.мм} = 1210$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-775</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-780</p> <p> $F \text{ см}^2 = 25.520$ $Q \text{ кг.} = 6.92$ $D \text{ оп.мм} = 163.0$ $P \text{ н.мм} = 386.6$ Гр. сл. = II Точн. = П </p>











	БПО-781 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$		БПО-786 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$
	БПО-782 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$		БПО-787 $F \text{ см}^2 = 1.795$ $Q \text{ кг.} = 0.49$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 73.55$ $\text{Гр. сл.} = \text{II}$ $\text{Точн.} = \text{H}$
	БПО-783 $F \text{ см}^2 = 6.358$ $Q \text{ кг.} = 1.723$ $D \text{ оп.мм} = 78.0$ $P \text{ н.мм} = 300.6$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$		БПО-788 $F \text{ см}^2 = 0.684$ $Q \text{ кг.} = 0.19$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 54.15$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
	БПО-784 $F \text{ см}^2 = 0.34$ $Q \text{ кг.} = 0.092$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 70$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		БПО-789 $F \text{ см}^2 = 5.260$ $Q \text{ кг.} = 1.43$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 116.4$ $\text{Гр. сл.} = \text{II}$ $\text{Точн.} = \text{H}$
	БПО-785 $F \text{ см}^2 = 1.856$ $Q \text{ кг.} = 0.503$ $D \text{ оп.мм} = 46$ $P \text{ н.мм} = 191$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		БПО-0790 $F \text{ см}^2 = 4.707$ $Q \text{ кг.} = 1.276$ $D \text{ оп.мм} = 169.0$ $P \text{ н.мм} = 576.1$ $\text{Гр. сл.} = \text{Особ.}$ $\text{Точн.} = \text{П}$









	<p>БПО-791</p> <p> $F \text{ см}^2 = 0.992$ $Q \text{ кг.} = 0.268$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 123.2$ Гр. сл. = III Точн. = П </p>		<p>БПО-796</p> <p> $F \text{ см}^2 = 5.810$ $Q \text{ кг.} = 1.575$ $D \text{ оп.мм} = 141.6$ $P \text{ н.мм} = 376.3$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-792</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-797</p> <p> $F \text{ см}^2 = 11.660$ $Q \text{ кг.} = 3.160$ $D \text{ оп.мм} = 150.0$ $P \text{ н.мм} = 357.4$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-793</p> <p> $F \text{ см}^2 = 1.329$ $Q \text{ кг.} = 0.36$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 167.4$ Гр. сл. = V Точн. = П </p>		<p>БПО-798</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-794</p> <p> $F \text{ см}^2 = 18.400$ $Q \text{ кг.} = 4.99$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 421.8$ Гр. сл. = V Точн. = П </p>		<p>БПО-0799</p> <p> $F \text{ см}^2 = 3.809$ $Q \text{ кг.} = 1.032$ $D \text{ оп.мм} = 140.9$ $P \text{ н.мм} = 519.5$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-795</p> <p> $F \text{ см}^2 = 13.290$ $Q \text{ кг.} = 3.6$ $D \text{ оп.мм} = 151.5$ $P \text{ н.мм} = 440.0$ Гр. сл. = V Точн. = Н </p>		<p>БПО-0800</p> <p> $F \text{ см}^2 = 2.770$ $Q \text{ кг.} = 0.751$ $D \text{ оп.мм} = 101.0$ $P \text{ н.мм} = 270.7$ Гр. сл. = V Точн. = П </p>










	<p>БПО-0801</p> <p> $F \text{ см}^2 = 2.230$ $Q \text{ кг.} = 0.604$ $D \text{ оп.мм} = 130.0$ $P \text{ н.мм} = 299.4$ Гр. сл. = V Точн. = П </p>		<p>БПО-0806</p> <p> $F \text{ см}^2 = 0.880$ $Q \text{ кг.} = 0.238$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 128.8$ Гр. сл. = V Точн. = П </p>
	<p>БПО-0802</p> <p> $F \text{ см}^2 = 1.010$ $Q \text{ кг.} = 0.274$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 63.8$ Гр. сл. = III Точн. = Н </p>		<p>БПО-0807</p> <p> $F \text{ см}^2 = 3.185$ $Q \text{ кг.} = 0.863$ $D \text{ оп.мм} = 91.0$ $P \text{ н.мм} = 437.0$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-0803</p> <p> $F \text{ см}^2 = 0.920$ $Q \text{ кг.} = 0.249$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 135.6$ Гр. сл. = V Точн. = 0соб. </p>		<p>БПО-0808</p> <p> $F \text{ см}^2 = 1.394$ $Q \text{ кг.} = 0.378$ $D \text{ оп.мм} = 65.5$ $P \text{ н.мм} = 216.0$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-0804</p> <p> $F \text{ см}^2 = 0.926$ $Q \text{ кг.} = 0.251$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 137.1$ Гр. сл. = V Точн. = 0соб. </p>		<p>БПО-0809</p> <p> $F \text{ см}^2 = 1.481$ $Q \text{ кг.} = 0.401$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 217.5$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-0805</p> <p> $F \text{ см}^2 = 0.695$ $Q \text{ кг.} = 0.188$ $D \text{ оп.мм} = 24.7$ $P \text{ н.мм} = 102.6$ Гр. сл. = V Точн. = П </p>		<p>БПО-810</p> <p> $F \text{ см}^2 = 6.600$ $Q \text{ кг.} = 1.79$ $D \text{ оп.мм} = 167.0$ $P \text{ н.мм} = 410.0$ Гр. сл. = IV Точн. = П </p>











	БПО-811 $F \text{ см}^2 = 3.035$ $Q \text{ кг.} = 0.822$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 232.5$ Гр. сл. = IV Точн. = П		БПО-816 $F \text{ см}^2 = 0.776$ $Q \text{ кг.} = 0.210$ $D \text{ оп.мм} = 25.2$ $P \text{ н.мм} = 55.54$ Гр. сл. = I Точн. = Н
	БПО-812 $F \text{ см}^2 = 22.620$ $Q \text{ кг.} = 6.130$ $D \text{ оп.мм} = 138.0$ $P \text{ н.мм} = 1065$ Гр. сл. = 0соб. Точн. = Н		БПО-817 $F \text{ см}^2 = 1.230$ $Q \text{ кг.} = 0.333$ $D \text{ оп.мм} = 30.3$ $P \text{ н.мм} = 67.54$ Гр. сл. = I Точн. = Н
	БПО-813 $F \text{ см}^2 = 5.500$ $Q \text{ кг.} = 1.49$ $D \text{ оп.мм} = 138.0$ $P \text{ н.мм} = 477.0$ Гр. сл. = V Точн. = Н		БПО-818 $F \text{ см}^2 = 1.640$ $Q \text{ кг.} = 0.444$ $D \text{ оп.мм} = 40.2$ $P \text{ н.мм} = 87.54$ Гр. сл. = I Точн. = Н
	БПО-814 $F \text{ см}^2 = 2.17$ $Q \text{ кг.} = 0.588$ $D \text{ оп.мм} = 83.0$ $P \text{ н.мм} = 292.8$ Гр. сл. = V Точн. = П		БПО-819 $F \text{ см}^2 = 2.020$ $Q \text{ кг.} = 0.547$ $D \text{ оп.мм} = 40.3$ $P \text{ н.мм} = 89.54$ Гр. сл. = I Точн. = Н
	БПО-815 $F \text{ см}^2 = 1.244$ $Q \text{ кг.} = 0.337$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 177.2$ Гр. сл. = V Точн. = П		БПО-820 $F \text{ см}^2 = 2.500$ $Q \text{ кг.} = 0.677$ $D \text{ оп.мм} = 50.3$ $P \text{ н.мм} = 110.0$ Гр. сл. = I Точн. = П











	<p>БПО-821</p> <p> $F \text{ см}^2 = 3.700$ $Q \text{ кг.} = 1.0$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 131.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-826</p> <p> $F \text{ см}^2 = 0.964$ $Q \text{ кг.} = 0.26$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 42.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-822</p> <p> $F \text{ см}^2 = 6.530$ $Q \text{ кг.} = 1.770$ $D \text{ оп.мм} = 81.0$ $P \text{ н.мм} = 175.5$ Гр. сл. = I Точн. = Н </p>		<p>БПО-827</p> <p> $F \text{ см}^2 = 3.960$ $Q \text{ кг.} = 1.1$ $D \text{ оп.мм} = 110.0$ $P \text{ н.мм} = 368.0$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-823</p> <p> $F \text{ см}^2 = 10.160$ $Q \text{ кг.} = 2.75$ $D \text{ оп.мм} = 101.0$ $P \text{ н.мм} = 219.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-828</p> <p> $F \text{ см}^2 = 5.020$ $Q \text{ кг.} = 1.37$ $D \text{ оп.мм} = 43.0$ $P \text{ н.мм} = 120.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-824</p> <p> $F \text{ см}^2 = 1.050$ $Q \text{ кг.} = 0.285$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 124.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-829</p> <p> $F \text{ см}^2 = 5.155$ $Q \text{ кг.} = 1.266$ $D \text{ оп.мм} = 180.1$ $P \text{ н.мм} = 383.3$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-825</p> <p> $F \text{ см}^2 = 1.580$ $Q \text{ кг.} = 0.428$ $D \text{ оп.мм} = 36.5$ $P \text{ н.мм} = 156.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-830</p> <p> $F \text{ см}^2 = 3.248$ $Q \text{ кг.} = 0.892$ $D \text{ оп.мм} = 120.1$ $P \text{ н.мм} = 262.7$ Гр. сл. = VI Точн. = Н </p>











	БПО-831 $F \text{ см}^2 = 2.545$ $Q \text{ кг.} = 0.705$ $D \text{ оп.мм} = 90.5$ $P \text{ н.мм} = 202.7$ Гр. сл. = VI Точн. = Н		БПО-836 $F \text{ см}^2 = 2.230$ $Q \text{ кг.} = 0.604$ $D \text{ оп.мм} = 57.16$ $P \text{ н.мм} = 184.6$ Гр. сл. = IV Точн. = Н
	БПО-0832 $F \text{ см}^2 = 0.619$ $Q \text{ кг.} = 0.168$ $D \text{ оп.мм} = 23.4$ $P \text{ н.мм} = 114.8$ Гр. сл. = IV Точн. = П		БПО-837 $F \text{ см}^2 = 2.17$ $Q \text{ кг.} = 0.588$ $D \text{ оп.мм} = 64.56$ $P \text{ н.мм} = 220.7$ Гр. сл. = III Точн. = Н
	БПО-0833 $F \text{ см}^2 = 1.853$ $Q \text{ кг.} = 0.502$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 273.7$ Гр. сл. = VI Точн. = П		БПО-838 $F \text{ см}^2 = 0.699$ $Q \text{ кг.} = 0.189$ $D \text{ оп.мм} = 15.0$ $P \text{ н.мм} = 59.8$ Гр. сл. = III Точн. = П
	БПО-834 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. =		БПО-0839 $F \text{ см}^2 = 1.498$ $Q \text{ кг.} = 0.406$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 204.5$ Гр. сл. = IV Точн. = П
	БПО-835 $F \text{ см}^2 = 3.673$ $Q \text{ кг.} = 1.000$ $D \text{ оп.мм} = 52.2$ $P \text{ н.мм} = 234.5$ Гр. сл. = IV Точн. = П		БПО-0840 $F \text{ см}^2 = 0.684$ $Q \text{ кг.} = 0.185$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 126.3$ Гр. сл. = V Точн. = П










	<p>БПО-0841</p> <p> $F \text{ см}^2 = 27.650$ $Q \text{ кг.} = 7.493$ $D \text{ оп.мм} = 178.0$ $P \text{ н.мм} = 965.4$ Гр. сл. = VI Точн. = П </p>		<p>БПО-0846</p> <p> $F \text{ см}^2 = 1.71$ $Q \text{ кг.} = 0.463$ $D \text{ оп.мм} = 48.3$ $P \text{ н.мм} = 183.8$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-0842</p> <p> $F \text{ см}^2 = 3.167$ $Q \text{ кг.} = 0.858$ $D \text{ оп.мм} = 104.0$ $P \text{ н.мм} = 277.8$ Гр. сл. = VI Точн. = П </p>		<p>БПО-847</p> <p> $F \text{ см}^2 = 2.33$ $Q \text{ кг.} = 0.631$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 278.1$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-0843</p> <p> $F \text{ см}^2 = 1.629$ $Q \text{ кг.} = 0.441$ $D \text{ оп.мм} = 37.6$ $P \text{ н.мм} = 155.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-848</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-0844</p> <p> $F \text{ см}^2 = 1.328$ $Q \text{ кг.} = 0.360$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 144.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-849</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-0845</p> <p> $F \text{ см}^2 = 4.144$ $Q \text{ кг.} = 1.123$ $D \text{ оп.мм} = 128.0$ $P \text{ н.мм} = 403.4$ Гр. сл. = V Точн. = П </p>		<p>БПО-850</p> <p> $F \text{ см}^2 = 5.720$ $Q \text{ кг.} = 1.550$ $D \text{ оп.мм} = 88.0$ $P \text{ н.мм} = 424.0$ Гр. сл. = VI Точн. = П </p>










	<p>БПО-851</p> <p> $F \text{ см}^2 = 3.080$ $Q \text{ кг.} = 0.835$ $D \text{ оп.мм} = 44.3$ $P \text{ н.мм} = 206.2$ Гр. сл. = v Точн. = П </p>		<p>БПО-856</p> <p> $F \text{ см}^2 = 3.040$ $Q \text{ кг.} = 0.824$ $D \text{ оп.мм} = 56.5$ $P \text{ н.мм} = 160.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-852</p> <p> $F \text{ см}^2 = 8.840$ $Q \text{ кг.} = 2.4$ $D \text{ оп.мм} = 98.2$ $P \text{ н.мм} = 637.9$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-857</p> <p> $F \text{ см}^2 = 0.960$ $Q \text{ кг.} = 0.260$ $D \text{ оп.мм} = 41.3$ $P \text{ н.мм} = 100.0$ Гр. сл. = III Точн. = Н </p>
			<p>БПО-858</p> <p> $F \text{ см}^2 = 3.07$ $Q \text{ кг.} = 0.832$ $D \text{ оп.мм} = 76.6$ $P \text{ н.мм} = 310.7$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-854</p> <p> $F \text{ см}^2 = 1.160$ $Q \text{ кг.} = 0.314$ $D \text{ оп.мм} = 42.5$ $P \text{ н.мм} = 120.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-859</p> <p> $F \text{ см}^2 = 1.710$ $Q \text{ кг.} = 0.463$ $D \text{ оп.мм} = 42.5$ $P \text{ н.мм} = 120.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-855</p> <p> $F \text{ см}^2 = 2.310$ $Q \text{ кг.} = 0.626$ $D \text{ оп.мм} = 56.5$ $P \text{ н.мм} = 160.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-860</p> <p> $F \text{ см}^2 = 1.260$ $Q \text{ кг.} = 0.34$ $D \text{ оп.мм} = 16.0$ $P \text{ н.мм} = 46.3$ Гр. сл. = III Точн. = П </p>









	<p>БПО-861</p> <p> $F \text{ см}^2 = 1.334$ $Q \text{ кг.} = 0.362$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 140.2$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-866</p> <p> $F \text{ см}^2 = 1.080$ $Q \text{ кг.} = 0.292$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 112.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-862</p> <p> $F \text{ см}^2 = 1.425$ $Q \text{ кг.} = 0.386$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 223.1$ Гр. сл. = VI Точн. = П </p>		<p>БПО-867</p> <p> $F \text{ см}^2 = 2.758$ $Q \text{ кг.} = 0.747$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 220.7$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-863</p> <p> $F \text{ см}^2 = 1.570$ $Q \text{ кг.} = 0.425$ $D \text{ оп.мм} = 32.5$ $P \text{ н.мм} = 123.9$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-868</p> <p> $F \text{ см}^2 = 3.29$ $Q \text{ кг.} = 0.892$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 247.7$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-864</p> <p> $F \text{ см}^2 = 4.750$ $Q \text{ кг.} = 1.287$ $D \text{ оп.мм} = 70.7$ $P \text{ н.мм} = 200.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-869</p> <p> $F \text{ см}^2 = 1.636$ $Q \text{ кг.} = 0.443$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 135.14$ Гр. сл. = III Точн. = П </p>
	<p>БПО-865</p> <p> $F \text{ см}^2 = 1.980$ $Q \text{ кг.} = 0.537$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 203.5$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-870</p> <p> $F \text{ см}^2 = 3.765$ $Q \text{ кг.} = 1.02$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 210.7$ Гр. сл. = IV Точн. = П </p>










	<p>БПО-861</p> <p> $F \text{ см}^2 = 1.334$ $Q \text{ кг.} = 0.362$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 140.2$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-866</p> <p> $F \text{ см}^2 = 1.080$ $Q \text{ кг.} = 0.292$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 112.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-862</p> <p> $F \text{ см}^2 = 1.425$ $Q \text{ кг.} = 0.386$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 223.1$ Гр. сл. = VI Точн. = П </p>		<p>БПО-867</p> <p> $F \text{ см}^2 = 2.758$ $Q \text{ кг.} = 0.747$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 220.7$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-863</p> <p> $F \text{ см}^2 = 1.570$ $Q \text{ кг.} = 0.425$ $D \text{ оп.мм} = 32.5$ $P \text{ н.мм} = 123.9$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-868</p> <p> $F \text{ см}^2 = 3.29$ $Q \text{ кг.} = 0.892$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 247.7$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-864</p> <p> $F \text{ см}^2 = 4.750$ $Q \text{ кг.} = 1.287$ $D \text{ оп.мм} = 70.7$ $P \text{ н.мм} = 200.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-869</p> <p> $F \text{ см}^2 = 1.636$ $Q \text{ кг.} = 0.443$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 135.14$ Гр. сл. = III Точн. = П </p>
	<p>БПО-865</p> <p> $F \text{ см}^2 = 1.980$ $Q \text{ кг.} = 0.537$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 203.5$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-870</p> <p> $F \text{ см}^2 = 3.765$ $Q \text{ кг.} = 1.02$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 210.7$ Гр. сл. = IV Точн. = П </p>











	<p>БПО-871</p> <p> $F \text{ см}^2 = 0.520$ $Q \text{ кг.} = 0.14$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 77.6$ Гр. сл. = V Точн. = Н </p>		<p>БПО-876</p> <p> $F \text{ см}^2 = 3.58$ $Q \text{ кг.} = 0.97$ $D \text{ оп.мм} = 43.2$ $P \text{ н.мм} = 193.8$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-872</p> <p> $F \text{ см}^2 = 2.910$ $Q \text{ кг.} = 0.788$ $D \text{ оп.мм} = 72.0$ $P \text{ н.мм} = 200.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-877</p> <p> $F \text{ см}^2 = 4.000$ $Q \text{ кг.} = 1.08$ $D \text{ оп.мм} = 44.5$ $P \text{ н.мм} = 199.3$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-873</p> <p> $F \text{ см}^2 = 2.010$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 140.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-878</p> <p> $F \text{ см}^2 = 0.506$ $Q \text{ кг.} = 0.137$ $D \text{ оп.мм} = 15.0$ $P \text{ н.мм} = 64.0$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-874</p> <p> $F \text{ см}^2 = 2.367$ $Q \text{ кг.} = 0.641$ $D \text{ оп.мм} = 33.7$ $P \text{ н.мм} = 148.6$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-879</p> <p> $F \text{ см}^2 = 1.414$ $Q \text{ кг.} = 0.383$ $D \text{ оп.мм} = 43.6$ $P \text{ н.мм} = 173.2$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-875</p> <p> $F \text{ см}^2 = 3.375$ $Q \text{ кг.} = 0.915$ $D \text{ оп.мм} = 72.0$ $P \text{ н.мм} = 275.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-880</p> <p> $F \text{ см}^2 = 0.888$ $Q \text{ кг.} = 0.213$ $D \text{ оп.мм} = 31.6$ $P \text{ н.мм} = 111.6$ Гр. сл. = IV Точн. = Н </p>











	<p>БПО-881</p> <p> $F \text{ см}^2 = 19.030$ $Q \text{ кг.} = 5.16$ $D \text{ оп.мм} = 73.5$ $P \text{ н.мм} = 190.3$ Гр. сл. = I Точн. = Н </p>		<p>БПО-886</p> <p> $F \text{ см}^2 = 3.700$ $Q \text{ кг.} = 1.0$ $D \text{ оп.мм} = 45.8$ $P \text{ н.мм} = 197.2$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-882</p> <p> $F \text{ см}^2 = 2.570$ $Q \text{ кг.} = 0.696$ $D \text{ оп.мм} = 40.1$ $P \text{ н.мм} = 160.8$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-887</p> <p> $F \text{ см}^2 = 4.104$ $Q \text{ кг.} = 1.112$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 238.1$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-883</p> <p> $F \text{ см}^2 = 0.553$ $Q \text{ кг.} = 0.150$ $D \text{ оп.мм} = 18.3$ $P \text{ н.мм} = 53.5$ Гр. сл. = II Точн. = Н </p>		<p>БПО-888</p> <p> $F \text{ см}^2 = 1.105$ $Q \text{ кг.} = 0.3$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 85.5$ Гр. сл. = III Точн. = Н </p>
			<p>БПО-889</p> <p> $F \text{ см}^2 = 0.868$ $Q \text{ кг.} = 0.235$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 80.5$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-885</p> <p> $F \text{ см}^2 = 3.310$ $Q \text{ кг.} = 0.897$ $D \text{ оп.мм} = 44.5$ $P \text{ н.мм} = 204.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-890</p> <p> $F \text{ см}^2 = 1.010$ $Q \text{ кг.} = 0.274$ $D \text{ оп.мм} = 31.5$ $P \text{ н.мм} = 88.7$ Гр. сл. = IV Точн. = Н </p>











	<p>БПО-891</p> <p> $F \text{ см}^2 = 4.050$ $Q \text{ кг.} = 1.1$ $D \text{ оп.мм} = 22.6$ $P \text{ н.мм} = 211.5$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-896</p> <p> $F \text{ см}^2 = 0.510$ $Q \text{ кг.} = 0.138$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 75.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-892</p> <p> $F \text{ см}^2 = 0.547$ $Q \text{ кг.} = 0.15$ $D \text{ оп.мм} = 28.4$ $P \text{ н.мм} = 77.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-897</p> <p> $F \text{ см}^2 = 1.572$ $Q \text{ кг.} = 0.426$ $D \text{ оп.мм} = 49.2$ $P \text{ н.мм} = 191.2$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-893</p> <p> $F \text{ см}^2 = 3.090$ $Q \text{ кг.} = 0.84$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 195.3$ Гр. сл. = 0соб. Точн. = Н </p>		
	<p>БПО-894</p> <p> $F \text{ см}^2 = 0.785$ $Q \text{ кг.} = 0.213$ $D \text{ оп.мм} = 32.5$ $P \text{ н.мм} = 86.6$ Гр. сл. = II Точн. = Н </p>		<p>БПО-899</p> <p> $F \text{ см}^2 = 1.839$ $Q \text{ кг.} = 0.227$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 102.2$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-895</p> <p> $F \text{ см}^2 = 0.520$ $Q \text{ кг.} = 0.141$ $D \text{ оп.мм} = 25.5$ $P \text{ н.мм} = 55.6$ Гр. сл. = I Точн. = Н </p>		<p>БПО-900</p> <p> $F \text{ см}^2 = 0.942$ $Q \text{ кг.} = 0.255$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 114.2$ Гр. сл. = II Точн. = Н </p>











	<p>БПО-901</p> <p> $F \text{ см}^2 = 1.57$ $Q \text{ кг.} = 0.425$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 188.2$ Гр. сл. = II Точн. = Н </p>		
	<p>БПО-902</p> <p> $F \text{ см}^2 = 1.162$ $Q \text{ кг.} = 0.315$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 140.2$ Гр. сл. = II Точн. = Н </p>		<p>БПО-907</p> <p> $F \text{ см}^2 = 2.856$ $Q \text{ кг.} = 0.774$ $D \text{ оп.мм} = 66.7$ $P \text{ н.мм} = 302.8$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-903</p> <p> $F \text{ см}^2 = 1.417$ $Q \text{ кг.} = 0.384$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 170.2$ Гр. сл. = II Точн. = Н </p>		<p>БПО-908</p> <p> $F \text{ см}^2 = 0.860$ $Q \text{ кг.} = 0.233$ $D \text{ оп.мм} = 30.5$ $P \text{ н.мм} = 111.9$ Гр. сл. = IV Точн. = Н </p>
			<p>БПО-909</p> <p> $F \text{ см}^2 = 1.416$ $Q \text{ кг.} = 0.383$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 170$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-905</p> <p> $F \text{ см}^2 = 14.160$ $Q \text{ кг.} = 3.84$ $D \text{ оп.мм} = 160.0$ $P \text{ н.мм} = 716.0$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-910</p> <p> $F \text{ см}^2 = 1.320$ $Q \text{ кг.} = 0.358$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 206.0$ Гр. сл. = 0соб. Точн. = П </p>









	<p>БПО-911</p> <p> $F \text{ см}^2 = 1.880$ $Q \text{ кг.} = 0.509$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 291.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-916</p> <p> $F \text{ см}^2 = 1.160$ $Q \text{ кг.} = 0.314$ $D \text{ оп.мм} = 44.7$ $P \text{ н.мм} = 120.0$ Гр. сл. = III Точн. = Н </p>
			<p>БПО-917</p> <p> $F \text{ см}^2 = 1.340$ $Q \text{ кг.} = 0.363$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 110.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-913</p> <p> $F \text{ см}^2 = 0.760$ $Q \text{ кг.} = 0.206$ $D \text{ оп.мм} = 28.3$ $P \text{ н.мм} = 80.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-918</p> <p> $F \text{ см}^2 = 1.460$ $Q \text{ кг.} = 0.42$ $D \text{ оп.мм} = 56.6$ $P \text{ н.мм} = 160.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-914</p> <p> $F \text{ см}^2 = 0.960$ $Q \text{ кг.} = 0.260$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 100.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-919</p> <p> $F \text{ см}^2 = 1.440$ $Q \text{ кг.} = 0.390$ $D \text{ оп.мм} = 28.4$ $P \text{ н.мм} = 80.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-915</p> <p> $F \text{ см}^2 = 0.860$ $Q \text{ кг.} = 0.233$ $D \text{ оп.мм} = 33.5$ $P \text{ н.мм} = 90.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-920</p> <p> $F \text{ см}^2 = 1.360$ $Q \text{ кг.} = 0.37$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 140.0$ Гр. сл. = IV Точн. = Н </p>

	<p>БПО-921</p> <p> $F \text{ см}^2 = 1.560$ $Q \text{ кг.} = 0.423$ $D \text{ оп.мм} = 58.3$ $P \text{ н.мм} = 160.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-926</p> <p> $F \text{ см}^2 = 2.910$ $Q \text{ кг.} = 0.789$ $D \text{ оп.мм} = 70.7$ $P \text{ н.мм} = 200.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-922</p> <p> $F \text{ см}^2 = 1.960$ $Q \text{ кг.} = 0.531$ $D \text{ оп.мм} = 70.7$ $P \text{ н.мм} = 200.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-927</p> <p> $F \text{ см}^2 = 1.410$ $Q \text{ кг.} = 0.382$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 100.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-923</p> <p> $F \text{ см}^2 = 1.560$ $Q \text{ кг.} = 0.423$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 160.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-928</p> <p> $F \text{ см}^2 = 0.560$ $Q \text{ кг.} = 0.152$ $D \text{ оп.мм} = 21.2$ $P \text{ н.мм} = 60.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-924</p> <p> $F \text{ см}^2 = 1.710$ $Q \text{ кг.} = 0.463$ $D \text{ оп.мм} = 44.7$ $P \text{ н.мм} = 120.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-929</p> <p> $F \text{ см}^2 = 3.510$ $Q \text{ кг.} = 0.951$ $D \text{ оп.мм} = 84.9$ $P \text{ н.мм} = 240.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-925</p> <p> $F \text{ см}^2 = 2.310$ $Q \text{ кг.} = 0.626$ $D \text{ оп.мм} = 58.3$ $P \text{ н.мм} = 160.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-930</p> <p> $F \text{ см}^2 = 3.750$ $Q \text{ кг.} = 1.016$ $D \text{ оп.мм} = 56.6$ $P \text{ н.мм} = 160.0$ Гр. сл. = I Точн. = Н </p>











	<p>БПО-931</p> <p> $F \text{ см}^2 = 3.840$ $Q \text{ кг.} = 1.041$ $D \text{ оп.мм} = 70.7$ $P \text{ н.мм} = 200.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-936</p> <p> $F \text{ см}^2 = 3.510$ $Q \text{ кг.} = 0.951$ $D \text{ оп.мм} = 89.4$ $P \text{ н.мм} = 240.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-932</p> <p> $F \text{ см}^2 = 4.710$ $Q \text{ кг.} = 1.276$ $D \text{ оп.мм} = 133.4$ $P \text{ н.мм} = 320.0$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-937</p> <p> $F \text{ см}^2 = 4.640$ $Q \text{ кг.} = 1.257$ $D \text{ оп.мм} = 89.4$ $P \text{ н.мм} = 240.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-933</p> <p> $F \text{ см}^2 = 4.640$ $Q \text{ кг.} = 1.257$ $D \text{ оп.мм} = 84.9$ $P \text{ н.мм} = 240.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-938</p> <p> $F \text{ см}^2 = 6.840$ $Q \text{ кг.} = 1.853$ $D \text{ оп.мм} = 84.9$ $P \text{ н.мм} = 240.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-934</p> <p> $F \text{ см}^2 = 3.840$ $Q \text{ кг.} = 1.041$ $D \text{ оп.мм} = 72.1$ $P \text{ н.мм} = 200.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-939</p> <p> $F \text{ см}^2 = 3.810$ $Q \text{ кг.} = 1.03$ $D \text{ оп.мм} = 105.0$ $P \text{ н.мм} = 260.0$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-935</p> <p> $F \text{ см}^2 = 3.210$ $Q \text{ кг.} = 0.870$ $D \text{ оп.мм} = 85.4$ $P \text{ н.мм} = 220.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-940</p> <p> $F \text{ см}^2 = 4.110$ $Q \text{ кг.} = 1.113$ $D \text{ оп.мм} = 107.7$ $P \text{ н.мм} = 280.0$ Гр. сл. = IV Точн. = Н </p>









	<p>БПО-941</p> <p> $F \text{ см}^2 = 4.410$ $Q \text{ кг.} = 1.195$ $D \text{ оп.мм} = 111.8$ $P \text{ н.мм} = 300.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-946</p> <p> $F \text{ см}^2 = 1.720$ $Q \text{ кг.} = 0.466$ $D \text{ оп.мм} = 42.4$ $P \text{ н.мм} = 176.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-942</p> <p> $F \text{ см}^2 = 7.250$ $Q \text{ кг.} = 1.964$ $D \text{ оп.мм} = 111.8$ $P \text{ н.мм} = 300.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-947</p> <p> $F \text{ см}^2 = 3.120$ $Q \text{ кг.} = 0.846$ $D \text{ оп.мм} = 58.3$ $P \text{ н.мм} = 214.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-943</p> <p> $F \text{ см}^2 = 4.710$ $Q \text{ кг.} = 1.276$ $D \text{ оп.мм} = 137.4$ $P \text{ н.мм} = 320.0$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-948</p> <p> $F \text{ см}^2 = 3.020$ $Q \text{ кг.} = 1.089$ $D \text{ оп.мм} = 72.1$ $P \text{ н.мм} = 274.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-944</p> <p> $F \text{ см}^2 = 1.120$ $Q \text{ кг.} = 0.303$ $D \text{ оп.мм} = 28.3$ $P \text{ н.мм} = 116.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-949</p> <p> $F \text{ см}^2 = 3.420$ $Q \text{ кг.} = 0.967$ $D \text{ оп.мм} = 56.6$ $P \text{ н.мм} = 234.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-945</p> <p> $F \text{ см}^2 = 1.420$ $Q \text{ кг.} = 0.385$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 146.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-950</p> <p> $F \text{ см}^2 = 4.480$ $Q \text{ кг.} = 1.214$ $D \text{ оп.мм} = 56.6$ $P \text{ н.мм} = 232.0$ Гр. сл. = II Точн. = Н </p>











	<p>БПО-951</p> <p> $F \text{ см}^2 = 4.620$ $Q \text{ кг.} = 1.252$ $D \text{ оп.мм} = 78.1$ $P \text{ н.мм} = 314.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-956</p> <p> $F \text{ см}^2 = 3.000$ $Q \text{ кг.} = 0.813$ $D \text{ оп.мм} = 60.2$ $P \text{ н.мм} = 130.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-952</p> <p> $F \text{ см}^2 = 1.000$ $Q \text{ кг.} = 0.271$ $D \text{ оп.мм} = 20.6$ $P \text{ н.мм} = 50.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-957</p> <p> $F \text{ см}^2 = 5.000$ $Q \text{ кг.} = 1.355$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 120.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-953</p> <p> $F \text{ см}^2 = 0.900$ $Q \text{ кг.} = 0.244$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 66.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-958</p> <p> $F \text{ см}^2 = 6.000$ $Q \text{ кг.} = 1.626$ $D \text{ оп.мм} = 60.8$ $P \text{ н.мм} = 140.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-954</p> <p> $F \text{ см}^2 = 3.000$ $Q \text{ кг.} = 0.813$ $D \text{ оп.мм} = 31.6$ $P \text{ н.мм} = 80.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-959</p> <p> $F \text{ см}^2 = 15.000$ $Q \text{ кг.} = 4.065$ $D \text{ оп.мм} = 156.3$ $P \text{ н.мм} = 320.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-955</p> <p> $F \text{ см}^2 = 1.200$ $Q \text{ кг.} = 0.325$ $D \text{ оп.мм} = 40.1$ $P \text{ н.мм} = 86.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-960</p> <p> $F \text{ см}^2 = 1.590$ $Q \text{ кг.} = 0.431$ $D \text{ оп.мм} = 50.8$ $P \text{ н.мм} = 155.0$ Гр. сл. = IV Точн. = Н </p>











	<p>БПО-961</p> <p> $F \text{ см}^2 = 1.040$ $Q \text{ кг.} = 0.282$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 93.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-966</p> <p> $F \text{ см}^2 = 0.860$ $Q \text{ кг.} = 0.23$ $D \text{ оп.мм} = 39.95$ $P \text{ н.мм} = 117.9$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-962</p> <p> $F \text{ см}^2 = 3.120$ $Q \text{ кг.} = 0.845$ $D \text{ оп.мм} = 53.5$ $P \text{ н.мм} = 199.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-967</p> <p> $F \text{ см}^2 = 2.470$ $Q \text{ кг.} = 0.67$ $D \text{ оп.мм} = 85.6$ $P \text{ н.мм} = 275.0$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-963</p> <p> $F \text{ см}^2 = 3.880$ $Q \text{ кг.} = 1.051$ $D \text{ оп.мм} = 77.3$ $P \text{ н.мм} = 316.8$ Гр. сл. = II Точн. = Н </p>		<p>БПО-968</p> <p> $F \text{ см}^2 = 0.500$ $Q \text{ кг.} = 0.14$ $D \text{ оп.мм} = 36.15$ $P \text{ н.мм} = 72.14$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-964</p> <p> $F \text{ см}^2 = 1.346$ $Q \text{ кг.} = 0.365$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 182.4$ Гр. сл. = 0соб. Точн. = Н </p>		
	<p>БПО-965</p> <p> $F \text{ см}^2 = 3.360$ $Q \text{ кг.} = 0.910$ $D \text{ оп.мм} = 70.6$ $P \text{ н.мм} = 416.6$ Гр. сл. = IV Точн. = Н </p>		











	<p>БПО-973</p> <p> $F \text{ см}^2 = 6.386$ $Q \text{ кг.} = 1.731$ $D \text{ оп.мм} = 77.8$ $P \text{ н.мм} = 212.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-978</p> <p> $F \text{ см}^2 = 3.210$ $Q \text{ кг.} = 0.870$ $D \text{ оп.мм} = 60.1$ $P \text{ н.мм} = 201.9$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-974</p> <p> $F \text{ см}^2 = 0.960$ $Q \text{ кг.} = 0.260$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 69.9$ Гр. сл. = I Точн. = Н </p>		<p>БПО-979</p> <p> $F \text{ см}^2 = 3.810$ $Q \text{ кг.} = 1.03$ $D \text{ оп.мм} = 143.0$ $P \text{ н.мм} = 413.8$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-0975</p> <p> $F \text{ см}^2 = 9.230$ $Q \text{ кг.} = 2.501$ $D \text{ оп.мм} = 128.1$ $P \text{ н.мм} = 277.7$ Гр. сл. = III Точн. = Н </p>		<p>БПО-980</p> <p> $F \text{ см}^2 = 0.750$ $Q \text{ кг.} = 0.2$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 118.4$ Гр. сл. = IV Точн. = Н </p>











	<p>БПО-981</p> <p> $F \text{ см}^2 = 8.980$ $Q \text{ кг.} = 2.43$ $D \text{ оп.мм} = 71.0$ $P \text{ н.мм} = 416.5$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-986</p> <p> $F \text{ см}^2 = 13.130$ $Q \text{ кг.} = 3.55$ $D \text{ оп.мм} = 102.0$ $P \text{ н.мм} = 418.7$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-982</p> <p> $F \text{ см}^2 = 4.080$ $Q \text{ кг.} = 1.11$ $D \text{ оп.мм} = 73.0$ $P \text{ н.мм} = 270.6$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-987</p> <p> $F \text{ см}^2 = 7.150$ $Q \text{ кг.} = 1.94$ $D \text{ оп.мм} = 56.2$ $P \text{ н.мм} = 257.7$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-983</p> <p> $F \text{ см}^2 = 17.430$ $Q \text{ кг.} = 4.72$ $D \text{ оп.мм} = 129.3$ $P \text{ н.мм} = 1197.8$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-988</p> <p> $F \text{ см}^2 = 15.010$ $Q \text{ кг.} = 4.07$ $D \text{ оп.мм} = 101.2$ $P \text{ н.мм} = 553.7$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-984</p> <p> $F \text{ см}^2 = 2.15$ $Q \text{ кг.} = 0.582$ $D \text{ оп.мм} = 72.0$ $P \text{ н.мм} = 291.1$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-989.01</p> <p> $F \text{ см}^2 = 1.106$ $Q \text{ кг.} = 0.3$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 104.2$ Гр. сл. = III Точн. = П </p>
	<p>БПО-985</p> <p> $F \text{ см}^2 = 3.680$ $Q \text{ кг.} = 0.997$ $D \text{ оп.мм} = 63.0$ $P \text{ н.мм} = 192.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-990</p> <p> $F \text{ см}^2 = 0.563$ $Q \text{ кг.} = 0.153$ $D \text{ оп.мм} = 17.0$ $P \text{ н.мм} = 77.5$ Гр. сл. = III Точн. = Н </p>











	БПО-991 $F \text{ см}^2 = 1.890$ $Q \text{ кг.} = 0.499$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 100.0$ Гр. сл. = I Точн. = Н		БПО-996 $F \text{ см}^2 = 5.660$ $Q \text{ кг.} = 1.534$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 92.4$ Гр. сл. = II Точн. = Н
			БПО-997 $F \text{ см}^2 = 2.54$ $Q \text{ кг.} = 0.688$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 273.7$ Гр. сл. = IV Точн. = Н
			БПО-998 $F \text{ см}^2 = 3.2$ $Q \text{ кг.} = 0.867$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 168$ Гр. сл. = IV Точн. = Н
	БПО-994 $F \text{ см}^2 = 2.115$ $Q \text{ кг.} = 0.573$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 277.1$ Гр. сл. = VI Точн. = П		БПО-999 $F \text{ см}^2 = 0.936$ $Q \text{ кг.} = 0.254$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 119.1$ Гр. сл. = IV Точн. = Н
	БПО-995 $F \text{ см}^2 = 4.130$ $Q \text{ кг.} = 1.119$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 305.8$ Гр. сл. = VI Точн. = П		БПО-1000 $F \text{ см}^2 = 0.500$ $Q \text{ кг.} = 0.136$ $D \text{ оп.мм} = 18.1$ $P \text{ н.мм} = 66.8$ Гр. сл. = II Точн. = Н











	<p>БПО-1001</p> <p> $F \text{ см}^2 = 1.057$ $Q \text{ кг.} = 0.286$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 98.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1006</p> <p> $F \text{ см}^2 = 9.630$ $Q \text{ кг.} = 2.610$ $D \text{ оп.мм} = 186.1$ $P \text{ н.мм} = 380.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1002</p> <p> $F \text{ см}^2 = 3.050$ $Q \text{ кг.} = 0.826$ $D \text{ оп.мм} = 87.0$ $P \text{ н.мм} = 245.5$ Гр. сл. = V Точн. = Н </p>		<p>БПО-1007</p> <p> $F \text{ см}^2 = 1.205$ $Q \text{ кг.} = 0.327$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 163.0$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-1003</p> <p> $F \text{ см}^2 = 2.440$ $Q \text{ кг.} = 0.66$ $D \text{ оп.мм} = 45.7$ $P \text{ н.мм} = 192.8$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-1008</p> <p> $F \text{ см}^2 = 1.260$ $Q \text{ кг.} = 0.341$ $D \text{ оп.мм} = 52.5$ $P \text{ н.мм} = 130.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1004</p> <p> $F \text{ см}^2 = 2.170$ $Q \text{ кг.} = 0.588$ $D \text{ оп.мм} = 46.5$ $P \text{ н.мм} = 174.2$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1009</p> <p> $F \text{ см}^2 = 2.310$ $Q \text{ кг.} = 0.626$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 160.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1005</p> <p> $F \text{ см}^2 = 37.400$ $Q \text{ кг.} = 10.135$ $D \text{ оп.мм} = 186.0$ $P \text{ н.мм} = 410.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1010</p> <p> $F \text{ см}^2 = 1.960$ $Q \text{ кг.} = 0.531$ $D \text{ оп.мм} = 77.5$ $P \text{ н.мм} = 200.0$ Гр. сл. = IV Точн. = Н </p>











	<p>БПО-1011</p> <p> $F \text{ см}^2 = 2.240$ $Q \text{ кг.} = 0.6$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 120.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1016</p> <p> $F \text{ см}^2 = 0.800$ $Q \text{ кг.} = 0.217$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 84.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1012</p> <p> $F \text{ см}^2 = 5.750$ $Q \text{ кг.} = 1.558$ $D \text{ оп.мм} = 84.9$ $P \text{ н.мм} = 240.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1017</p> <p> $F \text{ см}^2 = 2.520$ $Q \text{ кг.} = 0.683$ $D \text{ оп.мм} = 42.4$ $P \text{ н.мм} = 174.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1013</p> <p> $F \text{ см}^2 = 6.750$ $Q \text{ кг.} = 1.83$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 280.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1018</p> <p> $F \text{ см}^2 = 2.070$ $Q \text{ кг.} = 0.561$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 144.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1014</p> <p> $F \text{ см}^2 = 19.0$ $Q \text{ кг.} = 5.149$ $D \text{ оп.мм} = 141.5$ $P \text{ н.мм} = 400.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1019</p> <p> $F \text{ см}^2 = 2.910$ $Q \text{ кг.} = 0.789$ $D \text{ оп.мм} = 77.0$ $P \text{ н.мм} = 200.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1015</p> <p> $F \text{ см}^2 = 1.110$ $Q \text{ кг.} = 0.301$ $D \text{ оп.мм} = 28.3$ $P \text{ н.мм} = 80.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1020</p> <p> $F \text{ см}^2 = 2.610$ $Q \text{ кг.} = 0.707$ $D \text{ оп.мм} = 67.1$ $P \text{ н.мм} = 180.0$ Гр. сл. = III Точн. = Н </p>











	<p>БПО-1021</p> <p> $F \text{ см}^2 = 3.000$ $Q \text{ кг.} = 0.813$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 112.0$ Гр. сл. = I Точн. = 0соб. </p>		<p>БПО-1026</p> <p> $F \text{ см}^2 = 13.767$ $Q \text{ кг.} = 3.731$ $D \text{ оп.мм} = 105.9$ $P \text{ н.мм} = 330.5$ Гр. сл. = II Точн. = H </p>
	<p>БПО-1022</p> <p> $F \text{ см}^2 = 4.000$ $Q \text{ кг.} = 1.08$ $D \text{ оп.мм} = 50.6$ $P \text{ н.мм} = 116.0$ Гр. сл. = I Точн. = 0соб. </p>		<p>БПО-1027</p> <p> $F \text{ см}^2 = 1.064$ $Q \text{ кг.} = 0.288$ $D \text{ оп.мм} = 32.7$ $P \text{ н.мм} = 98.2$ Гр. сл. = VI Точн. = H </p>
	<p>БПО-1023</p> <p> $F \text{ см}^2 = 1.800$ $Q \text{ кг.} = 0.487$ $D \text{ оп.мм} = 30.6$ $P \text{ н.мм} = 72.0$ Гр. сл. = I Точн. = 0соб. </p>		<p>БПО-1028</p> <p> $F \text{ см}^2 = 1.920$ $Q \text{ кг.} = 0.520$ $D \text{ оп.мм} = 44.7$ $P \text{ н.мм} = 196.0$ Гр. сл. = VI Точн. = 0соб. </p>
	<p>БПО-1024</p> <p> $F \text{ см}^2 = 5.680$ $Q \text{ кг.} = 1.539$ $D \text{ оп.мм} = 71.0$ $P \text{ н.мм} = 292.0$ Гр. сл. = II Точн. = 0соб. </p>		<p>БПО-1029</p> <p> $F \text{ см}^2 = 1.520$ $Q \text{ кг.} = 0.4119$ $D \text{ оп.мм} = 36.05$ $P \text{ н.мм} = 156.0$ Гр. сл. = IV Точн. = 0соб. </p>
	<p>БПО-1025</p> <p> $F \text{ см}^2 = 1.620$ $Q \text{ кг.} = 0.439$ $D \text{ оп.мм} = 28.3$ $P \text{ н.мм} = 114.0$ Гр. сл. = V Точн. = 0соб. </p>		<p>БПО-1030</p> <p> $F \text{ см}^2 = 2.420$ $Q \text{ кг.} = 0.656$ $D \text{ оп.мм} = 53.8$ $P \text{ н.мм} = 137.4$ Гр. сл. = III Точн. = H </p>











	<p>БПО-1031</p> <p> $F \text{ см}^2 = 3.075$ $Q \text{ кг.} = 0.833$ $D \text{ оп.мм} = 60.5$ $P \text{ н.мм} = 194.7$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-1036</p> <p> $F \text{ см}^2 = 0.750$ $Q \text{ кг.} = 0.203$ $D \text{ оп.мм} = 16.0$ $P \text{ н.мм} = 40.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1032</p> <p> $F \text{ см}^2 = 2.330$ $Q \text{ кг.} = 0.63$ $D \text{ оп.мм} = 40.6$ $P \text{ н.мм} = 155.0$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-1037</p> <p> $F \text{ см}^2 = 7.500$ $Q \text{ кг.} = 2.033$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 110.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1033</p> <p> $F \text{ см}^2 = 1.121$ $Q \text{ кг.} = 0.304$ $D \text{ оп.мм} = 30.4$ $P \text{ н.мм} = 118.4$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-1038</p> <p> $F \text{ см}^2 = 5.250$ $Q \text{ кг.} = 1.423$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 100.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1034</p> <p> $F \text{ см}^2 = 2.380$ $Q \text{ кг.} = 0.645$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 89.7$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1039</p> <p> $F \text{ см}^2 = 2.400$ $Q \text{ кг.} = 0.651$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 76.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1035</p> <p> $F \text{ см}^2 = 7.000$ $Q \text{ кг.} = 1.897$ $D \text{ оп.мм} = 70.71$ $P \text{ н.мм} = 290.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1040</p> <p> $F \text{ см}^2 = 6.750$ $Q \text{ кг.} = 1.829$ $D \text{ оп.мм} = 47.5$ $P \text{ н.мм} = 120.0$ Гр. сл. = I Точн. = Н </p>









	<p>БПО-1041</p> <p> $F \text{ см}^2 = 4.000$ $Q \text{ кг.} = 1.084$ $D \text{ оп.мм} = 41.3$ $P \text{ н.мм} = 100.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1046</p> <p> $F \text{ см}^2 = 4.800$ $Q \text{ кг.} = 1.30$ $D \text{ оп.мм} = 60.5$ $P \text{ н.мм} = 136.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1042</p> <p> $F \text{ см}^2 = 1.500$ $Q \text{ кг.} = 0.407$ $D \text{ оп.мм} = 50.1$ $P \text{ н.мм} = 106.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1047</p> <p> $F \text{ см}^2 = 4.000$ $Q \text{ кг.} = 1.084$ $D \text{ оп.мм} = 80.1$ $P \text{ н.мм} = 170.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1043</p> <p> $F \text{ см}^2 = 2.000$ $Q \text{ кг.} = 0.542$ $D \text{ оп.мм} = 50.2$ $P \text{ н.мм} = 108.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1048</p> <p> $F \text{ см}^2 = 8.000$ $Q \text{ кг.} = 2.168$ $D \text{ оп.мм} = 80.6$ $P \text{ н.мм} = 180.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1044</p> <p> $F \text{ см}^2 = 1.800$ $Q \text{ кг.} = 0.488$ $D \text{ оп.мм} = 60.1$ $P \text{ н.мм} = 126.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1049</p> <p> $F \text{ см}^2 = 0.760$ $Q \text{ кг.} = 0.206$ $D \text{ оп.мм} = 29.2$ $P \text{ н.мм} = 80.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1045</p> <p> $F \text{ см}^2 = 2.400$ $Q \text{ кг.} = 0.650$ $D \text{ оп.мм} = 60.1$ $P \text{ н.мм} = 128.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1050</p> <p> $F \text{ см}^2 = 0.660$ $Q \text{ кг.} = 0.179$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 70.0$ Гр. сл. = I Точн. = Н </p>











	<p>БПО-1051</p> <p> $F \text{ см}^2 = 1.410$ $Q \text{ кг.} = 0.382$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 100.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1056</p> <p> $F \text{ см}^2 = 6.040$ $Q \text{ кг.} = 1.64$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 244.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1052</p> <p> $F \text{ см}^2 = 2.610$ $Q \text{ кг.} = 0.707$ $D \text{ оп.мм} = 72.8$ $P \text{ н.мм} = 180.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1057</p> <p> $F \text{ см}^2 = 1.566$ $Q \text{ кг.} = 0.424$ $D \text{ оп.мм} = 38.5$ $P \text{ н.мм} = 115.6$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1053</p> <p> $F \text{ см}^2 = 6.840$ $Q \text{ кг.} = 1.854$ $D \text{ оп.мм} = 89.5$ $P \text{ н.мм} = 240.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1058</p> <p> $F \text{ см}^2 = 3.750$ $Q \text{ кг.} = 1.016$ $D \text{ оп.мм} = 58.3$ $P \text{ н.мм} = 160.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1054</p> <p> $F \text{ см}^2 = 4.710$ $Q \text{ кг.} = 1.276$ $D \text{ оп.мм} = 126.5$ $P \text{ н.мм} = 320.0$ Гр. сл. = V Точн. = Н </p>		<p>БПО-1059</p> <p> $F \text{ см}^2 = 2.010$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм} = 51.5$ $P \text{ н.мм} = 140.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1055</p> <p> $F \text{ см}^2 = 5.040$ $Q \text{ кг.} = 1.366$ $D \text{ оп.мм} = 94.3$ $P \text{ н.мм} = 260.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1060</p> <p> $F \text{ см}^2 = 23.750$ $Q \text{ кг.} = 6.436$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 172.7$ Гр. сл. = I Точн. = Н </p>











	<p>БПО-1051</p> <p> $F \text{ см}^2 = 1.410$ $Q \text{ кг.} = 0.382$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 100.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1056</p> <p> $F \text{ см}^2 = 6.040$ $Q \text{ кг.} = 1.64$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 244.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1052</p> <p> $F \text{ см}^2 = 2.610$ $Q \text{ кг.} = 0.707$ $D \text{ оп.мм} = 72.8$ $P \text{ н.мм} = 180.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1057</p> <p> $F \text{ см}^2 = 1.566$ $Q \text{ кг.} = 0.424$ $D \text{ оп.мм} = 38.5$ $P \text{ н.мм} = 115.6$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1053</p> <p> $F \text{ см}^2 = 6.840$ $Q \text{ кг.} = 1.854$ $D \text{ оп.мм} = 89.5$ $P \text{ н.мм} = 240.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1058</p> <p> $F \text{ см}^2 = 3.750$ $Q \text{ кг.} = 1.016$ $D \text{ оп.мм} = 58.3$ $P \text{ н.мм} = 160.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1054</p> <p> $F \text{ см}^2 = 4.710$ $Q \text{ кг.} = 1.276$ $D \text{ оп.мм} = 126.5$ $P \text{ н.мм} = 320.0$ Гр. сл. = V Точн. = Н </p>		<p>БПО-1059</p> <p> $F \text{ см}^2 = 2.010$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм} = 51.5$ $P \text{ н.мм} = 140.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1055</p> <p> $F \text{ см}^2 = 5.040$ $Q \text{ кг.} = 1.366$ $D \text{ оп.мм} = 94.3$ $P \text{ н.мм} = 260.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1060</p> <p> $F \text{ см}^2 = 23.750$ $Q \text{ кг.} = 6.436$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 172.7$ Гр. сл. = I Точн. = Н </p>











	<p>БПО-1071</p> <p> $F \text{ см}^2 = 1.000$ $Q \text{ кг.} = 0.271$ $D \text{ оп.мм} = 25.4$ $P \text{ н.мм} = 58.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1076</p> <p> $F \text{ см}^2 = 4.500$ $Q \text{ кг.} = 1.220$ $D \text{ оп.мм} = 33.5$ $P \text{ н.мм} = 90.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1072</p> <p> $F \text{ см}^2 = 2.020$ $Q \text{ кг.} = 0.547$ $D \text{ оп.мм} = 49.5$ $P \text{ н.мм} = 206.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1077</p> <p> $F \text{ см}^2 = 2.400$ $Q \text{ кг.} = 0.650$ $D \text{ оп.мм} = 40.4$ $P \text{ н.мм} = 92.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1073</p> <p> $F \text{ см}^2 = 2.880$ $Q \text{ кг.} = 0.780$ $D \text{ оп.мм} = 56.6$ $P \text{ н.мм} = 235.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1078</p> <p> $F \text{ см}^2 = 3.200$ $Q \text{ кг.} = 0.867$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 96.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1074</p> <p> $F \text{ см}^2 = 1.250$ $Q \text{ кг.} = 0.339$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 60.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1079</p> <p> $F \text{ см}^2 = 6.000$ $Q \text{ кг.} = 1.626$ $D \text{ оп.мм} = 42.7$ $P \text{ н.мм} = 110.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1075</p> <p> $F \text{ см}^2 = 6.000$ $Q \text{ кг.} = 1.626$ $D \text{ оп.мм} = 36.1$ $P \text{ н.мм} = 100.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1080</p> <p> $F \text{ см}^2 = 8.000$ $Q \text{ кг.} = 2.168$ $D \text{ оп.мм} = 44.7$ $P \text{ н.мм} = 120.0$ Гр. сл. = I Точн. = Н </p>










	БПО-1081 $F \text{ см}^2 = 7.500$ $Q \text{ кг.} = 2.03$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 130.0$ Гр. сл. = I Точн. = Н		БПО-1086 $F \text{ см}^2 = 6.000$ $Q \text{ кг.} = 1.626$ $D \text{ оп.мм} = 100.2$ $P \text{ н.мм} = 212.0$ Гр. сл. = II Точн. = Н
	БПО-1082 $F \text{ см}^2 = 7.000$ $Q \text{ кг.} = 1.9$ $D \text{ оп.мм} = 70.7$ $P \text{ н.мм} = 160.0$ Гр. сл. = I Точн. = Н		БПО-1087 $F \text{ см}^2 = 6.000$ $Q \text{ кг.} = 1.626$ $D \text{ оп.мм} = 120.5$ $P \text{ н.мм} = 250.0$ Гр. сл. = II Точн. = Н
	БПО-1083 $F \text{ см}^2 = 3.500$ $Q \text{ кг.} = 0.949$ $D \text{ оп.мм} = 71.8$ $P \text{ н.мм} = 150.0$ Гр. сл. = I Точн. = Н		БПО-1088 $F \text{ см}^2 = 9.500$ $Q \text{ кг.} = 2.575$ $D \text{ оп.мм} = 111.8$ $P \text{ н.мм} = 390.0$ Гр. сл. = III Точн. = Н
	БПО-1084 $F \text{ см}^2 = 4.800$ $Q \text{ кг.} = 1.301$ $D \text{ оп.мм} = 80.5$ $P \text{ н.мм} = 172.0$ Гр. сл. = I Точн. = Н		БПО-1089 $F \text{ см}^2 = 7.840$ $Q \text{ кг.} = 2.125$ $D \text{ оп.мм} = 158.1$ $P \text{ н.мм} = 400.0$ Гр. сл. = IV Точн. = Н
	БПО-1085 $F \text{ см}^2 = 5.000$ $Q \text{ кг.} = 1.356$ $D \text{ оп.мм} = 100.1$ $P \text{ н.мм} = 210.0$ Гр. сл. = II Точн. = Н		БПО-1090 $F \text{ см}^2 = 4.396$ $Q \text{ кг.} = 1.191$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 180.0$ Гр. сл. = IV Точн. = Н









			БПО-1096
			$F \text{ см}^2 = 2.750$ $Q \text{ кг.} = 0.745$ $D \text{ оп.мм} = 42.5$ $P \text{ н.мм} = 120.0$ $\text{Гр. сл.} = \text{I}$ $\text{Точн.} = \text{H}$
			БПО-1097
			$F \text{ см}^2 = 0.560$ $Q \text{ кг.} = 0.152$ $D \text{ оп.мм} = 22.4$ $P \text{ н.мм} = 60.0$ $\text{Гр. сл.} = \text{I}$ $\text{Точн.} = \text{H}$
	БПО-1093		БПО-1098
	$F \text{ см}^2 = 1.182$ $Q \text{ кг.} = 0.32$ $D \text{ оп.мм} = 22.9$ $P \text{ н.мм} = 108.1$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 4.800$ $Q \text{ кг.} = 1.301$ $D \text{ оп.мм} = 94.8$ $P \text{ н.мм} = 326.0$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
	БПО-1094		БПО-1099
	$F \text{ см}^2 = 2.940$ $Q \text{ кг.} = 0.797$ $D \text{ оп.мм} = 84.8$ $P \text{ н.мм} = 240.0$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 3.65$ $Q \text{ кг.} = 0.989$ $D \text{ оп.мм} = 88.0$ $P \text{ н.мм} = 428.3$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
	БПО-1095		БПО-1100
	$F \text{ см}^2 = 11.640$ $Q \text{ кг.} = 3.154$ $D \text{ оп.мм} = 141.4$ $P \text{ н.мм} = 400.0$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 1.169$ $Q \text{ кг.} = 0.317$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 109.6$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$











	<p>БПО-1101</p> <p> $F \text{ см}^2 = 0.935$ $Q \text{ кг.} = 0.253$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 119$ Гр. сл. = V Точн. = П </p>		<p>БПО-1106</p> <p> $F \text{ см}^2 = 4.320$ $Q \text{ кг.} = 1.171$ $D \text{ оп.мм} = 70.7$ $P \text{ н.мм} = 294.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1102</p> <p> $F \text{ см}^2 = 3.440$ $Q \text{ кг.} = 0.932$ $D \text{ оп.мм} = 67.1$ $P \text{ н.мм} = 180.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1107</p> <p> $F \text{ см}^2 = 4.020$ $Q \text{ кг.} = 1.09$ $D \text{ оп.мм} = 85.4$ $P \text{ н.мм} = 274.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1103</p> <p> $F \text{ см}^2 = 4.750$ $Q \text{ кг.} = 1.287$ $D \text{ оп.мм} = 72.1$ $P \text{ н.мм} = 200.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1108</p> <p> $F \text{ см}^2 = 5.220$ $Q \text{ кг.} = 1.415$ $D \text{ оп.мм} = 107.7$ $P \text{ н.мм} = 354.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1104</p> <p> $F \text{ см}^2 = 12.160$ $Q \text{ кг.} = 3.295$ $D \text{ оп.мм} = 113.1$ $P \text{ н.мм} = 320.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1109</p> <p> $F \text{ см}^2 = 0.450$ $Q \text{ кг.} = 0.122$ $D \text{ оп.мм} = 15.3$ $P \text{ н.мм} = 36.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1105</p> <p> $F \text{ см}^2 = 7.840$ $Q \text{ кг.} = 2.125$ $D \text{ оп.мм} = 141.4$ $P \text{ н.мм} = 400.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1110</p> <p> $F \text{ см}^2 = 2.500$ $Q \text{ кг.} = 0.678$ $D \text{ оп.мм} = 26.9$ $P \text{ н.мм} = 70.0$ Гр. сл. = I Точн. = Н </p>











	<p>БПО-1111</p> <p> $F \text{ см}^2 = 10.000$ $Q \text{ кг.} = 2.710$ $D \text{ оп.мм} = 53.85$ $P \text{ н.мм} = 140.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1116</p> <p> $F \text{ см}^2 = 1.760$ $Q \text{ кг.} = 0.477$ $D \text{ оп.мм} = 67.0$ $P \text{ н.мм} = 180.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1112</p> <p> $F \text{ см}^2 = 12.000$ $Q \text{ кг.} = 3.252$ $D \text{ оп.мм} = 120.4$ $P \text{ н.мм} = 260.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1117</p> <p> $F \text{ см}^2 = 4.750$ $Q \text{ кг.} = 1.287$ $D \text{ оп.мм} = 62.6$ $P \text{ н.мм} = 200.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1113</p> <p> $F \text{ см}^2 = 2.240$ $Q \text{ кг.} = 0.607$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 120.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1118</p> <p> $F \text{ см}^2 = 5.440$ $Q \text{ кг.} = 1.474$ $D \text{ оп.мм} = 136.6$ $P \text{ н.мм} = 327.9$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1114</p> <p> $F \text{ см}^2 = 1.2600$ $Q \text{ кг.} = 0.341$ $D \text{ оп.мм} = 47.2$ $P \text{ н.мм} = 130.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1119</p> <p> $F \text{ см}^2 = 3.463$ $Q \text{ кг.} = 0.938$ $D \text{ оп.мм} = 58.3$ $P \text{ н.мм} = 282.0$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1115</p> <p> $F \text{ см}^2 = 2.840$ $Q \text{ кг.} = 0.770$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 150.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1120</p> <p> $F \text{ см}^2 = 2.036$ $Q \text{ кг.} = 0.552$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 143.0$ Гр. сл. = 0соб. Точн. = Н </p>









	<p>БПО-1121</p> <p> $F \text{ см}^2 = 18.000$ $Q \text{ кг.} = 4.878$ $D \text{ оп.мм} = 120.9$ $P \text{ н.мм} = 270.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1126</p> <p> $F \text{ см}^2 = 4.590$ $Q \text{ кг.} = 1.244$ $D \text{ оп.мм} = 44.7$ $P \text{ н.мм} = 211.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1122</p> <p> $F \text{ см}^2 = 1.876$ $Q \text{ кг.} = 0.508$ $D \text{ оп.мм} = 45.3$ $P \text{ н.мм} = 196.4$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1127</p> <p> $F \text{ см}^2 = 0.780$ $Q \text{ кг.} = 0.211$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 105.9$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1123</p> <p> $F \text{ см}^2 = 7.930$ $Q \text{ кг.} = 2.149$ $D \text{ оп.мм} = 116.0$ $P \text{ н.мм} = 385.0$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1128</p> <p> $F \text{ см}^2 = 8.500$ $Q \text{ кг.} = 2.304$ $D \text{ оп.мм} = 94.4$ $P \text{ н.мм} = 350.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1124</p> <p> $F \text{ см}^2 = 8.270$ $Q \text{ кг.} = 2.241$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 357.0$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1129</p> <p> $F \text{ см}^2 = 1.000$ $Q \text{ кг.} = 0.271$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 104.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1125</p> <p> $F \text{ см}^2 = 2.180$ $Q \text{ кг.} = 0.591$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 142.8$ Гр. сл. = II Точн. = П </p>		<p>БПО-1130</p> <p> $F \text{ см}^2 = 15.000$ $Q \text{ кг.} = 4.065$ $D \text{ оп.мм} = 58.3$ $P \text{ н.мм} = 160.0$ Гр. сл. = I Точн. = Н </p>











	<p>БПО-1131</p> <p> $F \text{ см}^2 = 24.000$ $Q \text{ кг.} = 6.504$ $D \text{ оп.мм} = 72.1$ $P \text{ н.мм} = 200.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1136</p> <p> $F \text{ см}^2 = 1.120$ $Q \text{ кг.} = 0.304$ $D \text{ оп.мм} = 42.9$ $P \text{ н.мм} = 116.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1132</p> <p> $F \text{ см}^2 = 12.000$ $Q \text{ кг.} = 3.252$ $D \text{ оп.мм} = 81.4$ $P \text{ н.мм} = 190.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1137</p> <p> $F \text{ см}^2 = 5.700$ $Q \text{ кг.} = 1.545$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 348.0$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1133</p> <p> $F \text{ см}^2 = 4.640$ $Q \text{ кг.} = 1.257$ $D \text{ оп.мм} = 75.0$ $P \text{ н.мм} = 240.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1138</p> <p> $F \text{ см}^2 = 5.820$ $Q \text{ кг.} = 1.997$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 409.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1134</p> <p> $F \text{ см}^2 = 1.600$ $Q \text{ кг.} = 0.434$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 88.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1139</p> <p> $F \text{ см}^2 = 7.100$ $Q \text{ кг.} = 1.924$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 402.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1135</p> <p> $F \text{ см}^2 = 1.600$ $Q \text{ кг.} = 0.434$ $D \text{ оп.мм} = 21.5$ $P \text{ н.мм} = 56.0$ Гр. сл. = I Точн. = Н </p>		











			БПО-1146 $F \text{ см}^2 = 5.04$ $Q \text{ кг.} = 1.366$ $D \text{ оп.мм} = 89.4$ $P \text{ н.мм} = 382.6$ Гр. сл. = VI Точн. = П
			БПО-1147 $F \text{ см}^2 = 5.280$ $Q \text{ кг.} = 1.431$ $D \text{ оп.мм} = 72.1$ $P \text{ н.мм} = 272.0$ Гр. сл. = II Точн. = Н
	БПО-1143 $F \text{ см}^2 = 1.570$ $Q \text{ кг.} = 0.425$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 241.0$ Гр. сл. = 0соб. Точн. = П		БПО-1148 $F \text{ см}^2 = 4.230$ $Q \text{ кг.} = 1.146$ $D \text{ оп.мм} = 82.7$ $P \text{ н.мм} = 343.0$ Гр. сл. = IV Точн. = Н
	БПО-1144 $F \text{ см}^2 = 6.269$ $Q \text{ кг.} = 1.699$ $D \text{ оп.мм} = 153.0$ $P \text{ н.мм} = 340.7$ Гр. сл. = III Точн. = Н		БПО-1149 $F \text{ см}^2 = 8.000$ $Q \text{ кг.} = 2.168$ $D \text{ оп.мм} = 100.2$ $P \text{ н.мм} = 216.0$ Гр. сл. = I Точн. = Н
	БПО-1145 $F \text{ см}^2 = 3.31$ $Q \text{ кг.} = 0.897$ $D \text{ оп.мм} = 42.2$ $P \text{ н.мм} = 147.8$ Гр. сл. = II Точн. = Н		БПО-1150 $F \text{ см}^2 = 2.000$ $Q \text{ кг.} = 0.542$ $D \text{ оп.мм} = 26.2$ $P \text{ н.мм} = 66.0$ Гр. сл. = I Точн. = Н











	<p>БПО-1151</p> <p> $F \text{ см}^2 = 5.820$ $Q \text{ кг.} = 1.577$ $D \text{ оп.мм} = 126.0$ $P \text{ н.мм} = 394.0$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-1156</p> <p> $F \text{ см}^2 = 0.638$ $Q \text{ кг.} = 0.173$ $D \text{ оп.мм} = 17.8$ $P \text{ н.мм} = 89.3$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1152</p> <p> $F \text{ см}^2 = 1.080$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 78.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1157</p> <p> $F \text{ см}^2 = 12.000$ $Q \text{ кг.} = 3.252$ $D \text{ оп.мм} = 63.0$ $P \text{ н.мм} = 160.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1153</p> <p> $F \text{ см}^2 = 9.680$ $Q \text{ кг.} = 2.623$ $D \text{ оп.мм} = 143.0$ $P \text{ н.мм} = 492.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1158</p> <p> $F \text{ см}^2 = 3.040$ $Q \text{ кг.} = 0.824$ $D \text{ оп.мм} = 54.6$ $P \text{ н.мм} = 160.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1154</p> <p> $F \text{ см}^2 = 0.530$ $Q \text{ кг.} = 0.144$ $D \text{ оп.мм} = 25.2$ $P \text{ н.мм} = 27.7$ Гр. сл. = III Точн. = П </p>		<p>БПО-1159</p> <p> $F \text{ см}^2 = 3.440$ $Q \text{ кг.} = 0.932$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 180.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1155</p> <p> $F \text{ см}^2 = 1.19$ $Q \text{ кг.} = 0.322$ $D \text{ оп.мм} = 35.3$ $P \text{ н.мм} = 157.1$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1160</p> <p> $F \text{ см}^2 = 11.000$ $Q \text{ кг.} = 2.981$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 240.0$ Гр. сл. = I Точн. = Н </p>











	<p>БПО-1161</p> <p> $F \text{ см}^2 = 3.449$ $Q \text{ кг.} = 0.935$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 350.4$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1166</p> <p> $F \text{ см}^2 = 0.790$ $Q \text{ кг.} = 0.214$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 134.0$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1162</p> <p> $F \text{ см}^2 = 1.728$ $Q \text{ кг.} = 0.468$ $D \text{ оп.мм} = 23.7$ $P \text{ н.мм} = 108.9$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1167</p> <p> $F \text{ см}^2 = 1.340$ $Q \text{ кг.} = 0.363$ $D \text{ оп.мм} = 47.4$ $P \text{ н.мм} = 162.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1163</p> <p> $F \text{ см}^2 = 1.600$ $Q \text{ кг.} = 0.434$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 164.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1168</p> <p> $F \text{ см}^2 = 0.680$ $Q \text{ кг.} = 0.184$ $D \text{ оп.мм} = 17.0$ $P \text{ н.мм} = 79.4$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1164</p> <p> $F \text{ см}^2 = 2.020$ $Q \text{ кг.} = 0.547$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 217.0$ Гр. сл. = V Точн. = Н </p>		<p>БПО-1169</p> <p> $F \text{ см}^2 = 2.220$ $Q \text{ кг.} = 0.602$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 292.0$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1165</p> <p> $F \text{ см}^2 = 0.420$ $Q \text{ кг.} = 0.114$ $D \text{ оп.мм} = 13.7$ $P \text{ н.мм} = 56.0$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1170</p> <p> $F \text{ см}^2 = 2.382$ $Q \text{ кг.} = 0.646$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 152.0$ Гр. сл. = IV Точн. = П </p>










	БПО-1171 $F \text{ см}^2 = 6.333$ $Q \text{ кг.} = 1.716$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 344.8$ Гр. сл. = VI Точн. = П		БПО-1176 $F \text{ см}^2 = 1.706$ $Q \text{ кг.} = 0.462$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 159.5$ Гр. сл. = V Точн. = П
	БПО-1172 $F \text{ см}^2 = 10.800$ $Q \text{ кг.} = 2.927$ $D \text{ оп.мм} = 75.0$ $P \text{ н.мм} = 713.0$ Гр. сл. = 0соб. Точн. = П		БПО-1177 $F \text{ см}^2 = 1.734$ $Q \text{ кг.} = 0.470$ $D \text{ оп.мм} = 37.7$ $P \text{ н.мм} = 115.2$ Гр. сл. = III Точн. = П
	БПО-1173 $F \text{ см}^2 = 0.469$ $Q \text{ кг.} = 0.127$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 70.6$ Гр. сл. = IV Точн. = П		БПО-1178 $F \text{ см}^2 = 15.000$ $Q \text{ кг.} = 4.065$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 1263$ Гр. сл. = VI Точн. = П
			БПО-1179 $F \text{ см}^2 = 3.060$ $Q \text{ кг.} = 0.829$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 370.2$ Гр. сл. = VI Точн. = П
			БПО-1180 $F \text{ см}^2 = 1.060$ $Q \text{ кг.} = 0.287$ $D \text{ оп.мм} = 29.6$ $P \text{ н.мм} = 110.0$ Гр. сл. = II Точн. = Н











	<p>БПО-1181</p> <p> $F \text{ см}^2 = 0.720$ $Q \text{ кг.} = 0.195$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 57.7$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1186</p> <p> $F \text{ см}^2 = 0.672$ $Q \text{ кг.} = 0.182$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 92.6$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1182</p> <p> $F \text{ см}^2 = 0.650$ $Q \text{ кг.} = 0.176$ $D \text{ оп.мм} = 22.4$ $P \text{ н.мм} = 102.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1187</p> <p> $F \text{ см}^2 = 0.570$ $Q \text{ кг.} = 0.154$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 75.1$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1183</p> <p> $F \text{ см}^2 = 0.804$ $Q \text{ кг.} = 0.218$ $D \text{ оп.мм} = 33.1$ $P \text{ н.мм} = 111.7$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1188</p> <p> $F \text{ см}^2 = 0.665$ $Q \text{ кг.} = 0.180$ $D \text{ оп.мм} = 30.5$ $P \text{ н.мм} = 91.8$ Гр. сл. = III Точн. = П </p>
	<p>БПО-1184</p> <p> $F \text{ см}^2 = 0.771$ $Q \text{ кг.} = 0.209$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 115.1$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1189</p> <p> $F \text{ см}^2 = 0.513$ $Q \text{ кг.} = 0.139$ $D \text{ оп.мм} = 11.0$ $P \text{ н.мм} = 50.9$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1185</p> <p> $F \text{ см}^2 = 0.550$ $Q \text{ кг.} = 0.149$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 63.3$ Гр. сл. = III Точн. = П </p>		<p>БПО-1190</p> <p> $F \text{ см}^2 = 0.514$ $Q \text{ кг.} = 0.139$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 78.1$ Гр. сл. = IV Точн. = П </p>











	БПО-1191 $F \text{ см}^2 = 0.995$ $Q \text{ кг.} = 0.270$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 139.0$ Гр. сл. = IV Точн. = П		БПО-1196 $F \text{ см}^2 = 3.320$ $Q \text{ кг.} = 0.900$ $D \text{ оп.мм} = 162.0$ $P \text{ н.мм} = 336$ Гр. сл. = II Точн. = Н
	БПО-1192 $F \text{ см}^2 = 3.700$ $Q \text{ кг.} = 1.003$ $D \text{ оп.мм} = 97.3$ $P \text{ н.мм} = 262.9$ Гр. сл. = VI Точн. = П		БПО-1197 $F \text{ см}^2 = 1.920$ $Q \text{ кг.} = 0.520$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 175.8$ Гр. сл. = 0соб. Точн. = Н
	БПО-1193 $F \text{ см}^2 = 1.440$ $Q \text{ кг.} = 0.390$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 101.6$ Гр. сл. = III Точн. = Н		БПО-1198 $F \text{ см}^2 = 1.100$ $Q \text{ кг.} = 0.298$ $D \text{ оп.мм} = 54.5$ $P \text{ н.мм} = 163.0$ Гр. сл. = VI Точн. = Н
	БПО-1194 $F \text{ см}^2 = 1.800$ $Q \text{ кг.} = 0.488$ $D \text{ оп.мм} = 52.3$ $P \text{ н.мм} = 240.0$ Гр. сл. = VI Точн. = Н		БПО-1199 $F \text{ см}^2 = 1.604$ $Q \text{ кг.} = 0.435$ $D \text{ оп.мм} = 50.8$ $P \text{ н.мм} = 182.0$ Гр. сл. = V Точн. = Н
	БПО-1195 $F \text{ см}^2 = 2.02$ $Q \text{ кг.} = 0.547$ $D \text{ оп.мм} = 116.0$ $P \text{ н.мм} = 242.2$ Гр. сл. = II Точн. = Н		БПО-1200 $F \text{ см}^2 = 5.890$ $Q \text{ кг.} = 1.596$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 404.7$ Гр. сл. = 0соб. Точн. = Н











	<p>БПО-1201</p> <p> $F \text{ см}^2 = 1.650$ $Q \text{ кг.} = 0.45$ $D \text{ оп.мм} = 33.5$ $P \text{ н.мм} = 154.1$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1206</p> <p> $F \text{ см}^2 = 1.400$ $Q \text{ кг.} = 0.38$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 87.6$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1202</p> <p> $F \text{ см}^2 = 4.3$ $Q \text{ кг.} = 1.165$ $D \text{ оп.мм} = 63.6$ $P \text{ н.мм} = 177.9$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1207</p> <p> $F \text{ см}^2 = 1.070$ $Q \text{ кг.} = 0.290$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 106.9$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1203</p> <p> $F \text{ см}^2 = 7.974$ $Q \text{ кг.} = 2.161$ $D \text{ оп.мм} = 78.1$ $P \text{ н.мм} = 217.8$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1208</p> <p> $F \text{ см}^2 = 0.500$ $Q \text{ кг.} = 0.136$ $D \text{ оп.мм} = 20.8$ $P \text{ н.мм} = 65.5$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1204</p> <p> $F \text{ см}^2 = 1.260$ $Q \text{ кг.} = 0.341$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 130.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1209</p> <p> $F \text{ см}^2 = 0.600$ $Q \text{ кг.} = 0.163$ $D \text{ оп.мм} = 21.5$ $P \text{ н.мм} = 49.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1205</p> <p> $F \text{ см}^2 = 2.420$ $Q \text{ кг.} = 0.656$ $D \text{ оп.мм} = 51.4$ $P \text{ н.мм} = 161.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1210</p> <p> $F \text{ см}^2 = 2.920$ $Q \text{ кг.} = 0.791$ $D \text{ оп.мм} = 90.8$ $P \text{ н.мм} = 331.4$ Гр. сл. = 0соб. Точн. = Н </p>











	<p>БПО-1211</p> <p> $F \text{ см}^2 = 1.487$ $Q \text{ кг.} = 0.403$ $D \text{ оп.мм} = 36.6$ $P \text{ н.мм} = 135.4$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1216</p> <p> $F \text{ см}^2 = 4.800$ $Q \text{ кг.} = 1.301$ $D \text{ оп.мм} = 41.7$ $P \text{ н.мм} = 104.0$ Гр. сл. = i Точн. = Н </p>
	<p>БПО-1212</p> <p> $F \text{ см}^2 = 5.100$ $Q \text{ кг.} = 1.382$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 286.4$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1217</p> <p> $F \text{ см}^2 = 15.000$ $Q \text{ кг.} = 4.065$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 170.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1213</p> <p> $F \text{ см}^2 = 0.506$ $Q \text{ кг.} = 0.137$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 71.5$ Гр. сл. = V Точн. = Н </p>		<p>БПО-1218</p> <p> $F \text{ см}^2 = 16.000$ $Q \text{ кг.} = 4.336$ $D \text{ оп.мм} = 82.5$ $P \text{ н.мм} = 200.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1214</p> <p> $F \text{ см}^2 = 6.060$ $Q \text{ кг.} = 1.642$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 225.3$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1219</p> <p> $F \text{ см}^2 = 1.960$ $Q \text{ кг.} = 0.531$ $D \text{ оп.мм} = 82.5$ $P \text{ н.мм} = 200.0$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-1215</p> <p> $F \text{ см}^2 = 0.789$ $Q \text{ кг.} = 0.214$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 96.3$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1220</p> <p> $F \text{ см}^2 = 12.250$ $Q \text{ кг.} = 3.320$ $D \text{ оп.мм} = 49.5$ $P \text{ н.мм} = 140.0$ Гр. сл. = II Точн. = Н </p>

	БПО-1221 $F \text{ см}^2 = 12.160$ $Q \text{ кг.} = 3.295$ $D \text{ оп.мм} = 164.0$ $P \text{ н.мм} = 616.5$ Гр. сл. = V Точн. = П		БПО-1226 $F \text{ см}^2 = 6.12$ $Q \text{ кг.} = 1.659$ $D \text{ оп.мм} = 144.1$ $P \text{ н.мм} = 387.1$ Гр. сл. = V Точн. = Н
	БПО-1222 $F \text{ см}^2 = 27.200$ $Q \text{ кг.} = 7.371$ $D \text{ оп.мм} = 102.0$ $P \text{ н.мм} = 2157.0$ Гр. сл. = VI Точн. = П		
	БПО-1223 $F \text{ см}^2 = 5.249$ $Q \text{ кг.} = 1.422$ $D \text{ оп.мм} = 136.0$ $P \text{ н.мм} = 338.2$ Гр. сл. = IV Точн. = П		БПО-1228 $F \text{ см}^2 = 6.712$ $Q \text{ кг.} = 1.819$ $D \text{ оп.мм} = 139.0$ $P \text{ н.мм} = 462.7$ Гр. сл. = IV Точн. = П
	БПО-1224 $F \text{ см}^2 = 9.750$ $Q \text{ кг.} = 2.642$ $D \text{ оп.мм} = 144.0$ $P \text{ н.мм} = 400.0$ Гр. сл. = III Точн. = Н		БПО-1229 $F \text{ см}^2 = 5.970$ $Q \text{ кг.} = 1.618$ $D \text{ оп.мм} = 180.0$ $P \text{ н.мм} = 657.0$ Гр. сл. = VI Точн. = П
	БПО-1225 $F \text{ см}^2 = 13.495$ $Q \text{ кг.} = 3.657$ $D \text{ оп.мм} = 114.7$ $P \text{ н.мм} = 929.8$ Гр. сл. = III Точн. = Н		БПО-1230 $F \text{ см}^2 = 1.100$ $Q \text{ кг.} = 0.298$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 141.6$ Гр. сл. = VI Точн. = П











	<p>БПО-1231</p> <p> $F \text{ см}^2 = 0.400$ $Q \text{ кг.} = 0.108$ $D \text{ оп.мм} = 80.3$ $P \text{ н.мм} = 44.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1236</p> <p> $F \text{ см}^2 = 4.900$ $Q \text{ кг.} = 1.328$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 78.5$ Гр. сл. = i Точн. = Н </p>
	<p>БПО-1232</p> <p> $F \text{ см}^2 = 0.771$ $Q \text{ кг.} = 0.209$ $D \text{ оп.мм} = 27.8$ $P \text{ н.мм} = 103.6$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1237</p> <p> $F \text{ см}^2 = 3.294$ $Q \text{ кг.} = 0.893$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 234.4$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1233</p> <p> $F \text{ см}^2 = 12.200$ $Q \text{ кг.} = 3.306$ $D \text{ оп.мм} = 183.0$ $P \text{ н.мм} = 700.0$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1238</p> <p> $F \text{ см}^2 = 15.890$ $Q \text{ кг.} = 4.306$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 1230.0$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-1234</p> <p> $F \text{ см}^2 = 0.600$ $Q \text{ кг.} = 0.163$ $D \text{ оп.мм} = 20.2$ $P \text{ н.мм} = 46.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1239</p> <p> $F \text{ см}^2 = 0.400$ $Q \text{ кг.} = 0.108$ $D \text{ оп.мм} = 16.2$ $P \text{ н.мм} = 37.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1235</p> <p> $F \text{ см}^2 = 1.769$ $Q \text{ кг.} = 0.479$ $D \text{ оп.мм} = 53.9$ $P \text{ н.мм} = 123.9$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1240</p> <p> $F \text{ см}^2 = 1.200$ $Q \text{ кг.} = 0.325$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 52.0$ Гр. сл. = I Точн. = Н </p>











	<p>БПО-1241</p> <p> $F \text{ см}^2 = 0.43$ $Q \text{ кг.} = 0.117$ $D \text{ оп.мм} = 16.2$ $P \text{ н.мм} = 80.8$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1246</p> <p> $F \text{ см}^2 = 4.000$ $Q \text{ кг.} = 1.084$ $D \text{ оп.мм} = 28.3$ $P \text{ н.мм} = 80.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1242</p> <p> $F \text{ см}^2 = 3.37$ $Q \text{ кг.} = 0.913$ $D \text{ оп.мм} = 72.5$ $P \text{ н.мм} = 367.13$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1247</p> <p> $F \text{ см}^2 = 6.250$ $Q \text{ кг.} = 1.694$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 100.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1243</p> <p> $F \text{ см}^2 = 1.799$ $Q \text{ кг.} = 0.488$ $D \text{ оп.мм} = 37.5$ $P \text{ н.мм} = 203.5$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1248</p> <p> $F \text{ см}^2 = 9.000$ $Q \text{ кг.} = 2.439$ $D \text{ оп.мм} = 42.4$ $P \text{ н.мм} = 120.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1244</p> <p> $F \text{ см}^2 = 1.679$ $Q \text{ кг.} = 0.455$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 214.74$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1249</p> <p> $F \text{ см}^2 = 0.570$ $Q \text{ кг.} = 0.154$ $D \text{ оп.мм} = 28.3$ $P \text{ н.мм} = 80.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1245</p> <p> $F \text{ см}^2 = 3.48$ $Q \text{ кг.} = 0.943$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 391.64$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1250</p> <p> $F \text{ см}^2 = 0.728$ $Q \text{ кг.} = 0.197$ $D \text{ оп.мм} = 35.3$ $P \text{ н.мм} = 100.0$ Гр. сл. = III Точн. = Н </p>











	<p>БПО-1251</p> <p> $F \text{ см}^2 = 0.878$ $Q \text{ кг.} = 0.238$ $D \text{ оп.мм} = 42.4$ $P \text{ н.мм} = 120.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1256</p> <p> $F \text{ см}^2 = 0.600$ $Q \text{ кг.} = 0.163$ $D \text{ оп.мм} = 15.5$ $P \text{ н.мм} = 38.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1252</p> <p> $F \text{ см}^2 = 2.360$ $Q \text{ кг.} = 0.640$ $D \text{ оп.мм} = 84.9$ $P \text{ н.мм} = 240.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1257</p> <p> $F \text{ см}^2 = 1.200$ $Q \text{ кг.} = 0.325$ $D \text{ оп.мм} = 17.0$ $P \text{ н.мм} = 46.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1253</p> <p> $F \text{ см}^2 = 0.960$ $Q \text{ кг.} = 0.260$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 70.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1258</p> <p> $F \text{ см}^2 = 2.820$ $Q \text{ кг.} = 0.764$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 194.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1254</p> <p> $F \text{ см}^2 = 0.860$ $Q \text{ кг.} = 0.233$ $D \text{ оп.мм} = 92.0$ $P \text{ н.мм} = 90.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1259</p> <p> $F \text{ см}^2 = 2.800$ $Q \text{ кг.} = 0.759$ $D \text{ оп.мм} = 35.9$ $P \text{ н.мм} = 86.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1255</p> <p> $F \text{ см}^2 = 1.060$ $Q \text{ кг.} = 0.287$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 110.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1260</p> <p> $F \text{ см}^2 = 3.500$ $Q \text{ кг.} = 0.949$ $D \text{ оп.мм} = 36.4$ $P \text{ н.мм} = 90.0$ Гр. сл. = I Точн. = Н </p>











	<p>БПО-1261</p> <p> $F \text{ см}^2 = 10.500$ $Q \text{ кг.} = 2.846$ $D \text{ оп.мм} = 46.1$ $P \text{ н.мм} = 130.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1266</p> <p> $F \text{ см}^2 = 1.060$ $Q \text{ кг.} = 0.287$ $D \text{ оп.мм} = 42.7$ $P \text{ н.мм} = 110.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1262</p> <p> $F \text{ см}^2 = 0.785$ $Q \text{ кг.} = 0.213$ $D \text{ оп.мм} = 10.0$ $P \text{ н.мм} = 31.4$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1267</p> <p> $F \text{ см}^2 = 2.640$ $Q \text{ кг.} = 0.715$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 140.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1263</p> <p> $F \text{ см}^2 = 1.767$ $Q \text{ кг.} = 0.479$ $D \text{ оп.мм} = 15.0$ $P \text{ н.мм} = 47.1$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1268</p> <p> $F \text{ см}^2 = 0.760$ $Q \text{ кг.} = 0.206$ $D \text{ оп.мм} = 25.2$ $P \text{ н.мм} = 80.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1264</p> <p> $F \text{ см}^2 = 1.060$ $Q \text{ кг.} = 0.287$ $D \text{ оп.мм} = 40.3$ $P \text{ н.мм} = 110.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1269</p> <p> $F \text{ см}^2 = 1.160$ $Q \text{ кг.} = 0.314$ $D \text{ оп.мм} = 37.5$ $P \text{ н.мм} = 120.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1265</p> <p> $F \text{ см}^2 = 7.068$ $Q \text{ кг.} = 1.915$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 94.3$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1270</p> <p> $F \text{ см}^2 = 1.710$ $Q \text{ кг.} = 0.463$ $D \text{ оп.мм} = 37.5$ $P \text{ н.мм} = 120.0$ Гр. сл. = I Точн. = Н </p>

	<p>БПО-1271</p> <p> $F \text{ см}^2 = 2.968$ $Q \text{ кг.} = 0.804$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 142.7$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1276</p> <p> $F \text{ см}^2 = 0.559$ $Q \text{ кг.} = 0.151$ $D \text{ оп.мм} = 25.9$ $P \text{ н.мм} = 74.6$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1272</p> <p> $F \text{ см}^2 = 5.865$ $Q \text{ кг.} = 1.589$ $D \text{ оп.мм} = 92.4$ $P \text{ н.мм} = 294.1$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1277</p> <p> $F \text{ см}^2 = 0.887$ $Q \text{ кг.} = 0.240$ $D \text{ оп.мм} = 30.3$ $P \text{ н.мм} = 116.1$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1273</p> <p> $F \text{ см}^2 = 1.520$ $Q \text{ кг.} = 0.412$ $D \text{ оп.мм} = 44.7$ $P \text{ н.мм} = 156.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1278</p> <p> $F \text{ см}^2 = 1.360$ $Q \text{ кг.} = 0.369$ $D \text{ оп.мм} = 51.6$ $P \text{ н.мм} = 173.8$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1274</p> <p> $F \text{ см}^2 = 2.220$ $Q \text{ кг.} = 0.602$ $D \text{ оп.мм} = 44.7$ $P \text{ н.мм} = 154.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1279</p> <p> $F \text{ см}^2 = 1.228$ $Q \text{ кг.} = 0.27$ $D \text{ оп.мм} = 46.2$ $P \text{ н.мм} = 164$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1275</p> <p> $F \text{ см}^2 = 1.320$ $Q \text{ кг.} = 0.358$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 136.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1280</p> <p> $F \text{ см}^2 = 0.864$ $Q \text{ кг.} = 0.234$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 89.13$ Гр. сл. = III Точн. = Н </p>











	<p>БПО-1281</p> <p> $F \text{ см}^2 = 1.41$ $Q \text{ кг.} = 0.385$ $D \text{ оп.мм} = 34.3$ $P \text{ н.мм} = 169.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1286</p> <p> $F \text{ см}^2 = 2.91$ $Q \text{ кг.} = 0.789$ $D \text{ оп.мм} = 89.6$ $P \text{ н.мм} = 383.8$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1282</p> <p> $F \text{ см}^2 = 1.610$ $Q \text{ кг.} = 0.436$ $D \text{ оп.мм} = 34.6$ $P \text{ н.мм} = 169.4$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1287</p> <p> $F \text{ см}^2 = 3.074$ $Q \text{ кг.} = 0.833$ $D \text{ оп.мм} = 128.0$ $P \text{ н.мм} = 380.8$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1283</p> <p> $F \text{ см}^2 = 2.37$ $Q \text{ кг.} = 0.642$ $D \text{ оп.мм} = 69.0$ $P \text{ н.мм} = 310.3$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1288</p> <p> $F \text{ см}^2 = 0.997$ $Q \text{ кг.} = 0.27$ $D \text{ оп.мм} = 37.4$ $P \text{ н.мм} = 137.3$ Гр. сл. = III Точн. = П </p>
	<p>БПО-1284</p> <p> $F \text{ см}^2 = 2.203$ $Q \text{ кг.} = 0.597$ $D \text{ оп.мм} = 56.14$ $P \text{ н.мм} = 223$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1289</p> <p> $F \text{ см}^2 = 2.300$ $Q \text{ кг.} = 0.623$ $D \text{ оп.мм} = 78.5$ $P \text{ н.мм} = 288.7$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1285</p> <p> $F \text{ см}^2 = 0.584$ $Q \text{ кг.} = 0.158$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 67$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1290</p> <p> $F \text{ см}^2 = 8.240$ $Q \text{ кг.} = 2.233$ $D \text{ оп.мм} = 148.4$ $P \text{ н.мм} = 695.0$ Гр. сл. = 0соб. Точн. = Н </p>










	<p>БПО-1291</p> <p> $F \text{ см}^2 = 3.040$ $Q \text{ кг.} = 0.824$ $D \text{ оп.мм} = 132.0$ $P \text{ н.мм} = 294.0$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1296</p> <p> $F \text{ см}^2 = 2.188$ $Q \text{ кг.} = 0.593$ $D \text{ оп.мм} = 75.8$ $P \text{ н.мм} = 272.1$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1292</p> <p> $F \text{ см}^2 = 2.174$ $Q \text{ кг.} = 0.589$ $D \text{ оп.мм} = 48.8$ $P \text{ н.мм} = 238.2$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1297</p> <p> $F \text{ см}^2 = 1.583$ $Q \text{ кг.} = 0.429$ $D \text{ оп.мм} = 48.6$ $P \text{ н.мм} = 186.6$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-1293</p> <p> $F \text{ см}^2 = 2.495$ $Q \text{ кг.} = 0.676$ $D \text{ оп.мм} = 65.3$ $P \text{ н.мм} = 310.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-1298</p> <p> $F \text{ см}^2 = 2.754$ $Q \text{ кг.} = 0.746$ $D \text{ оп.мм} = 63.0$ $P \text{ н.мм} = 335.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1294</p> <p> $F \text{ см}^2 = 1.703$ $Q \text{ кг.} = 0.462$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 234.9$ Гр. сл. = 0соб. Точн. = 0соб. </p>		<p>БПО-1299</p> <p> $F \text{ см}^2 = 1.776$ $Q \text{ кг.} = 0.481$ $D \text{ оп.мм} = 97.0$ $P \text{ н.мм} = 228.5$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-1295</p> <p> $F \text{ см}^2 = 2.385$ $Q \text{ кг.} = 0.646$ $D \text{ оп.мм} = 62.0$ $P \text{ н.мм} = 293.4$ Гр. сл. = V Точн. = П </p>		<p>БПО-1300</p> <p> $F \text{ см}^2 = 1.280$ $Q \text{ кг.} = 0.347$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 140.5$ Гр. сл. = V Точн. = П </p>










	<p>БПО-1301</p> <p> $F \text{ см}^2 = 3.584$ $Q \text{ кг.} = 0.971$ $D \text{ оп.мм} = 67.2$ $P \text{ н.мм} = 397.8$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1306</p> <p> $F \text{ см}^2 = 2.758$ $Q \text{ кг.} = 0.747$ $D \text{ оп.мм} = 139.9$ $P \text{ н.мм} = 354.4$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-1302</p> <p> $F \text{ см}^2 = 2.906$ $Q \text{ кг.} = 0.788$ $D \text{ оп.мм} = 67.2$ $P \text{ н.мм} = 370.16$ Гр. сл. = V Точн. = П </p>		<p>БПО-1307</p> <p> $F \text{ см}^2 = 1.18$ $Q \text{ кг.} = 0.32$ $D \text{ оп.мм} = 52.3$ $P \text{ н.мм} = 154.4$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1303</p> <p> $F \text{ см}^2 = 2.767$ $Q \text{ кг.} = 0.750$ $D \text{ оп.мм} = 63.1$ $P \text{ н.мм} = 313.9$ Гр. сл. = V Точн. = П </p>		<p>БПО-1308</p> <p> $F \text{ см}^2 = 1.362$ $Q \text{ кг.} = 0.369$ $D \text{ оп.мм} = 50.8$ $P \text{ н.мм} = 159.5$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1304</p> <p> $F \text{ см}^2 = 1.45$ $Q \text{ кг.} = 0.393$ $D \text{ оп.мм} = 42.4$ $P \text{ н.мм} = 174.9$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1309</p> <p> $F \text{ см}^2 = 1.165$ $Q \text{ кг.} = 0.316$ $D \text{ оп.мм} = 60.3$ $P \text{ н.мм} = 153.9$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-1305</p> <p> $F \text{ см}^2 = 0.859$ $Q \text{ кг.} = 0.233$ $D \text{ оп.мм} = 42.9$ $P \text{ н.мм} = 108.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-1310</p> <p> $F \text{ см}^2 = 7.961$ $Q \text{ кг.} = 2.157$ $D \text{ оп.мм} = 203.6$ $P \text{ н.мм} = 633.6$ Гр. сл. = 0соб. Точн. = П </p>







	<p>БПО-1311</p> <p> $F \text{ см}^2 = 1.146$ $Q \text{ кг.} = 0.311$ $D \text{ оп.мм} = 60.3$ $P \text{ н.мм} = 145.1$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1316</p> <p> $F \text{ см}^2 = 2.763$ $Q \text{ кг.} = 0.749$ $D \text{ оп.мм} = 65.7$ $P \text{ н.мм} = 355.14$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-1312</p> <p> $F \text{ см}^2 = 2.65$ $Q \text{ кг.} = 0.718$ $D \text{ оп.мм} = 68.2$ $P \text{ н.мм} = 337.7$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1317</p> <p> $F \text{ см}^2 = 3.749$ $Q \text{ кг.} = 1.016$ $D \text{ оп.мм} = 87.4$ $P \text{ н.мм} = 479.6$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-1313</p> <p> $F \text{ см}^2 = 1.697$ $Q \text{ кг.} = 0.460$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 218.9$ Гр. сл. = Точн. = П </p>		<p>БПО-1318</p> <p> $F \text{ см}^2 = 1.422$ $Q \text{ кг.} = 0.385$ $D \text{ оп.мм} = 69.5$ $P \text{ н.мм} = 185.0$ Гр. сл. = II Точн. = П </p>
	<p>БПО-1314</p> <p> $F \text{ см}^2 = 2.110$ $Q \text{ кг.} = 0.572$ $D \text{ оп.мм} = 61.7$ $P \text{ н.мм} = 272.1$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1319</p> <p> $F \text{ см}^2 = 2.927$ $Q \text{ кг.} = 0.793$ $D \text{ оп.мм} = 76.0$ $P \text{ н.мм} = 179.1$ Гр. сл. = II Точн. = П </p>
	<p>БПО-1315</p> <p> $F \text{ см}^2 = 2.740$ $Q \text{ кг.} = 0.743$ $D \text{ оп.мм} = 86.7$ $P \text{ н.мм} = 353.4$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1320</p> <p> $F \text{ см}^2 = 3.276$ $Q \text{ кг.} = 0.888$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 177.8$ Гр. сл. = II Точн. = П </p>











	<p>БПО-1321</p> <p> $F \text{ см}^2 = 3.11$ $Q \text{ кг.} = 0.844$ $D \text{ оп.мм} = 62.6$ $P \text{ н.мм} = 306.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1326</p> <p> $F \text{ см}^2 = 1.843$ $Q \text{ кг.} = 0.499$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 190.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1322</p> <p> $F \text{ см}^2 = 4.481$ $Q \text{ кг.} = 1.214$ $D \text{ оп.мм} = 119.3$ $P \text{ н.мм} = 441.2$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1327</p> <p> $F \text{ см}^2 = 9.000$ $Q \text{ кг.} = 2.439$ $D \text{ оп.мм} = 62.0$ $P \text{ н.мм} = 150.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1323</p> <p> $F \text{ см}^2 = 1.260$ $Q \text{ кг.} = 0.341$ $D \text{ оп.мм} = 55.5$ $P \text{ н.мм} = 199.7$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1328</p> <p> $F \text{ см}^2 = 1.380$ $Q \text{ кг.} = 0.374$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 142.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1324</p> <p> $F \text{ см}^2 = 5.260$ $Q \text{ кг.} = 1.425$ $D \text{ оп.мм} = 108.0$ $P \text{ н.мм} = 452.7$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1329</p> <p> $F \text{ см}^2 = 1.560$ $Q \text{ кг.} = 0.423$ $D \text{ оп.мм} = 40.3$ $P \text{ н.мм} = 110.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1325</p> <p> $F \text{ см}^2 = 2.926$ $Q \text{ кг.} = 0.793$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 307.2$ Гр. сл. = V Точн. = Н </p>		<p>БПО-1330</p> <p> $F \text{ см}^2 = 2.369$ $Q \text{ кг.} = 0.642$ $D \text{ оп.мм} = 99.8$ $P \text{ н.мм} = 232.0$ Гр. сл. = V Точн. = П </p>











	<p>БПО-1331</p> <p> $F \text{ см}^2 = 3.040$ $Q \text{ кг.} = 0.824$ $D \text{ оп.мм} = 58.3$ $P \text{ н.мм} = 160.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1336</p> <p> $F \text{ см}^2 = 3.27$ $Q \text{ кг.} = 0.886$ $D \text{ оп.мм} = 77.24$ $P \text{ н.мм} = 324$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1332</p> <p> $F \text{ см}^2 = 1.320$ $Q \text{ кг.} = 0.358$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 136.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1337</p> <p> $F \text{ см}^2 = 3.107$ $Q \text{ кг.} = 0.842$ $D \text{ оп.мм} = 102.3$ $P \text{ н.мм} = 311.5$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1333</p> <p> $F \text{ см}^2 = 2.750$ $Q \text{ кг.} = 0.745$ $D \text{ оп.мм} = 55.2$ $P \text{ н.мм} = 120.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1338</p> <p> $F \text{ см}^2 = 3.418$ $Q \text{ кг.} = 0.926$ $D \text{ оп.мм} = 51.8$ $P \text{ н.мм} = 174.2$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1334</p> <p> $F \text{ см}^2 = 1.480$ $Q \text{ кг.} = 0.401$ $D \text{ оп.мм} = 71.5$ $P \text{ н.мм} = 214.7$ Гр. сл. = V Точн. = П </p>		<p>БПО-1339</p> <p> $F \text{ см}^2 = 0.943$ $Q \text{ кг.} = 0.256$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 119.3$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1335</p> <p> $F \text{ см}^2 = 1.436$ $Q \text{ кг.} = 0.389$ $D \text{ оп.мм} = 56.1$ $P \text{ н.мм} = 186.2$ Гр. сл. = V Точн. = П </p>		<p>БПО-1340</p> <p> $F \text{ см}^2 = 0.434$ $Q \text{ кг.} = 0.118$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 51.1$ Гр. сл. = IV Точн. = Н </p>











	<p>БПО-1341</p> <p> $F \text{ см}^2 = 3.000$ $Q \text{ кг.} = 0.813$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 156.8$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1346</p> <p> $F \text{ см}^2 = 5.354$ $Q \text{ кг.} = 1.451$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 449.1$ Гр. сл. = Точн. = Н </p>
	<p>БПО-1342</p> <p> $F \text{ см}^2 = 0.780$ $Q \text{ кг.} = 0.211$ $D \text{ оп.мм} = 23.4$ $P \text{ н.мм} = 68.0$ Гр. сл. = I Точн. = П </p>		<p>БПО-1347</p> <p> $F \text{ см}^2 = 28.330$ $Q \text{ кг.} = 7.677$ $D \text{ оп.мм} = 182.0$ $P \text{ н.мм} = 1270.3$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-1343</p> <p> $F \text{ см}^2 = 1.049$ $Q \text{ кг.} = 0.284$ $D \text{ оп.мм} = 24.3$ $P \text{ н.мм} = 122.4$ Гр. сл. = III Точн. = П </p>		<p>БПО-1348</p> <p> $F \text{ см}^2 = 11.460$ $Q \text{ кг.} = 3.106$ $D \text{ оп.мм} = 176.0$ $P \text{ н.мм} = 723.4$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1344</p> <p> $F \text{ см}^2 = 2.610$ $Q \text{ кг.} = 0.707$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 180.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1349</p> <p> $F \text{ см}^2 = 2.065$ $Q \text{ кг.} = 0.560$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 142.3$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1345</p> <p> $F \text{ см}^2 = 0.649$ $Q \text{ кг.} = 0.176$ $D \text{ оп.мм} = 20.4$ $P \text{ н.мм} = 85.8$ Гр. сл. = III Точн. = Н </p>		











			БПО-1356 $F \text{ см}^2 = 2.180$ $Q \text{ кг.} = 0.591$ $D \text{ оп.мм} = 37.9$ $P \text{ н.мм} = 149.2$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
	БПО-1352 $F \text{ см}^2 = 1.751$ $Q \text{ кг.} = 0.475$ $D \text{ оп.мм} = 41.7$ $P \text{ н.мм} = 247.8$ $\text{Гр. сл.} = \text{Особ.}$ $\text{Точн.} = \text{П}$		БПО-1357 $F \text{ см}^2 = 2.133$ $Q \text{ кг.} = 0.578$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 85.3$ $\text{Гр. сл.} = \text{II}$ $\text{Точн.} = \text{П}$
	БПО-1353 $F \text{ см}^2 = 1.559$ $Q \text{ кг.} = 0.422$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 229.7$ $\text{Гр. сл.} = \text{Особ.}$ $\text{Точн.} = \text{П}$		БПО-1358 $F \text{ см}^2 = 2.419$ $Q \text{ кг.} = 0.656$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 134.9$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{П}$
	БПО-1354 $F \text{ см}^2 = 5.600$ $Q \text{ кг.} = 1.518$ $D \text{ оп.мм} = 171.1$ $P \text{ н.мм} = 516.1$ $\text{Гр. сл.} = \text{Особ.}$ $\text{Точн.} = \text{H}$		БПО-1359 $F \text{ см}^2 = 5.640$ $Q \text{ кг.} = 1.528$ $D \text{ оп.мм} = 72.0$ $P \text{ н.мм} = 200.0$ $\text{Гр. сл.} = \text{I}$ $\text{Точн.} = \text{H}$
	БПО-1355 $F \text{ см}^2 = 1.914$ $Q \text{ кг.} = 0.519$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 126.7$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$		БПО-1360 $F \text{ см}^2 = 0.380$ $Q \text{ кг.} = 0.103$ $D \text{ оп.мм} = 16.2$ $P \text{ н.мм} = 42.0$ $\text{Гр. сл.} = \text{I}$ $\text{Точн.} = \text{H}$











	<p>БПО-1361</p> <p> $F \text{ см}^2 = 1.347$ $Q \text{ кг.} = 0.365$ $D \text{ оп.мм} = 18.4$ $P \text{ н.мм} = 71.2$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1366</p> <p> $F \text{ см}^2 = 2.681$ $Q \text{ кг.} = 0.727$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 211.9$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1362</p> <p> $F \text{ см}^2 = 17.640$ $Q \text{ кг.} = 4.780$ $D \text{ оп.мм} = 59.4$ $P \text{ н.мм} = 168.0$ Гр. сл. = II Точн. = Н </p>		
	<p>БПО-1363</p> <p> $F \text{ см}^2 = 8.98$ $Q \text{ кг.} = 2.433$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 406.6$ Гр. сл. = IV Точн. = Н </p>		
	<p>БПО-1364</p> <p> $F \text{ см}^2 = 3.210$ $Q \text{ кг.} = 0.870$ $D \text{ оп.мм} = 86.0$ $P \text{ н.мм} = 199.8$ Гр. сл. = V Точн. = Н </p>		
	<p>БПО-1365</p> <p> $F \text{ см}^2 = 1.200$ $Q \text{ кг.} = 0.325$ $D \text{ оп.мм} = 30.5$ $P \text{ н.мм} = 105.2$ Гр. сл. = IV Точн. = Н </p>		










	<p>БПО-1371</p> <p> $F \text{ см}^2 = 4.208$ $Q \text{ кг.} = 1.13$ $D \text{ оп.мм} = 158.3$ $P \text{ н.мм} = 424.8$ Гр. сл. = III Точн. = П </p>		<p>БПО-1376</p> <p> $F \text{ см}^2 = 1.670$ $Q \text{ кг.} = 0.453$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 172.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1372</p> <p> $F \text{ см}^2 = 0.802$ $Q \text{ кг.} = 0.216$ $D \text{ оп.мм} = 43.2$ $P \text{ н.мм} = 104.6$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1377</p> <p> $F \text{ см}^2 = 2.395$ $Q \text{ кг.} = 0.649$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 178.0$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1373</p> <p> $F \text{ см}^2 = 1.203$ $Q \text{ кг.} = 0.324$ $D \text{ оп.мм} = 39.8$ $P \text{ н.мм} = 136.6$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1378</p> <p> $F \text{ см}^2 = 2.020$ $Q \text{ кг.} = 0.547$ $D \text{ оп.мм} = 60.5$ $P \text{ н.мм} = 206.0$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1374</p> <p> $F \text{ см}^2 = 2.049$ $Q \text{ кг.} = 0.555$ $D \text{ оп.мм} = 62.4$ $P \text{ н.мм} = 244.4$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1379</p> <p> $F \text{ см}^2 = 1.076$ $Q \text{ кг.} = 0.292$ $D \text{ оп.мм} = 30.6$ $P \text{ н.мм} = 93.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1375</p> <p> $F \text{ см}^2 = 2.020$ $Q \text{ кг.} = 0.547$ $D \text{ оп.мм} = 76.0$ $P \text{ н.мм} = 207.8$ Гр. сл. = V Точн. = Н </p>		<p>БПО-1380</p> <p> $F \text{ см}^2 = 1.230$ $Q \text{ кг.} = 0.333$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 110.2$ Гр. сл. = II Точн. = Н </p>











	<p>БПО-1381</p> <p> $F \text{ см}^2 = 3.570$ $Q \text{ кг.} = 0.967$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 231.5$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1386</p> <p> $F \text{ см}^2 = 7.275$ $Q \text{ кг.} = 1.972$ $D \text{ оп.мм} = 171.2$ $P \text{ н.мм} = 633.7$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-1382</p> <p> $F \text{ см}^2 = 2.478$ $Q \text{ кг.} = 0.672$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 144.9$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1387</p> <p> $F \text{ см}^2 = 1.146$ $Q \text{ кг.} = 0.311$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 94.2$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1383</p> <p> $F \text{ см}^2 = 1.279$ $Q \text{ кг.} = 0.347$ $D \text{ оп.мм} = 34.3$ $P \text{ н.мм} = 130.4$ Гр. сл. = V Точн. = П </p>		<p>БПО-1388</p> <p> $F \text{ см}^2 = 3.215$ $Q \text{ кг.} = 0.871$ $D \text{ оп.мм} = 45.2$ $P \text{ н.мм} = 108.8$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1384</p> <p> $F \text{ см}^2 = 1.936$ $Q \text{ кг.} = 0.525$ $D \text{ оп.мм} = 35.5$ $P \text{ н.мм} = 123.7$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1389</p> <p> $F \text{ см}^2 = 1.424$ $Q \text{ кг.} = 0.386$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 71.9$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1385</p> <p> $F \text{ см}^2 = 4.648$ $Q \text{ кг.} = 1.260$ $D \text{ оп.мм} = 53.0$ $P \text{ н.мм} = 257.5$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1390</p> <p> $F \text{ см}^2 = 9.030$ $Q \text{ кг.} = 2.447$ $D \text{ оп.мм} = 190.0$ $P \text{ н.мм} = 676.6$ Гр. сл. = 0соб. Точн. = Т </p>











	<p>БПО-1391</p> <p> $F \text{ см}^2 = 3.060$ $Q \text{ кг.} = 0.829$ $D \text{ оп.мм} = 97.7$ $P \text{ н.мм} = 312.9$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1396</p> <p> $F \text{ см}^2 = 2.563$ $Q \text{ кг.} = 0.695$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 210.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1392</p> <p> $F \text{ см}^2 = 1.895$ $Q \text{ кг.} = 0.514$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 224.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-1397</p> <p> $F \text{ см}^2 = 0.212$ $Q \text{ кг.} = 0.057$ $D \text{ оп.мм} = 6.0$ $P \text{ н.мм} = 21.7$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1393</p> <p> $F \text{ см}^2 = 1.144$ $Q \text{ кг.} = 0.31$ $D \text{ оп.мм} = 36.6$ $P \text{ н.мм} = 149.9$ Гр. сл. = III Точн. = П </p>		<p>БПО-1399</p> <p> $F \text{ см}^2 = 1.555$ $Q \text{ кг.} = 0.421$ $D \text{ оп.мм} = 87.6$ $P \text{ н.мм} = 241$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1394</p> <p> $F \text{ см}^2 = 1.225$ $Q \text{ кг.} = 0.332$ $D \text{ оп.мм} = 68.4$ $P \text{ н.мм} = 177.8$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1400</p> <p> $F \text{ см}^2 = 3.927$ $Q \text{ кг.} = 1.064$ $D \text{ оп.мм} = 48.7$ $P \text{ н.мм} = 190.7$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1395</p> <p> $F \text{ см}^2 = 1.018$ $Q \text{ кг.} = 0.276$ $D \text{ оп.мм} = 24.8$ $P \text{ н.мм} = 106.8$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1400</p> <p> $F \text{ см}^2 = 3.927$ $Q \text{ кг.} = 1.064$ $D \text{ оп.мм} = 48.7$ $P \text{ н.мм} = 190.7$ Гр. сл. = 0соб. Точн. = Н </p>











	<p>БПО-1401</p> <p> $F \text{ см}^2 = 3.645$ $Q \text{ кг.} = 0.988$ $D \text{ оп.мм} = 39.1$ $P \text{ н.мм} = 185.3$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1406</p> <p> $F \text{ см}^2 = 5.092$ $Q \text{ кг.} = 1.380$ $D \text{ оп.мм} = 48.7$ $P \text{ н.мм} = 262.4$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1402</p> <p> $F \text{ см}^2 = 4.879$ $Q \text{ кг.} = 1.322$ $D \text{ оп.мм} = 48.7$ $P \text{ н.мм} = 257.5$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1407</p> <p> $F \text{ см}^2 = 5.910$ $Q \text{ кг.} = 1.602$ $D \text{ оп.мм} = 142.0$ $P \text{ н.мм} = 400.0$ Гр. сл. = IV Точн. = DIN </p>
	<p>БПО-1403</p> <p> $F \text{ см}^2 = 6.032$ $Q \text{ кг.} = 1.635$ $D \text{ оп.мм} = 48.7$ $P \text{ н.мм} = 327.4$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1408</p> <p> $F \text{ см}^2 = 4.147$ $Q \text{ кг.} = 1.124$ $D \text{ оп.мм} = 48.7$ $P \text{ н.мм} = 229.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1404</p> <p> $F \text{ см}^2 = 3.842$ $Q \text{ кг.} = 1.041$ $D \text{ оп.мм} = 48.7$ $P \text{ н.мм} = 189.4$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1409</p> <p> $F \text{ см}^2 = 2.726$ $Q \text{ кг.} = 0.739$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 366.5$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-1405</p> <p> $F \text{ см}^2 = 3.864$ $Q \text{ кг.} = 1.047$ $D \text{ оп.мм} = 48.7$ $P \text{ н.мм} = 189.7$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1410</p> <p> $F \text{ см}^2 = 2.796$ $Q \text{ кг.} = 0.758$ $D \text{ оп.мм} = 42.6$ $P \text{ н.мм} = 165.2$ Гр. сл. = IV Точн. = Н </p>








	<p>БПО-1411</p> <p> $F \text{ см}^2 = 2.818$ $Q \text{ кг.} = 0.764$ $D \text{ оп.мм} = 38.5$ $P \text{ н.мм} = 168.1$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1416</p> <p> $F \text{ см}^2 = 3.595$ $Q \text{ кг.} = 0.974$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 154$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1412</p> <p> $F \text{ см}^2 = 2.395$ $Q \text{ кг.} = 0.649$ $D \text{ оп.мм} = 50.6$ $P \text{ н.мм} = 159.3$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1417</p> <p> $F \text{ см}^2 = 0.456$ $Q \text{ кг.} = 0.124$ $D \text{ оп.мм} = 19.3$ $P \text{ н.мм} = 78.4$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1413</p> <p> $F \text{ см}^2 = 2.377$ $Q \text{ кг.} = 0.644$ $D \text{ оп.мм} = 44.1$ $P \text{ н.мм} = 148.9$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1418</p> <p> $F \text{ см}^2 = 2.308$ $Q \text{ кг.} = 0.625$ $D \text{ оп.мм} = 108.3$ $P \text{ н.мм} = 275.7$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-1414</p> <p> $F \text{ см}^2 = 4.148$ $Q \text{ кг.} = 1.124$ $D \text{ оп.мм} = 50.4$ $P \text{ н.мм} = 258.6$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1419</p> <p> $F \text{ см}^2 = 0.480$ $Q \text{ кг.} = 0.130$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 52.0$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1415</p> <p> $F \text{ см}^2 = 4.606$ $Q \text{ кг.} = 1.248$ $D \text{ оп.мм} = 57.7$ $P \text{ н.мм} = 287.2$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1420</p> <p> $F \text{ см}^2 = 0.500$ $Q \text{ кг.} = 0.136$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 44.1$ Гр. сл. = II Точн. = Н </p>








	<p>БПО-1421</p> <p> $F \text{ см}^2 = 1.160$ $Q \text{ кг.} = 0.314$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 120.0$ Гр. сл. = III Точн. = П </p>		<p>БПО-1426</p> <p> $F \text{ см}^2 = 3.610$ $Q \text{ кг.} = 0.978$ $D \text{ оп.мм} = 46.7$ $P \text{ н.мм} = 150.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1422</p> <p> $F \text{ см}^2 = 4.960$ $Q \text{ кг.} = 1.344$ $D \text{ оп.мм} = 90.6$ $P \text{ н.мм} = 256.0$ Гр. сл. = III Точн. = П </p>		<p>БПО-1427</p> <p> $F \text{ см}^2 = 7.787$ $Q \text{ кг.} = 2.11$ $D \text{ оп.мм} = 112.3$ $P \text{ н.мм} = 397.3$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1423</p> <p> $F \text{ см}^2 = 4.660$ $Q \text{ кг.} = 1.263$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 120.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-1428</p> <p> $F \text{ см}^2 = 3.665$ $Q \text{ кг.} = 0.993$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 181.6$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-1429</p> <p> $F \text{ см}^2 = 4.126$ $Q \text{ кг.} = 1.118$ $D \text{ оп.мм} = 44.6$ $P \text{ н.мм} = 195.0$ Гр. сл. = II Точн. = П </p>
	<p>БПО-1425</p> <p> $F \text{ см}^2 = 1.435$ $Q \text{ кг.} = 0.389$ $D \text{ оп.мм} = 26.4$ $P \text{ н.мм} = 109.2$ Гр. сл. = II Точн. = П </p>		<p>БПО-1430</p> <p> $F \text{ см}^2 = 1.383$ $Q \text{ кг.} = 0.375$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 78.9$ Гр. сл. = II Точн. = П </p>











	БПО-1431 $F \text{ см}^2 = 2.040$ $Q \text{ кг.} = 0.553$ $D \text{ оп.мм} = 37.2$ $P \text{ н.мм} = 160.0$ Гр. сл. = II Точн. = Н		БПО-1436 $F \text{ см}^2 = 0.575$ $Q \text{ кг.} = 0.156$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 55.0$ Гр. сл. = II Точн. = Н
	БПО-1432 $F \text{ см}^2 = 0.825$ $Q \text{ кг.} = 0.224$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 64.4$ Гр. сл. = IV Точн. = П		БПО-1437 $F \text{ см}^2 = 0.996$ $Q \text{ кг.} = 0.270$ $D \text{ оп.мм} = 23.1$ $P \text{ н.мм} = 131.4$ Гр. сл. = III Точн. = Н
	БПО-1433 $F \text{ см}^2 = 0.750$ $Q \text{ кг.} = 0.203$ $D \text{ оп.мм} = 20.4$ $P \text{ н.мм} = 67.4$ Гр. сл. = IV Точн. = П		БПО-1438 $F \text{ см}^2 = 1.852$ $Q \text{ кг.} = 0.495$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 138.1$ Гр. сл. = II Точн. = Н
	БПО-1434 $F \text{ см}^2 = 0.760$ $Q \text{ кг.} = 0.206$ $D \text{ оп.мм} = 20.4$ $P \text{ н.мм} = 59.4$ Гр. сл. = IV Точн. = П		БПО-1439 $F \text{ см}^2 = 3.695$ $Q \text{ кг.} = 1.001$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 203.7$ Гр. сл. = VI Точн. = Н
	БПО-1435 $F \text{ см}^2 = 1.562$ $Q \text{ кг.} = 0.423$ $D \text{ оп.мм} = 42.8$ $P \text{ н.мм} = 107.1$ Гр. сл. = IV Точн. = Н		БПО-1440 $F \text{ см}^2 = 1.523$ $Q \text{ кг.} = 0.413$ $D \text{ оп.мм} = 52.2$ $P \text{ н.мм} = 194.3$ Гр. сл. = 0соб. Точн. = П











	<p>БПО-1441</p> <p> $F \text{ см}^2 = 1.102$ $Q \text{ кг.} = 0.299$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 76.5$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1446</p> <p> $F \text{ см}^2 = 1.998$ $Q \text{ кг.} = 0.541$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 171.4$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1442</p> <p> $F \text{ см}^2 = 0.736$ $Q \text{ кг.} = 0.199$ $D \text{ оп.мм} = 18.4$ $P \text{ н.мм} = 77.1$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1447</p> <p> $F \text{ см}^2 = 1.267$ $Q \text{ кг.} = 0.343$ $D \text{ оп.мм} = 53.2$ $P \text{ н.мм} = 167.7$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-1443</p> <p> $F \text{ см}^2 = 2.210$ $Q \text{ кг.} = 0.599$ $D \text{ оп.мм} = 43.0$ $P \text{ н.мм} = 148.4$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1448</p> <p> $F \text{ см}^2 = 0.510$ $Q \text{ кг.} = 0.138$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 48.9$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1444</p> <p> $F \text{ см}^2 = 1.486$ $Q \text{ кг.} = 0.403$ $D \text{ оп.мм} = 44.8$ $P \text{ н.мм} = 199.3$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1449</p> <p> $F \text{ см}^2 = 3.340$ $Q \text{ кг.} = 0.905$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 241.5$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1445</p> <p> $F \text{ см}^2 = 0.828$ $Q \text{ кг.} = 0.224$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 106.1$ Гр. сл. = V Точн. = П </p>		<p>БПО-1450</p> <p> $F \text{ см}^2 = 0.753$ $Q \text{ кг.} = 0.204$ $D \text{ оп.мм} = 31.8$ $P \text{ н.мм} = 148.3$ Гр. сл. = IV Точн. = П </p>











	БПО-1451 $F \text{ см}^2 = 0.916$ $Q \text{ кг.} = 0.248$ $D \text{ оп.мм} = 41.25$ $P \text{ н.мм} = 180.9$ Гр. сл. = IV Точн. = П		БПО-1456 $F \text{ см}^2 = 3.188$ $Q \text{ кг.} = 0.864$ $D \text{ оп.мм} = 61.1$ $P \text{ н.мм} = 363.3$ Гр. сл. = VI Точн. = П
	БПО-1452 $F \text{ см}^2 = 0.921$ $Q \text{ кг.} = 0.250$ $D \text{ оп.мм} = 30.2$ $P \text{ н.мм} = 139.8$ Гр. сл. = IV Точн. = П		БПО-1457 $F \text{ см}^2 = 3.14$ $Q \text{ кг.} = 0.851$ $D \text{ оп.мм} = 80.1$ $P \text{ н.мм} = 358.8$ Гр. сл. = IV Точн. = П
	БПО-1453 $F \text{ см}^2 = 5.280$ $Q \text{ кг.} = 1.431$ $D \text{ оп.мм} = 115.0$ $P \text{ н.мм} = 456.3$ Гр. сл. = III Точн. = П		БПО-1458 $F \text{ см}^2 = 3.119$ $Q \text{ кг.} = 0.845$ $D \text{ оп.мм} = 49.9$ $P \text{ н.мм} = 251.6$ Гр. сл. = IV Точн. = П
	БПО-1454 $F \text{ см}^2 = 4.424$ $Q \text{ кг.} = 1.199$ $D \text{ оп.мм} = 124.1$ $P \text{ н.мм} = 449$ Гр. сл. = V Точн. = П		БПО-1459 $F \text{ см}^2 = 1.15$ $Q \text{ кг.} = 0.312$ $D \text{ оп.мм} = 46.8$ $P \text{ н.мм} = 164.2$ Гр. сл. = IV Точн. = П
	БПО-1455 $F \text{ см}^2 = 2.739$ $Q \text{ кг.} = 0.742$ $D \text{ оп.мм} = 68.5$ $P \text{ н.мм} = 284.2$ Гр. сл. = III Точн. = П		БПО-1460 $F \text{ см}^2 = 0.975$ $Q \text{ кг.} = 0.264$ $D \text{ оп.мм} = 44.2$ $P \text{ н.мм} = 137.12$ Гр. сл. = IV Точн. = П










	<p>БПО-1471</p> <p> $F \text{ см}^2 = 1.28$ $Q \text{ кг.} = 0.347$ $D \text{ оп.мм} = 32.2$ $P \text{ н.мм} = 72$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1476</p> <p> $F \text{ см}^2 = 2.116$ $Q \text{ кг.} = 0.573$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 99.6$ Гр. сл. = II Точн. = П </p>
	<p>БПО-1472</p> <p> $F \text{ см}^2 = 0.398$ $Q \text{ кг.} = 0.108$ $D \text{ оп.мм} = 9.5$ $P \text{ н.мм} = 45.1$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1477</p> <p> $F \text{ см}^2 = 12.566$ $Q \text{ кг.} = 3.405$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 125.7$ Гр. сл. = I Точн. = Н </p>
			<p>БПО-1478</p> <p> $F \text{ см}^2 = 1.945$ $Q \text{ кг.} = 0.527$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 225.8$ Гр. сл. = V Точн. = П </p>
			<p>БПО-1479</p> <p> $F \text{ см}^2 = 1.813$ $Q \text{ кг.} = 0.491$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 150.0$ Гр. сл. = III Точн. = Н </p>
			<p>БПО-1480</p> <p> $F \text{ см}^2 = 2.010$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм} = 49.5$ $P \text{ н.мм} = 140.0$ Гр. сл. = III Точн. = Н </p>










	<p>БПО-1471</p> <p> $F \text{ см}^2 = 1.28$ $Q \text{ кг.} = 0.347$ $D \text{ оп.мм} = 32.2$ $P \text{ н.мм} = 72$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1476</p> <p> $F \text{ см}^2 = 2.116$ $Q \text{ кг.} = 0.573$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 99.6$ Гр. сл. = II Точн. = П </p>
	<p>БПО-1472</p> <p> $F \text{ см}^2 = 0.398$ $Q \text{ кг.} = 0.108$ $D \text{ оп.мм} = 9.5$ $P \text{ н.мм} = 45.1$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1477</p> <p> $F \text{ см}^2 = 12.566$ $Q \text{ кг.} = 3.405$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 125.7$ Гр. сл. = I Точн. = Н </p>
			<p>БПО-1478</p> <p> $F \text{ см}^2 = 1.945$ $Q \text{ кг.} = 0.527$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 225.8$ Гр. сл. = V Точн. = П </p>
			<p>БПО-1479</p> <p> $F \text{ см}^2 = 1.813$ $Q \text{ кг.} = 0.491$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 150.0$ Гр. сл. = III Точн. = Н </p>
			<p>БПО-1480</p> <p> $F \text{ см}^2 = 2.010$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм} = 49.5$ $P \text{ н.мм} = 140.0$ Гр. сл. = III Точн. = Н </p>

	<p>БПО-1481</p> <p> $F \text{ см}^2 = 1.110$ $Q \text{ кг.} = 0.301$ $D \text{ оп.мм} = 25.1$ $P \text{ н.мм} = 80.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1486</p> <p> $F \text{ см}^2 = 1.779$ $Q \text{ кг.} = 0.482$ $D \text{ оп.мм} = 32.4$ $P \text{ н.мм} = 136.1$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-1482</p> <p> $F \text{ см}^2 = 1.410$ $Q \text{ кг.} = 0.382$ $D \text{ оп.мм} = 31.3$ $P \text{ н.мм} = 100.0$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1487</p> <p> $F \text{ см}^2 = 2.298$ $Q \text{ кг.} = 0.623$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 155.3$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-1483</p> <p> $F \text{ см}^2 = 2.310$ $Q \text{ кг.} = 0.626$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 160.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1488</p> <p> $F \text{ см}^2 = 0.398$ $Q \text{ кг.} = 0.108$ $D \text{ оп.мм} = 16.3$ $P \text{ н.мм} = 80.44$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1484</p> <p> $F \text{ см}^2 = 1.863$ $Q \text{ кг.} = 0.505$ $D \text{ оп.мм} = 46.8$ $P \text{ н.мм} = 136.5$ Гр. сл. = II Точн. = П </p>		<p>БПО-1489</p> <p> $F \text{ см}^2 = 3.019$ $Q \text{ кг.} = 0.818$ $D \text{ оп.мм} = 66.63$ $P \text{ н.мм} = 394.3$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1485</p> <p> $F \text{ см}^2 = 1.315$ $Q \text{ кг.} = 0.356$ $D \text{ оп.мм} = 26.7$ $P \text{ н.мм} = 128.1$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1490</p> <p> $F \text{ см}^2 = 2.36$ $Q \text{ кг.} = 0.64$ $D \text{ оп.мм} = 79.12$ $P \text{ н.мм} = 239.14$ Гр. сл. = III Точн. = П </p>











	БПО-1491 $F \text{ см}^2 = 1.523$ $Q \text{ кг.} = 0.413$ $D \text{ оп.мм} = 70.5$ $R \text{ н.мм} = 204$ Гр. сл. = V Точн. = П		БПО-1496 $F \text{ см}^2 = 0.562$ $Q \text{ кг.} = 0.152$ $D \text{ оп.мм} = 24.0$ $R \text{ н.мм} = 96.7$ Гр. сл. = IV Точн. = Н
	БПО-1492 $F \text{ см}^2 = 4.6$ $Q \text{ кг.} = 1.247$ $D \text{ оп.мм} = 168.5$ $R \text{ н.мм} = 435.2$ Гр. сл. = 0соб. Точн. = П		БПО-1497 $F \text{ см}^2 = 0.150$ $Q \text{ кг.} = 0.041$ $D \text{ оп.мм} = 9.0$ $R \text{ н.мм} = 31.8$ Гр. сл. = IV Точн. = П
	БПО-1493 $F \text{ см}^2 = 4.24$ $Q \text{ кг.} = 1.149$ $D \text{ оп.мм} = 154.1$ $R \text{ н.мм} = 424.5$ Гр. сл. = 0соб. Точн. = П		БПО-1498 $F \text{ см}^2 = 0.694$ $Q \text{ кг.} = 0.188$ $D \text{ оп.мм} = 16.7$ $R \text{ н.мм} = 67.0$ Гр. сл. = V Точн. = П
	БПО-1494 $F \text{ см}^2 = 2.72$ $Q \text{ кг.} = 0.737$ $D \text{ оп.мм} = 101.3$ $R \text{ н.мм} = 275.7$ Гр. сл. = V Точн. = П		БПО-1499 $F \text{ см}^2 = 0.966$ $Q \text{ кг.} = 0.262$ $D \text{ оп.мм} = 30.7$ $R \text{ н.мм} = 98.4$ Гр. сл. = III Точн. = П
	БПО-1495 $F \text{ см}^2 = 0.285$ $Q \text{ кг.} = 0.077$ $D \text{ оп.мм} = 20.2$ $R \text{ н.мм} = 50.8$ Гр. сл. = IV Точн. = Н		БПО-1500 $F \text{ см}^2 = 1.835$ $Q \text{ кг.} = 0.497$ $D \text{ оп.мм} = 100.0$ $R \text{ н.мм} = 219.5$ Гр. сл. = 0соб. Точн. = П











	БПО-1501 $F \text{ см}^2 = 2.923$ $Q \text{ кг.} = 0.792$ $D \text{ оп.мм} = 105.0$ $P \text{ н.мм} = 337.1$ Гр. сл. = 0соб. Точн. = П		БПО-1506 $F \text{ см}^2 = 0.850$ $Q \text{ кг.} = 0.230$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 104.0$ Гр. сл. = IV Точн. = Н
	БПО-1502 $F \text{ см}^2 = 3.535$ $Q \text{ кг.} = 0.958$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 408.1$ Гр. сл. = 0соб. Точн. = П		БПО-1507 $F \text{ см}^2 = 1.247$ $Q \text{ кг.} = 0.338$ $D \text{ оп.мм} = 63.0$ $P \text{ н.мм} = 162.7$ Гр. сл. = VI Точн. = Н
	БПО-1503 $F \text{ см}^2 = 0.860$ $Q \text{ кг.} = 0.233$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 115.8$ Гр. сл. = IV Точн. = Н		БПО-1508 $F \text{ см}^2 = 1.0$ $Q \text{ кг.} = 0.271$ $D \text{ оп.мм} = 25.5$ $P \text{ н.мм} = 104$ Гр. сл. = II Точн. = Н
	БПО-1504 $F \text{ см}^2 = 0.525$ $Q \text{ кг.} = 0.142$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 75.4$ Гр. сл. = IV Точн. = Н		БПО-1509 $F \text{ см}^2 = 4.320$ $Q \text{ кг.} = 1.171$ $D \text{ оп.мм} = 70.5$ $P \text{ н.мм} = 179.5$ Гр. сл. = IV Точн. = Н
	БПО-1505 $F \text{ см}^2 = 0.683$ $Q \text{ кг.} = 0.185$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 88.8$ Гр. сл. = IV Точн. = Н		БПО-1510 $F \text{ см}^2 = 5.190$ $Q \text{ кг.} = 1.406$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 307.6$ Гр. сл. = IV Точн. = Н










	<p>БПО-1511</p> <p> $F \text{ см}^2 = 3.080$ $Q \text{ кг.} = 0.835$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 182.4$ Гр. сл. = III Точн. = Н </p>		
	<p>БПО-1512</p> <p> $F \text{ см}^2 = 2.083$ $Q \text{ кг.} = 0.564$ $D \text{ оп.мм} = 68.8$ $P \text{ н.мм} = 275.1$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1517</p> <p> $F \text{ см}^2 = 2.065$ $Q \text{ кг.} = 0.560$ $D \text{ оп.мм} = 43.1$ $P \text{ н.мм} = 112.1$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1513</p> <p> $F \text{ см}^2 = 1.592$ $Q \text{ кг.} = 0.432$ $D \text{ оп.мм} = 57.1$ $P \text{ н.мм} = 213.7$ Гр. сл. = IV Точн. = Т </p>		<p>БПО-1518</p> <p> $F \text{ см}^2 = 1.070$ $Q \text{ кг.} = 0.290$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 126.9$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1514</p> <p> $F \text{ см}^2 = 2.052$ $Q \text{ кг.} = 0.556$ $D \text{ оп.мм} = 71.2$ $P \text{ н.мм} = 288.6$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-1519</p> <p> $F \text{ см}^2 = 0.385$ $Q \text{ кг.} = 0.104$ $D \text{ оп.мм} = 15.3$ $P \text{ н.мм} = 78.2$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1515</p> <p> $F \text{ см}^2 = 1.884$ $Q \text{ кг.} = 0.511$ $D \text{ оп.мм} = 67.4$ $P \text{ н.мм} = 252.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1520</p> <p> $F \text{ см}^2 = 58.140$ $Q \text{ кг.} = 15.756$ $D \text{ оп.мм} = 157.0$ $P \text{ н.мм} = 382.0$ Гр. сл. = II Точн. = Н </p>










	<p>БПО-1521</p> <p> $F \text{ см}^2 = 1.721$ $Q \text{ кг.} = 0.466$ $D \text{ оп.мм} = 40.6$ $P \text{ н.мм} = 102.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1526</p> <p> $F \text{ см}^2 = 0.996$ $Q \text{ кг.} = 0.270$ $D \text{ оп.мм} = 28.8$ $P \text{ н.мм} = 104.3$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1522</p> <p> $F \text{ см}^2 = 2.400$ $Q \text{ кг.} = 0.650$ $D \text{ оп.мм} = 81.0$ $P \text{ н.мм} = 166.0$ Гр. сл. = III Точн. = Н </p>		
	<p>БПО-1523</p> <p> $F \text{ см}^2 = 4.530$ $Q \text{ кг.} = 1.228$ $D \text{ оп.мм} = 122.0$ $P \text{ н.мм} = 421.0$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-1528</p> <p> $F \text{ см}^2 = 0.518$ $Q \text{ кг.} = 0.140$ $D \text{ оп.мм} = 22.9$ $P \text{ н.мм} = 72.5$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1524</p> <p> $F \text{ см}^2 = 1.078$ $Q \text{ кг.} = 0.292$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 62.4$ Гр. сл. = I Точн. = П </p>		<p>БПО-1529</p> <p> $F \text{ см}^2 = 1.847$ $Q \text{ кг.} = 0.501$ $D \text{ оп.мм} = 58.7$ $P \text{ н.мм} = 242.7$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1525</p> <p> $F \text{ см}^2 = 1.770$ $Q \text{ кг.} = 0.479$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 224.7$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-1530</p> <p> $F \text{ см}^2 = 2.398$ $Q \text{ кг.} = 0.650$ $D \text{ оп.мм} = 64.2$ $P \text{ н.мм} = 315.1$ Гр. сл. = V Точн. = П </p>











	<p>БПО-1531</p> <p> $F \text{ см}^2 = 2.239$ $Q \text{ кг.} = 0.607$ $D \text{ оп.мм} = 65.5$ $P \text{ н.мм} = 291.8$ Гр. сл. = V Точн. = П </p>		<p>БПО-1536</p> <p> $F \text{ см}^2 = 1.470$ $Q \text{ кг.} = 0.398$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 197.9$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1532</p> <p> $F \text{ см}^2 = 1.896$ $Q \text{ кг.} = 0.514$ $D \text{ оп.мм} = 73.7$ $P \text{ н.мм} = 247.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-1537</p> <p> $F \text{ см}^2 = 1.300$ $Q \text{ кг.} = 0.352$ $D \text{ оп.мм} = 56.5$ $P \text{ н.мм} = 175.4$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1533</p> <p> $F \text{ см}^2 = 1.636$ $Q \text{ кг.} = 0.443$ $D \text{ оп.мм} = 51.3$ $P \text{ н.мм} = 215.8$ Гр. сл. = V Точн. = П </p>		<p>БПО-1538</p> <p> $F \text{ см}^2 = 1.510$ $Q \text{ кг.} = 0.409$ $D \text{ оп.мм} = 53.2$ $P \text{ н.мм} = 204.3$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1534</p> <p> $F \text{ см}^2 = 1.534$ $Q \text{ кг.} = 0.416$ $D \text{ оп.мм} = 51.1$ $P \text{ н.мм} = 196.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-1539</p> <p> $F \text{ см}^2 = 2.830$ $Q \text{ кг.} = 0.767$ $D \text{ оп.мм} = 144.9$ $P \text{ н.мм} = 337.2$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1535</p> <p> $F \text{ см}^2 = 2.290$ $Q \text{ кг.} = 0.621$ $D \text{ оп.мм} = 56.1$ $P \text{ н.мм} = 167.8$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1540</p> <p> $F \text{ см}^2 = 3.120$ $Q \text{ кг.} = 0.846$ $D \text{ оп.мм} = 36.8$ $P \text{ н.мм} = 107.4$ Гр. сл. = II Точн. = Н </p>








	<p>БПО-1541</p> <p> $F \text{ см}^2 = 0.865$ $Q \text{ кг.} = 0.234$ $D \text{ оп.мм} = 35.2$ $P \text{ н.мм} = 170.7$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1546</p> <p> $F \text{ см}^2 = 0.503$ $Q \text{ кг.} = 0.136$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 74.2$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1542</p> <p> $F \text{ см}^2 = 0.530$ $Q \text{ кг.} = 0.144$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 53.9$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1547</p> <p> $F \text{ см}^2 = 0.465$ $Q \text{ кг.} = 0.126$ $D \text{ оп.мм} = 20.4$ $P \text{ н.мм} = 74.9$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1543</p> <p> $F \text{ см}^2 = 0.720$ $Q \text{ кг.} = 0.195$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 76.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1548</p> <p> $F \text{ см}^2 = 0.605$ $Q \text{ кг.} = 0.164$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 61.3$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1544</p> <p> $F \text{ см}^2 = 0.806$ $Q \text{ кг.} = 0.218$ $D \text{ оп.мм} = 16.0$ $P \text{ н.мм} = 42.1$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1549</p> <p> $F \text{ см}^2 = 2.800$ $Q \text{ кг.} = 0.759$ $D \text{ оп.мм} = 53.0$ $P \text{ н.мм} = 180.7$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1545</p> <p> $F \text{ см}^2 = 0.796$ $Q \text{ кг.} = 0.216$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 78.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1550</p> <p> $F \text{ см}^2 = 0.721$ $Q \text{ кг.} = 0.195$ $D \text{ оп.мм} = 14.0$ $P \text{ н.мм} = 36.5$ Гр. сл. = II Точн. = Н </p>








	<p>БПО-1551</p> <p> $F \text{ см}^2 = 1.125$ $Q \text{ кг.} = 0.305$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 48.9$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1556</p> <p> $F \text{ см}^2 = 2.010$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 140.0$ Гр. сл. = III Точн. = П </p>
	<p>БПО-1552</p> <p> $F \text{ см}^2 = 0.895$ $Q \text{ кг.} = 0.243$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 61.7$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1557</p> <p> $F \text{ см}^2 = 1.394$ $Q \text{ кг.} = 0.378$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 201.8$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-1553</p> <p> $F \text{ см}^2 = 0.897$ $Q \text{ кг.} = 0.243$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 87.8$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1558</p> <p> $F \text{ см}^2 = 7.300$ $Q \text{ кг.} = 1.978$ $D \text{ оп.мм} = 91.0$ $P \text{ н.мм} = 438.2$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1554</p> <p> $F \text{ см}^2 = 0.937$ $Q \text{ кг.} = 0.254$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 98.6$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1559</p> <p> $F \text{ см}^2 = 8.085$ $Q \text{ кг.} = 2.191$ $D \text{ оп.мм} = 191.0$ $P \text{ н.мм} = 701.0$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1555</p> <p> $F \text{ см}^2 = 0.975$ $Q \text{ кг.} = 0.264$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 108.2$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1560</p> <p> $F \text{ см}^2 = 1.000$ $Q \text{ кг.} = 0.271$ $D \text{ оп.мм} = 40.4$ $P \text{ н.мм} = 135.8$ Гр. сл. = IV Точн. = Н </p>






	<p>БПО-1561</p> <p> $F \text{ см}^2 = 0.670$ $Q \text{ кг.} = 0.182$ $D \text{ оп.мм} = 21.7$ $P \text{ н.мм} = 55.1$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1566</p> <p> $F \text{ см}^2 = 0.774$ $Q \text{ кг.} = 0.21$ $D \text{ оп.мм} = 30.8$ $P \text{ н.мм} = 155.8$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-1562</p> <p> $F \text{ см}^2 = 0.600$ $Q \text{ кг.} = 0.163$ $D \text{ оп.мм} = 30.1$ $P \text{ н.мм} = 64.0$ Гр. сл. = I Точн. = П </p>		
	<p>БПО-1563</p> <p> $F \text{ см}^2 = 0.360$ $Q \text{ кг.} = 0.098$ $D \text{ оп.мм} = 14.1$ $P \text{ н.мм} = 40.0$ Гр. сл. = I Точн. = П </p>		<p>БПО-1568</p> <p> $F \text{ см}^2 = 0.770$ $Q \text{ кг.} = 0.209$ $D \text{ оп.мм} = 19.8$ $P \text{ н.мм} = 48.2$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1564</p> <p> $F \text{ см}^2 = 1.840$ $Q \text{ кг.} = 0.499$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 100.0$ Гр. сл. = I Точн. = П </p>		<p>БПО-1569</p> <p> $F \text{ см}^2 = 0.071$ $Q \text{ кг.} = 0.019$ $D \text{ оп.мм} = 3.0$ $P \text{ н.мм} = 9.4$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1565</p> <p> $F \text{ см}^2 = 2.010$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм} = 45.7$ $P \text{ н.мм} = 140.0$ Гр. сл. = II Точн. = П </p>		<p>БПО-1570</p> <p> $F \text{ см}^2 = 6.854$ $Q \text{ кг.} = 1.857$ $D \text{ оп.мм} = 183.0$ $P \text{ н.мм} = 553.0$ Гр. сл. = V Точн. = П </p>











	<p>БПО-1571</p> <p> $F \text{ см}^2 = 4.099$ $Q \text{ кг.} = 1.111$ $D \text{ оп.мм} = 143.0$ $P \text{ н.мм} = 414.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-1576</p> <p> $F \text{ см}^2 = 12.160$ $Q \text{ кг.} = 3.295$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 214.8$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1572</p> <p> $F \text{ см}^2 = 3.596$ $Q \text{ кг.} = 0.975$ $D \text{ оп.мм} = 116.0$ $P \text{ н.мм} = 276.4$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1577</p> <p> $F \text{ см}^2 = 6.74$ $Q \text{ кг.} = 1.827$ $D \text{ оп.мм} = 81$ $P \text{ н.мм} = 184$ Гр. сл. = II Точн. = П </p>
	<p>БПО-1573</p> <p> $F \text{ см}^2 = 0.749$ $Q \text{ кг.} = 0.203$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 49.8$ Гр. сл. = I Точн. = Н </p>		
	<p>БПО-1574</p> <p> $F \text{ см}^2 = 1.794$ $Q \text{ кг.} = 0.486$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 242.2$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1579</p> <p> $F \text{ см}^2 = 2.944$ $Q \text{ кг.} = 0.798$ $D \text{ оп.мм} = 119.4$ $P \text{ н.мм} = 325.2$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1575</p> <p> $F \text{ см}^2 = 3.155$ $Q \text{ кг.} = 0.855$ $D \text{ оп.мм} = 69.8$ $P \text{ н.мм} = 306.3$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1580</p> <p> $F \text{ см}^2 = 0.894$ $Q \text{ кг.} = 0.242$ $D \text{ оп.мм} = 34.1$ $P \text{ н.мм} = 179.1$ Гр. сл. = VI Точн. = П </p>











	<p>БПО-1581</p> <p> $F \text{ см}^2 = 0.343$ $Q \text{ кг.} = 0.093$ $D \text{ оп.мм} = 22.1$ $P \text{ н.мм} = 71.2$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1586</p> <p> $F \text{ см}^2 = 0.785$ $Q \text{ кг.} = 0.213$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 123.0$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1582</p> <p> $F \text{ см}^2 = 1.682$ $Q \text{ кг.} = 0.456$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 200.7$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1587</p> <p> $F \text{ см}^2 = 0.665$ $Q \text{ кг.} = 0.180$ $D \text{ оп.мм} = 25.9$ $P \text{ н.мм} = 133.3$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1583</p> <p> $F \text{ см}^2 = 2.585$ $Q \text{ кг.} = 0.701$ $D \text{ оп.мм} = 92.8$ $P \text{ н.мм} = 268.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1588</p> <p> $F \text{ см}^2 = 0.824$ $Q \text{ кг.} = 0.223$ $D \text{ оп.мм} = 18.5$ $P \text{ н.мм} = 45.9$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1584</p> <p> $F \text{ см}^2 = 1.570$ $Q \text{ кг.} = 0.425$ $D \text{ оп.мм} = 52.9$ $P \text{ н.мм} = 246.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-1589</p> <p> $F \text{ см}^2 = 1.344$ $Q \text{ кг.} = 0.364$ $D \text{ оп.мм} = 41.2$ $P \text{ н.мм} = 231.7$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-1585</p> <p> $F \text{ см}^2 = 5.808$ $Q \text{ кг.} = 1.574$ $D \text{ оп.мм} = 131.2$ $P \text{ н.мм} = 403.8$ Гр. сл. = V Точн. = П </p>		<p>БПО-1590</p> <p> $F \text{ см}^2 = 2.900$ $Q \text{ кг.} = 0.786$ $D \text{ оп.мм} = 72.0$ $P \text{ н.мм} = 240.7$ Гр. сл. = IV Точн. = Н </p>











	<p>БПО-1591</p> <p> $F \text{ см}^2 = 0.635$ $Q \text{ кг.} = 0.172$ $D \text{ оп.мм} = 25.9$ $P \text{ н.мм} = 126.0$ Гр. сл. = I Точн. = П </p>		<p>БПО-1596</p> <p> $F \text{ см}^2 = 1.690$ $Q \text{ кг.} = 0.458$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 227.2$ Гр. сл. = V Точн. = П </p>
			<p>БПО-1597</p> <p> $F \text{ см}^2 = 1.610$ $Q \text{ кг.} = 0.436$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 192.0$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-1593</p> <p> $F \text{ см}^2 = 1.05$ $Q \text{ кг.} = 0.285$ $D \text{ оп.мм} = 134$ $P \text{ н.мм} = 134$ Гр. сл. = V Точн. = П </p>		<p>БПО-1598</p> <p> $F \text{ см}^2 = 1.036$ $Q \text{ кг.} = 0.281$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 123.0$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-1599</p> <p> $F \text{ см}^2 = 3.320$ $Q \text{ кг.} = 0.900$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 331.0$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-1600</p> <p> $F \text{ см}^2 = 5.400$ $Q \text{ кг.} = 1.463$ $D \text{ оп.мм} = 180.0$ $P \text{ н.мм} = 366.0$ Гр. сл. = 0соб. Точн. = Н </p>






	<p>БПО-1601</p> <p> $F \text{ см}^2 = 2.440$ $Q \text{ кг.} = 0.661$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 85.4$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1606</p> <p> $F \text{ см}^2 = 2.457$ $Q \text{ кг.} = 0.666$ $D \text{ оп.мм} = 55.1$ $P \text{ н.мм} = 177.0$ Гр. сл. = III Точн. = П </p>
	<p>БПО-1602</p> <p> $F \text{ см}^2 = 3.764$ $Q \text{ кг.} = 1.020$ $D \text{ оп.мм} = 71.4$ $P \text{ н.мм} = 257.1$ Гр. сл. = III Точн. = П </p>		<p>БПО-1607</p> <p> $F \text{ см}^2 = 4.040$ $Q \text{ кг.} = 1.095$ $D \text{ оп.мм} = 106.0$ $P \text{ н.мм} = 479.0$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-1603</p> <p> $F \text{ см}^2 = 2.195$ $Q \text{ кг.} = 0.595$ $D \text{ оп.мм} = 65.7$ $P \text{ н.мм} = 154.0$ Гр. сл. = III Точн. = П </p>		
	<p>БПО-1604</p> <p> $F \text{ см}^2 = 2.939$ $Q \text{ кг.} = 0.796$ $D \text{ оп.мм} = 68.9$ $P \text{ н.мм} = 366.3$ Гр. сл. = VI Точн. = П </p>		
	<p>БПО-1605</p> <p> $F \text{ см}^2 = 2.353$ $Q \text{ кг.} = 0.639$ $D \text{ оп.мм} = 72.3$ $P \text{ н.мм} = 293.0$ Гр. сл. = VI Точн. = П </p>		











			БПО-1616
			$F \text{ см}^2 = 3.434$ $Q \text{ кг.} = 0.931$ $D \text{ оп.мм} = 75.0$ $P \text{ н.мм} = 299.3$ Гр. сл. = VI Точн. = П
	БПО-1612		БПО-1617
			$F \text{ см}^2 = 3.000$ $Q \text{ кг.} = 0.813$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 74.0$ Гр. сл. = I Точн. = П
	БПО-1613		БПО-1618
			$F \text{ см}^2 = 0.600$ $Q \text{ кг.} = 0.163$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 64.0$ Гр. сл. = I Точн. = П
			БПО-1619
	БПО-1615		БПО-1620
	$F \text{ см}^2 = 3.043$ $Q \text{ кг.} = 0.825$ $D \text{ оп.мм} = 65.8$ $P \text{ н.мм} = 257.8$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 = 32.000$ $Q \text{ кг.} = 8.672$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 240.0$ Гр. сл. = I Точн. = П










	<p>БПО-1621</p> <p> $F \text{ см}^2 = 20.000$ $Q \text{ кг.} = 5.420$ $D \text{ оп.мм} = 102.0$ $P \text{ н.мм} = 240.0$ Гр. сл. = I Точн. = П </p>		<p>БПО-1626</p> <p> $F \text{ см}^2 = 2.428$ $Q \text{ кг.} = 0.658$ $D \text{ оп.мм} = 59.3$ $P \text{ н.мм} = 296.8$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1622</p> <p> $F \text{ см}^2 = 22.500$ $Q \text{ кг.} = 6.098$ $D \text{ оп.мм} = 151.0$ $P \text{ н.мм} = 330.0$ Гр. сл. = I Точн. = П </p>		<p>БПО-1627</p> <p> $F \text{ см}^2 = 2.826$ $Q \text{ кг.} = 0.766$ $D \text{ оп.мм} = 60.9$ $P \text{ н.мм} = 334.9$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1623</p> <p> $F \text{ см}^2 = 1.240$ $Q \text{ кг.} = 0.336$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 128.0$ Гр. сл. = III Точн. = П </p>		<p>БПО-1628</p> <p> $F \text{ см}^2 = 3.625$ $Q \text{ кг.} = 0.982$ $D \text{ оп.мм} = 65.3$ $P \text{ н.мм} = 399.4$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-1624</p> <p> $F \text{ см}^2 = 5.640$ $Q \text{ кг.} = 1.528$ $D \text{ оп.мм} = 71.0$ $P \text{ н.мм} = 200.0$ Гр. сл. = I Точн. = П </p>		<p>БПО-1629</p> <p> $F \text{ см}^2 = 2.944$ $Q \text{ кг.} = 0.798$ $D \text{ оп.мм} = 65.3$ $P \text{ н.мм} = 371.8$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1625</p> <p> $F \text{ см}^2 = 2.533$ $Q \text{ кг.} = 0.686$ $D \text{ оп.мм} = 64.6$ $P \text{ н.мм} = 309.7$ Гр. сл. = V Точн. = П </p>		<p>БПО-1630</p> <p> $F \text{ см}^2 = 2.805$ $Q \text{ кг.} = 0.760$ $D \text{ оп.мм} = 60.9$ $P \text{ н.мм} = 317.1$ Гр. сл. = V Точн. = П </p>











	<p>БПО-1631</p> <p> $F \text{ см}^2 = 5.280$ $Q \text{ кг.} = 1.431$ $D \text{ оп.мм} = 150.0$ $P \text{ н.мм} = 483.0$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-1636</p> <p> $F \text{ см}^2 = 7.910$ $Q \text{ кг.} = 2.144$ $D \text{ оп.мм} = 85.1$ $P \text{ н.мм} = 240.0$ Гр. сл. = II Точн. = П </p>
	<p>БПО-1632</p> <p> $F \text{ см}^2 = 1.400$ $Q \text{ кг.} = 0.379$ $D \text{ оп.мм} = 41.4$ $P \text{ н.мм} = 144.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1637</p> <p> $F \text{ см}^2 = 1.875$ $Q \text{ кг.} = 0.508$ $D \text{ оп.мм} = 44.7$ $P \text{ н.мм} = 155.0$ Гр. сл. = III Точн. = П </p>
	<p>БПО-1633</p> <p> $F \text{ см}^2 = 1.846$ $Q \text{ кг.} = 0.500$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 94.8$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1638</p> <p> $F \text{ см}^2 = 0.855$ $Q \text{ кг.} = 0.232$ $D \text{ оп.мм} = 28.3$ $P \text{ н.мм} = 117.0$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1634</p> <p> $F \text{ см}^2 = 3.696$ $Q \text{ кг.} = 1.002$ $D \text{ оп.мм} = 64.4$ $P \text{ н.мм} = 307.1$ Гр. сл. = V Точн. = Н </p>		<p>БПО-1639</p> <p> $F \text{ см}^2 = 1.490$ $Q \text{ кг.} = 0.404$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 172.8$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1635</p> <p> $F \text{ см}^2 = 2.991$ $Q \text{ кг.} = 0.811$ $D \text{ оп.мм} = 66.7$ $P \text{ н.мм} = 242.7$ Гр. сл. = V Точн. = Н </p>		<p>БПО-1640</p> <p> $F \text{ см}^2 = 2.220$ $Q \text{ кг.} = 0.602$ $D \text{ оп.мм} = 66.2$ $P \text{ н.мм} = 253.7$ Гр. сл. = V Точн. = П </p>











	<p>БПО-1641</p> <p> $F \text{ см}^2 = 1.693$ $Q \text{ кг.} = 0.459$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 192.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-1649</p> <p> $F \text{ см}^2 = 1.095$ $Q \text{ кг.} = 0.297$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 149.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1642</p> <p> $F \text{ см}^2 = 0.300$ $Q \text{ кг.} = 0.081$ $D \text{ оп.мм} = 15.0$ $P \text{ н.мм} = 34.0$ Гр. сл. = I Точн. = П </p>		<p>БПО-1647</p> <p> $F \text{ см}^2 = 0.831$ $Q \text{ кг.} = 0.225$ $D \text{ оп.мм} = 31.4$ $P \text{ н.мм} = 135.5$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1643</p> <p> $F \text{ см}^2 = 0.360$ $Q \text{ кг.} = 0.098$ $D \text{ оп.мм} = 15.0$ $P \text{ н.мм} = 40.0$ Гр. сл. = I Точн. = П </p>		<p>БПО-1648</p> <p> $F \text{ см}^2 = 2.010$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 140.0$ Гр. сл. = II Точн. = П </p>
	<p>БПО-1644</p> <p> $F \text{ см}^2 = 1.840$ $Q \text{ кг.} = 0.499$ $D \text{ оп.мм} = 36.4$ $P \text{ н.мм} = 100.0$ Гр. сл. = II Точн. = П </p>		<p>БПО-1649</p> <p> $F \text{ см}^2 = 2.160$ $Q \text{ кг.} = 0.585$ $D \text{ оп.мм} = 54.1$ $P \text{ н.мм} = 150.0$ Гр. сл. = II Точн. = П </p>
	<p>БПО-1645</p>		<p>БПО-1650</p> <p> $F \text{ см}^2 = 2.375$ $Q \text{ кг.} = 0.644$ $D \text{ оп.мм} = 44.7$ $P \text{ н.мм} = 195.0$ Гр. сл. = III Точн. = П </p>









	БПО-1651 $F \text{ см}^2 = 1.818$ $Q \text{ кг.} = 0.494$ $D \text{ оп.мм} = 91.6$ $P \text{ н.мм} = 216.8$ Гр. сл. = vi Точн. = П		БПО-1656 $F \text{ см}^2 = 2.010$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм} = 43.4$ $P \text{ н.мм} = 140.0$ Гр. сл. = II Точн. = П
			БПО-1657 $F \text{ см}^2 = 7.910$ $Q \text{ кг.} = 2.144$ $D \text{ оп.мм} = 81.5$ $P \text{ н.мм} = 240.0$ Гр. сл. = II Точн. = П
			БПО-1658 $F \text{ см}^2 = 5.031$ $Q \text{ кг.} = 1.363$ $D \text{ оп.мм} = 140.0$ $P \text{ н.мм} = 476.7$ Гр. сл. = V Точн. = Н
	БПО-1655 $F \text{ см}^2 = 2.870$ $Q \text{ кг.} = 0.778$ $D \text{ оп.мм} = 68.0$ $P \text{ н.мм} = 234.6$ Гр. сл. = V Точн. = Н		










	<p>БПО-1661</p> <p> $F \text{ см}^2 = 5.760$ $Q \text{ кг.} = 1.561$ $D \text{ оп.мм} = 132.0$ $P \text{ н.мм} = 657.2$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1666</p> <p> $F \text{ см}^2 = 7.970$ $Q \text{ кг.} = 2.160$ $D \text{ оп.мм} = 100.1$ $P \text{ н.мм} = 212.6$ Гр. сл. = I Точн. = Н </p>
	<p>БПО-1662</p> <p> $F \text{ см}^2 = 0.790$ $Q \text{ кг.} = 0.214$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 108.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-1667</p> <p> $F \text{ см}^2 = 1.905$ $Q \text{ кг.} = 0.516$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 272.6$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1663</p> <p> $F \text{ см}^2 = 3.380$ $Q \text{ кг.} = 0.916$ $D \text{ оп.мм} = 94.0$ $P \text{ н.мм} = 212.2$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1668</p> <p> $F \text{ см}^2 = 0.868$ $Q \text{ кг.} = 0.235$ $D \text{ оп.мм} = 28.6$ $P \text{ н.мм} = 135.9$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-1664</p> <p> $F \text{ см}^2 = 1.890$ $Q \text{ кг.} = 0.512$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 108.0$ Гр. сл. = III Точн. = П </p>		<p>БПО-1669</p> <p> $F \text{ см}^2 = 1.960$ $Q \text{ кг.} = 0.531$ $D \text{ оп.мм} = 68.2$ $P \text{ н.мм} = 243.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1665</p> <p> $F \text{ см}^2 = 31.5$ $Q \text{ кг.} = 8.53$ $D \text{ оп.мм} = 192$ $P \text{ н.мм} = 650.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1670</p> <p> $F \text{ см}^2 = 1.703$ $Q \text{ кг.} = 0.462$ $D \text{ оп.мм} = 75.4$ $P \text{ н.мм} = 209.7$ Гр. сл. = V Точн. = П </p>







			БПО-1676 $F \text{ см}^2 = 2.350$ $Q \text{ кг.} = 0.637$ $D \text{ оп.мм} = 88.6$ $P \text{ н.мм} = 309.0$ Гр. сл. = VI Точн. = П
	БПО-1672 $F \text{ см}^2 = 1.720$ $Q \text{ кг.} = 0.466$ $D \text{ оп.мм} = 98.9$ $P \text{ н.мм} = 234.3$ Гр. сл. = IV Точн. = П		БПО-1677 $F \text{ см}^2 = 2.850$ $Q \text{ кг.} = 0.772$ $D \text{ оп.мм} = 96.4$ $P \text{ н.мм} = 374.0$ Гр. сл. = VI Точн. = П
	БПО-1673 $F \text{ см}^2 = 14.400$ $Q \text{ кг.} = 3.902$ $D \text{ оп.мм} = 121.0$ $P \text{ н.мм} = 264.0$ Гр. сл. = I Точн. = Н		БПО-1678 $F \text{ см}^2 = 4.410$ $Q \text{ кг.} = 1.195$ $D \text{ оп.мм} = 161.0$ $P \text{ н.мм} = 485.0$ Гр. сл. = 0соб. Точн. = Н
	БПО-1674 $F \text{ см}^2 = 2.210$ $Q \text{ кг.} = 0.599$ $D \text{ оп.мм} = 73.6$ $P \text{ н.мм} = 290.0$ Гр. сл. = VI Точн. = П		БПО-1679 $F \text{ см}^2 = 2.730$ $Q \text{ кг.} = 0.740$ $D \text{ оп.мм} = 92.2$ $P \text{ н.мм} = 287.5$ Гр. сл. = V Точн. = Н
	БПО-1675 $F \text{ см}^2 = 2.660$ $Q \text{ кг.} = 0.721$ $D \text{ оп.мм} = 96.5$ $P \text{ н.мм} = 350.0$ Гр. сл. = VI Точн. = П		БПО-1680 $F \text{ см}^2 = 3.180$ $Q \text{ кг.} = 0.862$ $D \text{ оп.мм} = 91.3$ $P \text{ н.мм} = 275.6$ Гр. сл. = V Точн. = Н











	<p>БПО-1681</p> <p> $F \text{ см}^2 = 7.083$ $Q \text{ кг.} = 1.919$ $D \text{ оп.мм} = 106.0$ $P \text{ н.мм} = 255.4$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1686</p> <p> $F \text{ см}^2 = 2.723$ $Q \text{ кг.} = 0.738$ $D \text{ оп.мм} = 118.1$ $P \text{ н.мм} = 271.3$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1682</p> <p> $F \text{ см}^2 = 3.647$ $Q \text{ кг.} = 0.988$ $D \text{ оп.мм} = 56.6$ $P \text{ н.мм} = 150.7$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1687</p> <p> $F \text{ см}^2 = 0.658$ $Q \text{ кг.} = 0.178$ $D \text{ оп.мм} = 25.8$ $P \text{ н.мм} = 131.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1683</p> <p> $F \text{ см}^2 = 15.310$ $Q \text{ кг.} = 4.149$ $D \text{ оп.мм} = 92.7$ $P \text{ н.мм} = 229.8$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1688</p> <p> $F \text{ см}^2 = 8.323$ $Q \text{ кг.} = 2.256$ $D \text{ оп.мм} = 82$ $P \text{ н.мм} = 313.3$ Гр. сл. = III Точн. = П </p>
	<p>БПО-1684</p> <p> $F \text{ см}^2 = 5.233$ $Q \text{ кг.} = 1.418$ $D \text{ оп.мм} = 81.0$ $P \text{ н.мм} = 202.3$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1689</p> <p> $F \text{ см}^2 = 0.680$ $Q \text{ кг.} = 0.184$ $D \text{ оп.мм} = 45.1$ $P \text{ н.мм} = 93.3$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1685</p> <p> $F \text{ см}^2 = 0.901$ $Q \text{ кг.} = 0.244$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 93.7$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-1690</p> <p> $F \text{ см}^2 = 0.670$ $Q \text{ кг.} = 0.182$ $D \text{ оп.мм} = 35.5$ $P \text{ н.мм} = 136.9$ Гр. сл. = V Точн. = П </p>










	<p>БПО-1691</p> <p> $F \text{ см}^2 = 13.080$ $Q \text{ кг.} = 3.545$ $D \text{ оп.мм} = 127.4$ $P \text{ н.мм} = 356.4$ Гр. сл. = V Точн. = П </p>		<p>БПО-1696</p> <p> $F \text{ см}^2 = 1.750$ $Q \text{ кг.} = 0.474$ $D \text{ оп.мм} = 54.6$ $P \text{ н.мм} = 229.3$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1692</p> <p> $F \text{ см}^2 = 1.370$ $Q \text{ кг.} = 0.371$ $D \text{ оп.мм} = 105.6$ $P \text{ н.мм} = 232.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1697</p> <p> $F \text{ см}^2 = 1.490$ $Q \text{ кг.} = 0.404$ $D \text{ оп.мм} = 48.1$ $P \text{ н.мм} = 203.3$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1693</p> <p> $F \text{ см}^2 = 3.040$ $Q \text{ кг.} = 0.824$ $D \text{ оп.мм} = 50.1$ $P \text{ н.мм} = 160.0$ Гр. сл. = II Точн. = DIN </p>		<p>БПО-1698</p> <p> $F \text{ см}^2 = 6.591$ $Q \text{ кг.} = 1.786$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 105.3$ Гр. сл. = I Точн. = H </p>
	<p>БПО-1694</p> <p> $F \text{ см}^2 = 1.760$ $Q \text{ кг.} = 0.477$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 180.0$ Гр. сл. = IV Точн. = DIN </p>		<p>БПО-1699</p> <p> $F \text{ см}^2 = 5.576$ $Q \text{ кг.} = 1.511$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 91.5$ Гр. сл. = II Точн. = П </p>
	<p>БПО-1695</p> <p> $F \text{ см}^2 = 1.940$ $Q \text{ кг.} = 0.526$ $D \text{ оп.мм} = 54.3$ $P \text{ н.мм} = 256.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-1700</p> <p> $F \text{ см}^2 = 1.473$ $Q \text{ кг.} = 0.399$ $D \text{ оп.мм} = 53.4$ $P \text{ н.мм} = 199.5$ Гр. сл. = V Точн. = H </p>











	<p>БПО-1701</p> <p> $F \text{ см}^2 = 1.727$ $Q \text{ кг.} = 0.468$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 233.3$ Гр. сл. = V Точн. = Н </p>		
	<p>БПО-1702</p> <p> $F \text{ см}^2 = 2.457$ $Q \text{ кг.} = 0.666$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 315.9$ Гр. сл. = VI Точн. = П </p>		
	<p>БПО-1703</p> <p> $F \text{ см}^2 = 2.633$ $Q \text{ кг.} = 0.714$ $D \text{ оп.мм} = 51.8$ $P \text{ н.мм} = 327.3$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1708</p> <p> $F \text{ см}^2 = 7.080$ $Q \text{ кг.} = 1.919$ $D \text{ оп.мм} = 74.3$ $P \text{ н.мм} = 239.0$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1704</p> <p> $F \text{ см}^2 = 2.847$ $Q \text{ кг.} = 0.772$ $D \text{ оп.мм} = 63.5$ $P \text{ н.мм} = 360.4$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1709</p> <p> $F \text{ см}^2 = 1.560$ $Q \text{ кг.} = 0.423$ $D \text{ оп.мм} = 42.7$ $P \text{ н.мм} = 110.0$ Гр. сл. = I Точн. = DIN </p>
	<p>БПО-1705</p> <p> $F \text{ см}^2 = 3.228$ $Q \text{ кг.} = 0.875$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 331.9$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1710</p> <p> $F \text{ см}^2 = 18.560$ $Q \text{ кг.} = 5.030$ $D \text{ оп.мм} = 169.7$ $P \text{ н.мм} = 480.0$ Гр. сл. = II Точн. = П </p>











	<p>БПО-1711</p> <p> $F \text{ см}^2 = 14.720$ $Q \text{ кг.} = 3.989$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 384.0$ Гр. сл. = II Точн. = П </p>		<p>БПО-1716</p> <p> $F \text{ см}^2 = 1.415$ $Q \text{ кг.} = 0.383$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 147.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1712</p> <p> $F \text{ см}^2 = 2.460$ $Q \text{ кг.} = 0.667$ $D \text{ оп.мм} = 72.0$ $P \text{ н.мм} = 170.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1717</p> <p> $F \text{ см}^2 = 1.549$ $Q \text{ кг.} = 0.420$ $D \text{ оп.мм} = 57.1$ $P \text{ н.мм} = 173.3$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1713</p> <p> $F \text{ см}^2 = 12.084$ $Q \text{ кг.} = 3.275$ $D \text{ оп.мм} = 107.3$ $P \text{ н.мм} = 807.9$ Гр. сл. = 0соб. Точн. = Н </p>		
	<p>БПО-1714</p> <p> $F \text{ см}^2 = 4.658$ $Q \text{ кг.} = 1.262$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 454.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1719</p> <p> $F \text{ см}^2 = 2.937$ $Q \text{ кг.} = 0.796$ $D \text{ оп.мм} = 102.0$ $P \text{ н.мм} = 239.8$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1715</p> <p> $F \text{ см}^2 = 2.810$ $Q \text{ кг.} = 0.762$ $D \text{ оп.мм} = 68.0$ $P \text{ н.мм} = 2.7$ Гр. сл. = V Точн. = Н </p>		<p>БПО-1720</p> <p> $F \text{ см}^2 = 1.168$ $Q \text{ кг.} = 0.317$ $D \text{ оп.мм} = 36.4$ $P \text{ н.мм} = 104.6$ Гр. сл. = II Точн. = П </p>










	<p>БПО-1721</p> <p> $F \text{ см}^2 = 1.160$ $Q \text{ кг.} = 0.314$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 174.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-1726</p> <p> $F \text{ см}^2 = 2.150$ $Q \text{ кг.} = 0.583$ $D \text{ оп.мм} = 91.4$ $P \text{ н.мм} = 256.4$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1722</p> <p> $F \text{ см}^2 = 1.451$ $Q \text{ кг.} = 0.393$ $D \text{ оп.мм} = 53.0$ $P \text{ н.мм} = 165.0$ Гр. сл. = V Точн. = Н </p>		
	<p>БПО-1723</p> <p> $F \text{ см}^2 = 1.367$ $Q \text{ кг.} = 0.370$ $D \text{ оп.мм} = 51.6$ $P \text{ н.мм} = 153.0$ Гр. сл. = V Точн. = П </p>		
	<p>БПО-1724</p> <p> $F \text{ см}^2 = 1.762$ $Q \text{ кг.} = 0.478$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 209.0$ Гр. сл. = VI Точн. = П </p>		
	<p>БПО-1725</p> <p> $F \text{ см}^2 = 2.300$ $Q \text{ кг.} = 0.623$ $D \text{ оп.мм} = 70.3$ $P \text{ н.мм} = 278.4$ Гр. сл. = IV Точн. = П </p>		









	БПО-1731 $F \text{ см}^2 = 1.780$ $Q \text{ кг.} = 0.482$ $D \text{ оп.мм} = 112$ $P \text{ н.мм} = 263$ Гр. сл. = 0соб. Точн. = П		БПО-1736 $F \text{ см}^2 = 1.182$ $Q \text{ кг.} = 0.320$ $D \text{ оп.мм} = 48.7$ $P \text{ н.мм} = 152.9$ Гр. сл. = VI Точн. = П
	БПО-1732 $F \text{ см}^2 = 1.720$ $Q \text{ кг.} = 0.463$ $D \text{ оп.мм} = 112$ $P \text{ н.мм} = 254$ Гр. сл. = 0соб. Точн. = П		БПО-1737 $F \text{ см}^2 = 0.627$ $Q \text{ кг.} = 0.170$ $D \text{ оп.мм} = 30.6$ $P \text{ н.мм} = 76.4$ Гр. сл. = III Точн. = П
	БПО-1733 $F \text{ см}^2 = 1.680$ $Q \text{ кг.} = 0.455$ $D \text{ оп.мм} = 112$ $P \text{ н.мм} = 250$ Гр. сл. = 0соб. Точн. = П		БПО-1738 $F \text{ см}^2 = 1.437$ $Q \text{ кг.} = 0.389$ $D \text{ оп.мм} = 43.0$ $P \text{ н.мм} = 120.0$ Гр. сл. = II Точн. = П
	БПО-1734 $F \text{ см}^2 = 1.720$ $Q \text{ кг.} = 0.463$ $D \text{ оп.мм} = 112$ $P \text{ н.мм} = 258$ Гр. сл. = 0соб. Точн. = П		БПО-1739 $F \text{ см}^2 = 1.660$ $Q \text{ кг.} = 0.450$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 170.0$ Гр. сл. = IV Точн. = П
	БПО-1735 $F \text{ см}^2 = 1.136$ $Q \text{ кг.} = 0.308$ $D \text{ оп.мм} = 45.3$ $P \text{ н.мм} = 147.0$ Гр. сл. = VI Точн. = П		БПО-1740 $F \text{ см}^2 = 2.760$ $Q \text{ кг.} = 0.748$ $D \text{ оп.мм} = 114.0$ $P \text{ н.мм} = 280.0$ Гр. сл. = 0соб. Точн. = П









	<p>БПО-1741</p> <p> $F \text{ см}^2 = 0.810$ $Q \text{ кг.} = 0.220$ $D \text{ оп.мм} = 21.3$ $P \text{ н.мм} = 60.0$ Гр. сл. = I Точн. = П </p>		<p>БПО-1746</p> <p> $F \text{ см}^2 = 1.080$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм} = 32.5$ $P \text{ н.мм} = 112.0$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1742</p>		<p>БПО-1747</p> <p> $F \text{ см}^2 = 3.320$ $Q \text{ кг.} = 0.900$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 206.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1743</p> <p> $F \text{ см}^2 = 2.360$ $Q \text{ кг.} = 0.640$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 240.0$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1748</p> <p> $F \text{ см}^2 = 0.688$ $Q \text{ кг.} = 0.186$ $D \text{ оп.мм} = 19.0$ $P \text{ н.мм} = 71.6$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1744</p> <p> $F \text{ см}^2 = 1.260$ $Q \text{ кг.} = 0.341$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 90.0$ Гр. сл. = I Точн. = П </p>		<p>БПО-1749</p> <p> $F \text{ см}^2 = 1.310$ $Q \text{ кг.} = 0.355$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 197.2$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-1745</p> <p> $F \text{ см}^2 = 3.080$ $Q \text{ кг.} = 0.835$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 206.0$ Гр. сл. = V Точн. = Н </p>		<p>БПО-1750</p> <p> $F \text{ см}^2 = 4.295$ $Q \text{ кг.} = 1.164$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 243.7$ Гр. сл. = III Точн. = Н </p>









	<p>БПО-1751</p> <p> $F \text{ см}^2 = 2.100$ $Q \text{ кг.} = 0.569$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 165.1$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1756</p> <p> $F \text{ см}^2 = 1.390$ $Q \text{ кг.} = 0.377$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 105.5$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1752</p> <p> $F \text{ см}^2 = 3.239$ $Q \text{ кг.} = 0.878$ $D \text{ оп.мм} = 59.4$ $P \text{ н.мм} = 207.1$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1757</p> <p> $F \text{ см}^2 = 1.390$ $Q \text{ кг.} = 0.377$ $D \text{ оп.мм} = 45.7$ $P \text{ н.мм} = 143.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1753</p> <p> $F \text{ см}^2 = 3.861$ $Q \text{ кг.} = 1.046$ $D \text{ оп.мм} = 59.4$ $P \text{ н.мм} = 230.2$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1758</p> <p> $F \text{ см}^2 = 1.730$ $Q \text{ кг.} = 0.469$ $D \text{ оп.мм} = 45.9$ $P \text{ н.мм} = 129.3$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1754</p> <p> $F \text{ см}^2 = 2.708$ $Q \text{ кг.} = 0.73$ $D \text{ оп.мм} = 56$ $P \text{ н.мм} = 180.6$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1759</p> <p> $F \text{ см}^2 = 1.241$ $Q \text{ кг.} = 0.336$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 95.3$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1755</p> <p> $F \text{ см}^2 = 1.370$ $Q \text{ кг.} = 0.371$ $D \text{ оп.мм} = 35.3$ $P \text{ н.мм} = 77.9$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1760</p> <p> $F \text{ см}^2 = 1.847$ $Q \text{ кг.} = 0.501$ $D \text{ оп.мм} = 40.2$ $P \text{ н.мм} = 104.8$ Гр. сл. = II Точн. = Н </p>










	<p>БПО-1761</p> <p> $F \text{ см}^2 = 4.360$ $Q \text{ кг.} = 1.182$ $D \text{ оп.мм} = 64.8$ $P \text{ н.мм} = 219.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-1766</p> <p> $F \text{ см}^2 = 8.500$ $Q \text{ кг.} = 2.304$ $D \text{ оп.мм} = 84.9$ $P \text{ н.мм} = 350.0$ Гр. сл. = II Точн. = □ </p>
	<p>БПО-1762</p> <p> $F \text{ см}^2 = 1.921$ $Q \text{ кг.} = 0.521$ $D \text{ оп.мм} = 73.6$ $P \text{ н.мм} = 298.5$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-1767</p> <p> $F \text{ см}^2 = 0.490$ $Q \text{ кг.} = 0.133$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 100.0$ Гр. сл. = IV Точн. = □ </p>
	<p>БПО-1763</p> <p> $F \text{ см}^2 = 1.261$ $Q \text{ кг.} = 0.342$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 105.6$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1768</p> <p> $F \text{ см}^2 = 0.754$ $Q \text{ кг.} = 0.204$ $D \text{ оп.мм} = 45.3$ $P \text{ н.мм} = 128.0$ Гр. сл. = V Точн. = □ </p>
	<p>БПО-1764</p> <p> $F \text{ см}^2 = 1.410$ $Q \text{ кг.} = 0.382$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 110.6$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1769</p> <p> $F \text{ см}^2 = 0.898$ $Q \text{ кг.} = 0.243$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 152.0$ Гр. сл. = V Точн. = □ </p>
	<p>БПО-1765</p> <p> $F \text{ см}^2 = 4.861$ $Q \text{ кг.} = 1.317$ $D \text{ оп.мм} = 86.7$ $P \text{ н.мм} = 218.9$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1770</p> <p> $F \text{ см}^2 = 1.186$ $Q \text{ кг.} = 0.321$ $D \text{ оп.мм} = 70.8$ $P \text{ н.мм} = 200.0$ Гр. сл. = 0соб. Точн. = □ </p>











	<p>БПО-1771</p> <p> $F \text{ см}^2 = 1.140$ $Q \text{ кг.} = 0.309$ $D \text{ оп.мм} = 32.1$ $P \text{ н.мм} = 82.0$ Гр. сл. = II Точн. = □ </p>		<p>БПО-1776</p> <p> $F \text{ см}^2 = 0.684$ $Q \text{ кг.} = 0.185$ $D \text{ оп.мм} = 28.7$ $P \text{ н.мм} = 116.4$ Гр. сл. = IV Точн. = □ </p>
	<p>БПО-1772</p> <p> $F \text{ см}^2 = 0.750$ $Q \text{ кг.} = 0.203$ $D \text{ оп.мм} = 25.2$ $P \text{ н.мм} = 56.0$ Гр. сл. = I Точн. = □ </p>		<p>БПО-1777</p> <p> $F \text{ см}^2 = 0.468$ $Q \text{ кг.} = 0.127$ $D \text{ оп.мм} = 23.7$ $P \text{ н.мм} = 80.4$ Гр. сл. = IV Точн. = □ </p>
	<p>БПО-1773</p> <p> $F \text{ см}^2 = 0.480$ $Q \text{ кг.} = 0.130$ $D \text{ оп.мм} = 32.2$ $P \text{ н.мм} = 67.0$ Гр. сл. = I Точн. = □ </p>		
	<p>БПО-1774</p> <p> $F \text{ см}^2 = 0.640$ $Q \text{ кг.} = 0.173$ $D \text{ оп.мм} = 32.1$ $P \text{ н.мм} = 68.0$ Гр. сл. = II Точн. = □ </p>		<p>БПО-1779</p> <p> $F \text{ см}^2 = 0.660$ $Q \text{ кг.} = 0.179$ $D \text{ оп.мм} = 20.6$ $P \text{ н.мм} = 66.0$ Гр. сл. = III Точн. = □ </p>
	<p>БПО-1775</p> <p> $F \text{ см}^2 = 0.576$ $Q \text{ кг.} = 0.156$ $D \text{ оп.мм} = 24.4$ $P \text{ н.мм} = 98.4$ Гр. сл. = IV Точн. = □ </p>		<p>БПО-1780</p> <p> $F \text{ см}^2 = 3.480$ $Q \text{ кг.} = 0.943$ $D \text{ оп.мм} = 59.0$ $P \text{ н.мм} = 150.0$ Гр. сл. = IV Точн. = H </p>











			БПО-1786
			$F \text{ см}^2 = 0.788$ $Q \text{ кг.} = 0.214$ $D \text{ оп.мм} = 36.2$ $P \text{ н.мм} = 116.0$ Гр. сл. = IV Точн. = П
			БПО-1787
			$F \text{ см}^2 = 2.032$ $Q \text{ кг.} = 0.551$ $D \text{ оп.мм} = 109.0$ $P \text{ н.мм} = 241.0$ Гр. сл. = IV Точн. = П
	БПО-1783		БПО-1788
	$F \text{ см}^2 = 0.370$ $Q \text{ кг.} = 0.100$ $D \text{ оп.мм} = 21.8$ $P \text{ н.мм} = 52.8$ Гр. сл. = IV Точн. = П		$F \text{ см}^2 = 3.000$ $Q \text{ кг.} = 0.814$ $D \text{ оп.мм} = 113.0$ $P \text{ н.мм} = 309.6$ Гр. сл. = IV Точн. = П
	БПО-1784		БПО-1789
	$F \text{ см}^2 = 0.510$ $Q \text{ кг.} = 0.138$ $D \text{ оп.мм} = 27.6$ $P \text{ н.мм} = 56.1$ Гр. сл. = IV Точн. = П		$F \text{ см}^2 = 1.613$ $Q \text{ кг.} = 0.437$ $D \text{ оп.мм} = 46.6$ $P \text{ н.мм} = 251.7$ Гр. сл. = V Точн. = П
	БПО-1785-1		БПО-1790
	$F \text{ см}^2 = 1.312$ $Q \text{ кг.} = 0.355$ $D \text{ оп.мм} = 48.2$ $P \text{ н.мм} = 249.6$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 1.530$ $Q \text{ кг.} = 0.415$ $D \text{ оп.мм} = 49.6$ $P \text{ н.мм} = 240.0$ Гр. сл. = V Точн. = П











	<p>БПО-1791</p> <p> $F \text{ см}^2 = 0.403$ $Q \text{ кг.} = 0.109$ $D \text{ оп.мм} = 16.3$ $P \text{ н.мм} = 69.6$ Гр. сл. = V Точн. = П </p>		<p>БПО-1796</p> <p> $F \text{ см}^2 = 8.000$ $Q \text{ кг.} = 2.168$ $D \text{ оп.мм} = 82.2$ $P \text{ н.мм} = 392.0$ Гр. сл. = 0соб. Точн. = Н </p>
			<p>БПО-1797</p> <p> $F \text{ см}^2 = 7.666$ $Q \text{ кг.} = 2.077$ $D \text{ оп.мм} = 171.0$ $P \text{ н.мм} = 702.6$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-1793</p> <p> $F \text{ см}^2 = 8.872$ $Q \text{ кг.} = 2.404$ $D \text{ оп.мм} = 189.0$ $P \text{ н.мм} = 523.7$ Гр. сл. = 0соб. Точн. = П </p>		
	<p>БПО-1794</p> <p> $F \text{ см}^2 = 2.270$ $Q \text{ кг.} = 0.615$ $D \text{ оп.мм} = 60.8$ $P \text{ н.мм} = 241.7$ Гр. сл. = III Точн. = П </p>		<p>БПО-1799</p> <p> $F \text{ см}^2 = 2.281$ $Q \text{ кг.} = 0.618$ $D \text{ оп.мм} = 74.2$ $P \text{ н.мм} = 287.7$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1795</p> <p> $F \text{ см}^2 = 0.280$ $Q \text{ кг.} = 0.076$ $D \text{ оп.мм} = 16.2$ $P \text{ н.мм} = 44.2$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1800</p> <p> $F \text{ см}^2 = 2.020$ $Q \text{ кг.} = 0.547$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 216.7$ Гр. сл. = V Точн. = П </p>






	<p>БПО-1801</p> <p> $F \text{ см}^2 = 3.970$ $Q \text{ кг.} = 1.076$ $D \text{ оп.мм} = 161.0$ $P \text{ н.мм} = 389.1$ Гр. сл. = V Точн. = П </p>		<p>БПО-1806</p>
	<p>БПО-1802</p> <p> $F \text{ см}^2 = 3.596$ $Q \text{ кг.} = 0.975$ $D \text{ оп.мм} = 88.0$ $P \text{ н.мм} = 356.6$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1807</p> <p> $F \text{ см}^2 = 15.000$ $Q \text{ кг.} = 4.065$ $D \text{ оп.мм} = 142$ $P \text{ н.мм} = 608.5$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1803</p> <p> $F \text{ см}^2 = 9.280$ $Q \text{ кг.} = 2.515$ $D \text{ оп.мм} = 113.2$ $P \text{ н.мм} = 472.0$ Гр. сл. = III Точн. = П </p>		<p>БПО-1808</p> <p> $F \text{ см}^2 = 2.166$ $Q \text{ кг.} = 0.587$ $D \text{ оп.мм} = 100$ $P \text{ н.мм} = 262$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1804</p> <p> $F \text{ см}^2 = 2.545$ $Q \text{ кг.} = 0.690$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 56.6$ Гр. сл. = I Точн. = П </p>		<p>БПО-1809</p> <p> $F \text{ см}^2 = 1.193$ $Q \text{ кг.} = 0.323$ $D \text{ оп.мм} = 46.5$ $P \text{ н.мм} = 162$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1805</p> <p> $F \text{ см}^2 = 16.000$ $Q \text{ кг.} = 4.336$ $D \text{ оп.мм} = 56.6$ $P \text{ н.мм} = 160.0$ Гр. сл. = I Точн. = П </p>		<p>БПО-1810</p>







	<p>БПО-1811</p> <p> $F \text{ см}^2 = 1.331$ $Q \text{ кг.} = 0.361$ $D \text{ оп.мм} = 86.0$ $P \text{ н.мм} = 199.2$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1816</p> <p> $F \text{ см}^2 = 5.325$ $Q \text{ кг.} = 1.443$ $D \text{ оп.мм} = 68.0$ $P \text{ н.мм} = 311.4$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-1812</p> <p> $F \text{ см}^2 = 4.250$ $Q \text{ кг.} = 1.152$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 180.0$ Гр. сл. = II Точн. = П </p>		<p>БПО-1817</p> <p> $F \text{ см}^2 = 3.600$ $Q \text{ кг.} = 0.976$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 188.0$ Гр. сл. = II Точн. = П </p>
	<p>БПО-1813</p> <p> $F \text{ см}^2 = 4.240$ $Q \text{ кг.} = 1.149$ $D \text{ оп.мм} = 78.1$ $P \text{ н.мм} = 220.0$ Гр. сл. = II Точн. = П </p>		<p>БПО-1818</p> <p> $F \text{ см}^2 = 5.200$ $Q \text{ кг.} = 1.409$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 146.0$ Гр. сл. = I Точн. = П </p>
	<p>БПО-1814</p> <p> $F \text{ см}^2 = 6.080$ $Q \text{ кг.} = 1.648$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 312.0$ Гр. сл. = III Точн. = П </p>		<p>БПО-1819</p> <p> $F \text{ см}^2 = 5.400$ $Q \text{ кг.} = 1.463$ $D \text{ оп.мм} = 114.0$ $P \text{ н.мм} = 366.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1815</p>		<p>БПО-1820</p> <p> $F \text{ см}^2 = 2.410$ $Q \text{ кг.} = 0.653$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 184.7$ Гр. сл. = 0соб. Точн. = П </p>









	БПО-1821 $F \text{ см}^2 = 1.845$ $Q \text{ кг.} = 0.500$ $D \text{ оп.мм} = 86.0$ $P \text{ н.мм} = 249.0$ Гр. сл. = 0соб. Точн. = П		БПО-1826 $F \text{ см}^2 = 0.840$ $Q \text{ кг.} = 0.228$ $D \text{ оп.мм} = 29.6$ $P \text{ н.мм} = 153.0$ Гр. сл. = V Точн. = П
	БПО-1822 $F \text{ см}^2 = 2.113$ $Q \text{ кг.} = 0.573$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 252.0$ Гр. сл. = 0соб. Точн. = П		БПО-1827 $F \text{ см}^2 = 3.220$ $Q \text{ кг.} = 0.873$ $D \text{ оп.мм} = 151.0$ $P \text{ н.мм} = 404.3$ Гр. сл. = 0соб. Точн. = П
	БПО-1823 $F \text{ см}^2 = 1.080$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм} = 60.5$ $P \text{ н.мм} = 147.0$ Гр. сл. = 0соб. Точн. = П		БПО-1828 $F \text{ см}^2 = 1.154$ $Q \text{ кг.} = 0.313$ $D \text{ оп.мм} = 41.9$ $P \text{ н.мм} = 153.6$ Гр. сл. = IV Точн. = П
	БПО-1824 $F \text{ см}^2 = 8.700$ $Q \text{ кг.} = 2.358$ $D \text{ оп.мм} = 146.0$ $P \text{ н.мм} = 302.0$ Гр. сл. = II Точн. = Н		БПО-1829 $F \text{ см}^2 = 6.000$ $Q \text{ кг.} = 1.626$ $D \text{ оп.мм} = 81.0$ $P \text{ н.мм} = 243.7$ Гр. сл. = VI Точн. = П
	БПО-1825 $F \text{ см}^2 = 0.506$ $Q \text{ кг.} = 0.137$ $D \text{ оп.мм} = 16.8$ $P \text{ н.мм} = 89.0$ Гр. сл. = VI Точн. = П		БПО-1830 $F \text{ см}^2 = 0.531$ $Q \text{ кг.} = 0.144$ $D \text{ оп.мм} = 18.3$ $P \text{ н.мм} = 41.1$ Гр. сл. = I Точн. = П











	<p>БПО-1831</p> <p> $F \text{ см}^2 = 0.881$ $Q \text{ кг.} = 0.239$ $D \text{ оп.мм} = 30.3$ $P \text{ н.мм} = 64.7$ Гр. сл. = I Точн. = Н </p>		<p>БПО-1836</p> <p> $F \text{ см}^2 = 2.019$ $Q \text{ кг.} = 0.547$ $D \text{ оп.мм} = 60.2$ $P \text{ н.мм} = 235.2$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1832</p> <p> $F \text{ см}^2 = 1.140$ $Q \text{ кг.} = 0.309$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 62.0$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1837</p> <p> $F \text{ см}^2 = 1.523$ $Q \text{ кг.} = 0.413$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 174.7$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1833</p> <p> $F \text{ см}^2 = 1.618$ $Q \text{ кг.} = 0.438$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 218.4$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1838</p> <p> $F \text{ см}^2 = 1.200$ $Q \text{ кг.} = 0.325$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 153.2$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1834</p> <p> $F \text{ см}^2 = 34.810$ $Q \text{ кг.} = 9.434$ $D \text{ оп.мм} = 161.1$ $P \text{ н.мм} = 380.6$ Гр. сл. = II Точн. = П </p>		<p>БПО-1839</p> <p> $F \text{ см}^2 = 1.220$ $Q \text{ кг.} = 0.331$ $D \text{ оп.мм} = 62.1$ $P \text{ н.мм} = 165.1$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1835</p> <p> $F \text{ см}^2 = 1.300$ $Q \text{ кг.} = 0.352$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 102.9$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1840</p> <p> $F \text{ см}^2 = 0.786$ $Q \text{ кг.} = 0.213$ $D \text{ оп.мм} = 36.5$ $P \text{ н.мм} = 159.5$ Гр. сл. = 0соб. Точн. = П </p>






	БПО-1841 $F \text{ см}^2 = 1.194$ $Q \text{ кг.} = 0.324$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 166.8$ Гр. сл. = 0соб. Точн. = П		БПО-1846 $F \text{ см}^2 = 0.864$ $Q \text{ кг.} = 0.234$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 124.5$ Гр. сл. = VI Точн. = Н
	БПО-1842 $F \text{ см}^2 = 2.145$ $Q \text{ кг.} = 0.581$ $D \text{ оп.мм} = 69.5$ $P \text{ н.мм} = 254.2$ Гр. сл. = I Точн. = П		БПО-1847 $F \text{ см}^2 = 0.723$ $Q \text{ кг.} = 0.196$ $D \text{ оп.мм} = 29.5$ $P \text{ н.мм} = 101.7$ Гр. сл. = V Точн. = П
	БПО-1843 $F \text{ см}^2 = 31.81$ $Q \text{ кг.} = 8.621$ $D \text{ оп.мм} = 166$ $P \text{ н.мм} = 341.9$ Гр. сл. = 0соб. Точн. = П		БПО-1848 $F \text{ см}^2 = 0.510$ $Q \text{ кг.} = 0.138$ $D \text{ оп.мм} = 23.9$ $P \text{ н.мм} = 74.6$ Гр. сл. = IV Точн. = Н
	БПО-1844 $F \text{ см}^2 = 7.700$ $Q \text{ кг.} = 2.087$ $D \text{ оп.мм} = 110.2$ $P \text{ н.мм} = 234.0$ Гр. сл. = I Точн. = Н		БПО-1849 $F \text{ см}^2 = 0.303$ $Q \text{ кг.} = 0.082$ $D \text{ оп.мм} = 20.8$ $P \text{ н.мм} = 61.3$ Гр. сл. = IV Точн. = П
	БПО-1845 $F \text{ см}^2 = 9.600$ $Q \text{ кг.} = 2.602$ $D \text{ оп.мм} = 120.3$ $P \text{ н.мм} = 256.0$ Гр. сл. = 0соб. Точн. = Н		БПО-1850 $F \text{ см}^2 = 0.313$ $Q \text{ кг.} = 0.085$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 63.3$ Гр. сл. = IV Точн. = П











	БПО-1851		БПО-1856
	<p> $F \text{ см}^2 = 0.532$ $Q \text{ кг.} = 0.144$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 90.2$ Гр. сл. = V Точн. = П </p>		
	БПО-1852		БПО-1857
	БПО-1853		БПО-1858
	<p> $F \text{ см}^2 = 0.889$ $Q \text{ кг.} = 0.241$ $D \text{ оп.мм} = 47.8$ $P \text{ н.мм} = 121.4$ Гр. сл. = IV Точн. = П </p>		
	БПО-1854		БПО-1859
	<p> $F \text{ см}^2 = 1.133$ $Q \text{ кг.} = 0.307$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 149.6$ Гр. сл. = V Точн. = П </p>		<p> $F \text{ см}^2 = 0.395$ $Q \text{ кг.} = 0.107$ $D \text{ оп.мм} = 17.2$ $P \text{ н.мм} = 57.2$ Гр. сл. = IV Точн. = П </p>
	БПО-1855		БПО-1860
			<p> $F \text{ см}^2 = 0.402$ $Q \text{ кг.} = 0.109$ $D \text{ оп.мм} = 18.3$ $P \text{ н.мм} = 63.3$ Гр. сл. = IV Точн. = П </p>








	БПО-1861		БПО-1866
			$F \text{ см}^2 = 0.801$ $Q \text{ кг.} = 0.217$ $D \text{ оп.мм} = 32.3$ $P \text{ н.мм} = 79.8$ Гр. сл. = IV Точн. = П
	БПО-1862		БПО-1867
	БПО-1863		БПО-1868
	$F \text{ см}^2 = 0.945$ $Q \text{ кг.} = 0.256$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 152.9$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 = 0.629$ $Q \text{ кг.} = 0.170$ $D \text{ оп.мм} = 28.6$ $P \text{ н.мм} = 101.2$ Гр. сл. = V Точн. = П
	БПО-1864		БПО-1869
	$F \text{ см}^2 = 0.561$ $Q \text{ кг.} = 0.152$ $D \text{ оп.мм} = 21.3$ $P \text{ н.мм} = 94.3$ Гр. сл. = Особ. Точн. = П		$F \text{ см}^2 = 3.360$ $Q \text{ кг.} = 0.911$ $D \text{ оп.мм} = 102.5$ $P \text{ н.мм} = 371.0$ Гр. сл. = IV Точн. = П
	БПО-1865		БПО-1870
			$F \text{ см}^2 = 1.383$ $Q \text{ кг.} = 0.375$ $D \text{ оп.мм} = 47.1$ $P \text{ н.мм} = 169.0$ Гр. сл. = V Точн. = П






	<p>БПО-1871</p> <p> $F \text{ см}^2 = 0.468$ $Q \text{ кг.} = 0.127$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 80.4$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1876</p> <p> $F \text{ см}^2 = 1.567$ $Q \text{ кг.} = 0.425$ $D \text{ оп.мм} = 85$ $P \text{ н.мм} = 243.3$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-1872</p> <p> $F \text{ см}^2 = 1.910$ $Q \text{ кг.} = 0.518$ $D \text{ оп.мм} = 48.9$ $P \text{ н.мм} = 234.2$ Гр. сл. = V Точн. = П </p>		<p>БПО-1877</p> <p> $F \text{ см}^2 = 3.373$ $Q \text{ кг.} = 0.914$ $D \text{ оп.мм} = 159$ $P \text{ н.мм} = 424.4$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1873</p> <p> $F \text{ см}^2 = 0.565$ $Q \text{ кг.} = 0.153$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 66.3$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1878</p> <p> $F \text{ см}^2 = 2.862$ $Q \text{ кг.} = 0.776$ $D \text{ оп.мм} = 141.6$ $P \text{ н.мм} = 384.1$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1874</p>		<p>БПО-1879</p> <p> $F \text{ см}^2 = 2.250$ $Q \text{ кг.} = 0.610$ $D \text{ оп.мм} = 115.4$ $P \text{ н.мм} = 323.8$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-1875</p>		<p>БПО-1880</p> <p> $F \text{ см}^2 = 2.560$ $Q \text{ кг.} = 0.694$ $D \text{ оп.мм} = 124$ $P \text{ н.мм} = 343.9$ Гр. сл. = IV Точн. = Н </p>









	<p>БПО-1881</p> <p> $F \text{ см}^2 = 3.53$ $Q \text{ кг.} = 0.957$ $D \text{ оп.мм} = 169$ $P \text{ н.мм} = 443.7$ Гр. сл. = Особ. Точн. = П </p>		<p>БПО-1886</p> <p> $F \text{ см}^2 = 2.909$ $Q \text{ кг.} = 0.788$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 174.1$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1882</p> <p> $F \text{ см}^2 = 3.77$ $Q \text{ кг.} = 1.022$ $D \text{ оп.мм} = 183.6$ $P \text{ н.мм} = 473.9$ Гр. сл. = Особ. Точн. = П </p>		<p>БПО-1887</p> <p> $F \text{ см}^2 = 5.301$ $Q \text{ кг.} = 1.437$ $D \text{ оп.мм} = 99.0$ $P \text{ н.мм} = 222.1$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-1883</p> <p> $F \text{ см}^2 = 1.033$ $Q \text{ кг.} = 0.280$ $D \text{ оп.мм} = 44.1$ $P \text{ н.мм} = 147.2$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1888</p> <p> $F \text{ см}^2 = 3.801$ $Q \text{ кг.} = 1.030$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 69.1$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1884</p> <p> $F \text{ см}^2 = 0.904$ $Q \text{ кг.} = 0.245$ $D \text{ оп.мм} = 31.5$ $P \text{ н.мм} = 152.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-1889</p> <p> $F \text{ см}^2 = 5.309$ $Q \text{ кг.} = 1.439$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 81.7$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1885</p> <p> $F \text{ см}^2 = 0.821$ $Q \text{ кг.} = 0.222$ $D \text{ оп.мм} = 30.1$ $P \text{ н.мм} = 138.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-1890</p> <p> $F \text{ см}^2 = 1.569$ $Q \text{ кг.} = 0.425$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 89.2$ Гр. сл. = IV Точн. = П </p>





	БПО-1891		БПО-1896
	$F \text{ см}^2 = 8.200$ $Q \text{ кг.} = 2.222$ $D \text{ оп.мм} = 144.0$ $P \text{ н.мм} = 514.9$ Гр. сл. = VI Точн. = П		
	БПО-1892		БПО-1897
	$F \text{ см}^2 = 1.595$ $Q \text{ кг.} = 0.432$ $D \text{ оп.мм} = 27$ $P \text{ н.мм} = 113.2$ Гр. сл. = II Точн. = П		
	БПО-1893		БПО-1898
			$F \text{ см}^2 = 1.031$ $Q \text{ кг.} = 0.279$ $D \text{ оп.мм} = 37.2$ $P \text{ н.мм} = 188$ Гр. сл. = V Точн. = П
	БПО-1894		БПО-1899
			$F \text{ см}^2 = 0.951$ $Q \text{ кг.} = 0.258$ $D \text{ оп.мм} = 34.2$ $P \text{ н.мм} = 173$ Гр. сл. = V Точн. = П
	БПО-1895		БПО-1900
	$F \text{ см}^2 = 1.01$ $Q \text{ кг.} = 0.274$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 124.8$ Гр. сл. = V Точн. = П		









	<p>БПО-1901-1</p> <p> $F \text{ см}^2 = 000$ $Q \text{ кг.} = 000$ $D \text{ оп.мм} = 000$ $P \text{ н.мм} = 000$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1906</p> <p> $F \text{ см}^2 = 9.400$ $Q \text{ кг.} = 2.547$ $D \text{ оп.мм} = 96$ $P \text{ н.мм} = 571.9$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1902</p> <p> $F \text{ см}^2 = 2.71$ $Q \text{ кг.} = 0.734$ $D \text{ оп.мм} = 133$ $P \text{ н.мм} = 364$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1907</p> <p> $F \text{ см}^2 = 7.413$ $Q \text{ кг.} = 2.010$ $D \text{ оп.мм} = 77$ $P \text{ н.мм} = 457$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1903</p> <p> $F \text{ см}^2 = 2.862$ $Q \text{ кг.} = 0.776$ $D \text{ оп.мм} = 141.6$ $P \text{ н.мм} = 384.1$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1908</p> <p> $F \text{ см}^2 = 12.380$ $Q \text{ кг.} = 3.355$ $D \text{ оп.мм} = 125$ $P \text{ н.мм} = 744.3$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-1904</p>		<p>БПО-1909</p> <p> $F \text{ см}^2 = 15.39$ $Q \text{ кг.} = 4.171$ $D \text{ оп.мм} = 128$ $P \text{ н.мм} = 1056$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-1905</p> <p> $F \text{ см}^2 = 4.431$ $Q \text{ кг.} = 1.200$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 284.6$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-1910</p> <p> $F \text{ см}^2 = 4.72$ $Q \text{ кг.} = 1.279$ $D \text{ оп.мм} = 180$ $P \text{ н.мм} = 476$ Гр. сл. = 0соб. Точн. = Н </p>

	<p>БПО-1911</p> <p> $F \text{ см}^2 = 2.771$ $Q \text{ кг.} = 0.751$ $D \text{ оп.мм} = 81$ $P \text{ н.мм} = 235.8$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1916</p> <p> $F \text{ см}^2 = 1.950$ $Q \text{ кг.} = 0.528$ $D \text{ оп.мм} = 80.8$ $P \text{ н.мм} = 268.4$ Гр. сл. = V Точн. = II </p>
	<p>БПО-1912</p> <p> $F \text{ см}^2 = 3.07$ $Q \text{ кг.} = 0.832$ $D \text{ оп.мм} = 86.4$ $P \text{ н.мм} = 235.5$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1917</p> <p> $F \text{ см}^2 = 2.110$ $Q \text{ кг.} = 0.571$ $D \text{ оп.мм} = 77$ $P \text{ н.мм} = 293.9$ Гр. сл. = V Точн. = II </p>
	<p>БПО-1913</p> <p> $F \text{ см}^2 = 3.96$ $Q \text{ кг.} = 1.073$ $D \text{ оп.мм} = 43$ $P \text{ н.мм} = 130$ Гр. сл. = III Точн. = Н </p>		<p>БПО-1918</p> <p> $F \text{ см}^2 = 3.110$ $Q \text{ кг.} = 0.840$ $D \text{ оп.мм} = 92.6$ $P \text{ н.мм} = 406$ Гр. сл. = V Точн. = II </p>
	<p>БПО-1914</p> <p> $F \text{ см}^2 = 0.470$ $Q \text{ кг.} = 0.127$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 63.2$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-1919</p>
	<p>БПО-1915</p>		<p>БПО-1920</p>








	БПО-1921		БПО-1926
	БПО-1922 $F \text{ см}^2 = 1.680$ $Q \text{ кг.} = 0.455$ $D \text{ оп.мм} = 54$ $P \text{ н.мм} = 202$ Гр. сл. = V Точн. = П		БПО-1927
	БПО-1923 $F \text{ см}^2 = 1.170$ $Q \text{ кг.} = 0.318$ $D \text{ оп.мм} = 46$ $P \text{ н.мм} = 130$ Гр. сл. = V Точн. = П		БПО-1928
	БПО-1924 $F \text{ см}^2 = 1.964$ $Q \text{ кг.} = 0.532$ $D \text{ оп.мм} = 82$ $P \text{ н.мм} = 267$ Гр. сл. = V Точн. = П		БПО-1929 $F \text{ см}^2 = 1.670$ $Q \text{ кг.} = 0.453$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 138.2$ Гр. сл. = III Точн. = Я
	БПО-1925 $F \text{ см}^2 = 0.789$ $Q \text{ кг.} = 0.214$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 108$ Гр. сл. = V Точн. = П		БПО-1930 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм} = 0$ $P \text{ н.мм} = 0$ Гр. сл. = 0 Точн. = Н






	<p>БПО-1931</p> <p> $F \text{ см}^2 = 0.746$ $Q \text{ кг.} = 0.202$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 102.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1936</p> <p> $F \text{ см}^2 = 1.060$ $Q \text{ кг.} = 0.287$ $D \text{ оп.мм} = 35.7$ $P \text{ н.мм} = 88.1$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-1932</p> <p> $F \text{ см}^2 = 1.257$ $Q \text{ кг.} = 0.341$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 187.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1937</p> <p> $F \text{ см}^2 = 1.148$ $Q \text{ кг.} = 0.311$ $D \text{ оп.мм} = 51.2$ $P \text{ н.мм} = 203.7$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1933</p> <p> $F \text{ см}^2 = 3.796$ $Q \text{ кг.} = 1.029$ $D \text{ оп.мм} = 51.2$ $P \text{ н.мм} = 203.7$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1938</p> <p> $F \text{ см}^2 = 0.950$ $Q \text{ кг.} = 0.257$ $D \text{ оп.мм} = 44.7$ $P \text{ н.мм} = 121.6$ Гр. сл. = VI Точн. = П </p>
			<p>БПО-1939</p> <p> $F \text{ см}^2 = 2.450$ $Q \text{ кг.} = 0.664$ $D \text{ оп.мм} = 77.6$ $P \text{ н.мм} = 280.6$ Гр. сл. = V Точн. = П </p>
			<p>БПО-1940</p> <p> $F \text{ см}^2 = 2.070$ $Q \text{ кг.} = 0.561$ $D \text{ оп.мм} = 69.8$ $P \text{ н.мм} = 206.0$ Гр. сл. = V Точн. = П </p>





	<p>БПО-1941</p> <p> $F \text{ см}^2 = 1.690$ $Q \text{ кг.} = 0.458$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 130.0$ Гр. сл. = V Точн. = П </p>		
	<p>БПО-1944</p> <p> $F \text{ см}^2 = 0.990$ $Q \text{ кг.} = 0.268$ $D \text{ оп.мм} = 32.7$ $P \text{ н.мм} = 82.1$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1949</p> <p> $F \text{ см}^2 = 4.530$ $Q \text{ кг.} = 1.228$ $D \text{ оп.мм} = 164.5$ $P \text{ н.мм} = 507.0$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-1950</p> <p> $F \text{ см}^2 = 3.640$ $Q \text{ кг.} = 0.986$ $D \text{ оп.мм} = 52.3$ $P \text{ н.мм} = 315.0$ Гр. сл. = VI Точн. = П </p>








	<p>БПО-1951</p> <p> $F \text{ см}^2 = 3.165$ $Q \text{ кг.} = 0.858$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 102.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-1956</p> <p> $F \text{ см}^2 = 2.460$ $Q \text{ кг.} = 0.667$ $D \text{ оп.мм} = 111.4$ $P \text{ н.мм} = 323.3$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1952</p> <p> $F \text{ см}^2 = 11.499$ $Q \text{ кг.} = 3.116$ $D \text{ оп.мм} = 166$ $P \text{ н.мм} = 1115.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-1957</p> <p> $F \text{ см}^2 = 2.783$ $Q \text{ кг.} = 0.754$ $D \text{ оп.мм} = 38.4$ $P \text{ н.мм} = 147.6$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-1953</p> <p> $F \text{ см}^2 = 0.317$ $Q \text{ кг.} = 0.086$ $D \text{ оп.мм} = 13.2$ $P \text{ н.мм} = 64.8$ Гр. сл. = VI Точн. = П </p>		<p>БПО-1958</p> <p> $F \text{ см}^2 = 2.160$ $Q \text{ кг.} = 0.585$ $D \text{ оп.мм} = 94.0$ $P \text{ н.мм} = 272.4$ Гр. сл. = V Точн. = П </p>
	<p>БПО-1954</p> <p> $F \text{ см}^2 = 0.901$ $Q \text{ кг.} = 0.244$ $D \text{ оп.мм} = 37.1$ $P \text{ н.мм} = 182.2$ Гр. сл. = VI Точн. = П </p>		
	<p>БПО-1955</p> <p> $F \text{ см}^2 = 2.750$ $Q \text{ кг.} = 0.745$ $D \text{ оп.мм} = 128.0$ $P \text{ н.мм} = 347.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-1960</p>










	БПО-1961 $F \text{ см}^2 = 2.984$ $Q \text{ кг.} = 0.809$ $D \text{ оп.мм} = 67.0$ $P \text{ н.мм} = 242.6$ Гр. сл. = IV Точн. = П		БПО-1966 $F \text{ см}^2 = 0.810$ $Q \text{ кг.} = 0.220$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 125.6$ Гр. сл. = - Точн. = П
	БПО-1962 $F \text{ см}^2 = 1.370$ $Q \text{ кг.} = 0.371$ $D \text{ оп.мм} = 55.8$ $P \text{ н.мм} = 173.3$ Гр. сл. = V Точн. = П		БПО-1967 $F \text{ см}^2 = 0.680$ $Q \text{ кг.} = 0.184$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 109.4$ Гр. сл. = Точн. = П
	БПО-1963 $F \text{ см}^2 = 3.080$ $Q \text{ кг.} = 0.835$ $D \text{ оп.мм} = 29.2$ $P \text{ н.мм} = 224.4$ Гр. сл. = - Точн. = П		БПО-1968 $F \text{ см}^2 = 0.430$ $Q \text{ кг.} = 0.117$ $D \text{ оп.мм} = 22.7$ $P \text{ н.мм} = 73.5$ Гр. сл. = Точн. = П
	БПО-1964 $F \text{ см}^2 = 1.700$ $Q \text{ кг.} = 0.461$ $D \text{ оп.мм} = 42.6$ $P \text{ н.мм} = 210.9$ Гр. сл. = Точн. = П		БПО-1969
	БПО-1965 $F \text{ см}^2 = 1.610$ $Q \text{ кг.} = 0.436$ $D \text{ оп.мм} = 40.6$ $P \text{ н.мм} = 199.7$ Гр. сл. = Точн. = П		БПО-1970 $F \text{ см}^2 = 0.970$ $Q \text{ кг.} = 0.263$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 87.2$ Гр. сл. = Точн. = П









	БПО-1971		БПО-1976
	БПО-1972 $F \text{ см}^2 = 5.220$ $Q \text{ кг.} = 1.415$ $D \text{ оп.мм} = 179.0$ $P \text{ н.мм} = 523.6$ Гр. сл. = V Точн. = П		БПО-1977 $F \text{ см}^2 = 7.423$ $Q \text{ кг.} = 2.012$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 222.2$ Гр. сл. = VI Точн. = П
	БПО-1973 $F \text{ см}^2 = 4.670$ $Q \text{ кг.} = 1.266$ $D \text{ оп.мм} = 158.0$ $P \text{ н.мм} = 470.0$ Гр. сл. = V Точн. = П		БПО-1978 $F \text{ см}^2 = 7.100$ $Q \text{ кг.} = 1.924$ $D \text{ оп.мм} = 132.4$ $P \text{ н.мм} = 310.0$ Гр. сл. = IV Точн. = П
	БПО-1974 $F \text{ см}^2 = 3.960$ $Q \text{ кг.} = 1.073$ $D \text{ оп.мм} = 127.6$ $P \text{ н.мм} = 546.9$ Гр. сл. = V Точн. = П		БПО-1979 $F \text{ см}^2 = 8.597$ $Q \text{ кг.} = 2.330$ $D \text{ оп.мм} = 131.7$ $P \text{ н.мм} = 327.5$ Гр. сл. = IV Точн. = П
	БПО-1975 $F \text{ см}^2 = 1.826$ $Q \text{ кг.} = 0.495$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 232.4$ Гр. сл. = IV Точн. = П		БПО-1980










	БПО-1981		БПО-1986
	БПО-1982		БПО-1987 $F \text{ см}^2 = 2.820$ $Q \text{ кг.} = 0.764$ $D \text{ оп.мм} = 77.3$ $P \text{ н.мм} = 244.3$ Гр. сл. = V Точн. = П
	БПО-1983 $F \text{ см}^2 = 18.970$ $Q \text{ кг.} = 5.141$ $D \text{ оп.мм} = 98.0$ $P \text{ н.мм} = 287.2$ Гр. сл. = V Точн. = П		БПО-1988 $F \text{ см}^2 = 1.340$ $Q \text{ кг.} = 0.363$ $D \text{ оп.мм} = 62.6$ $P \text{ н.мм} = 176.6$ Гр. сл. = IV Точн. = П
	БПО-1984 $F \text{ см}^2 = 2.560$ $Q \text{ кг.} = 0.694$ $D \text{ оп.мм} = 83.0$ $P \text{ н.мм} = 260.0$ Гр. сл. = V Точн. = Н		БПО-1989 $F \text{ см}^2 = 0.377$ $Q \text{ кг.} = 0.102$ $D \text{ оп.мм} = 19.0$ $P \text{ н.мм} = 43.4$ Гр. сл. = III Точн. = П
	БПО-1985		











	БПО-1991		БПО-1996
	БПО-1992		БПО-1997
	БПО-1993 $F \text{ см}^2 = 0.740$ $Q \text{ кг.} = 0.201$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 89.2$ Гр. сл. = III Точн. = П		БПО-1998
	БПО-1994 $F \text{ см}^2 = 2.160$ $Q \text{ кг.} = 0.585$ $D \text{ оп.мм} = 36.5$ $P \text{ н.мм} = 84.0$ Гр. сл. = II Точн. = Н		БПО-1999 $F \text{ см}^2 = 0.650$ $Q \text{ кг.} = 0.176$ $D \text{ оп.мм} = 27.4$ $P \text{ н.мм} = 100.0$ Гр. сл. = V Точн. = П
			БПО-2000 $F \text{ см}^2 = 1.450$ $Q \text{ кг.} = 0.393$ $D \text{ оп.мм} = 46.3$ $P \text{ н.мм} = 173.0$ Гр. сл. = V Точн. = П











	<p>БПО-2001</p> <p> $F \text{ см}^2 = 2.515$ $Q \text{ кг.} = 0.682$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 238.0$ Гр. сл. = V Точн. = П </p>		
	<p>БПО-2002</p> <p> $F \text{ см}^2 = 1.474$ $Q \text{ кг.} = 0.399$ $D \text{ оп.мм} = 30.5$ $P \text{ н.мм} = 70.1$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2007</p> <p> $F \text{ см}^2 = 5.552$ $Q \text{ кг.} = 1.505$ $D \text{ оп.мм} = 117.2$ $P \text{ н.мм} = 399.9$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2003</p> <p> $F \text{ см}^2 = 4.080$ $Q \text{ кг.} = 1.106$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 113.6$ Гр. сл. = III Точн. = Н </p>		
	<p>БПО-2004</p> <p> $F \text{ см}^2 = 6.606$ $Q \text{ кг.} = 1.790$ $D \text{ оп.мм} = 57.6$ $P \text{ н.мм} = 141.7$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2009</p>
	<p>БПО-2005</p> <p> $F \text{ см}^2 = 11.852$ $Q \text{ кг.} = 3.212$ $D \text{ оп.мм} = 77.1$ $P \text{ н.мм} = 202.9$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2010</p> <p> $F \text{ см}^2 = 9.487$ $Q \text{ кг.} = 2.571$ $D \text{ оп.мм} = 119.0$ $P \text{ н.мм} = 387.4$ Гр. сл. = IV Точн. = Н </p>











	<p>БПО-2011</p> <p> $F \text{ см}^2 = 5.888$ $Q \text{ кг.} = 1.596$ $D \text{ оп.мм} = 74$ $P \text{ н.мм} = 236.5$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2016</p> <p> $F \text{ см}^2 = 1.913$ $Q \text{ кг.} = 0.518$ $D \text{ оп.мм} = 59.0$ $P \text{ н.мм} = 187.8$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2012</p> <p> $F \text{ см}^2 = 9.243$ $Q \text{ кг.} = 2.5$ $D \text{ оп.мм} = 157$ $P \text{ н.мм} = 369$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2017</p> <p> $F \text{ см}^2 = 2.354$ $Q \text{ кг.} = 0.638$ $D \text{ оп.мм} = 85$ $P \text{ н.мм} = 260.9$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2013</p> <p> $F \text{ см}^2 = 8.214$ $Q \text{ кг.} = 2.226$ $D \text{ оп.мм} = 105.3$ $P \text{ н.мм} = 333.7$ Гр. сл. = III Точн. = Н </p>		
	<p>БПО-2014</p> <p> $F \text{ см}^2 = 8.806$ $Q \text{ кг.} = 2.386$ $D \text{ оп.мм} = 120.2$ $P \text{ н.мм} = 362.3$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2019</p> <p> $F \text{ см}^2 = 0.817$ $Q \text{ кг.} = 0.221$ $D \text{ оп.мм} = 33$ $P \text{ н.мм} = 131.1$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-2015</p> <p> $F \text{ см}^2 = 0.357$ $Q \text{ кг.} = 0.097$ $D \text{ оп.мм} = 22$ $P \text{ н.мм} = 68.3$ Гр. сл. = III Точн. = П </p>		<p>БПО-2020</p> <p> $F \text{ см}^2 = 0.998$ $Q \text{ кг.} = 0.267$ $D \text{ оп.мм} = 35.3$ $P \text{ н.мм} = 178.9$ Гр. сл. = V Точн. = П </p>











	<p>БПО-2021</p> <p> $F \text{ см}^2 = 0.707$ $Q \text{ кг.} = 0.192$ $D \text{ оп.мм} = 33$ $P \text{ н.мм} = 113.3$ Гр. сл. = V Точн. = П </p>		<p>БПО-2026</p> <p> $F \text{ см}^2 = 2.61$ $Q \text{ кг.} = 0.707$ $D \text{ оп.мм} = 36$ $P \text{ н.мм} = 304.1$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2022</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-2027</p> <p> $F \text{ см}^2 = 1.164$ $Q \text{ кг.} = 0.314$ $D \text{ оп.мм} = 47$ $P \text{ н.мм} = 166.6$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2023</p> <p> $F \text{ см}^2 = 2.28$ $Q \text{ кг.} = 0.618$ $D \text{ оп.мм} = 55$ $P \text{ н.мм} = 251$ Гр. сл. = V Точн. = П </p>		<p>БПО-2028</p> <p> $F \text{ см}^2 = 50.265$ $Q \text{ кг.} = 13.622$ $D \text{ оп.мм} = 80$ $P \text{ н.мм} = 80$ Гр. сл. = III Точн. = H </p>
	<p>БПО-2024</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-2029</p> <p> $F \text{ см}^2 = 1.083$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм} = 46$ $P \text{ н.мм} = 1.4$ Гр. сл. = IV Точн. = H </p>
	<p>БПО-2025</p> <p> $F \text{ см}^2 = 1.59$ $Q \text{ кг.} = 0.431$ $D \text{ оп.мм} = 44.6$ $P \text{ н.мм} = 138.7$ Гр. сл. = V Точн. = П </p>		<p>БПО-2030</p> <p> $F \text{ см}^2 = 4.886$ $Q \text{ кг.} = 1.324$ $D \text{ оп.мм} = 153$ $P \text{ н.мм} = 482.7$ Гр. сл. = V Точн. = П </p>











	<p>БПО-2031</p> <p> $F \text{ см}^2 = 4.749$ $Q \text{ кг.} = 1.287$ $D \text{ оп.мм} = 124$ $P \text{ н.мм} = 449$ Гр. сл. = V Точн. = П </p>		<p>БПО-2036</p> <p> $F \text{ см}^2 = 1.623$ $Q \text{ кг.} = 0.44$ $D \text{ оп.мм} = 34.1$ $P \text{ н.мм} = 178.3$ Гр. сл. = 0 Точн. = П </p>
	<p>БПО-2032</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-2037</p> <p> $F \text{ см}^2 = 0.3$ $Q \text{ кг.} = 0.0813$ $D \text{ оп.мм} = 13.3$ $P \text{ н.мм} = 49.95$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2033</p> <p> $F \text{ см}^2 = 5.779$ $Q \text{ кг.} = 1.566$ $D \text{ оп.мм} = 118$ $P \text{ н.мм} = 408.4$ Гр. сл. = 0 Точн. = П </p>		<p>БПО-2038</p> <p> $F \text{ см}^2 = 1.7$ $Q \text{ кг.} = 0.461$ $D \text{ оп.мм} = 85$ $P \text{ н.мм} = 264.2$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2034</p> <p> $F \text{ см}^2 = 1.874$ $Q \text{ кг.} = 0.508$ $D \text{ оп.мм} = 32.1$ $P \text{ н.мм} = 155.1$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2039</p> <p> $F \text{ см}^2 = 0.962$ $Q \text{ кг.} = 0.261$ $D \text{ оп.мм} = 42$ $P \text{ н.мм} = 149.8$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2035</p> <p> $F \text{ см}^2 = 1.304$ $Q \text{ кг.} = 0.353$ $D \text{ оп.мм} = 33$ $P \text{ н.мм} = 137.1$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2040</p> <p> $F \text{ см}^2 = 1.317$ $Q \text{ кг.} = 0.357$ $D \text{ оп.мм} = 51$ $P \text{ н.мм} = 188.2$ Гр. сл. = V Точн. = П </p>










	<p>БПО-2041</p> <p> $F \text{ см}^2 = 2.85$ $Q \text{ кг.} = 0.772$ $D \text{ оп.мм} = 134$ $P \text{ н.мм} = 378$ Гр. сл. = V Точн. = П </p>		<p>БПО-2046</p> <p> $F \text{ см}^2 = 0.769$ $Q \text{ кг.} = 0.208$ $D \text{ оп.мм} = 20$ $P \text{ н.мм} = 47.3$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-2042</p> <p> $F \text{ см}^2 = 0.4$ $Q \text{ кг.} = 0.108$ $D \text{ оп.мм} = 23$ $P \text{ н.мм} = 58.3$ Гр. сл. = V Точн. = П </p>		<p>БПО-2047</p> <p> $F \text{ см}^2 = 5.076$ $Q \text{ кг.} = 1.376$ $D \text{ оп.мм} = 45$ $P \text{ н.мм} = 156.2$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2043</p> <p> $F \text{ см}^2 = 2.930$ $Q \text{ кг.} = 0.794$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 378.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-2048</p> <p> $F \text{ см}^2 = 6.24$ $Q \text{ кг.} = 1.691$ $D \text{ оп.мм} = 127$ $P \text{ н.мм} = 320$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2044</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-2049</p> <p> $F \text{ см}^2 = 0.51$ $Q \text{ кг.} = 0.139$ $D \text{ оп.мм} = 22.9$ $P \text{ н.мм} = 82.29$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2045</p> <p> $F \text{ см}^2 = 3.482$ $Q \text{ кг.} = 0.944$ $D \text{ оп.мм} = 35$ $P \text{ н.мм} = 88.7$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2050</p> <p> $F \text{ см}^2 = 3.303$ $Q \text{ кг.} = 0.895$ $D \text{ оп.мм} = 29$ $P \text{ н.мм} = 74.6$ Гр. сл. = II Точн. = Н </p>









	<p>БПО-2051</p> <p> $F \text{ см}^2 = 1.355$ $Q \text{ кг.} = 0.367$ $D \text{ оп.мм} = 52.9$ $P \text{ н.мм} = 113.6$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2056</p> <p> $F \text{ см}^2 = 2.070$ $Q \text{ кг.} = 0.561$ $D \text{ оп.мм} = 58.2$ $P \text{ н.мм} = 276.3$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2052</p> <p> $F \text{ см}^2 = 1.502$ $Q \text{ кг.} = 0.407$ $D \text{ оп.мм} = 43.0$ $P \text{ н.мм} = 236.9$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2057</p> <p> $F \text{ см}^2 = 2.030$ $Q \text{ кг.} = 0.550$ $D \text{ оп.мм} = 81.5$ $P \text{ н.мм} = 271.0$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2053</p> <p> $F \text{ см}^2 = 0.780$ $Q \text{ кг.} = 0.211$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 96.9$ Гр. сл. = V Точн. = Н </p>		<p>БПО-2058</p> <p> $F \text{ см}^2 = 0.800$ $Q \text{ кг.} = 0.217$ $D \text{ оп.мм} = 20.5$ $P \text{ н.мм} = 54.8$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-2054</p> <p> $F \text{ см}^2 = 1.305$ $Q \text{ кг.} = 0.354$ $D \text{ оп.мм} = 46.5$ $P \text{ н.мм} = 221.7$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2059</p> <p> $F \text{ см}^2 = 1.386$ $Q \text{ кг.} = 0.376$ $D \text{ оп.мм} = 55.7$ $P \text{ н.мм} = 223.9$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2055</p> <p> $F \text{ см}^2 = 1.493$ $Q \text{ кг.} = 0.405$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 250.0$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2060</p> <p> $F \text{ см}^2 = 1.432$ $Q \text{ кг.} = 0.388$ $D \text{ оп.мм} = 53.5$ $P \text{ н.мм} = 215.9$ Гр. сл. = VI Точн. = П </p>











	<p>БПО-2061</p> <p> $F \text{ см}^2 = 0.794$ $Q \text{ кг.} = 0.215$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 133.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2066</p> <p> $F \text{ см}^2 = 2.100$ $Q \text{ кг.} = 0.569$ $D \text{ оп.мм} = 22.3$ $P \text{ н.мм} = 78.1$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-2062</p> <p> $F \text{ см}^2 = 1.480$ $Q \text{ кг.} = 0.401$ $D \text{ оп.мм} = 50.9$ $P \text{ н.мм} = 217.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-2067</p> <p> $F \text{ см}^2 = 1.740$ $Q \text{ кг.} = 0.472$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 122.0$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-2063</p> <p> $F \text{ см}^2 = 0.758$ $Q \text{ кг.} = 0.205$ $D \text{ оп.мм} = 30.3$ $P \text{ н.мм} = 127.4$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2068</p> <p> $F \text{ см}^2 = 1.210$ $Q \text{ кг.} = 0.328$ $D \text{ оп.мм} = 38.1$ $P \text{ н.мм} = 125.5$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2064</p> <p> $F \text{ см}^2 = 0.820$ $Q \text{ кг.} = 0.222$ $D \text{ оп.мм} = 26.6$ $P \text{ н.мм} = 122.5$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2069</p> <p> $F \text{ см}^2 = 3.470$ $Q \text{ кг.} = 0.940$ $D \text{ оп.мм} = 39.8$ $P \text{ н.мм} = 210.1$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-2065</p> <p> $F \text{ см}^2 = 18.535$ $Q \text{ кг.} = 5.023$ $D \text{ оп.мм} = 170.0$ $P \text{ н.мм} = 488.1$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2070</p> <p> $F \text{ см}^2 = 2.610$ $Q \text{ кг.} = 0.707$ $D \text{ оп.мм} = 36.7$ $P \text{ н.мм} = 173.7$ Гр. сл. = V Точн. = Н </p>






	<p>БПО-2071</p> <p> $F \text{ см}^2 = 1.096$ $Q \text{ кг.} = 0.297$ $D \text{ оп.мм} = 37.5$ $P \text{ н.мм} = 111$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2076</p> <p> $F \text{ см}^2 = 1.15$ $Q \text{ кг.} = 0.312$ $D \text{ оп.мм} = 34.1$ $P \text{ н.мм} = 101.3$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2072</p> <p> $F \text{ см}^2 = 2.814$ $Q \text{ кг.} = 0.763$ $D \text{ оп.мм} = 56$ $P \text{ н.мм} = 199.6$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2077</p> <p> $F \text{ см}^2 = 4.148$ $Q \text{ кг.} = 3.692$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 111.1$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2073</p> <p> $F \text{ см}^2 = 2.26$ $Q \text{ кг.} = 0.61$ $D \text{ оп.мм} = 15$ $P \text{ н.мм} = 85$ Гр. сл. = V Точн. = П </p>		<p>БПО-2078</p> <p> $F \text{ см}^2 = 4.825$ $Q \text{ кг.} = 4.294$ $D \text{ оп.мм} = 53$ $P \text{ н.мм} = 151.4$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2074</p> <p> $F \text{ см}^2 = 3.04$ $Q \text{ кг.} = 0.824$ $D \text{ оп.мм} = 51$ $P \text{ н.мм} = 160$ Гр. сл. = III Точн. = П </p>		<p>БПО-2079</p> <p> $F \text{ см}^2 = 0.69$ $Q \text{ кг.} = 0.186$ $D \text{ оп.мм} = 23$ $P \text{ н.мм} = 108.5$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2075</p> <p> $F \text{ см}^2 = 2$ $Q \text{ кг.} = 0.542$ $D \text{ оп.мм} = 35$ $P \text{ н.мм} = 120.1$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2080</p> <p> $F \text{ см}^2 = 2.43$ $Q \text{ кг.} = 0.67$ $D \text{ оп.мм} = 66$ $P \text{ н.мм} = 291.9$ Гр. сл. = V Точн. = П </p>











	<p>БПО-2081</p> <p> $F \text{ см}^2 = 2.52$ $Q \text{ кг.} = 0.694$ $D \text{ оп.мм} = 65.5$ $P \text{ н.мм} = 299.4$ Гр. сл. = V Точн. = П </p>		<p>БПО-2086</p> <p> $F \text{ см}^2 = 0.884$ $Q \text{ кг.} = 0.24$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 109.5$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2082</p> <p> $F \text{ см}^2 = 2.51$ $Q \text{ кг.} = 0.69$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 298,1$ Гр. сл. = V Точн. = П </p>		<p>БПО-2087</p> <p> $F \text{ см}^2 = 0.87$ $Q \text{ кг.} = 0.236$ $D \text{ оп.мм} = 33$ $P \text{ н.мм} = 115.4$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2083</p> <p> $F \text{ см}^2 = 2.41$ $Q \text{ кг.} = 0.67$ $D \text{ оп.мм} = 97$ $P \text{ н.мм} = 308.9$ Гр. сл. = V Точн. = П </p>		<p>БПО-2088</p> <p> $F \text{ см}^2 = 2.5$ $Q \text{ кг.} = 0.678$ $D \text{ оп.мм} = 46.5$ $P \text{ н.мм} = 172.1$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2084</p> <p> $F \text{ см}^2 = 2.3$ $Q \text{ кг.} = 0.621$ $D \text{ оп.мм} = 88.7$ $P \text{ н.мм} = 289.1$ Гр. сл. = V Точн. = П </p>		<p>БПО-2089</p> <p> $F \text{ см}^2 = 0.965$ $Q \text{ кг.} = 0.262$ $D \text{ оп.мм} = 31$ $P \text{ н.мм} = 90.1$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2085</p> <p> $F \text{ см}^2 = 1.59$ $Q \text{ кг.} = 0.431$ $D \text{ оп.мм} = 60$ $P \text{ н.мм} = 213.3$ Гр. сл. = V Точн. = П </p>		<p>БПО-2090</p> <p> $F \text{ см}^2 = 0.725$ $Q \text{ кг.} = 0.196$ $D \text{ оп.мм} = 24$ $P \text{ н.мм} = 77$ Гр. сл. = IV Точн. = П </p>










	<p>БПО-2091</p> <p> $F \text{ см}^2 = 1.54$ $Q \text{ кг.} = 0.417$ $D \text{ оп.мм} = 90$ $P \text{ н.мм} = 260.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-2096</p> <p> $F \text{ см}^2 = 1$ $Q \text{ кг.} = 1$ $D \text{ оп.мм} = 1$ $P \text{ н.мм} = 1$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2092</p> <p> $F \text{ см}^2 = 1.22$ $Q \text{ кг.} = 0.33$ $D \text{ оп.мм} = 90$ $P \text{ н.мм} = 205.4$ Гр. сл. = V Точн. = П </p>		<p>БПО-2097</p> <p> $F \text{ см}^2 = 4.148$ $Q \text{ кг.} = 3.692$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 111.1$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2093</p> <p> $F \text{ см}^2 = 0.923$ $Q \text{ кг.} = 0.25$ $D \text{ оп.мм} = 49.5$ $P \text{ н.мм} = 155.8$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2098</p> <p> $F \text{ см}^2 = 1.12$ $Q \text{ кг.} = 0.302$ $D \text{ оп.мм} = 43.2$ $P \text{ н.мм} = 149.8$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2094</p> <p> $F \text{ см}^2 = 2.33$ $Q \text{ кг.} = 0.631$ $D \text{ оп.мм} = 78.3$ $P \text{ н.мм} = 237.2$ Гр. сл. = V Точн. = Н </p>		<p>БПО-2099</p> <p> $F \text{ см}^2 = 2.14$ $Q \text{ кг.} = 0.58$ $D \text{ оп.мм} = 55.7$ $P \text{ н.мм} = 235.4$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2095</p> <p> $F \text{ см}^2 = 3.16$ $Q \text{ кг.} = 0.856$ $D \text{ оп.мм} = 105.6$ $P \text{ н.мм} = 320.2$ Гр. сл. = V Точн. = Н </p>		<p>БПО-2100</p> <p> $F \text{ см}^2 = 2.1$ $Q \text{ кг.} = 0.57$ $D \text{ оп.мм} = 55$ $P \text{ н.мм} = 242.8$ Гр. сл. = VI Точн. = П </p>








	<p>БПО-2101</p> <p> $F \text{ см}^2 = 2.431$ $Q \text{ кг.} = 0.659$ $D \text{ оп.мм} = 61$ $P \text{ н.мм} = 268.5$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2106</p> <p> $F \text{ см}^2 = 2.910$ $Q \text{ кг.} = 0.789$ $D \text{ оп.мм} = 79.4$ $P \text{ н.мм} = 322.8$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2102</p> <p> $F \text{ см}^2 = 3.530$ $Q \text{ кг.} = 0.957$ $D \text{ оп.мм} = 108.2$ $P \text{ н.мм} = 339.1$ Гр. сл. = V Точн. = П </p>		<p>БПО-2107</p>
	<p>БПО-2103</p> <p> $F \text{ см}^2 = 1.950$ $Q \text{ кг.} = 0.528$ $D \text{ оп.мм} = 75.0$ $P \text{ н.мм} = 256.7$ Гр. сл. = IV Точн. = П </p>		
	<p>БПО-2104</p> <p> $F \text{ см}^2 = 1.895$ $Q \text{ кг.} = 0.514$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 206.1$ Гр. сл. = V Точн. = П </p>		<p>БПО-2109</p> <p> $F \text{ см}^2 = 1.173$ $Q \text{ кг.} = 0.318$ $D \text{ оп.мм} = 28.3$ $P \text{ н.мм} = 98.9$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2105</p>		<p>БПО-2110</p> <p> $F \text{ см}^2 = 4.337$ $Q \text{ кг.} = 1.175$ $D \text{ оп.мм} = 73.6$ $P \text{ н.мм} = 292.3$ Гр. сл. = IV Точн. = Н </p>










	<p>БПО-2111</p> <p> $F \text{ см}^2 = 1.16$ $Q \text{ кг.} = 0.312$ $D \text{ оп.мм} = 27$ $P \text{ н.мм} = 102.2$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2116</p> <p> $F \text{ см}^2 = 3.173$ $Q \text{ кг.} = 0.86$ $D \text{ оп.мм} = 110$ $P \text{ н.мм} = 305.3$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2112</p> <p> $F \text{ см}^2 = 5.21$ $Q \text{ кг.} = 1.411$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 153.8$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2117</p> <p> $F \text{ см}^2 = 1.543$ $Q \text{ кг.} = 0.416$ $D \text{ оп.мм} = 77.6$ $P \text{ н.мм} = 191.2$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2113</p> <p> $F \text{ см}^2 = 0.54$ $Q \text{ кг.} = 0.146$ $D \text{ оп.мм} = 17$ $P \text{ н.мм} = 68$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2118</p> <p> $F \text{ см}^2 = 2.05$ $Q \text{ кг.} = 0.55$ $D \text{ оп.мм} = 56$ $P \text{ н.мм} = 168.3$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2114</p> <p> $F \text{ см}^2 = 1.58$ $Q \text{ кг.} = 0.428$ $D \text{ оп.мм} = 34$ $P \text{ н.мм} = 162$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2119</p> <p> $F \text{ см}^2 = 2.37$ $Q \text{ кг.} = 0.64$ $D \text{ оп.мм} = 59$ $P \text{ н.мм} = 197.9$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2115</p> <p> $F \text{ см}^2 = 1.676$ $Q \text{ кг.} = 0.454$ $D \text{ оп.мм} = 33$ $P \text{ н.мм} = 141.2$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2120</p> <p> $F \text{ см}^2 = 2.1$ $Q \text{ кг.} = 0.57$ $D \text{ оп.мм} = 55$ $P \text{ н.мм} = 242.8$ Гр. сл. = VI Точн. = П </p>











	<p>БПО-2121</p> <p> $F \text{ см}^2 = 1.97$ $Q \text{ кг.} = 0.533$ $D \text{ оп.мм} = 47$ $P \text{ н.мм} = 188.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-2126</p>
	<p>БПО-2122</p> <p> $F \text{ см}^2 = 9.2$ $Q \text{ кг.} = 2.493$ $D \text{ оп.мм} = 72$ $P \text{ н.мм} = 180$ Гр. сл. = III Точн. = П </p>		<p>БПО-2127</p> <p> $F \text{ см}^2 = 3.173$ $Q \text{ кг.} = 2.824$ $D \text{ оп.мм} = 31$ $P \text{ н.мм} = 74.3$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2123</p>		<p>БПО-2128</p> <p> $F \text{ см}^2 = 1$ $Q \text{ кг.} = 1$ $D \text{ оп.мм} = 1$ $P \text{ н.мм} = 1$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2124</p>		<p>БПО-2129</p> <p> $F \text{ см}^2 = 3.482$ $Q \text{ кг.} = 3.1$ $D \text{ оп.мм} = 32$ $P \text{ н.мм} = 87$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2125</p>		<p>БПО-2130</p> <p> $F \text{ см}^2 = 3.415$ $Q \text{ кг.} = 0.925$ $D \text{ оп.мм} = 130$ $P \text{ н.мм} = 358$ Гр. сл. = V Точн. = П </p>








	<p>БПО-2131</p> <p> $F \text{ см}^2 = 0.43$ $Q \text{ кг.} = 0.12$ $D \text{ оп.мм} = 21$ $P \text{ н.мм} = 67.8$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$ </p>		<p>БПО-2136</p> <p> $F \text{ см}^2 = 1.298$ $Q \text{ кг.} = 0.352$ $D \text{ оп.мм} = 31$ $P \text{ н.мм} = 177.2$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$ </p>
	<p>БПО-2132</p> <p> $F \text{ см}^2 = 1.024$ $Q \text{ кг.} = 0.278$ $D \text{ оп.мм} = 37.6$ $P \text{ н.мм} = 151.5$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$ </p>		<p>БПО-2137</p> <p> $F \text{ см}^2 = 1.158$ $Q \text{ кг.} = 0.314$ $D \text{ оп.мм} = 29$ $P \text{ н.мм} = 140.6$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$ </p>
	<p>БПО-2133</p> <p> $F \text{ см}^2 = 1$ $Q \text{ кг.} = 1$ $D \text{ оп.мм} = 1$ $P \text{ н.мм} = 1$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$ </p>		<p>БПО-2138</p> <p> $F \text{ см}^2 = 1.899$ $Q \text{ кг.} = 0.515$ $D \text{ оп.мм} = 82$ $P \text{ н.мм} = 230.8$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$ </p>
	<p>БПО-2134</p> <p> $F \text{ см}^2 = 1$ $Q \text{ кг.} = 1$ $D \text{ оп.мм} = 1$ $P \text{ н.мм} = 1$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = Н$ </p>		<p>БПО-2139</p> <p> $F \text{ см}^2 = 1.915$ $Q \text{ кг.} = 0.519$ $D \text{ оп.мм} = 60$ $P \text{ н.мм} = 188$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$ </p>
	<p>БПО-2135</p> <p> $F \text{ см}^2 = 2.874$ $Q \text{ кг.} = 0.78$ $D \text{ оп.мм} = 84$ $P \text{ н.мм} = 273.3$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$ </p>		<p>БПО-2140</p> <p> $F \text{ см}^2 = 1.66$ $Q \text{ кг.} = 0.45$ $D \text{ оп.мм} = 27$ $P \text{ н.мм} = 74.6$ $\Gamma \text{ р. сл.} = II$ $\text{Точн.} = Н$ </p>









	БПО-2141 $F \text{ см}^2 = 1$ $Q \text{ кг.} = 1$ $D \text{ оп.мм} = 1$ $P \text{ н.мм} = 1$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$		БПО-2146 $F \text{ см}^2 = 16.426$ $Q \text{ кг.} = 4.452$ $D \text{ оп.мм} = 76$ $P \text{ н.мм} = 649.4$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$
	БПО-2142 $F \text{ см}^2 = 5.468$ $Q \text{ кг.} = 1.482$ $D \text{ оп.мм} = 158$ $P \text{ н.мм} = 548.5$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$		БПО-2147 $F \text{ см}^2 = 3.437$ $Q \text{ кг.} = 0.932$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 211.1$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$
	БПО-2143 $F \text{ см}^2 = 3.36$ $Q \text{ кг.} = 0.91$ $D \text{ оп.мм} = 119$ $P \text{ н.мм} = 333.2$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$		БПО-2148 $F \text{ см}^2 = 5.344$ $Q \text{ кг.} = 1.448$ $D \text{ оп.мм} = 124$ $P \text{ н.мм} = 394.5$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$
	БПО-2144 $F \text{ см}^2 = 6.523$ $Q \text{ кг.} = 1.767$ $D \text{ оп.мм} = 63$ $P \text{ н.мм} = 169.4$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = Н$		БПО-2149 $F \text{ см}^2 = 3.832$ $Q \text{ кг.} = 1.038$ $D \text{ оп.мм} = 107.4$ $P \text{ н.мм} = 332.5$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$
	БПО-2145 $F \text{ см}^2 = 3.32$ $Q \text{ кг.} = 0.9$ $D \text{ оп.мм} = 145$ $P \text{ н.мм} = 365$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$		БПО-2150 $F \text{ см}^2 = 1.961$ $Q \text{ кг.} = 0.531$ $D \text{ оп.мм} = 70$ $P \text{ н.мм} = 263.3$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$










	<p>БПО-2151</p> <p> $F \text{ см}^2 = 0.549$ $Q \text{ кг.} = 0.149$ $D \text{ оп.мм} = 20$ $P \text{ н.мм} = 76.2$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2156</p>
	<p>БПО-2152</p> <p> $F \text{ см}^2 = 0.52$ $Q \text{ кг.} = 0.14$ $D \text{ оп.мм} = 22.5$ $P \text{ н.мм} = 64$ Гр. сл. = V Точн. = П </p>		<p>БПО-2157</p>
	<p>БПО-2153</p> <p> $F \text{ см}^2 = 3.243$ $Q \text{ кг.} = 0.879$ $D \text{ оп.мм} = 109$ $P \text{ н.мм} = 320.6$ Гр. сл. = особая Точн. = П </p>		<p>БПО-2158</p> <p> $F \text{ см}^2 = 1.790$ $Q \text{ кг.} = 0.485$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 184.8$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2154</p> <p> $F \text{ см}^2 = 0.975$ $Q \text{ кг.} = 0.264$ $D \text{ оп.мм} = 44$ $P \text{ н.мм} = 151.7$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2159</p> <p> $F \text{ см}^2 = 2.54$ $Q \text{ кг.} = 0.69$ $D \text{ оп.мм} = 170$ $P \text{ н.мм} = 343.5$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2155</p>		<p>БПО-2160</p> <p> $F \text{ см}^2 = 27.65$ $Q \text{ кг.} = 7.493$ $D \text{ оп.мм} = 140$ $P \text{ н.мм} = 1182$ Гр. сл. = особая Точн. = П </p>











	<p>БПО-2161</p> <p> $F \text{ см}^2 = 19.920$ $Q \text{ кг.} = 5.398$ $D \text{ оп.мм} = 108.0$ $P \text{ н.мм} = 959.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2166</p> <p> $F \text{ см}^2 = 0.427$ $Q \text{ кг.} = 0.116$ $D \text{ оп.мм} = 17.2$ $P \text{ н.мм} = 56.5$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2162</p> <p> $F \text{ см}^2 = 52.300$ $Q \text{ кг.} = 14.173$ $D \text{ оп.мм} = 182.4$ $P \text{ н.мм} = 1925.4$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2167</p> <p> $F \text{ см}^2 = 1.818$ $Q \text{ кг.} = 0.493$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 271.3$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2163</p> <p> $F \text{ см}^2 = 31.910$ $Q \text{ кг.} = 8.648$ $D \text{ оп.мм} = 248.0$ $P \text{ н.мм} = 1021.5$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2168</p> <p> $F \text{ см}^2 = 0.891$ $Q \text{ кг.} = 0.241$ $D \text{ оп.мм} = 22.4$ $P \text{ н.мм} = 80.7$ Гр. сл. = VI Точн. = П </p>
			<p>БПО-2169</p> <p> $F \text{ см}^2 = 2.414$ $Q \text{ кг.} = 0.654$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 289.9$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2165</p> <p> $F \text{ см}^2 = 3.290$ $Q \text{ кг.} = 0.892$ $D \text{ оп.мм} = 156.8$ $P \text{ н.мм} = 413.9$ Гр. сл. = V Точн. = П </p>		<p>БПО-2170</p> <p> $F \text{ см}^2 = 0.290$ $Q \text{ кг.} = 0.079$ $D \text{ оп.мм} = 13.3$ $P \text{ н.мм} = 34.2$ Гр. сл. = III Точн. = П </p>











	<p>БПО-2171</p> <p> $F \text{ см}^2 = 1.69$ $Q \text{ кг.} = 0.458$ $D \text{ оп.мм} = 35.5$ $P \text{ н.мм} = 130.9$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2176</p> <p> $F \text{ см}^2 = 1.46$ $Q \text{ кг.} = 0.396$ $D \text{ оп.мм} = 42$ $P \text{ н.мм} = 102.7$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2172</p> <p> $F \text{ см}^2 = 12.06$ $Q \text{ кг.} = 3.268$ $D \text{ оп.мм} = 88$ $P \text{ н.мм} = 841.5$ Гр. сл. = особая Точн. = П </p>		<p>БПО-2177</p> <p> $F \text{ см}^2 = 2.76$ $Q \text{ кг.} = 0.748$ $D \text{ оп.мм} = 53$ $P \text{ н.мм} = 247$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2173</p> <p> $F \text{ см}^2 = 0.413$ $Q \text{ кг.} = 0.112$ $D \text{ оп.мм} = 23$ $P \text{ н.мм} = 71.2$ Гр. сл. = III Точн. = П </p>		<p>БПО-2178</p> <p> $F \text{ см}^2 = 1.27$ $Q \text{ кг.} = 0.344$ $D \text{ оп.мм} = 45$ $P \text{ н.мм} = 131$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2174</p> <p> $F \text{ см}^2 = 1.163$ $Q \text{ кг.} = 0.315$ $D \text{ оп.мм} = 49$ $P \text{ н.мм} = 149.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2179</p> <p> $F \text{ см}^2 = 1.387$ $Q \text{ кг.} = 0.376$ $D \text{ оп.мм} = 43$ $P \text{ н.мм} = 145.5$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2175</p> <p> $F \text{ см}^2 = 0.81$ $Q \text{ кг.} = 0.22$ $D \text{ оп.мм} = 24$ $P \text{ н.мм} = 107$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2180</p> <p> $F \text{ см}^2 = 3.287$ $Q \text{ кг.} = 0.89$ $D \text{ оп.мм} = 51$ $P \text{ н.мм} = 157.5$ Гр. сл. = V Точн. = П </p>











	<p>БПО-2181</p> <p> $F \text{ см}^2 = 0.925$ $Q \text{ кг.} = 0.251$ $D \text{ оп.мм} = 33.2$ $P \text{ н.мм} = 165.4$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2186</p> <p> $F \text{ см}^2 = 6.750$ $Q \text{ кг.} = 1.829$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 132.9$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-2182</p> <p> $F \text{ см}^2 = 0.715$ $Q \text{ кг.} = 0.194$ $D \text{ оп.мм} = 25.8$ $P \text{ н.мм} = 126.8$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2187</p> <p> $F \text{ см}^2 = 3.300$ $Q \text{ кг.} = 0.894$ $D \text{ оп.мм} = 90.8$ $P \text{ н.мм} = 40.8$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2188</p> <p> $F \text{ см}^2 = 1.570$ $Q \text{ кг.} = 0.425$ $D \text{ оп.мм} = 63.5$ $P \text{ н.мм} = 208.7$ Гр. сл. = V Точн. = П </p>
			<p>БПО-2189</p> <p> $F \text{ см}^2 = 2.050$ $Q \text{ кг.} = 0.556$ $D \text{ оп.мм} = 57.1$ $P \text{ н.мм} = 262.3$ Гр. сл. = V Точн. = П </p>
			<p>БПО-2190</p> <p> $F \text{ см}^2 = 1.120$ $Q \text{ кг.} = 0.304$ $D \text{ оп.мм} = 28.6$ $P \text{ н.мм} = 138.3$ Гр. сл. = V Точн. = П </p>








	<p>БПО-2191</p> <p> $F \text{ см}^2 = 0.930$ $Q \text{ кг.} = 0.252$ $D \text{ оп.мм} = 23.5$ $P \text{ н.мм} = 103.4$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2196</p> <p> $F \text{ см}^2 = 14.000$ $Q \text{ кг.} = 3.794$ $D \text{ оп.мм} = 73.0$ $P \text{ н.мм} = 180.0$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2192</p> <p> $F \text{ см}^2 = 2.350$ $Q \text{ кг.} = 0.637$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 101.4$ Гр. сл. = III Точн. = П </p>		<p>БПО-2197</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-2193</p> <p> $F \text{ см}^2 = 0.508$ $Q \text{ кг.} = 0.138$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 70.8$ Гр. сл. = IV Точн. = П </p>		
	<p>БПО-2194</p> <p> $F \text{ см}^2 = 0.612$ $Q \text{ кг.} = 0.166$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 67.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2199</p> <p> $F \text{ см}^2 = 1.773$ $Q \text{ кг.} = 0.480$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 168.1$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2195</p> <p> $F \text{ см}^2 = 2.620$ $Q \text{ кг.} = 0.710$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 198.4$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2200</p> <p> $F \text{ см}^2 = 2.038$ $Q \text{ кг.} = 0.552$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 194.9$ Гр. сл. = IV Точн. = Н </p>








	<p>БПО-2201</p> <p> $F \text{ см}^2 = 0.413$ $Q \text{ кг.} = 0.112$ $D \text{ оп.мм} = 27.6$ $P \text{ н.мм} = 83.1$ Гр. сл. = V Точн. = П </p>		<p>БПО-2206</p> <p> $F \text{ см}^2 = 3.621$ $Q \text{ кг.} = 0.981$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 110.3$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2202</p> <p> $F \text{ см}^2 = 4.19$ $Q \text{ кг.} = 1.138$ $D \text{ оп.мм} = 118.0$ $P \text{ н.мм} = 350.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-2207</p> <p> $F \text{ см}^2 = 3.684$ $Q \text{ кг.} = 0.998$ $D \text{ оп.мм} = 40.4$ $P \text{ н.мм} = 117.6$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2203</p> <p> $F \text{ см}^2 = 3.090$ $Q \text{ кг.} = 0.837$ $D \text{ оп.мм} = 96.8$ $P \text{ н.мм} = 255.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-2208</p> <p> $F \text{ см}^2 = 3.850$ $Q \text{ кг.} = 1.043$ $D \text{ оп.мм} = 153.0$ $P \text{ н.мм} = 502.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2204</p> <p> $F \text{ см}^2 = 1.720$ $Q \text{ кг.} = 0.466$ $D \text{ оп.мм} = 75.0$ $P \text{ н.мм} = 189.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-2209</p> <p> $F \text{ см}^2 = 0.740$ $Q \text{ кг.} = 0.201$ $D \text{ оп.мм} = 22.1$ $P \text{ н.мм} = 95.5$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2210</p> <p> $F \text{ см}^2 = 0.650$ $Q \text{ кг.} = 0.176$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 87.4$ Гр. сл. = V Точн. = П </p>











	<p>БПО-2211</p> <p> $F \text{ см}^2 = 1.185$ $Q \text{ кг.} = 0.321$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 161.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-2216</p> <p> $F \text{ см}^2 = 3.116$ $Q \text{ кг.} = 0.844$ $D \text{ оп.мм} = 54.4$ $P \text{ н.мм} = 220.5$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2212</p> <p> $F \text{ см}^2 = 16.863$ $Q \text{ кг.} = 4.570$ $D \text{ оп.мм} = 143.0$ $P \text{ н.мм} = 658.9$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2217</p> <p> $F \text{ см}^2 = 4.335$ $Q \text{ кг.} = 1.175$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 415.4$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2213</p> <p> $F \text{ см}^2 = 0.453$ $Q \text{ кг.} = 0.123$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 65.7$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2218</p> <p> $F \text{ см}^2 = 6.252$ $Q \text{ кг.} = 1.694$ $D \text{ оп.мм} = 142.0$ $P \text{ н.мм} = 556.8$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2214</p> <p> $F \text{ см}^2 = 4.493$ $Q \text{ кг.} = 1.218$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 166.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2219</p> <p> $F \text{ см}^2 = 4.232$ $Q \text{ кг.} = 1.147$ $D \text{ оп.мм} = 117.0$ $P \text{ н.мм} = 385.1$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2215</p> <p> $F \text{ см}^2 = 0.300$ $Q \text{ кг.} = 0.081$ $D \text{ оп.мм} = 22.6$ $P \text{ н.мм} = 61.4$ Гр. сл. = V Точн. = П </p>		<p>БПО-2220</p> <p> $F \text{ см}^2 = 0.400$ $Q \text{ кг.} = 0.108$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 58.1$ Гр. сл. = IV Точн. = Н </p>











	<p>БПО-2221</p> <p> $F \text{ см}^2 = 0.640$ $Q \text{ кг.} = 0.173$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 89.6$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2226</p> <p> $F \text{ см}^2 = 5.630$ $Q \text{ кг.} = 1.526$ $D \text{ оп.мм} = 40.5$ $P \text{ н.мм} = 128.9$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-2222</p> <p> $F \text{ см}^2 = 0.652$ $Q \text{ кг.} = 0.177$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 67.8$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2227</p> <p> $F \text{ см}^2 = 5.023$ $Q \text{ кг.} = 1.361$ $D \text{ оп.мм} = 71.0$ $P \text{ н.мм} = 167.9$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2223</p> <p> $F \text{ см}^2 = 0.380$ $Q \text{ кг.} = 0.103$ $D \text{ оп.мм} = 29.8$ $P \text{ н.мм} = 62.3$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2228</p> <p> $F \text{ см}^2 = 2.117$ $Q \text{ кг.} = 0.574$ $D \text{ оп.мм} = 17.0$ $P \text{ н.мм} = 54.5$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2224</p> <p> $F \text{ см}^2 = 0.520$ $Q \text{ кг.} = 0.141$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 69.6$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2229</p> <p> $F \text{ см}^2 = 6.000$ $Q \text{ кг.} = 1.626$ $D \text{ оп.мм} = 78.0$ $P \text{ н.мм} = 166.0$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2225</p> <p> $F \text{ см}^2 = 5.300$ $Q \text{ кг.} = 1.436$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 121.6$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2230</p> <p> $F \text{ см}^2 = 1.230$ $Q \text{ кг.} = 0.333$ $D \text{ оп.мм} = 29.6$ $P \text{ н.мм} = 265.8$ Гр. сл. = V Точн. = П </p>











	<p>БПО-2231</p> <p> $F \text{ см}^2 = 7.512$ $Q \text{ кг.} = 2.036$ $D \text{ оп.мм} = 130.0$ $P \text{ н.мм} = 508.2$ Гр. сл. = V Точн. = П </p>		<p>БПО-2236</p> <p> $F \text{ см}^2 = 3.308$ $Q \text{ кг.} = 0.896$ $D \text{ оп.мм} = 62.0$ $P \text{ н.мм} = 403.1$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2232</p> <p> $F \text{ см}^2 = 8.828$ $Q \text{ кг.} = 2.392$ $D \text{ оп.мм} = 174.0$ $P \text{ н.мм} = 597.3$ Гр. сл. = V Точн. = П </p>		<p>БПО-2237</p> <p> $F \text{ см}^2 = 2.094$ $Q \text{ кг.} = 0.567$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 264.9$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2233</p> <p> $F \text{ см}^2 = 0.791$ $Q \text{ кг.} = 0.214$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 116.4$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2238</p> <p> $F \text{ см}^2 = 2.097$ $Q \text{ кг.} = 0.568$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 270.9$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2234</p> <p> $F \text{ см}^2 = 2.007$ $Q \text{ кг.} = 0.544$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 159.6$ Гр. сл. = III Точн. = П </p>		<p>БПО-2239</p> <p> $F \text{ см}^2 = 4.410$ $Q \text{ кг.} = 1.195$ $D \text{ оп.мм} = 128.0$ $P \text{ н.мм} = 357.5$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2235</p> <p> $F \text{ см}^2 = 5.121$ $Q \text{ кг.} = 1.388$ $D \text{ оп.мм} = 93.0$ $P \text{ н.мм} = 300.3$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2240</p> <p> $F \text{ см}^2 = 0.442$ $Q \text{ кг.} = 0.120$ $D \text{ оп.мм} = 21.4$ $P \text{ н.мм} = 49.4$ Гр. сл. = II Точн. = Н </p>











	<p>БПО-2241</p> <p> $F \text{ см}^2 = 0.447$ $Q \text{ кг.} = 0.121$ $D \text{ оп.мм} = 22.5$ $P \text{ н.мм} = 51.4$ Гр. сл. = II Точн. = Н </p>		<p>БПО-2246</p> <p> $F \text{ см}^2 = 6.283$ $Q \text{ кг.} = 1.703$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 411.7$ Гр. сл. = VI Точн. = П </p>
			<p>БПО-2248</p> <p> $F \text{ см}^2 = 6.399$ $Q \text{ кг.} = 1.734$ $D \text{ оп.мм} = 39.5$ $P \text{ н.мм} = 105.9$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2244</p> <p> $F \text{ см}^2 = 56.500$ $Q \text{ кг.} = 15.312$ $D \text{ оп.мм} = 108.0$ $P \text{ н.мм} = 302.7$ Гр. сл. = II Точн. = Н </p>		<p>БПО-2249</p> <p> $F \text{ см}^2 = 0.732$ $Q \text{ кг.} = 0.198$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 87.3$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2245</p> <p> $F \text{ см}^2 = 0.535$ $Q \text{ кг.} = 0.145$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 95.4$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2250</p> <p> $F \text{ см}^2 = 0.430$ $Q \text{ кг.} = 0.117$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 74.6$ Гр. сл. = V Точн. = П </p>











	БПО-2251		БПО-2256
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 2.580$ $Q \text{ кг.} = 0.699$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 99.0$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
	БПО-2252		БПО-2257
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 3.420$ $Q \text{ кг.} = 0.927$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 112.4$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	БПО-2253		БПО-2258
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 0.785$ $Q \text{ кг.} = 0.213$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 57.5$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	БПО-2254		БПО-2259
	$F \text{ см}^2 = 11.891$ $Q \text{ кг.} = 3.222$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 256.0$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 0.790$ $Q \text{ кг.} = 0.214$ $D \text{ оп.мм} = 32.3$ $P \text{ н.мм} = 160.0$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-2255		БПО-2260
	$F \text{ см}^2 = 10.540$ $Q \text{ кг.} = 2.856$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 230.6$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 0.929$ $Q \text{ кг.} = 0.252$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 154.3$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$











	<p>БПО-2261</p> <p> $F \text{ см}^2 = 1.695$ $Q \text{ кг.} = 0.459$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 145.7$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2266</p> <p> $F \text{ см}^2 = 2.249$ $Q \text{ кг.} = 0.609$ $D \text{ оп.мм} = 68.0$ $P \text{ н.мм} = 246.2$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2262</p> <p> $F \text{ см}^2 = 0.400$ $Q \text{ кг.} = 0.108$ $D \text{ оп.мм} = 27.6$ $P \text{ н.мм} = 83.1$ Гр. сл. = V Точн. = П </p>		<p>БПО-2267</p> <p> $F \text{ см}^2 = 0.663$ $Q \text{ кг.} = 0.180$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 54.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2263</p> <p> $F \text{ см}^2 = 0.450$ $Q \text{ кг.} = 0.122$ $D \text{ оп.мм} = 21.2$ $P \text{ н.мм} = 59.4$ Гр. сл. = III Точн. = П </p>		<p>БПО-2268</p> <p> $F \text{ см}^2 = 0.373$ $Q \text{ кг.} = 0.101$ $D \text{ оп.мм} = 20.2$ $P \text{ н.мм} = 59.1$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2264</p> <p> $F \text{ см}^2 = 4.700$ $Q \text{ кг.} = 1.274$ $D \text{ оп.мм} = 64.9$ $P \text{ н.мм} = 315.9$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2269</p> <p> $F \text{ см}^2 = 1.215$ $Q \text{ кг.} = 0.329$ $D \text{ оп.мм} = 39.1$ $P \text{ н.мм} = 104.0$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2265</p> <p> $F \text{ см}^2 = 1.474$ $Q \text{ кг.} = 0.399$ $D \text{ оп.мм} = 36.6$ $P \text{ н.мм} = 124.5$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2270</p> <p> $F \text{ см}^2 = 21.120$ $Q \text{ кг.} = 5.724$ $D \text{ оп.мм} = 144.0$ $P \text{ н.мм} = 658.4$ Гр. сл. = VI Точн. = П </p>










	<p>БПО-2271</p> <p> $F \text{ см}^2 = 1.060$ $Q \text{ кг.} = 0.287$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 195.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-2276</p> <p> $F \text{ см}^2 = 0.948$ $Q \text{ кг.} = 0.257$ $D \text{ оп.мм} = 29.5$ $P \text{ н.мм} = 89.9$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2272</p> <p> $F \text{ см}^2 = 0.980$ $Q \text{ кг.} = 0.266$ $D \text{ оп.мм} = 35.5$ $P \text{ н.мм} = 180.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-2277</p> <p> $F \text{ см}^2 = 1.525$ $Q \text{ кг.} = 0.413$ $D \text{ оп.мм} = 53.0$ $P \text{ н.мм} = 205.4$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-2273</p> <p> $F \text{ см}^2 = 1.620$ $Q \text{ кг.} = 0.439$ $D \text{ оп.мм} = 34.6$ $P \text{ н.мм} = 135.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2278</p> <p> $F \text{ см}^2 = 0.526$ $Q \text{ кг.} = 0.143$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 93.8$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2274</p> <p> $F \text{ см}^2 = 2.550$ $Q \text{ кг.} = 0.691$ $D \text{ оп.мм} = 38.4$ $P \text{ н.мм} = 164.9$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2279</p> <p> $F \text{ см}^2 = 0.537$ $Q \text{ кг.} = 0.146$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 96.9$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2275</p> <p> $F \text{ см}^2 = 11.240$ $Q \text{ кг.} = 3.046$ $D \text{ оп.мм} = 67.5$ $P \text{ н.мм} = 221.2$ Гр. сл. = II Точн. = Н </p>		<p>БПО-2280</p> <p> $F \text{ см}^2 = 3.848$ $Q \text{ кг.} = 1.043$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 244.0$ Гр. сл. = 0соб. Точн. = П </p>







	<p>БПО-2281</p> <p> $F \text{ см}^2 = 2.578$ $Q \text{ кг.} = 0.699$ $D \text{ оп.мм} = 91$ $P \text{ н.мм} = 257$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>		<p>БПО-2286</p> <p> $F \text{ см}^2 = 4.368$ $Q \text{ кг.} = 1.184$ $D \text{ оп.мм} = 122$ $P \text{ н.мм} = 442.3$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = Н$ </p>
	<p>БПО-2282</p> <p> $F \text{ см}^2 = 1.049$ $Q \text{ кг.} = 0.284$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 107.1$ $\Gamma \text{р. сл.} = II$ $\text{Точн.} = П$ </p>		<p>БПО-2287</p> <p> $F \text{ см}^2 = 5.668$ $Q \text{ кг.} = 1.536$ $D \text{ оп.мм} = 127$ $P \text{ н.мм} = 486$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$ </p>
	<p>БПО-2283</p> <p> $F \text{ см}^2 = 1.809$ $Q \text{ кг.} = 0.49$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 112.8$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$ </p>		<p>БПО-2288</p> <p> $F \text{ см}^2 = 1.05$ $Q \text{ кг.} = 0.285$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 89.9$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = Н$ </p>
	<p>БПО-2284</p> <p> $F \text{ см}^2 = 0.423$ $Q \text{ кг.} = 0.115$ $D \text{ оп.мм} = 20$ $P \text{ н.мм} = 46.3$ $\Gamma \text{р. сл.} = II$ $\text{Точн.} = П$ </p>		<p>БПО-2289</p> <p> $F \text{ см}^2 = 1.27$ $Q \text{ кг.} = 0.344$ $D \text{ оп.мм} = 48$ $P \text{ н.мм} = 143.7$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$ </p>
	<p>БПО-2285</p> <p> $F \text{ см}^2 = 1.06$ $Q \text{ кг.} = 0.297$ $D \text{ оп.мм} = 41.9$ $P \text{ н.мм} = 147.8$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$ </p>		<p>БПО-2290</p> <p> $F \text{ см}^2 = 0.401$ $Q \text{ кг.} = 0.109$ $D \text{ оп.мм} = 25.2$ $P \text{ н.мм} = 60.7$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$ </p>








	<p>БПО-2291</p> <p> $F \text{ см}^2 = 5.344$ $Q \text{ кг.} = 1.448$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 128.9$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2296</p> <p> $F \text{ см}^2 = 1.925$ $Q \text{ кг.} = 0.522$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 225.6$ Гр. сл. = V Точн. = Н </p>
	<p>БПО-2292</p> <p> $F \text{ см}^2 = 42.130$ $Q \text{ кг.} = 11.417$ $D \text{ оп.мм} = 232.0$ $P \text{ н.мм} = 957.2$ Гр. сл. = V Точн. = П </p>		<p>БПО-2297</p> <p> $F \text{ см}^2 = 1.284$ $Q \text{ кг.} = 0.348$ $D \text{ оп.мм} = 48.7$ $P \text{ н.мм} = 189.2$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2293</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-2298</p> <p> $F \text{ см}^2 = 3.624$ $Q \text{ кг.} = 0.982$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 177.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2294</p> <p> $F \text{ см}^2 = 5.728$ $Q \text{ кг.} = 1.552$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 119.7$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2299</p> <p> $F \text{ см}^2 = 4.720$ $Q \text{ кг.} = 1.279$ $D \text{ оп.мм} = 148.0$ $P \text{ н.мм} = 415.0$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2295</p> <p> $F \text{ см}^2 = 7.100$ $Q \text{ кг.} = 1.924$ $D \text{ оп.мм} = 161.0$ $P \text{ н.мм} = 650.5$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2300</p> <p> $F \text{ см}^2 = 13.490$ $Q \text{ кг.} = 3.656$ $D \text{ оп.мм} = 156.0$ $P \text{ н.мм} = 337.1$ Гр. сл. = V Точн. = П </p>










	<p>БПО-2301</p> <p> $F \text{ см}^2 = 32.17$ $Q \text{ кг.} = 8.718$ $D \text{ оп.мм} = 109$ $P \text{ н.мм} = 1482$ Гр. сл. = особая Точн. = Н </p>		<p>БПО-2306</p> <p> $F \text{ см}^2 = 2.129$ $Q \text{ кг.} = 0.577$ $D \text{ оп.мм} = 55$ $P \text{ н.мм} = 250.4$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2302</p> <p> $F \text{ см}^2 = 2.405$ $Q \text{ кг.} = 0.652$ $D \text{ оп.мм} = 100$ $P \text{ н.мм} = 245.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2307</p> <p> $F \text{ см}^2 = 2.328$ $Q \text{ кг.} = 0.631$ $D \text{ оп.мм} = 69$ $P \text{ н.мм} = 287.5$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2303</p> <p> $F \text{ см}^2 = 0.603$ $Q \text{ кг.} = 0.163$ $D \text{ оп.мм} = 31$ $P \text{ н.мм} = 94$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2308</p> <p> $F \text{ см}^2 = 12.47$ $Q \text{ кг.} = 3.379$ $D \text{ оп.мм} = 150$ $P \text{ н.мм} = 456.1$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2304</p> <p> $F \text{ см}^2 = 0.6$ $Q \text{ кг.} = 0.163$ $D \text{ оп.мм} = 22$ $P \text{ н.мм} = 83.6$ Гр. сл. = V Точн. = особая </p>		<p>БПО-2309</p> <p> $F \text{ см}^2 = 28.07$ $Q \text{ кг.} = 7.61$ $D \text{ оп.мм} = 142$ $P \text{ н.мм} = 587.5$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2305</p> <p> $F \text{ см}^2 = 1.489$ $Q \text{ кг.} = 0.404$ $D \text{ оп.мм} = 53$ $P \text{ н.мм} = 209.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2310</p> <p> $F \text{ см}^2 = 0.918$ $Q \text{ кг.} = 0.249$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 148.4$ Гр. сл. = VI Точн. = П </p>











	<p>БПО-2311</p> <p> $F \text{ см}^2 = 1.503$ $Q \text{ кг.} = 0.407$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 200.7$ Гр. сл. = V Точн. = П </p>		<p>БПО-2316</p> <p> $F \text{ см}^2 = 7.665$ $Q \text{ кг.} = 2.077$ $D \text{ оп.мм} = 82$ $P \text{ н.мм} = 657.0$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-2312</p> <p> $F \text{ см}^2 = 1.404$ $Q \text{ кг.} = 0.380$ $D \text{ оп.мм} = 67.5$ $P \text{ н.мм} = 187.6$ Гр. сл. = V Точн. = П </p>		<p>БПО-2317</p> <p> $F \text{ см}^2 = 1.293$ $Q \text{ кг.} = 0.350$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 188.1$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2313</p> <p> $F \text{ см}^2 = 0.928$ $Q \text{ кг.} = 0.251$ $D \text{ оп.мм} = 23.3$ $P \text{ н.мм} = 100.4$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2318</p> <p> $F \text{ см}^2 = 2.196$ $Q \text{ кг.} = 0.595$ $D \text{ оп.мм} = 130.0$ $P \text{ н.мм} = 289.7$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2314</p> <p> $F \text{ см}^2 = 4.616$ $Q \text{ кг.} = 1.251$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 302.2$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-2319</p> <p> $F \text{ см}^2 = 1.143$ $Q \text{ кг.} = 0.310$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 80.1$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2315</p> <p> $F \text{ см}^2 = 0.550$ $Q \text{ кг.} = 0.149$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 47.2$ Гр. сл. = II Точн. = Н </p>		<p>БПО-2320</p> <p> $F \text{ см}^2 = 2.099$ $Q \text{ кг.} = 0.569$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 248.1$ Гр. сл. = IV Точн. = П </p>










	<p>БПО-2321</p> <p> $F \text{ см}^2 = 1.449$ $Q \text{ кг.} = 0.393$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 115.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-2326</p> <p> $F \text{ см}^2 = 2.526$ $Q \text{ кг.} = 0.685$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 343.5$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2322</p> <p> $F \text{ см}^2 = 52.560$ $Q \text{ кг.} = 14.244$ $D \text{ оп.мм} = 148.0$ $P \text{ н.мм} = 1874.0$ Гр. сл. = 0соб. Точн. = Н </p>		<p>БПО-2327</p> <p> $F \text{ см}^2 = 1.335$ $Q \text{ кг.} = 0.362$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 206.8$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2323</p> <p> $F \text{ см}^2 = 2.254$ $Q \text{ кг.} = 0.611$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 123.8$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2328</p> <p> $F \text{ см}^2 = 2.054$ $Q \text{ кг.} = 0.557$ $D \text{ оп.мм} = 66.1$ $P \text{ н.мм} = 176.9$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2324</p> <p> $F \text{ см}^2 = 2.619$ $Q \text{ кг.} = 0.710$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 153.8$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2329</p> <p> $F \text{ см}^2 = 23.834$ $Q \text{ кг.} = 6.459$ $D \text{ оп.мм} = 155.0$ $P \text{ н.мм} = 786.0$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2325</p> <p> $F \text{ см}^2 = 3.798$ $Q \text{ кг.} = 1.029$ $D \text{ оп.мм} = 48.5$ $P \text{ н.мм} = 211.5$ Гр. сл. = VI Точн. = П </p>		







			БПО-2336 $F \text{ см}^2 = 0.897$ $Q \text{ кг.} = 0.243$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 121.9$ Гр. сл. = IV Точн. = П
	БПО-2332 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. =		БПО-2337 $F \text{ см}^2 = 0.380$ $Q \text{ кг.} = 0.103$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 60.8$ Гр. сл. = IV Точн. = П
	БПО-2333 $F \text{ см}^2 = 2.990$ $Q \text{ кг.} = 0.810$ $D \text{ оп.мм} = 46.1$ $P \text{ н.мм} = 210.8$ Гр. сл. = VI Точн. = П		БПО-2338 $F \text{ см}^2 = 10.730$ $Q \text{ кг.} = 2.908$ $D \text{ оп.мм} = 83.0$ $P \text{ н.мм} = 842.9$ Гр. сл. = VI Точн. = П
	БПО-2334 $F \text{ см}^2 = 0.973$ $Q \text{ кг.} = 0.264$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 59.2$ Гр. сл. = III Точн. = П		
	БПО-2335 $F \text{ см}^2 = 0.796$ $Q \text{ кг.} = 0.216$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 127.0$ Гр. сл. = IV Точн. = Н		БПО-2340 $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. =











	<p>БПО-2341</p> <p> $F \text{ см}^2 = 5.972$ $Q \text{ кг.} = 1.618$ $D \text{ оп.мм} = 190$ $P \text{ н.мм} = 524$ Гр. сл. = V Точн. = Н </p>		<p>БПО-2346</p> <p> $F \text{ см}^2 = 7.675$ $Q \text{ кг.} = 2.080$ $D \text{ оп.мм} = 78.0$ $P \text{ н.мм} = 292.4$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2342</p> <p> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм} = 0$ $P \text{ н.мм} = 0$ Гр. сл. = 0 Точн. = 0 </p>		<p>БПО-2347</p> <p> $F \text{ см}^2 = 1.439$ $Q \text{ кг.} = 0.39$ $D \text{ оп.мм} = 32$ $P \text{ н.мм} = 136.8$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2343</p> <p> $F \text{ см}^2 = 0.673$ $Q \text{ кг.} = 0.182$ $D \text{ оп.мм} = 24$ $P \text{ н.мм} = 100$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2348</p> <p> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм} = 0$ $P \text{ н.мм} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-2344</p> <p> $F \text{ см}^2 = 0.843$ $Q \text{ кг.} = 0.228$ $D \text{ оп.мм} = 35$ $P \text{ н.мм} = 102.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2349</p> <p> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм} = 0$ $P \text{ н.мм} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-2345</p> <p> $F \text{ см}^2 = 19.090$ $Q \text{ кг.} = 5.173$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 329.1$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2350</p> <p> $F \text{ см}^2 = 1.992$ $Q \text{ кг.} = 0.540$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 119.1$ Гр. сл. = V Точн. = П </p>











	<p>БПО-2351</p> <p> $F \text{ см}^2 = 0.208$ $Q \text{ кг.} = 0.327$ $D \text{ оп.мм} = \emptyset 2.0$ $P \text{ н.мм} = \emptyset 15.3$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2356</p> <p> $F \text{ см}^2 = 4.5$ $Q \text{ кг.} = 1.22$ $D \text{ оп.мм} = 81.7$ $P \text{ н.мм} = 361$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2352</p> <p> $F \text{ см}^2 = 0.994$ $Q \text{ кг.} = 0.540$ $D \text{ оп.мм} = \emptyset 9.0$ $P \text{ н.мм} = \emptyset 29.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-2357</p> <p> $F \text{ см}^2 = 6.248$ $Q \text{ кг.} = 1.693$ $D \text{ оп.мм} = 109$ $P \text{ н.мм} = 313.4$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2353</p> <p> $F \text{ см}^2 = 11.756$ $Q \text{ кг.} = 3.185$ $D \text{ оп.мм} = 109$ $P \text{ н.мм} = 553.7$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2358</p> <p> $F \text{ см}^2 = 2.62$ $Q \text{ кг.} = 0.71$ $D \text{ оп.мм} = 81$ $P \text{ н.мм} = 349.7$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2354</p> <p> $F \text{ см}^2 = 1.45$ $Q \text{ кг.} = 0.393$ $D \text{ оп.мм} = 41$ $P \text{ н.мм} = 159.2$ Гр. сл. = V Точн. = П </p>		<p>БПО-2359</p> <p> $F \text{ см}^2 = 3.06$ $Q \text{ кг.} = 0.829$ $D \text{ оп.мм} = 81$ $P \text{ н.мм} = 308.5$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2355</p> <p> $F \text{ см}^2 = 0.985$ $Q \text{ кг.} = 0.267$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 102$ Гр. сл. = IV Точн. = П </p>		










	<p>БПО-2361</p> <p> $F \text{ см}^2 = 0.981$ $Q \text{ кг.} = 0.266$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 132.5$ Гр. сл. = IV Точн. = 0соб. </p>		<p>БПО-2366</p> <p> $F \text{ см}^2 = 0.945$ $Q \text{ кг.} = 0.256$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 127.1$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2362</p> <p> $F \text{ см}^2 = 3.433$ $Q \text{ кг.} = 0.930$ $D \text{ оп.мм} = 50.6$ $P \text{ н.мм} = 125.7$ Гр. сл. = III Точн. = П </p>		<p>БПО-2367</p> <p> $F \text{ см}^2 = 0.619$ $Q \text{ кг.} = 0.168$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 60.9$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-2363</p> <p> $F \text{ см}^2 = 1.364$ $Q \text{ кг.} = 0.370$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 140.4$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2368</p> <p> $F \text{ см}^2 = 1.950$ $Q \text{ кг.} = 0.528$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 196.6$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2364</p> <p> $F \text{ см}^2 = 0.365$ $Q \text{ кг.} = 0.099$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 56.3$ Гр. сл. = III Точн. = П </p>		<p>БПО-2369</p> <p> $F \text{ см}^2 = 0.681$ $Q \text{ кг.} = 0.185$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 101.8$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2365</p> <p> $F \text{ см}^2 = 2.610$ $Q \text{ кг.} = 0.707$ $D \text{ оп.мм} = 32.2$ $P \text{ н.мм} = 263.1$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2370</p> <p> $F \text{ см}^2 = 2.069$ $Q \text{ кг.} = 0.561$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 277.4$ Гр. сл. = VI Точн. = Н </p>









	<p>БПО-2371</p> <p> $F \text{ см}^2 = 5.040$ $Q \text{ кг.} = 1.366$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 306.3$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2376</p> <p> $F \text{ см}^2 = 17.480$ $Q \text{ кг.} = 4.737$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 1284.6$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2372</p> <p> $F \text{ см}^2 = 2.420$ $Q \text{ кг.} = 0.656$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 176.3$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2377</p> <p> $F \text{ см}^2 = 1.402$ $Q \text{ кг.} = 0.380$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 159.3$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2373</p> <p> $F \text{ см}^2 = 13.855$ $Q \text{ кг.} = 3.755$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 132.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-2378</p> <p> $F \text{ см}^2 = 1.820$ $Q \text{ кг.} = 0.493$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 215.8$ Гр. сл. = V Точн. = П </p>
			<p>БПО-2379</p> <p> $F \text{ см}^2 = 0.934$ $Q \text{ кг.} = 0.253$ $D \text{ оп.мм} = 28.5$ $P \text{ н.мм} = 124.6$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2375</p> <p> $F \text{ см}^2 = 1.265$ $Q \text{ кг.} = 0.343$ $D \text{ оп.мм} = 56.6$ $P \text{ н.мм} = 196.6$ Гр. сл. = V Точн. = П </p>		<p>БПО-2380</p> <p> $F \text{ см}^2 = 0.518$ $Q \text{ кг.} = 0.140$ $D \text{ оп.мм} = 15.2$ $P \text{ н.мм} = 70.1$ Гр. сл. = IV Точн. = Н </p>









	<p>БПО-2381</p> <p> $F \text{ см}^2 = 0.413$ $Q \text{ кг.} = 0.112$ $D \text{ оп.мм} = 12.2$ $P \text{ н.мм} = 56.1$ Гр. сл. = IV Точн. = Н </p>		
	<p>БПО-2382</p> <p> $F \text{ см}^2 = 0.723$ $Q \text{ кг.} = 0.196$ $D \text{ оп.мм} = 19.0$ $P \text{ н.мм} = 95.8$ Гр. сл. = V Точн. = Н </p>		<p>БПО-2387</p> <p> $F \text{ см}^2 = 0.950$ $Q \text{ кг.} = 0.257$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 152.8$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2383</p> <p> $F \text{ см}^2 = 0.562$ $Q \text{ кг.} = 0.152$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 55.5$ Гр. сл. = IV Точн. = П </p>		
			<p>БПО-2389</p> <p> $F \text{ см}^2 = 0.616$ $Q \text{ кг.} = 0.167$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 101.2$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2390</p> <p> $F \text{ см}^2 = 0.481$ $Q \text{ кг.} = 0.130$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 78.8$ Гр. сл. = III Точн. = П </p>









	<p>БПО-2391</p> <p> $F \text{ см}^2 = 0.416$ $Q \text{ кг.} = 0.113$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 71.9$ Гр. сл. = III Точн. = П </p>		<p>БПО-2396</p> <p> $F \text{ см}^2 = 4.943$ $Q \text{ кг.} = 1.340$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 441.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2392</p> <p> $F \text{ см}^2 = 0.348$ $Q \text{ кг.} = 0.094$ $D \text{ оп.мм} = 20.4$ $P \text{ н.мм} = 58.9$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2397</p> <p> $F \text{ см}^2 = 2.557$ $Q \text{ кг.} = 0.693$ $D \text{ оп.мм} = 94.0$ $P \text{ н.мм} = 228.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2393</p> <p> $F \text{ см}^2 = 0.338$ $Q \text{ кг.} = 0.092$ $D \text{ оп.мм} = 20.4$ $P \text{ н.мм} = 59.9$ Гр. сл. = III Точн. = П </p>		<p>БПО-2398</p> <p> $F \text{ см}^2 = 1.654$ $Q \text{ кг.} = 0.448$ $D \text{ оп.мм} = 43.9$ $P \text{ н.мм} = 142.8$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2394</p> <p> $F \text{ см}^2 = 0.505$ $Q \text{ кг.} = 0.137$ $D \text{ оп.мм} = 28.8$ $P \text{ н.мм} = 79.4$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2399</p> <p> $F \text{ см}^2 = 5.840$ $Q \text{ кг.} = 1.583$ $D \text{ оп.мм} = 164.0$ $P \text{ н.мм} = 684.7$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2395</p> <p> $F \text{ см}^2 = 0.263$ $Q \text{ кг.} = 0.071$ $D \text{ оп.мм} = 13.3$ $P \text{ н.мм} = 44.5$ Гр. сл. = III Точн. = П </p>		<p>БПО-2400</p> <p> $F \text{ см}^2 = 1.486$ $Q \text{ кг.} = 0.403$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 113.8$ Гр. сл. = IV Точн. = Н </p>







	<p>БПО-2401</p> <p> $F \text{ см}^2 = 4.360$ $Q \text{ кг.} = 1.182$ $D \text{ оп.мм} = 145.0$ $P \text{ н.мм} = 400.5$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2406</p> <p> $F \text{ см}^2 = 6.386$ $Q \text{ кг.} = 1.731$ $D \text{ оп.мм} = 121.0$ $P \text{ н.мм} = 395.2$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2402</p> <p> $F \text{ см}^2 = 3.255$ $Q \text{ кг.} = 0.882$ $D \text{ оп.мм} = 136.0$ $P \text{ н.мм} = 352.9$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2407</p> <p> $F \text{ см}^2 = 4.723$ $Q \text{ кг.} = 1.280$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 166.9$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-2403</p> <p> $F \text{ см}^2 = 0.781$ $Q \text{ кг.} = 0.212$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 109.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-2408</p> <p> $F \text{ см}^2 = 4.663$ $Q \text{ кг.} = 1.264$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 129.1$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-2404</p> <p> $F \text{ см}^2 = 8.524$ $Q \text{ кг.} = 2.310$ $D \text{ оп.мм} = 128.0$ $P \text{ н.мм} = 576.9$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2409</p> <p> $F \text{ см}^2 = 7.863$ $Q \text{ кг.} = 2.131$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 209.1$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-2405</p> <p> $F \text{ см}^2 = 6.964$ $Q \text{ кг.} = 1.887$ $D \text{ оп.мм} = 166.0$ $P \text{ н.мм} = 545.9$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2410</p> <p> $F \text{ см}^2 = 6.750$ $Q \text{ кг.} = 1.829$ $D \text{ оп.мм} = 184.5$ $P \text{ н.мм} = 685.8$ Гр. сл. = 0соб. Точн. = Н </p>









	<p>БПО-2411</p> <p> $F \text{ см}^2 = 1.370$ $Q \text{ кг.} = 0.371$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 139.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2416</p> <p> $F \text{ см}^2 = 1.028$ $Q \text{ кг.} = 0.279$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 136.7$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2412</p> <p> $F \text{ см}^2 = 1.407$ $Q \text{ кг.} = 0.381$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 144.2$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2417</p> <p> $F \text{ см}^2 = 0.608$ $Q \text{ кг.} = 0.165$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 85.0$ Гр. сл. = V Точн. = П </p>
			<p>БПО-2418</p> <p> $F \text{ см}^2 = 0.820$ $Q \text{ кг.} = 0.222$ $D \text{ оп.мм} = 16.0$ $P \text{ н.мм} = 78.7$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2414</p> <p> $F \text{ см}^2 = 0.835$ $Q \text{ кг.} = 0.226$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 123.6$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2419</p> <p> $F \text{ см}^2 = 0.313$ $Q \text{ кг.} = 0.085$ $D \text{ оп.мм} = 17.0$ $P \text{ н.мм} = 53.5$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2415</p> <p> $F \text{ см}^2 = 1.099$ $Q \text{ кг.} = 0.298$ $D \text{ оп.мм} = 35.5$ $P \text{ н.мм} = 156.9$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2420</p> <p> $F \text{ см}^2 = 1.790$ $Q \text{ кг.} = 0.485$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 242.1$ Гр. сл. = V Точн. = П </p>











	<p>БПО-2421</p> <p> $F \text{ см}^2 = 25.030$ $Q \text{ кг.} = 6.783$ $D \text{ оп.мм} = 190.0$ $P \text{ н.мм} = 736.1$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2426</p> <p> $F \text{ см}^2 = 2.949$ $Q \text{ кг.} = 0.799$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 201.1$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2422</p> <p> $F \text{ см}^2 = 12.890$ $Q \text{ кг.} = 3.493$ $D \text{ оп.мм} = 127.0$ $P \text{ н.мм} = 528.8$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2427</p> <p> $F \text{ см}^2 = 2.857$ $Q \text{ кг.} = 0.774$ $D \text{ оп.мм} = 119.0$ $P \text{ н.мм} = 298.4$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2428</p> <p> $F \text{ см}^2 = 3.840$ $Q \text{ кг.} = 1.041$ $D \text{ оп.мм} = 125.0$ $P \text{ н.мм} = 312.3$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2424</p> <p> $F \text{ см}^2 = 9.742$ $Q \text{ кг.} = 2.640$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 276.9$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2429</p> <p> $F \text{ см}^2 = 0.781$ $Q \text{ кг.} = 0.212$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 104.1$ Гр. сл. = V Точн. = П </p>
			<p>БПО-2430</p> <p> $F \text{ см}^2 = 2.767$ $Q \text{ кг.} = 0.750$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 241.5$ Гр. сл. = VI Точн. = П </p>







	<p>БПО-2431</p> <p> $F \text{ см}^2 = 0.634$ $Q \text{ кг.} = 0.172$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 70.3$ Гр. сл. = III Точн. = П </p>		<p>БПО-2436</p> <p> $F \text{ см}^2 = 4.230$ $Q \text{ кг.} = 1.146$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 199.1$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2432</p> <p> $F \text{ см}^2 = 42.400$ $Q \text{ кг.} = 11.490$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 1306.0$ Гр. сл. = 0соб. Точн. = П </p>		
	<p>БПО-2433</p> <p> $F \text{ см}^2 = 0.638$ $Q \text{ кг.} = 0.173$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 130.3$ Гр. сл. = VI Точн. = 0соб. </p>		<p>БПО-2438</p> <p> $F \text{ см}^2 = 5.250$ $Q \text{ кг.} = 1.423$ $D \text{ оп.мм} = 164.0$ $P \text{ н.мм} = 356.0$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2434</p> <p> $F \text{ см}^2 = 0.962$ $Q \text{ кг.} = 0.261$ $D \text{ оп.мм} = 42.1$ $P \text{ н.мм} = 194.4$ Гр. сл. = 0соб. Точн. = 0соб. </p>		<p>БПО-2439</p> <p> $F \text{ см}^2 = 3.341$ $Q \text{ кг.} = 0.905$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 227.4$ Гр. сл. = III Точн. = П </p>
			<p>БПО-2440</p> <p> $F \text{ см}^2 = 1.900$ $Q \text{ кг.} = 0.515$ $D \text{ оп.мм} = 53.0$ $P \text{ н.мм} = 121.4$ Гр. сл. = III Точн. = H </p>










	<p>БПО-2441</p> <p> $F \text{ см}^2 = 0.505$ $Q \text{ кг.} = 0.137$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 94.4$ Гр. сл. = V Точн. = П </p>		
	<p>БПО-2442</p> <p> $F \text{ см}^2 = 10.430$ $Q \text{ кг.} = 2.827$ $D \text{ оп.мм} = 183.0$ $P \text{ н.мм} = 716.8$ Гр. сл. = 0соб. Точн. = П </p>		
	<p>БПО-2443</p> <p> $F \text{ см}^2 = 4.243$ $Q \text{ кг.} = 1.150$ $D \text{ оп.мм} = 74.0$ $P \text{ н.мм} = 349.7$ Гр. сл. = V Точн. = 0соб. </p>		<p>БПО-2448</p> <p> $F \text{ см}^2 = 5.413$ $Q \text{ кг.} = 1.467$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 86.6$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-2444</p> <p> $F \text{ см}^2 = 2.221$ $Q \text{ кг.} = 0.602$ $D \text{ оп.мм} = 45.1$ $P \text{ н.мм} = 153.3$ Гр. сл. = V Точн. = 0соб. </p>		<p>БПО-2449</p> <p> $F \text{ см}^2 = 6.585$ $Q \text{ кг.} = 1.785$ $D \text{ оп.мм} = 102$ $P \text{ н.мм} = 441.8$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2445</p> <p> $F \text{ см}^2 = 2.297$ $Q \text{ кг.} = 0.622$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 208.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-2450</p> <p> $F \text{ см}^2 = 1.590$ $Q \text{ кг.} = 0.431$ $D \text{ оп.мм} = 28.7$ $P \text{ н.мм} = 156.4$ Гр. сл. = III Точн. = П </p>








	<p>БПО-2451</p> <p> $F \text{ см}^2 = 3.741$ $Q \text{ кг.} = 1.014$ $D \text{ оп.мм} = 125.0$ $P \text{ н.мм} = 374.1$ Гр. сл. = VI Точн. = 0соб. </p>		
			<p>БПО-2457</p> <p> $F \text{ см}^2 = 1.600$ $Q \text{ кг.} = 0.434$ $D \text{ оп.мм} = 78.0$ $P \text{ н.мм} = 223.3$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2458</p> <p> $F \text{ см}^2 = 0.314$ $Q \text{ кг.} = 0.085$ $D \text{ оп.мм} = 9.5$ $P \text{ н.мм} = 55.5$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2459</p> <p> $F \text{ см}^2 = 2.440$ $Q \text{ кг.} = 0.661$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 208.8$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2455</p> <p> $F \text{ см}^2 = 3.761$ $Q \text{ кг.} = 1.019$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 218.8$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2460</p> <p> $F \text{ см}^2 = 2.975$ $Q \text{ кг.} = 0.806$ $D \text{ оп.мм} = 63.0$ $P \text{ н.мм} = 293$ Гр. сл. = V Точн. = П </p>










	<p>БПО-2461</p> <p> $F \text{ см}^2 = 1.350$ $Q \text{ кг.} = 0.366$ $D \text{ оп.мм} = 34.3$ $P \text{ н.мм} = 154.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2466</p> <p> $F \text{ см}^2 = 9.978$ $Q \text{ кг.} = 2.704$ $D \text{ оп.мм} = 180.0$ $P \text{ н.мм} = 475.8$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-2462</p> <p> $F \text{ см}^2 = 6.452$ $Q \text{ кг.} = 1.748$ $D \text{ оп.мм} = 102.0$ $P \text{ н.мм} = 585.5$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2467</p> <p> $F \text{ см}^2 = 1.420$ $Q \text{ кг.} = 0.385$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 263.0$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2463</p> <p> $F \text{ см}^2 = 5.292$ $Q \text{ кг.} = 1.434$ $D \text{ оп.мм} = 113.0$ $P \text{ н.мм} = 556.1$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2468</p> <p> $F \text{ см}^2 = 21.840$ $Q \text{ кг.} = 5.919$ $D \text{ оп.мм} = 130.0$ $P \text{ н.мм} = 364.0$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2465</p> <p> $F \text{ см}^2 = 0.413$ $Q \text{ кг.} = 0.112$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 64.5$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2470</p> <p> $F \text{ см}^2 = 8.000$ $Q \text{ кг.} = 2.168$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 330.0$ Гр. сл. = III Точн. = Особ. </p>











	<p>БПО-2471</p> <p> $F \text{ см}^2 = 8.899$ $Q \text{ кг.} = 2.412$ $D \text{ оп.мм} = 67.0$ $P \text{ н.мм} = 314.8$ Гр. сл. = IV Точн. = 0соб. </p>		<p>БПО-2476</p> <p> $F \text{ см}^2 = 1.794$ $Q \text{ кг.} = 0.486$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 232.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2472</p> <p> $F \text{ см}^2 = 5.180$ $Q \text{ кг.} = 1.404$ $D \text{ оп.мм} = 195.0$ $P \text{ н.мм} = 507.5$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2477</p> <p> $F \text{ см}^2 = 1.796$ $Q \text{ кг.} = 0.487$ $D \text{ оп.мм} = 51$ $P \text{ н.мм} = 165$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2473</p> <p> $F \text{ см}^2 = 0.435$ $Q \text{ кг.} = 0.118$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 80.8$ Гр. сл. = III Точн. = П </p>		<p>БПО-2478</p> <p> $F \text{ см}^2 = 2.969$ $Q \text{ кг.} = 0.805$ $D \text{ оп.мм} = 42$ $P \text{ н.мм} = 170.7$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2474</p> <p> $F \text{ см}^2 = 0.279$ $Q \text{ кг.} = 0.076$ $D \text{ оп.мм} = 14.0$ $P \text{ н.мм} = 47.7$ Гр. сл. = III Точн. = П </p>		<p>БПО-2479</p> <p> $F \text{ см}^2 = 2.187$ $Q \text{ кг.} = 0.593$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 222.6$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2475</p> <p> $F \text{ см}^2 = 0.593$ $Q \text{ кг.} = 0.161$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 103.7$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2480</p> <p> $F \text{ см}^2 = 3.377$ $Q \text{ кг.} = 0.915$ $D \text{ оп.мм} = 135.0$ $P \text{ н.мм} = 468.4$ Гр. сл. = V Точн. = П </p>











	<p>БПО-2481</p> <p> $F \text{ см}^2 = 1.480$ $Q \text{ кг.} = 0.401$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 152.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2486</p> <p> $F \text{ см}^2 = 4.140$ $Q \text{ кг.} = 1.122$ $D \text{ оп.мм} = 133.0$ $P \text{ н.мм} = 447.8$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2482</p> <p> $F \text{ см}^2 = 3.559$ $Q \text{ кг.} = 0.964$ $D \text{ оп.мм} = 74.0$ $P \text{ н.мм} = 272.8$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2487</p> <p> $F \text{ см}^2 = 0.390$ $Q \text{ кг.} = 0.106$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 69.5$ Гр. сл. = III Точн. = П </p>
			<p>БПО-2488</p> <p> $F \text{ см}^2 = 0.286$ $Q \text{ кг.} = 0.078$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 53.5$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2485</p> <p> $F \text{ см}^2 = 8.089$ $Q \text{ кг.} = 2.192$ $D \text{ оп.мм} = 159.0$ $P \text{ н.мм} = 648.2$ Гр. сл. = VI Точн. = П </p>		









	<p>БПО-2491</p> <p> $F \text{ см}^2 = 1.514$ $Q \text{ кг.} = 0.410$ $D \text{ оп.мм} = 36.5$ $P \text{ н.мм} = 117.9$ Гр. сл. = V Точн. = П </p>		<p>БПО-2496</p> <p> $F \text{ см}^2 = 1.910$ $Q \text{ кг.} = 0.518$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 264.0$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2492</p> <p> $F \text{ см}^2 = 5.895$ $Q \text{ кг.} = 1.598$ $D \text{ оп.мм} = 130.0$ $P \text{ н.мм} = 587.3$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2497</p> <p> $F \text{ см}^2 = 1.110$ $Q \text{ кг.} = 0.301$ $D \text{ оп.мм} = 60.2$ $P \text{ н.мм} = 181.6$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2493</p> <p> $F \text{ см}^2 = 3.772$ $Q \text{ кг.} = 1.022$ $D \text{ оп.мм} = 127.5$ $P \text{ н.мм} = 373.6$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2498</p> <p> $F \text{ см}^2 = 0.524$ $Q \text{ кг.} = 0.142$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 92.8$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2499</p> <p> $F \text{ см}^2 = 0.405$ $Q \text{ кг.} = 0.110$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 78.4$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2495</p> <p> $F \text{ см}^2 = 0.461$ $Q \text{ кг.} = 0.125$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 57.8$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2500</p> <p> $F \text{ см}^2 = 0.586$ $Q \text{ кг.} = 0.159$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 89.9$ Гр. сл. = V Точн. = П </p>










	<p>БПО-2501</p> <p> $F \text{ см}^2 = 7.243$ $Q \text{ кг.} = 1.963$ $D \text{ оп.мм} = 130.0$ $P \text{ н.мм} = 722.1$ Гр. сл. = VI Точн. = П </p>		
	<p>БПО-2502</p> <p> $F \text{ см}^2 = 1.599$ $Q \text{ кг.} = 0.433$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 224.1$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2507</p> <p> $F \text{ см}^2 = 2.600$ $Q \text{ кг.} = 0.705$ $D \text{ оп.мм} = 59.5$ $P \text{ н.мм} = 269.0$ Гр. сл. = IV Точн. = Н </p>
			<p>БПО-2508</p> <p> $F \text{ см}^2 = 1.340$ $Q \text{ кг.} = 0.363$ $D \text{ оп.мм} = 27.2$ $P \text{ н.мм} = 66.6$ Гр. сл. = III Точн. = Н </p>
			<p>БПО-2509</p> <p> $F \text{ см}^2 = 1.832$ $Q \text{ кг.} = 0.496$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 249.9$ Гр. сл. = VI Точн. = Н </p>
	<p>БПО-2505</p> <p> $F \text{ см}^2 = 3.496$ $Q \text{ кг.} = 0.947$ $D \text{ оп.мм} = 93.0$ $P \text{ н.мм} = 343.7$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2510</p> <p> $F \text{ см}^2 = 2.975$ $Q \text{ кг.} = 0.806$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 191.7$ Гр. сл. = IV Точн. = Н </p>








	<p>БПО-2511</p> <p> $F \text{ см}^2 = 4.220$ $Q \text{ кг.} = 1.144$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 405.6$ Гр. сл. = VI Точн. = П </p>		
	<p>БПО-2512</p> <p> $F \text{ см}^2 = 5.634$ $Q \text{ кг.} = 1.527$ $D \text{ оп.мм} = 72.3$ $P \text{ н.мм} = 520.6$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2517</p> <p> $F \text{ см}^2 = 0.400$ $Q \text{ кг.} = 0.108$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 47.1$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2513</p> <p> $F \text{ см}^2 = 0.430$ $Q \text{ кг.} = 0.117$ $D \text{ оп.мм} = 17.0$ $P \text{ н.мм} = 63.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2518</p> <p> $F \text{ см}^2 = 0.556$ $Q \text{ кг.} = 0.151$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 95.3$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2514</p> <p> $F \text{ см}^2 = 8.242$ $Q \text{ кг.} = 2.234$ $D \text{ оп.мм} = 123.0$ $P \text{ н.мм} = 761.8$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2519</p> <p> $F \text{ см}^2 = 1.078$ $Q \text{ кг.} = 0.292$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 181.9$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2515</p> <p> $F \text{ см}^2 = 1.368$ $Q \text{ кг.} = 0.371$ $D \text{ оп.мм} = 43.0$ $P \text{ н.мм} = 114.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2520</p> <p> $F \text{ см}^2 = 1.722$ $Q \text{ кг.} = 0.467$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 213.3$ Гр. сл. = VI Точн. = П </p>









	<p>БПО-2521</p> <p> $F \text{ см}^2 = 0.868$ $Q \text{ кг.} = 0.235$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 72.5$ Гр. сл. = III Точн. = П </p>		<p>БПО-2526</p> <p> $F \text{ см}^2 = 1.960$ $Q \text{ кг.} = 0.531$ $D \text{ оп.мм} = 36.5$ $P \text{ н.мм} = 149.3$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2522</p> <p> $F \text{ см}^2 = 1.605$ $Q \text{ кг.} = 0.435$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 214.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-2527</p> <p> $F \text{ см}^2 = 2.080$ $Q \text{ кг.} = 0.564$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 124.0$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2523</p> <p> $F \text{ см}^2 = 5.560$ $Q \text{ кг.} = 1.507$ $D \text{ оп.мм} = 104.0$ $P \text{ н.мм} = 548.2$ Гр. сл. = V Точн. = П </p>		<p>БПО-2528</p> <p> $F \text{ см}^2 = 2.200$ $Q \text{ кг.} = 0.596$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 139.6$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2524</p> <p> $F \text{ см}^2 = 5.672$ $Q \text{ кг.} = 1.537$ $D \text{ оп.мм} = 104.0$ $P \text{ н.мм} = 548.2$ Гр. сл. = особая Точн. = П </p>		<p>БПО-2529</p> <p> $F \text{ см}^2 = 3.867$ $Q \text{ кг.} = 1.048$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 210.0$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2525</p> <p> $F \text{ см}^2 = 4.081$ $Q \text{ кг.} = 1.106$ $D \text{ оп.мм} = 52.2$ $P \text{ н.мм} = 190.7$ Гр. сл. = V Точн. = П </p>		<p>БПО-2530</p> <p> $F \text{ см}^2 = 0.644$ $Q \text{ кг.} = 0.175$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 109.9$ Гр. сл. = IV Точн. = П </p>








	<p>БПО-2531</p> <p> $F \text{ см}^2 = 0.539$ $Q \text{ кг.} = 0.146$ $D \text{ оп.мм} = 29.2$ $P \text{ н.мм} = 69.2$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2536</p> <p> $F \text{ см}^2 = 2.063$ $Q \text{ кг.} = 0.559$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 62.9$ Гр. сл. = III Точн. = 0соб. </p>
	<p>БПО-2532</p> <p> $F \text{ см}^2 = 0.390$ $Q \text{ кг.} = 0.106$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 53.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2537</p> <p> $F \text{ см}^2 = 0.603$ $Q \text{ кг.} = 0.163$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 77.7$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2533</p> <p> $F \text{ см}^2 = 0.626$ $Q \text{ кг.} = 0.170$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 58.9$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2538</p> <p> $F \text{ см}^2 = 0.511$ $Q \text{ кг.} = 0.138$ $D \text{ оп.мм} = 29.4$ $P \text{ н.мм} = 87.9$ Гр. сл. = v Точн. = П </p>
	<p>БПО-2534</p> <p> $F \text{ см}^2 = 0.618$ $Q \text{ кг.} = 0.167$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 86.1$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2539</p> <p> $F \text{ см}^2 = 1.875$ $Q \text{ кг.} = 0.508$ $D \text{ оп.мм} = 59.0$ $P \text{ н.мм} = 249.8$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2535</p> <p> $F \text{ см}^2 = 0.506$ $Q \text{ кг.} = 0.137$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 67.3$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2540</p> <p> $F \text{ см}^2 = 1.793$ $Q \text{ кг.} = 0.486$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 149.0$ Гр. сл. = VI Точн. = П </p>








	<p>БПО-2541</p> <p> $F \text{ см}^2 = 3.027$ $Q \text{ кг.} = 0.820$ $D \text{ оп.мм} = 91.0$ $P \text{ н.мм} = 403.2$ Гр. сл. = V Точн. = П </p>		<p>БПО-2546</p> <p> $F \text{ см}^2 = 0.990$ $Q \text{ кг.} = 0.268$ $D \text{ оп.мм} = 16.0$ $P \text{ н.мм} = 72.0$ Гр. сл. = III Точн. = П </p>
			<p>БПО-2547</p> <p> $F \text{ см}^2 = 2.690$ $Q \text{ кг.} = 0.729$ $D \text{ оп.мм} = 62.0$ $P \text{ н.мм} = 204.4$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2548</p> <p> $F \text{ см}^2 = 1.000$ $Q \text{ кг.} = 0.271$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 85.8$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-2544</p> <p> $F \text{ см}^2 = 4.450$ $Q \text{ кг.} = 1.206$ $D \text{ оп.мм} = 60.1$ $P \text{ н.мм} = 243.3$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2549</p> <p> $F \text{ см}^2 = 0.306$ $Q \text{ кг.} = 0.083$ $D \text{ оп.мм} = 19.5$ $P \text{ н.мм} = 57.4$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2545</p> <p> $F \text{ см}^2 = 3.960$ $Q \text{ кг.} = 1.073$ $D \text{ оп.мм} = 48.4$ $P \text{ н.мм} = 211.3$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2550</p> <p> $F \text{ см}^2 = 0.674$ $Q \text{ кг.} = 0.183$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 73.9$ Гр. сл. = II Точн. = Н </p>











	<p>БПО-2551</p> <p> $F \text{ см}^2 = 9.523$ $Q \text{ кг.} = 2.581$ $D \text{ оп.мм} = 177$ $P \text{ н.мм} = 627.9$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2556</p> <p> $F \text{ см}^2 = 1.973$ $Q \text{ кг.} = 0.535$ $D \text{ оп.мм} = 95.0$ $P \text{ н.мм} = 238.0$ Гр. сл. = IV Точн. = 0соб. </p>
	<p>БПО-2552</p> <p> $F \text{ см} = 1.47$ $Q \text{ кг.} = 0.398$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 127.8$ Гр. сл. = V Точн. = П </p>		<p>БПО-2557</p> <p> $F \text{ см}^2 = 14.130$ $Q \text{ кг.} = 3.829$ $D \text{ оп.мм} = 172.0$ $P \text{ н.мм} = 570.6$ Гр. сл. = iv Точн. = П </p>
			<p>БПО-2558</p> <p> $F \text{ см}^2 = 13.022$ $Q \text{ кг.} = 3.529$ $D \text{ оп.мм} = 94.5$ $P \text{ н.мм} = 345.7$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2554</p> <p> $F \text{ см} = 2.000$ $Q \text{ кг.} = 0.542$ $D \text{ оп.мм} = 113.0$ $P \text{ н.мм} = 270.4$ Гр. сл. = V Точн. = П </p>		<p>БПО-2559</p> <p> $F \text{ см}^2 = 23.616$ $Q \text{ кг.} = 6.400$ $D \text{ оп.мм} = 263.0$ $P \text{ н.мм} = 942.3$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>БПО-2555</p> <p> $F \text{ см}^2 = 0.410$ $Q \text{ кг.} = 0.111$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 79.4$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2560</p> <p> $F \text{ см}^2 = 25.020$ $Q \text{ кг.} = 6.780$ $D \text{ оп.мм} = 2216.0$ $P \text{ н.мм} = 705.7$ Гр. сл. = 0соб. Точн. = Н </p>








	БПО-2561		БПО-2566
	$F \text{ см}^2 = 16.693$ $Q \text{ кг.} = 4.524$ $D \text{ оп.мм} = 137.7$ $P \text{ н.мм} = 1199.0$ Гр. сл. = 0соб. Точн. = П		$F \text{ см}^2 = 0.997$ $Q \text{ кг.} = 0.270$ $D \text{ оп.мм} = 30.6$ $P \text{ н.мм} = 89.2$ Гр. сл. = IV Точн. = П
			БПО-2567
			$F \text{ см}^2 = 3.050$ $Q \text{ кг.} = 0.827$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 201.4$ Гр. сл. = V Точн. = П
	БПО-2563		БПО-2568
	$F \text{ см}^2 = 1.52$ $Q \text{ кг.} = 0.412$ $D \text{ оп.мм} = 53$ $P \text{ н.мм} = 151.5$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 36.216$ $Q \text{ кг.} = 9.815$ $D \text{ оп.мм} = 147.0$ $P \text{ н.мм} = 336.6$ Гр. сл. = II Точн. = Н
	БПО-2564		БПО-2569
	$F \text{ см}^2 = 0.927$ $Q \text{ кг.} = 0.251$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 79.9$ Гр. сл. = III Точн. = П		$F \text{ см}^2 = 33.716$ $Q \text{ кг.} = 9.137$ $D \text{ оп.мм} = 137.0$ $P \text{ н.мм} = 316.6$ Гр. сл. = II Точн. = Н









	<p>БПО-2571</p> <p> $F \text{ см}^2 = 24.750$ $Q \text{ кг.} = 6.707$ $D \text{ оп.мм} = 72.0$ $P \text{ н.мм} = 200.0$ Гр. сл. = II Точн. = Н </p>		
	<p>БПО-2572</p> <p> $F \text{ см}^2 = 27.500$ $Q \text{ кг.} = 7.453$ $D \text{ оп.мм} = 75.0$ $P \text{ н.мм} = 210.0$ Гр. сл. = II Точн. = Н </p>		<p>БПО-2577</p> <p> $F \text{ см}^2 = 1.650$ $Q \text{ кг.} = 0.447$ $D \text{ оп.мм} = 22.4$ $P \text{ н.мм} = 84.0$ Гр. сл. = III Точн. = П </p>
			<p>БПО-2578</p> <p> $F \text{ см}^2 = 2.410$ $Q \text{ кг.} = 0.653$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 194.0$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2574</p> <p> $F \text{ см}^2 = 1.662$ $Q \text{ кг.} = 0.450$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 199.9$ Гр. сл. = V Точн. = П </p>		<p>БПО-2579</p> <p> $F \text{ см}^2 = 1.736$ $Q \text{ кг.} = 0.470$ $D \text{ оп.мм} = 49.1$ $P \text{ н.мм} = 156.0$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2575</p> <p> $F \text{ см}^2 = 18.960$ $Q \text{ кг.} = 5.138$ $D \text{ оп.мм} = 217.0$ $P \text{ н.мм} = 868.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2580</p> <p> $F \text{ см}^2 = 7.504$ $Q \text{ кг.} = 2.034$ $D \text{ оп.мм} = 165.0$ $P \text{ н.мм} = 633.3$ Гр. сл. = VI Точн. = П </p>








			БПО-2586 $F \text{ см}^2 = 0.518$ $Q \text{ кг.} = 0.140$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 55.5$ Гр. сл. = IV Точн. = П
	БПО-2582 $F \text{ см}^2 = 0.908$ $Q \text{ кг.} = 0.246$ $D \text{ оп.мм} = 42$ $P \text{ н.мм} = 124$ Гр. сл. = III Точн. = Н		БПО-2587 $F \text{ см}^2 = 3.954$ $Q \text{ кг.} = 1.072$ $D \text{ оп.мм} = 52.4$ $P \text{ н.мм} = 219.3$ Гр. сл. = VI Точн. = П
	БПО-2583 $F \text{ см}^2 = 0.375$ $Q \text{ кг.} = 0.101$ $D \text{ оп.мм} = 24$ $P \text{ н.мм} = 71.2$ Гр. сл. = IV Точн. = Н		БПО-2588 $F \text{ см}^2 = 2.049$ $Q \text{ кг.} = 0.555$ $D \text{ оп.мм} = 93.2$ $P \text{ н.мм} = 308.8$ Гр. сл. = VI Точн. = П
	БПО-2585 $F \text{ см}^2 = 0.893$ $Q \text{ кг.} = 0.242$ $D \text{ оп.мм} = 21.2$ $P \text{ н.мм} = 56.3$ Гр. сл. = II Точн. = П		БПО-2590 $F \text{ см}^2 = 28.274$ $Q \text{ кг.} = 7.662$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 288.6$ Гр. сл. = II Точн. = Н








	<p>БПО-2591</p> <p> $F \text{ см}^2 = 0.768$ $Q \text{ кг.} = 0.208$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 132.4$ Гр. сл. = IV Точн. = П </p>		
	<p>БПО-2592</p> <p> $F \text{ см}^2 = 0.370$ $Q \text{ кг.} = 0.100$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 62.9$ Гр. сл. = III Точн. = П </p>		<p>БПО-2597</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>
	<p>БПО-2593</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-2598</p> <p> $F \text{ см}^2 = 0.456$ $Q \text{ кг.} = 0.124$ $D \text{ оп.мм} = 20.1$ $P \text{ н.мм} = 53.4$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2594</p> <p> $F \text{ см}^2 = 4.800$ $Q \text{ кг.} = 1.301$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 376.2$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2599</p> <p> $F \text{ см}^2 = 2.194$ $Q \text{ кг.} = 0.595$ $D \text{ оп.мм} = 77.0$ $P \text{ н.мм} = 334.5$ Гр. сл. = VI Точн. = 0соб. </p>
	<p>БПО-2595</p> <p> $F \text{ см}^2 = 11.562$ $Q \text{ кг.} = 3.133$ $D \text{ оп.мм} = 155.0$ $P \text{ н.мм} = 694.3$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2600</p> <p> $F \text{ см}^2 = 55.504$ $Q \text{ кг.} = 15.042$ $D \text{ оп.мм} = 149.0$ $P \text{ н.мм} = 1875.0$ Гр. сл. = 0соб. Точн. = П </p>

	<p>БПО-2601</p> <p> $F \text{ см}^2 = 57.908$ $Q \text{ кг.} = 15.693$ $D \text{ оп.мм} = 149.0$ $P \text{ н.мм} = 1810.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2606</p> <p> $F \text{ см}^2 = 0.710$ $Q \text{ кг.} = 0.192$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 93.8$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2602</p> <p> $F \text{ см}^2 = 0.808$ $Q \text{ кг.} = 0.219$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 117.8$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2607</p> <p> $F \text{ см}^2 = 1.520$ $Q \text{ кг.} = 0.412$ $D \text{ оп.мм} = 41.7$ $P \text{ н.мм} = 178.4$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2603</p> <p> $F \text{ см}^2 = 0.933$ $Q \text{ кг.} = 0.253$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 139.2$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2608</p> <p> $F \text{ см}^2 = 2.290$ $Q \text{ кг.} = 0.621$ $D \text{ оп.мм} = 44.6$ $P \text{ н.мм} = 186.5$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2604</p> <p> $F \text{ см}^2 = 0.390$ $Q \text{ кг.} = 0.106$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 43.2$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2609</p> <p> $F \text{ см}^2 = 4.766$ $Q \text{ кг.} = 1.292$ $D \text{ оп.мм} = 72.0$ $P \text{ н.мм} = 464.0$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2605</p> <p> $F \text{ см}^2 = 6.160$ $Q \text{ кг.} = 1.669$ $D \text{ оп.мм} = 155.0$ $P \text{ н.мм} = 316.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2610</p> <p> $F \text{ см}^2 = 0.296$ $Q \text{ кг.} = 0.080$ $D \text{ оп.мм} = 12.6$ $P \text{ н.мм} = 52.3$ Гр. сл. = V Точн. = Н </p>


	<p>БПО-2611</p> <p> $F \text{ см}^2 = 1.674$ $Q \text{ кг.} = 0.454$ $D \text{ оп.мм} = 68.0$ $P \text{ н.мм} = 275.4$ Гр. сл. = vi Точн. = П </p>		
	<p>БПО-2613</p> <p> $F \text{ см}^2 = 8.878$ $Q \text{ кг.} = 2.406$ $D \text{ оп.мм} = 52.6$ $P \text{ н.мм} = 167.0$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2618</p> <p> $F \text{ см}^2 = 0.831$ $Q \text{ кг.} = 0.225$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 118.6$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2614</p> <p> $F \text{ см}^2 = 1.274$ $Q \text{ кг.} = 0.345$ $D \text{ оп.мм} = 58$ $P \text{ н.мм} = 211$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2619</p> <p> $F \text{ см}^2 = 3.976$ $Q \text{ кг.} = 1.077$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 183.9$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2615</p> <p> $F \text{ см}^2 = 4.997$ $Q \text{ кг.} = 1.354$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 153.6$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2620</p> <p> $F \text{ см}^2 = 0.363$ $Q \text{ кг.} = 0.098$ $D \text{ оп.мм} = 13.4$ $P \text{ н.мм} = 40.5$ Гр. сл. = III Точн. = П </p>

	<p>БПО-2621</p> <p> $F \text{ см}^2 = 2.680$ $Q \text{ кг.} = 0.726$ $D \text{ оп.мм} = 38.4$ $P \text{ н.мм} = 165.7$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2626</p> <p> $F \text{ см}^2 = 2.119$ $Q \text{ кг.} = 0.574$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 288.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2622</p> <p> $F \text{ см}^2 = 0.587$ $Q \text{ кг.} = 0.159$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 108.6$ Гр. сл. = V Точн. = П </p>		
	<p>БПО-2623</p> <p> $F \text{ см}^2 = 3.199$ $Q \text{ кг.} = 0.867$ $D \text{ оп.мм} = 53.2$ $P \text{ н.мм} = 189.7$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2628</p> <p> $F \text{ см}^2 = 1.213$ $Q \text{ кг.} = 0.329$ $D \text{ оп.мм} = 76.0$ $P \text{ н.мм} = 190.5$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2624</p> <p> $F \text{ см}^2 = 2.433$ $Q \text{ кг.} = 0.659$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 154.5$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2629</p> <p> $F \text{ см}^2 = 0.664$ $Q \text{ кг.} = 0.180$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 108.9$ Гр. сл. = VI Точн. = П </p>
			<p>БПО-2630</p> <p> $F \text{ см}^2 = 0.458$ $Q \text{ кг.} = 0.124$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 73.9$ Гр. сл. = VI Точн. = П </p>

	<p>БПО-2631</p> <p> $F \text{ см}^2 = 0.664$ $Q \text{ кг.} = 0.180$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 66.0$ Гр. сл. = II Точн. = П </p>		<p>БПО-2636</p> <p> $F \text{ см}^2 = 0.856$ $Q \text{ кг.} = 0.232$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 81.7$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2632</p> <p> $F \text{ см}^2 = 1.290$ $Q \text{ кг.} = 0.350$ $D \text{ оп.мм} = 31.2$ $P \text{ н.мм} = 97.4$ Гр. сл. = III Точн. = П </p>		
			<p>БПО-2638</p> <p> $F \text{ см}^2 = 2.370$ $Q \text{ кг.} = 0.642$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 176.0$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2634</p> <p> $F \text{ см}^2 = 0.740$ $Q \text{ кг.} = 0.201$ $D \text{ оп.мм} = 20.6$ $P \text{ н.мм} = 78.0$ Гр. сл. = III Точн. = П </p>		<p>БПО-2639</p> <p> $F \text{ см}^2 = 1.729$ $Q \text{ кг.} = 0.469$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 90.6$ Гр. сл. = III Точн. = П </p>
			<p>БПО-2640</p> <p> $F \text{ см}^2 = 0.637$ $Q \text{ кг.} = 0.173$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 65.5$ Гр. сл. = III Точн. = П </p>


			БПО-2646
			$F \text{ см}^2 = 1.127$ $Q \text{ кг.} = 0.305$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 113.8$ Гр. сл. = IV Точн. = П
			БПО-2647
			$F \text{ см}^2 = 0.762$ $Q \text{ кг.} = 0.207$ $D \text{ оп.мм} = 24.3$ $P \text{ н.мм} = 76.0$ Гр. сл. = II Точн. = П
			БПО-2648
			$F \text{ см}^2 = 0.850$ $Q \text{ кг.} = 0.230$ $D \text{ оп.мм} = 30.2$ $P \text{ н.мм} = 70.0$ Гр. сл. = III Точн. = П
	БПО-2644		БПО-2649
	$F \text{ см}^2 = 1.620$ $Q \text{ кг.} = 0.439$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 148.8$ Гр. сл. = IV Точн. = П		$F \text{ см}^2 = 0.801$ $Q \text{ кг.} = 0.217$ $D \text{ оп.мм} = 31.5$ $P \text{ н.мм} = 80.3$ Гр. сл. = III Точн. = П
	БПО-2645		БПО-2650
	$F \text{ см}^2 = 0.680$ $Q \text{ кг.} = 0.184$ $D \text{ оп.мм} = 18.8$ $P \text{ н.мм} = 67.8$ Гр. сл. = IV Точн. = П		$F \text{ см}^2 = 0.397$ $Q \text{ кг.} = 0.108$ $D \text{ оп.мм} = 14.0$ $P \text{ н.мм} = 33.9$ Гр. сл. = I Точн. = П

БПО-2652




$F \text{ см}^2 = 0.691$
 $Q \text{ кг.} = 0.187$
 $D \text{ оп.мм} = 26.0$
 $P \text{ н.мм} = 64.6$
 Гр. сл. = III
 Точн. = П

БПО-2657




$F \text{ см}^2 = 0.525$
 $Q \text{ кг.} = 0.142$
 $D \text{ оп.мм} = 22.0$
 $P \text{ н.мм} = 57.8$
 Гр. сл. = IV
 Точн. = П

БПО-2654





















$F \text{ см}^2 = 0.472$
 $Q \text{ кг.} = 0.128$
 $D \text{ оп.мм} = 28.0$
 $P \text{ н.мм} = 61.6$
 Гр. сл. = III
 Точн. = Н











БПО-2660
















$F \text{ см}^2 = 2.132$
 $Q \text{ кг.} = 0.578$
 $D \text{ оп.мм} = 59.0$
 $P \text{ н.мм} = 317.9$
 Гр. сл. = IV
 Точн. = П











	<p>БПО-2661</p> <p> $F \text{ см}^2 = 0.767$ $Q \text{ кг.} = 0.208$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 139.7$ Гр. сл. = III Точн. = 0соб. </p>		<p>БПО-2666</p> <p> $F \text{ см}^2 = 0.800$ $Q \text{ кг.} = 0.217$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 134.1$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2662</p> <p> $F \text{ см}^2 = 7.468$ $Q \text{ кг.} = 2.024$ $D \text{ оп.мм} = 156.0$ $P \text{ н.мм} = 631.0$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2667</p> <p> $F \text{ см}^2 = 1.507$ $Q \text{ кг.} = 0.408$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 126.1$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2663</p> <p> $F \text{ см}^2 = 0.617$ $Q \text{ кг.} = 0.167$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 54.2$ Гр. сл. = III Точн. = П </p>		<p>БПО-2668</p> <p> $F \text{ см}^2 = 0.321$ $Q \text{ кг.} = 0.087$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 72.7$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2664</p> <p> $F \text{ см}^2 = 0.675$ $Q \text{ кг.} = 0.183$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 110.9$ Гр. сл. = III Точн. = П </p>		<p>БПО-2669</p> <p> $F \text{ см}^2 = 2.295$ $Q \text{ кг.} = 0.622$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 117.2$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2665</p> <p> $F \text{ см}^2 = 1.400$ $Q \text{ кг.} = 0.379$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 243.7$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2670</p> <p> $F \text{ см}^2 = 2.935$ $Q \text{ кг.} = 0.795$ $D \text{ оп.мм} = 32.3$ $P \text{ н.мм} = 133.2$ Гр. сл. = IV Точн. = П </p>

			БПО-2676 $F \text{ см}^2 = 0.584$ $Q \text{ кг.} = 0.158$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 91.5$ Гр. сл. = III Точн. = П
	БПО-2672 $F \text{ см}^2 = 0.546$ $Q \text{ кг.} = 0.148$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 82.9$ Гр. сл. = III Точн. = П		БПО-2677 $F \text{ см}^2 = 21.940$ $Q \text{ кг.} = 5.946$ $D \text{ оп.мм} = 193.0$ $P \text{ н.мм} = 2459.0$ Гр. сл. = 0соб. Точн. = П
	БПО-2673 $F \text{ см}^2 = 2.720$ $Q \text{ кг.} = 0.737$ $D \text{ оп.мм} = 73.0$ $P \text{ н.мм} = 276.0$ Гр. сл. = V Точн. = П		
	БПО-2674 $F \text{ см}^2 = 1.380$ $Q \text{ кг.} = 0.374$ $D \text{ оп.мм} = 34.3$ $P \text{ н.мм} = 138.6$ Гр. сл. = IV Точн. = П		БПО-2679 $F \text{ см}^2 = 0.870$ $Q \text{ кг.} = 0.236$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 97.5$ Гр. сл. = IV Точн. = П
	БПО-2675 $F \text{ см}^2 = 0.868$ $Q \text{ кг.} = 0.235$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 85.3$ Гр. сл. = IV Точн. = Н		БПО-2680 $F \text{ см}^2 = 1.308$ $Q \text{ кг.} = 0.354$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 96.1$ Гр. сл. = VI Точн. = П


	<p>БПО-2681</p> <p> $F \text{ см}^2 = 2.391$ $Q \text{ кг.} = 0.648$ $D \text{ оп.мм} = 41$ $P \text{ н.мм} = 166.9$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2686</p> <p> $F \text{ см}^2 = 13.043$ $Q \text{ кг.} = 3.535$ $D \text{ оп.мм} = 147.0$ $P \text{ н.мм} = 474.6$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2682</p> <p> $F \text{ см}^2 = 13.095$ $Q \text{ кг.} = 3.549$ $D \text{ оп.мм} = 168.0$ $P \text{ н.мм} = 574.1$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2687</p> <p> $F \text{ см}^2 = 0.508$ $Q \text{ кг.} = 0.138$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 86.2$ Гр. сл. = IV Точн. = 0соб. </p>
	<p>БПО-2683</p> <p> $F \text{ см}^2 = 9.224$ $Q \text{ кг.} = 2.500$ $D \text{ оп.мм} = 140.0$ $P \text{ н.мм} = 377.3$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2688</p> <p> $F \text{ см}^2 = 4.192$ $Q \text{ кг.} = 1.136$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 76.2$ Гр. сл. = II Точн. = П </p>
	<p>БПО-2684</p> <p> $F \text{ см}^2 = 0.981$ $Q \text{ кг.} = 0.266$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 114.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-2689</p> <p> $F \text{ см}^2 = 5.927$ $Q \text{ кг.} = 1.61$ $D \text{ оп.мм} = 80$ $P \text{ н.мм} = 466.9$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2685</p> <p> $F \text{ см}^2 = 0.633$ $Q \text{ кг.} = 0.172$ $D \text{ оп.мм} = 25.2$ $P \text{ н.мм} = 73.3$ Гр. сл. = III Точн. = П </p>		<p>БПО-2690</p> <p> $F \text{ см}^2 = 1.332$ $Q \text{ кг.} = 0.361$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 132.4$ Гр. сл. = III Точн. = П </p>

	<p>БПО-2691</p> <p> $F \text{ см}^2 = 15.2$ $Q \text{ кг.} = 4.119$ $D \text{ оп.мм} = 190$ $P \text{ н.мм} = 860$ Гр. сл. = Особая Точн. = П </p>		
	<p>БПО-2692</p> <p> $F \text{ см}^2 = 2.276$ $Q \text{ кг.} = 0.617$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 302.9$ Гр. сл. = VI Точн. = П </p>		
	<p>БПО-2693</p> <p> $F \text{ см}^2 = 3.395$ $Q \text{ кг.} = 0.920$ $D \text{ оп.мм} = 110.0$ $P \text{ н.мм} = 284.4$ Гр. сл. = VI Точн. = П </p>		
	<p>БПО-2694</p> <p> $F \text{ см}^2 = 0.457$ $Q \text{ кг.} = 0.124$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 87.7$ Гр. сл. = III Точн. = П </p>		
	<p>БПО-2695</p> <p> $F \text{ см}^2 = 1.222$ $Q \text{ кг.} = 0.331$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 166.0$ Гр. сл. = IV Точн. = </p>		

	<p>БПО-2701</p> <p> $F \text{ см}^2 = 60.174$ $Q \text{ кг.} = 16.307$ $D \text{ оп.мм} = 185.4$ $P \text{ н.мм} = 2463$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2706</p> <p> $F \text{ см}^2 = 1.815$ $Q \text{ кг.} = 0.492$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 152.5$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2702</p> <p> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ Гр. сл. = Точн. = </p>		<p>БПО-2707</p> <p> $F \text{ см}^2 = 2.205$ $Q \text{ кг.} = 0.598$ $D \text{ оп.мм} = 48.2$ $P \text{ н.мм} = 179.2$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2703</p> <p> $F \text{ см}^2 = 0.982$ $Q \text{ кг.} = 0.266$ $D \text{ оп.мм} = 23.1$ $P \text{ н.мм} = 116.9$ Гр. сл. = V Точн. = П </p>		<p>БПО-2708</p> <p> $F \text{ см}^2 = 0.684$ $Q \text{ кг.} = 0.185$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 120.6$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2704</p> <p> $F \text{ см}^2 = 16.945$ $Q \text{ кг.} = 4.592$ $D \text{ оп.мм} = 267.0$ $P \text{ н.мм} = 1079.8$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2709</p> <p> $F \text{ см}^2 = 2.120$ $Q \text{ кг.} = 0.575$ $D \text{ оп.мм} = 30.1$ $P \text{ н.мм} = 85.4$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2705</p> <p> $F \text{ см}^2 = 19.923$ $Q \text{ кг.} = 5.399$ $D \text{ оп.мм} = 267.0$ $P \text{ н.мм} = 1293.0$ Гр. сл. = 0соб. Точн. = П </p>		


	<p>БПО-2711</p> <p> $F \text{ см}^2 = 6.017$ $Q \text{ кг.} = 1.631$ $D \text{ оп.мм} = 139.0$ $P \text{ н.мм} = 448.8$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2716</p> <p> $F \text{ см}^2 = 1.488$ $Q \text{ кг.} = 0.403$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 196.9$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2712</p> <p> $F \text{ см}^2 = 2.581$ $Q \text{ кг.} = 0.699$ $D \text{ оп.мм} = 46.8$ $P \text{ н.мм} = 180.9$ Гр. сл. = V Точн. = П </p>		<p>БПО-2717</p> <p> $F \text{ см}^2 = 6.493$ $Q \text{ кг.} = 1.760$ $D \text{ оп.мм} = 145.0$ $P \text{ н.мм} = 510.3$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2713</p> <p> $F \text{ см}^2 = 5.287$ $Q \text{ кг.} = 1.433$ $D \text{ оп.мм} = 121.0$ $P \text{ н.мм} = 414.0$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2718</p> <p> $F \text{ см}^2 = 1.925$ $Q \text{ кг.} = 0.522$ $D \text{ оп.мм} = 54.8$ $P \text{ н.мм} = 159.2$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2714</p> <p> $F \text{ см}^2 = 0.552$ $Q \text{ кг.} = 0.150$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 103.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2719</p> <p> $F \text{ см}^2 = 7.030$ $Q \text{ кг.} = 1.905$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 488.6$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2715</p> <p> $F \text{ см}^2 = 18.352$ $Q \text{ кг.} = 4.973$ $D \text{ оп.мм} = 180.1$ $P \text{ н.мм} = 503.6$ Гр. сл. = V Точн. = П </p>		<p>БПО-2720</p> <p> $F \text{ см}^2 = 6.130$ $Q \text{ кг.} = 1.661$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 404.6$ Гр. сл. = V Точн. = П </p>

БПО-2721



















$F \text{ см}^2 = 3.801$
 $Q \text{ кг.} = 1.030$
 $D \text{ оп.мм} = 104.0$
 $P \text{ н.мм} = 258.7$
Гр. сл. = IV
Точн. = П









БПО-2722
















$F \text{ см}^2 = 2.601$
 $Q \text{ кг.} = 0.705$
 $D \text{ оп.мм} = 64.1$
 $P \text{ н.мм} = 178.7$
Гр. сл. = IV
Точн. = П









	<p>БПО-2731</p> <p> $F \text{ см}^2 = 0.685$ $Q \text{ кг.} = 0186$ $D \text{ оп.мм} = 15.6$ $P \text{ н.мм} = 44$ Гр. сл. = II Точн. = П </p>		<p>БПО-2736</p> <p> $F \text{ см}^2 = 1.860$ $Q \text{ кг.} = 0.504$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 130.0$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2737</p> <p> $F \text{ см}^2 = 1.620$ $Q \text{ кг.} = 0.439$ $D \text{ оп.мм} = 43.0$ $P \text{ н.мм} = 166.0$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2738</p> <p> $F \text{ см}^2 = 1.860$ $Q \text{ кг.} = 0.504$ $D \text{ оп.мм} = 34.4$ $P \text{ н.мм} = 130.0$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2739</p> <p> $F \text{ см}^2 = 1.265$ $Q \text{ кг.} = 0.343$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 132.3$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2735</p> <p> $F \text{ см}^2 = 23.580$ $Q \text{ кг.} = 6.390$ $D \text{ оп.мм} = 198.0$ $P \text{ н.мм} = 1260.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2740</p> <p> $F \text{ см}^2 = 2.433$ $Q \text{ кг.} = 0.659$ $D \text{ оп.мм} = 35.5$ $P \text{ н.мм} = 155.5$ Гр. сл. = IV Точн. = П </p>










	<p>БПО-2741</p> <p> $F \text{ см}^2 = 23.700$ $Q \text{ кг.} = 6.423$ $D \text{ оп.мм} = 87.0$ $P \text{ н.мм} = 262.8$ Гр. сл. = III Точн. = Н </p>		<p>БПО-2746</p> <p> $F \text{ см}^2 = 1.024$ $Q \text{ кг.} = 0.278$ $D \text{ оп.мм} = 50.2$ $P \text{ н.мм} = 170.1$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2742</p> <p> $F \text{ см}^2 = 6.471$ $Q \text{ кг.} = 1.754$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 223.8$ Гр. сл. = III Точн. = П </p>		<p>БПО-2747</p> <p> $F \text{ см}^2 = 3.581$ $Q \text{ кг.} = 0.970$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 181.9$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2743</p> <p> $F \text{ см}^2 = 2.700$ $Q \text{ кг.} = 0.732$ $D \text{ оп.мм} = 60.3$ $P \text{ н.мм} = 129.1$ Гр. сл. = II Точн. = Н </p>		<p>БПО-2748</p> <p> $F \text{ см}^2 = 0.863$ $Q \text{ кг.} = 0.234$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 146.9$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2744</p> <p> $F \text{ см}^2 = 3.880$ $Q \text{ кг.} = 1.051$ $D \text{ оп.мм} = 47.8$ $P \text{ н.мм} = 201.5$ Гр. сл. = III Точн. = П </p>		<p>БПО-2749</p> <p> $F \text{ см}^2 = 0.625$ $Q \text{ кг.} = 0.169$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 107.0$ Гр. сл. = V Точн. = П </p>
			<p>БПО-2750</p> <p> $F \text{ см}^2 = 1.318$ $Q \text{ кг.} = 0.357$ $D \text{ оп.мм} = 65.1$ $P \text{ н.мм} = 220.7$ Гр. сл. = IV Точн. = П </p>





 <p>Diagram of a circular cross-section with diameter $\varnothing 70$.</p>	<p>БПО-2751</p> <p> $F \text{ см}^2 = 38.485$ $Q \text{ кг.} = 10.429$ $D \text{ оп.мм} = 70$ $P \text{ н.мм} = 219.9$ Гр. сл. = II Точн. = П </p>	 <p>Diagram of a U-shaped cross-section with height 15 and width 30.</p>	<p>БПО-2756</p> <p> $F \text{ см}^2 = 1.360$ $Q \text{ кг.} = 0.369$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 140.0$ Гр. сл. = IV Точн. = П </p>
 <p>Diagram of a channel cross-section with height 20 and width 21.7.</p>	<p>БПО-2752</p> <p> $F \text{ см}^2 = 0.816$ $Q \text{ кг.} = 0.221$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 111.5$ Гр. сл. = III Точн. = П </p>		
 <p>Diagram of a semi-circular arch cross-section with height 60 and width 135.</p>	<p>БПО-2753</p> <p> $F \text{ см}^2 = 3.639$ $Q \text{ кг.} = 0.986$ $D \text{ оп.мм} = 141.0$ $P \text{ н.мм} = 559.4$ Гр. сл. = V Точн. = П </p>		
 <p>Diagram of a channel cross-section with height 4.7 and width 33.5.</p>	<p>БПО-2754</p> <p> $F \text{ см}^2 = 0.826$ $Q \text{ кг.} = 0.224$ $D \text{ оп.мм} = 33.5$ $P \text{ н.мм} = 82.8$ Гр. сл. = IV Точн. = П </p>	 <p>Diagram of a channel cross-section with height 11.5 and width 120.</p>	<p>БПО-2759</p> <p> $F \text{ см}^2 = 5.134$ $Q \text{ кг.} = 1.391$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 395.1$ Гр. сл. = VI Точн. = П </p>
 <p>Diagram of a semi-circular arch cross-section with height 129 and width 170.</p>	<p>БПО-2755</p> <p> $F \text{ см}^2 = 14.641$ $Q \text{ кг.} = 3.968$ $D \text{ оп.мм} = 185.0$ $P \text{ н.мм} = 740.0$ Гр. сл. = 0соб. Точн. = П </p>	 <p>Diagram of a channel cross-section with height 34.5 and width 43.8.</p>	<p>БПО-2760</p> <p> $F \text{ см}^2 = 3.105$ $Q \text{ кг.} = 0.841$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 187.7$ Гр. сл. = V Точн. = П </p>







	<p>БПО-2761</p> <p> $F \text{ см}^2 = 8.971$ $Q \text{ кг.} = 2.431$ $D \text{ оп.мм} = 178.0$ $P \text{ н.мм} = 764.0$ Гр. сл. = 0соб. Точн. = П </p>		
	<p>БПО-2762</p> <p> $F \text{ см}^2 = 2.054$ $Q \text{ кг.} = 0.557$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 91.1$ Гр. сл. = III Точн. = П </p>		
	<p>БПО-2763</p> <p> $F \text{ см}^2 = 13.395$ $Q \text{ кг.} = 3.630$ $D \text{ оп.мм} = 122.7$ $P \text{ н.мм} = 487.6$ Гр. сл. = V Точн. = П </p>		
	<p>БПО-2764</p> <p> $F \text{ см}^2 = 0.348$ $Q \text{ кг.} = 0.094$ $D \text{ оп.мм} = 19.0$ $P \text{ н.мм} = 60.2$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2769</p> <p> $F \text{ см}^2 = 0.330$ $Q \text{ кг.} = 0.089$ $D \text{ оп.мм} = 13.4$ $P \text{ н.мм} = 46.6$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2765</p> <p> $F \text{ см}^2 = 3.010$ $Q \text{ кг.} = 0.816$ $D \text{ оп.мм} = 74.0$ $P \text{ н.мм} = 221.6$ Гр. сл. = V Точн. = П </p>		









	<p>БПО-2771</p> <p> $F \text{ см}^2 = 1.546$ $Q \text{ кг.} = 0.419$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 128.7$ Гр. сл. = III Точн. = П </p>		<p>БПО-2776</p> <p> $F \text{ см}^2 = 1.186$ $Q \text{ кг.} = 0.321$ $D \text{ оп.мм} = 18.2$ $P \text{ н.мм} = 51.5$ Гр. сл. = II Точн. = П </p>
	<p>БПО-2772</p> <p> $F \text{ см}^2 = 2.310$ $Q \text{ кг.} = 0.626$ $D \text{ оп.мм} = 25.2$ $P \text{ н.мм} = 71.7$ Гр. сл. = II Точн. = П </p>		
	<p>БПО-2773</p> <p> $F \text{ см}^2 = 2.452$ $Q \text{ кг.} = 0.664$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 68.0$ Гр. сл. = II Точн. = П </p>		
	<p>БПО-2774</p> <p> $F \text{ см}^2 = 2.250$ $Q \text{ кг.} = 0.610$ $D \text{ оп.мм} = 28.1$ $P \text{ н.мм} = 75.7$ Гр. сл. = II Точн. = П </p>		
	<p>БПО-2775</p> <p> $F \text{ см}^2 = 1.362$ $Q \text{ кг.} = 0.369$ $D \text{ оп.мм} = 16.0$ $P \text{ н.мм} = 43.7$ Гр. сл. = II Точн. = П </p>		<p>БПО-2780</p> <p> $F \text{ см}^2 = 1.702$ $Q \text{ кг.} = 0.461$ $D \text{ оп.мм} = 45.2$ $P \text{ н.мм} = 167.7$ Гр. сл. = III Точн. = П </p>











	<p>БПО-2781</p> <p> $F \text{ см}^2 = 2.872$ $Q \text{ кг.} = 0.778$ $D \text{ оп.мм} = 78.6$ $P \text{ н.мм} = 228.7$ Гр. сл. = III Точн. = П </p>		
	<p>БПО-2782</p> <p> $F \text{ см}^2 = 2.364$ $Q \text{ кг.} = 0.641$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 194.2$ Гр. сл. = III Точн. = П </p>		<p>БПО-2787</p> <p> $F \text{ см}^2 = 1.182$ $Q \text{ кг.} = 0.32$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 160.3$ Гр. сл. = VI Точн. = П </p>
			<p>БПО-2788</p> <p> $F \text{ см}^2 = 0.458$ $Q \text{ кг.} = 0.124$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 67.2$ Гр. сл. = II Точн. = Н </p>
	<p>БПО-2784</p> <p> $F \text{ см}^2 = 3.650$ $Q \text{ кг.} = 0.989$ $D \text{ оп.мм} = 71.0$ $P \text{ н.мм} = 261.7$ Гр. сл. = III Точн. = П </p>		<p>БПО-2789</p> <p> $F \text{ см}^2 = 0.804$ $Q \text{ кг.} = 0.218$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 86.3$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-2885</p> <p> $F \text{ см}^2 = 4.980$ $Q \text{ кг.} = 1.350$ $D \text{ оп.мм} = 52.2$ $P \text{ н.мм} = 151.4$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2790</p> <p> $F \text{ см}^2 = 2.362$ $Q \text{ кг.} = 0.64$ $D \text{ оп.мм} = 41$ $P \text{ н.мм} = 101.7$ Гр. сл. = VI Точн. = П </p>










	<p>БПО-2791</p> <p> $F \text{ см}^2 = 33.106$ $Q \text{ кг.} = 8.972$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 190.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2796</p> <p> $F \text{ см}^2 = 2.270$ $Q \text{ кг.} = 0.615$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 253.4$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2792</p> <p> $F \text{ см}^2 = 14.990$ $Q \text{ кг.} = 4.062$ $D \text{ оп.мм} = 181.0$ $P \text{ н.мм} = 425.0$ Гр. сл. = VI Точн. = Особ. </p>		<p>БПО-2797</p> <p> $F \text{ см}^2 = 0.328$ $Q \text{ кг.} = 0.089$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 54.5$ Гр. сл. = III Точн. = П </p>
	<p>БПО-2793</p> <p> $F \text{ см}^2 = 0.480$ $Q \text{ кг.} = 0.130$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 82.4$ Гр. сл. = III Точн. = П </p>		<p>БПО-2798</p> <p> $F \text{ см}^2 = 0.897$ $Q \text{ кг.} = 0.243$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 161.4$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2794</p> <p> $F \text{ см}^2 = 0.630$ $Q \text{ кг.} = 0.171$ $D \text{ оп.мм} = 36.7$ $P \text{ н.мм} = 109.1$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2799</p> <p> $F \text{ см}^2 = 0.897$ $Q \text{ кг.} = 0.243$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 161.4$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2800</p> <p> $F \text{ см}^2 = 1.585$ $Q \text{ кг.} = 0.430$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 141.6$ Гр. сл. = V Точн. = П </p>







	БПО-2801 $F \text{ см}^2 = 8.830$ $Q \text{ кг.} = 2.393$ $D \text{ оп.мм} = 168.0$ $P \text{ н.мм} = 700.8$ Гр. сл. = VI Точн. = П		БПО-2806 $F \text{ см}^2 = 4.221$ $Q \text{ кг.} = 1.144$ $D \text{ оп.мм} = 123.0$ $P \text{ н.мм} = 403.9$ Гр. сл. = V Точн. = П
			БПО-2808 $F \text{ см}^2 = 6.510$ $Q \text{ кг.} = 1.764$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 258.0$ Гр. сл. = V Точн. = Н
			БПО-2809 $F \text{ см}^2 = 9.621$ $Q \text{ кг.} = 2.607$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 110.0$ Гр. сл. = II Точн. = Н









	<p>БПО-2811</p> <p> $F \text{ см}^2 = 5.866$ $Q \text{ кг.} = 1.590$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 232.3$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2816</p> <p> $F \text{ см}^2 = 0.545$ $Q \text{ кг.} = 0.148$ $D \text{ оп.мм} = 27.4$ $P \text{ н.мм} = 80.3$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2812</p> <p> $F \text{ см}^2 = 4.916$ $Q \text{ кг.} = 1.332$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 194.3$ Гр. сл. = IV Точн. = П </p>		
	<p>БПО-2813</p> <p> $F \text{ см}^2 = 0.495$ $Q \text{ кг.} = 0.134$ $D \text{ оп.мм} = 92.2$ $P \text{ н.мм} = 92.2$ Гр. сл. = IV Точн. = П </p>		
	<p>БПО-2814</p> <p> $F \text{ см}^2 = 1.254$ $Q \text{ кг.} = 0.340$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 171.5$ Гр. сл. = IV Точн. = П </p>		
	<p>БПО-2815</p> <p> $F \text{ см}^2 = 1.220$ $Q \text{ кг.} = 0.331$ $D \text{ оп.мм} = 36.8$ $P \text{ н.мм} = 162.9$ Гр. сл. = IV Точн. = П </p>		









			БПО-2826 $F \text{ см}^2 = 0.903$ $Q \text{ кг.} = 0.245$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 118.8$ Гр. сл. = VI Точн. = П
	БПО-2822 $F \text{ см}^2 = 11.900$ $Q \text{ кг.} = 3.225$ $D \text{ оп.мм} = 140.0$ $P \text{ н.мм} = 746.0$ Гр. сл. = VI Точн. = П		БПО-2827 $F \text{ см}^2 = 0.997$ $Q \text{ кг.} = 0.270$ $D \text{ оп.мм} = 71.0$ $P \text{ н.мм} = 170.0$ Гр. сл. = IV Точн. = П
	БПО-2823 $F \text{ см}^2 = 11.640$ $Q \text{ кг.} = 3.154$ $D \text{ оп.мм} = 160.0$ $P \text{ н.мм} = 400.0$ Гр. сл. = III Точн. = П		БПО-2828 $F \text{ см}^2 = 0.941$ $Q \text{ кг.} = 0.255$ $D \text{ оп.мм} = 66.4$ $P \text{ н.мм} = 160.8$ Гр. сл. = IV Точн. = П
			БПО-2829 $F \text{ см}^2 = 1.438$ $Q \text{ кг.} = 0.390$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 217.8$ Гр. сл. = V Точн. = П
	БПО-2825 $F \text{ см}^2 = 0.640$ $Q \text{ кг.} = 0.173$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 94.5$ Гр. сл. = VI Точн. = П		БПО-2830 $F \text{ см}^2 = 1.633$ $Q \text{ кг.} = 0.443$ $D \text{ оп.мм} = 81.0$ $P \text{ н.мм} = 246.0$ Гр. сл. = V Точн. = П








	<p>БПО-2831</p> <p> $F \text{ см}^2 = 0.468$ $Q \text{ кг.} = 0.127$ $D \text{ оп.мм} = 17.0$ $P \text{ н.мм} = 72.7$ Гр. сл. = V Точн. = П </p>		<p>БПО-2836</p> <p> $F \text{ см}^2 = 1.099$ $Q \text{ кг.} = 0.298$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 173.2$ Гр. сл. = VI Точн. = 0соб. </p>
	<p>БПО-2832</p> <p> $F \text{ см}^2 = 0.780$ $Q \text{ кг.} = 0.211$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 64.9$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2837</p> <p> $F \text{ см}^2 = 21.050$ $Q \text{ кг.} = 5.705$ $D \text{ оп.мм} = 104.4$ $P \text{ н.мм} = 269.3$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2833</p> <p> $F \text{ см}^2 = 4.922$ $Q \text{ кг.} = 1.334$ $D \text{ оп.мм} = 82.6$ $P \text{ н.мм} = 419.0$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2838</p> <p> $F \text{ см}^2 = 34.710$ $Q \text{ кг.} = 9.406$ $D \text{ оп.мм} = 135.0$ $P \text{ н.мм} = 496.0$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2834</p> <p> $F \text{ см}^2 = 5.890$ $Q \text{ кг.} = 1.596$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 200.0$ Гр. сл. = V Точн. = П </p>		<p>БПО-2839</p> <p> $F \text{ см}^2 = 1.797$ $Q \text{ кг.} = 0.487$ $D \text{ оп.мм} = 91.8$ $P \text{ н.мм} = 239.0$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2835</p> <p> $F \text{ см}^2 = 1.094$ $Q \text{ кг.} = 0.296$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 86.7$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2840</p> <p> $F \text{ см}^2 = 2.104$ $Q \text{ кг.} = 0.570$ $D \text{ оп.мм} = 88.0$ $P \text{ н.мм} = 257.6$ Гр. сл. = VI Точн. = П </p>







	<p>БПО-2841</p> <p> $F \text{ см}^2 = 1.802$ $Q \text{ кг.} = 0.488$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 206.1$ Гр. сл. = 0соб. Точн. = П </p>		<p>БПО-2846</p> <p> $F \text{ см}^2 = 1.594$ $Q \text{ кг.} = 0.432$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 163.4$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2842</p> <p> $F \text{ см}^2 = 0.694$ $Q \text{ кг.} = 0.188$ $D \text{ оп.мм} = 27.5$ $P \text{ н.мм} = 93.6$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2847</p> <p> $F \text{ см}^2 = 1.209$ $Q \text{ кг.} = 0.328$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 124.9$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2843</p> <p> $F \text{ см}^2 = 5.381$ $Q \text{ кг.} = 1.458$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 349.7$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2848</p> <p> $F \text{ см}^2 = 2.780$ $Q \text{ кг.} = 0.753$ $D \text{ оп.мм} = 98.0$ $P \text{ н.мм} = 282.0$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2844</p> <p> $F \text{ см}^2 = 28.38$ $Q \text{ кг.} = 7.691$ $D \text{ оп.мм} = 131.0$ $P \text{ н.мм} = 302.0$ Гр. сл. = IV Точн. = П </p>		
			<p>БПО-2850</p> <p> $F \text{ см}^2 = 1.755$ $Q \text{ кг.} = 0.476$ $D \text{ оп.мм} = 41.4$ $P \text{ н.мм} = 117.5$ Гр. сл. = IV Точн. = П </p>








	<p>БПО-2851</p> <p> $F \text{ см}^2 = 1.810$ $Q \text{ кг.} = 0.491$ $D \text{ оп.мм} = 63.0$ $P \text{ н.мм} = 204.0$ Гр. сл. = IV Точн. = П </p>		
	<p>БПО-2852</p> <p> $F \text{ см}^2 = 1.202$ $Q \text{ кг.} = 0.326$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 121.7$ Гр. сл. = V Точн. = П </p>		<p>БПО-2857</p> <p> $F \text{ см}^2 = 2.357$ $Q \text{ кг.} = 0.639$ $D \text{ оп.мм} = 93.0$ $P \text{ н.мм} = 276.9$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2853</p> <p> $F \text{ см}^2 = 6.135$ $Q \text{ кг.} = 1.663$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 248.9$ Гр. сл. = Особ. Точн. = П </p>		<p>БПО-2858</p> <p> $F \text{ см}^2 = 1.926$ $Q \text{ кг.} = 0.522$ $D \text{ оп.мм} = 72.0$ $P \text{ н.мм} = 227.6$ Гр. сл. = VI Точн. = П </p>
			<p>БПО-2860</p> <p> $F \text{ см}^2 = 1.820$ $Q \text{ кг.} = 0.493$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 210.7$ Гр. сл. = VI Точн. = П </p>








			БПО-2866 $F \text{ см}^2 = 0.263$ $Q \text{ кг.} = 0.071$ $D \text{ оп.мм} = 11.0$ $P \text{ н.мм} = 28.6$ Гр. сл. = III Точн. = П
	БПО-2862 $F \text{ см}^2 = 5.060$ $Q \text{ кг.} = 1.371$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 133.2$ Гр. сл. = III Точн. = П		БПО-2867 $F \text{ см}^2 = 0.909$ $Q \text{ кг.} = 0.246$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 95.3$ Гр. сл. = V Точн. = П
			БПО-2868 $F \text{ см}^2 = 4.520$ $Q \text{ кг.} = 1.225$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 256.4$ Гр. сл. = VI Точн. = П
	БПО-2864 $F \text{ см}^2 = 1.250$ $Q \text{ кг.} = 0.339$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 172.1$ Гр. сл. = VI Точн. = П		БПО-2869 $F \text{ см}^2 = 4.098$ $Q \text{ кг.} = 1.111$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 232.4$ Гр. сл. = VI Точн. = П
	БПО-2865 $F \text{ см}^2 = 2.570$ $Q \text{ кг.} = 0.696$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 298.9$ Гр. сл. = VI Точн. = П		БПО-2870 $F \text{ см}^2 = 4.603$ $Q \text{ кг.} = 1.247$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 227.6$ Гр. сл. = VI Точн. = П









			БПО-2876 $F \text{ см}^2 = 2.472$ $Q \text{ кг.} = 0.670$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 129.9$ Гр. сл. = III Точн. = П
			БПО-2877 $F \text{ см}^2 = 1.243$ $Q \text{ кг.} = 0.337$ $D \text{ оп.мм} = 33.1$ $P \text{ н.мм} = 525.0$ Гр. сл. = V Точн. = 0соб.
	БПО-2873 $F \text{ см}^2 = 4.160$ $Q \text{ кг.} = 1.127$ $D \text{ оп.мм} = 164.0$ $P \text{ н.мм} = 392.1$ Гр. сл. = VI Точн. = П		БПО-2878 $F \text{ см}^2 = 1.310$ $Q \text{ кг.} = 0.355$ $D \text{ оп.мм} = 37.5$ $P \text{ н.мм} = 555.0$ Гр. сл. = V Точн. = 0соб.
	БПО-2874 $F \text{ см}^2 = 1.311$ $Q \text{ кг.} = 0.355$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 128.0$ Гр. сл. = IV Точн. = П		БПО-2879 $F \text{ см}^2 = 1.341$ $Q \text{ кг.} = 0.363$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 571.0$ Гр. сл. = V Точн. = 0соб.
	БПО-2875 $F \text{ см}^2 = 0.895$ $Q \text{ кг.} = 0.243$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 99.4$ Гр. сл. = VI Точн. = П		БПО-2880 $F \text{ см}^2 = 1.438$ $Q \text{ кг.} = 0.390$ $D \text{ оп.мм} = 37.7$ $P \text{ н.мм} = 612.0$ Гр. сл. = V Точн. = 0соб.









	<p>БПО-2881</p> <p> $F \text{ см}^2 = 9.060$ $Q \text{ кг.} = 2.455$ $D \text{ оп.мм} = 158.0$ $P \text{ н.мм} = 751.8$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2886</p> <p> $F \text{ см}^2 = 3.290$ $Q \text{ кг.} = 0.892$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 859.5$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2882</p> <p> $F \text{ см}^2 = 3.329$ $Q \text{ кг.} = 0.902$ $D \text{ оп.мм} = 114.0$ $P \text{ н.мм} = 343.6$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2887</p> <p> $F \text{ см}^2 = 0.612$ $Q \text{ кг.} = 0.166$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 94.6$ Гр. сл. = III Точн. = H </p>
	<p>БПО-2884</p> <p> $F \text{ см}^2 = 0.585$ $Q \text{ кг.} = 0.159$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 97.5$ Гр. сл. = V Точн. = П </p>		<p>БПО-2889</p> <p> $F \text{ см}^2 = 0.813$ $Q \text{ кг.} = 0.220$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 111.4$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2890</p> <p> $F \text{ см}^2 = 2.684$ $Q \text{ кг.} = 0.727$ $D \text{ оп.мм} = 125.0$ $P \text{ н.мм} = 379.8$ Гр. сл. = VI Точн. = П </p>








	<p>БПО-2891</p> <p> $F \text{ см}^2 = 1.826$ $Q \text{ кг.} = 0.495$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 260.7$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2896</p> <p> $F \text{ см}^2 = 15.633$ $Q \text{ кг.} = 4.237$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 207.8$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2897</p> <p> $F \text{ см}^2 = 2.307$ $Q \text{ кг.} = 0.625$ $D \text{ оп.мм} = 77.0$ $P \text{ н.мм} = 203.0$ Гр. сл. = VI Точн. = П </p>
			<p>БПО-2898</p> <p> $F \text{ см}^2 = 25.930$ $Q \text{ кг.} = 7.027$ $D \text{ оп.мм} = 150.0$ $P \text{ н.мм} = 687.5$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2894</p> <p> $F \text{ см}^2 = 9.132$ $Q \text{ кг.} = 2.475$ $D \text{ оп.мм} = 161.0$ $P \text{ н.мм} = 531.9$ Гр. сл. = VI Точн. = П </p>		
	<p>БПО-2895</p> <p> $F \text{ см}^2 = 1.386$ $Q \text{ кг.} = 0.376$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 175.8$ Гр. сл. = V Точн. = П </p>		









			БПО-2906
			$F \text{ см}^2 = 2.940$ $Q \text{ кг.} = 0.797$ $D \text{ оп.мм} = 72.8$ $P \text{ н.мм} = 366.0$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-2902		БПО-2907
	$F \text{ см}^2 = 2.822$ $Q \text{ кг.} = 0.765$ $D \text{ оп.мм} = 121.0$ $P \text{ н.мм} = 306.6$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 3.350$ $Q \text{ кг.} = 0.908$ $D \text{ оп.мм} = 72.8$ $P \text{ н.мм} = 347.0$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
			БПО-2908
			$F \text{ см}^2 = 0.990$ $Q \text{ кг.} = 0.268$ $D \text{ оп.мм} = 45.2$ $P \text{ н.мм} = 127.5$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-2904		БПО-2909
	$F \text{ см}^2 = 4.942$ $Q \text{ кг.} = 1.339$ $D \text{ оп.мм} = 166.0$ $P \text{ н.мм} = 498.2$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 1.890$ $Q \text{ кг.} = 0.512$ $D \text{ оп.мм} = 48.4$ $P \text{ н.мм} = 217.0$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-2905		
	$F \text{ см}^2 = 3.530$ $Q \text{ кг.} = 0.957$ $D \text{ оп.мм} = 124.0$ $P \text{ н.мм} = 323.0$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		








	<p>БПО-2941</p> <p> $F \text{ см}^2 = 1.111$ $Q \text{ кг.} = 0.301$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 177.9$ Гр. сл. = 0соб. Точн. = П </p>		
	<p>БПО-2942</p> <p> $F \text{ см}^2 = 1.780$ $Q \text{ кг.} = 0.482$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 124.7$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2947</p> <p> $F \text{ см}^2 = 0.506$ $Q \text{ кг.} = 0.137$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 54.6$ Гр. сл. = III Точн. = Н </p>
	<p>БПО-2943</p> <p> $F \text{ см}^2 = 1.836$ $Q \text{ кг.} = 0.498$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 130.7$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2948</p> <p> $F \text{ см}^2 = 2.942$ $Q \text{ кг.} = 0.797$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 392.0$ Гр. сл. = 0соб. Точн. = П </p>
			<p>БПО-2949</p> <p> $F \text{ см}^2 = 2.864$ $Q \text{ кг.} = 0.776$ $D \text{ оп.мм} = 86.0$ $P \text{ н.мм} = 374.7$ Гр. сл. = 0соб. Точн. = 0соб. </p>
	<p>БПО-2945</p> <p> $F \text{ см}^2 = 2.088$ $Q \text{ кг.} = 0.566$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 104.1$ Гр. сл. = IV Точн. = П </p>		










	<p>БПО-2951</p> <p> $F \text{ см}^2 = 2.230$ $Q \text{ кг.} = 0.604$ $D \text{ оп.мм} = 53.0$ $P \text{ н.мм} = 181.9$ Гр. сл. = IV Точн. = П </p>		
	<p>БПО-2952</p> <p> $F \text{ см}^2 = 8.562$ $Q \text{ кг.} = 2.320$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 156.0$ Гр. сл. = IV Точн. = П </p>		
	<p>БПО-2953</p> <p> $F \text{ см}^2 = 0.766$ $Q \text{ кг.} = 0.208$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 150.9$ Гр. сл. = IV Точн. = П </p>		<p>БПО-2958</p> <p> $F \text{ см}^2 = 12.600$ $Q \text{ кг.} = 3.415$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 292.8$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2954</p> <p> $F \text{ см}^2 = 4.866$ $Q \text{ кг.} = 1.319$ $D \text{ оп.мм} = 129.0$ $P \text{ н.мм} = 405.2$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2959</p> <p> $F \text{ см}^2 = 5.982$ $Q \text{ кг.} = 1.621$ $D \text{ оп.мм} = 148.0$ $P \text{ н.мм} = 494.6$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-2955</p> <p> $F \text{ см}^2 = 0.931$ $Q \text{ кг.} = 0.252$ $D \text{ оп.мм} = 43.5$ $P \text{ н.мм} = 124.6$ Гр. сл. = V Точн. = П </p>		<p>БПО-2960</p> <p> $F \text{ см}^2 = 9.839$ $Q \text{ кг.} = 2.666$ $D \text{ оп.мм} = 119.0$ $P \text{ н.мм} = 585.8$ Гр. сл. = VI Точн. = Особ. </p>






	<p>БПО-2961</p> <p> $F \text{ см}^2 = 4.985$ $Q \text{ кг.} = 1.351$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 313.6$ Гр. сл. = V Точн. = П </p>		<p>БПО-2966</p> <p> $F \text{ см}^2 = 4.761$ $Q \text{ кг.} = 1.290$ $D \text{ оп.мм} = 181.0$ $P \text{ н.мм} = 504.1$ Гр. сл. = 0соб. Точн. = П </p>
	<p>БПО-2962</p> <p> $F \text{ см}^2 = 1.080$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 217.8$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2967</p> <p> $F \text{ см}^2 = 2.317$ $Q \text{ кг.} = 0.628$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 204.0$ Гр. сл. = IV Точн. = Н </p>
	<p>БПО-2963</p> <p> $F \text{ см}^2 = 1.100$ $Q \text{ кг.} = 0.298$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 221.1$ Гр. сл. = VI Точн. = П </p>		
	<p>БПО-2964</p> <p> $F \text{ см}^2 = 1.216$ $Q \text{ кг.} = 0.330$ $D \text{ оп.мм} = 57.6$ $P \text{ н.мм} = 242.1$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2969</p> <p> $F \text{ см}^2 = 0.305$ $Q \text{ кг.} = 0.083$ $D \text{ оп.мм} = 10.0$ $P \text{ н.мм} = 36.3$ Гр. сл. = IV Точн. = П </p>
			<p>БПО-2970</p> <p> $F \text{ см}^2 = 6.830$ $Q \text{ кг.} = 1.851$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 262.8$ Гр. сл. = III Точн. = П </p>











	<p>БПО-2971</p> <p> $F \text{ см}^2 = 0.663$ $Q \text{ кг.} = 0.180$ $D \text{ оп.мм} = 30.1$ $P \text{ н.мм} = 67.7$ Гр. сл. = III Точн. = П </p>		
	<p>БПО-2972</p> <p> $F \text{ см}^2 = 0.675$ $Q \text{ кг.} = 0.183$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 74.0$ Гр. сл. = IV Точн. = Н </p>		
	<p>БПО-2973</p> <p> $F \text{ см}^2 = 0.347$ $Q \text{ кг.} = 0.094$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 54.0$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-2978</p> <p> $F \text{ см}^2 = 1.960$ $Q \text{ кг.} = 0.531$ $D \text{ оп.мм} = 81.0$ $P \text{ н.мм} = 352.6$ Гр. сл. = V Точн. = П </p>
			<p>БПО-2979</p> <p> $F \text{ см}^2 = 0.778$ $Q \text{ кг.} = 0.211$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 132.4$ Гр. сл. = V Точн. = П </p>
	<p>БПО-2975</p> <p> $F \text{ см}^2 = 1.057$ $Q \text{ кг.} = 0.286$ $D \text{ оп.мм} = 28.7$ $P \text{ н.мм} = 170.3$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2980</p> <p> $F \text{ см}^2 = 0.653$ $Q \text{ кг.} = 0.177$ $D \text{ оп.мм} = 37.3$ $P \text{ н.мм} = 111.6$ Гр. сл. = V Точн. = П </p>




	<p>БПО-2981</p> <p> $F \text{ см}^2 = 0.824$ $Q \text{ кг.} = 0.223$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 139.3$ Гр. сл. = V Точн. = П </p>		
	<p>БПО-2982</p> <p> $F \text{ см}^2 = 1.049$ $Q \text{ кг.} = 0.284$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 176.1$ Гр. сл. = V Точн. = П </p>		<p>БПО-2987</p> <p> $F \text{ см}^2 = 1.908$ $Q \text{ кг.} = 0.517$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 252.4$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2983</p> <p> $F \text{ см}^2 = 5.861$ $Q \text{ кг.} = 1.588$ $D \text{ оп.мм} = 160.0$ $P \text{ н.мм} = 456.0$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2988</p> <p> $F \text{ см}^2 = 2.849$ $Q \text{ кг.} = 0.772$ $D \text{ оп.мм} = 86.0$ $P \text{ н.мм} = 240.2$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-2984</p> <p> $F \text{ см}^2 = 1.082$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм} = 42.3$ $P \text{ н.мм} = 142.7$ Гр. сл. = VI Точн. = П </p>		<p>БПО-2989</p> <p> $F \text{ см}^2 = 5.02$ $Q \text{ кг.} = 1.36$ $D \text{ оп.мм} = 51$ $P \text{ н.мм} = 219.0$ Гр. сл. = III Точн. = Н </p>
			<p>БПО-2990</p> <p> $F \text{ см}^2 = 0.723$ $Q \text{ кг.} = 0.196$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 123.3$ Гр. сл. = V Точн. = П </p>








			БПО-2996 $F \text{ см}^2 = 0.900$ $Q \text{ кг.} = 0.244$ $D \text{ оп.мм} = 39.2$ $P \text{ н.мм} = 123.0$ Гр. сл. = IV Точн. = П
	БПО-2992 $F \text{ см}^2 = 3.250$ $Q \text{ кг.} = 0.881$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 168.6$ Гр. сл. = III Точн. = Н		
	БПО-2993 $F \text{ см}^2 = 0.927$ $Q \text{ кг.} = 0.251$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 173.9$ Гр. сл. = IV Точн. = П		БПО-2998 $F \text{ см}^2 = 30.846$ $Q \text{ кг.} = 8.359$ $D \text{ оп.мм} = 146.0$ $P \text{ н.мм} = 340.8$ Гр. сл. = IV Точн. = П
			БПО-2999 $F \text{ см}^2 = 5.470$ $Q \text{ кг.} = 1.482$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 203.3$ Гр. сл. = IV Точн. = П
	БПО-2995 $F \text{ см}^2 = 8.381$ $Q \text{ кг.} = 2.271$ $D \text{ оп.мм} = 119.0$ $P \text{ н.мм} = 768.8$ Гр. сл. = 0соб. Точн. = П		БПО-3000 $F \text{ см}^2 = 0.919$ $Q \text{ кг.} = 0.249$ $D \text{ оп.мм} = 53.0$ $P \text{ н.мм} = 154.2$ Гр. сл. = IV Точн. = П




	<p>БПО-3001</p> <p> $F \text{ см}^2 = 0.841$ $Q \text{ кг.} = 0.228$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 149.4$ Гр. сл. = IV Точн. = П </p>		<p>БПО-3006</p> <p> $F \text{ см}^2 = 6.2$ $Q \text{ кг.} = 1.68$ $D \text{ оп.мм} = 132$ $P \text{ н.мм} = 589.6$ Гр. сл. = особая Точн. = П </p>
	<p>БПО-3002</p> <p> $F \text{ см}^2 = 17.52$ $Q \text{ кг.} = 4.748$ $D \text{ оп.мм} = 137$ $P \text{ н.мм} = 454$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-3007</p> <p> $F \text{ см}^2 = 0.991$ $Q \text{ кг.} = 0.269$ $D \text{ оп.мм} = 34$ $P \text{ н.мм} = 125.8$ Гр. сл. = особая Точн. = П </p>
	<p>БПО-3003</p> <p> $F \text{ см}^2 = 0.917$ $Q \text{ кг.} = 0.249$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 155.2$ Гр. сл. = VI Точн. = Н </p>		<p>БПО-3008</p> <p> $F \text{ см}^2 = 3.4$ $Q \text{ кг.} = 0.921$ $D \text{ оп.мм} = 65$ $P \text{ н.мм} = 260$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-3004</p> <p> $F \text{ см}^2 = 50.375$ $Q \text{ кг.} = 13.652$ $D \text{ оп.мм} = 191$ $P \text{ н.мм} = 475.9$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3009</p> <p> $F \text{ см}^2 = 4.8$ $Q \text{ кг.} = 1.301$ $D \text{ оп.мм} = 120$ $P \text{ н.мм} = 388$ Гр. сл. = V Точн. = П </p>
			<p>БПО-3010</p> <p> $F \text{ см}^2 = 3.21$ $Q \text{ кг.} = 0.87$ $D \text{ оп.мм} = 108$ $P \text{ н.мм} = 260.7$ Гр. сл. = VI Точн. = П </p>



	БПО-3011 $F \text{ см}^2 = 5.620$ $Q \text{ кг.} = 1.523$ $D \text{ оп.мм} = 165.0$ $P \text{ н.мм} = 452.0$ Гр. сл. = 0соб. Точн. = П		БПО-3016 $F \text{ см}^2 = 1.660$ $Q \text{ кг.} = 0.450$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 206.0$ Гр. сл. = III Точн. = П
			БПО-3019 $F \text{ см}^2 = 3.113$ $Q \text{ кг.} = 0.844$ $D \text{ оп.мм} = 166.0$ $P \text{ н.мм} = 421.4$ Гр. сл. = VI Точн. = П
	БПО-3015 $F \text{ см}^2 = 1.908$ $Q \text{ кг.} = 0.517$ $D \text{ оп.мм} = 101.0$ $P \text{ н.мм} = 227.0$ Гр. сл. = III Точн. = П		БПО-3020 $F \text{ см}^2 = 22.956$ $Q \text{ кг.} = 6.221$ $D \text{ оп.мм} = 170.0$ $P \text{ н.мм} = 1028.0$ Гр. сл. = 0соб. Точн. = П









	<p>БПО-3021</p> <p> $F \text{ см}^2 = 1.815$ $Q \text{ кг.} = 0.492$ $D \text{ оп.мм} = 41$ $P \text{ н.мм} = 218.6$ Гр. сл. = V Точн. = П </p>		<p>БПО-3026</p> <p> $F \text{ см}^2 = 0.62$ $Q \text{ кг.} = 0.168$ $D \text{ оп.мм} = 42$ $P \text{ н.мм} = 124$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-3022</p> <p> $F \text{ см}^2 = 0.694$ $Q \text{ кг.} = 0.188$ $D \text{ оп.мм} = 22$ $P \text{ н.мм} = 95.8$ Гр. сл. = V Точн. = П </p>		<p>БПО-3027</p> <p> $F \text{ см}^2 = 0.736$ $Q \text{ кг.} = 0.199$ $D \text{ оп.мм} = 27$ $P \text{ н.мм} = 87.2$ Гр. сл. = III Точн. = П </p>
	<p>БПО-3023</p> <p> $F \text{ см}^2 = 11.109$ $Q \text{ кг.} = 3.011$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 177.1$ Гр. сл. = IV Точн. = П </p>		<p>БПО-3028</p> <p> $F \text{ см}^2 = 1.45$ $Q \text{ кг.} = 0.393$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 208.3$ Гр. сл. = V Точн. = П </p>
	<p>БПО-3024</p> <p> $F \text{ см}^2 = 0.584$ $Q \text{ кг.} = 0.158$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 81.7$ Гр. сл. = V Точн. = П </p>		<p>БПО-3029</p> <p> $F \text{ см}^2 = 7.173$ $Q \text{ кг.} = 1.944$ $D \text{ оп.мм} = 65$ $P \text{ н.мм} = 432.5$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-3025</p> <p> $F \text{ см}^2 = 0.848$ $Q \text{ кг.} = 0.23$ $D \text{ оп.мм} = 43$ $P \text{ н.мм} = 172.3$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3030</p> <p> $F \text{ см}^2 = 5.791$ $Q \text{ кг.} = 1.569$ $D \text{ оп.мм} = 142$ $P \text{ н.мм} = 452.9$ Гр. сл. = VI Точн. = П </p>









	БПО-3031		БПО-3036
	$F \text{ см}^2 = 2.648$ $Q \text{ кг.} = 0.717$ $D \text{ оп.мм.} = 74$ $P \text{ н.} = 424.1$ Гр. сл. = VI Точн. = П		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3032		БПО-3037
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3033		БПО-3038
	$F \text{ см} = 1.13$ $Q \text{ кг.} = 0.306$ $D \text{ оп.мм.} = 48$ $P \text{ н.} = 137.2$ Гр. сл. = IV Точн. = П		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3034		БПО-3039
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3035		БПО-3040
	$F \text{ см}^2 = 1.596$ $Q \text{ кг.} = 0.433$ $D \text{ оп.мм.} = 34.1$ $P \text{ н.} = 152.5$ Гр. сл. = IV Точн. = П		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0







	БПО-3041 $F \text{ см}^2 = 1.024$ $Q \text{ кг.} = 0.278$ $D \text{ оп.мм.} = 37$ $P \text{ н.} = 149.5$ Гр. сл. = V Точн. = П		БПО-3046 $F \text{ см} = 7.813$ $Q \text{ кг.} = 2.117$ $D \text{ оп.мм.} = 163$ $P \text{ н.} = 628.5$ Гр. сл. = особая Точн. = П
	БПО-3042 $F \text{ см} = 0.679$ $Q \text{ кг.} = 0.18$ $D \text{ оп.мм.} = 24$ $P \text{ н.} = 118$ Гр. сл. = особая Точн. = П		БПО-3047 $F \text{ см} = 7.539$ $Q \text{ кг.} = 2.043$ $D \text{ оп.мм.} = 108$ $P \text{ н.} = 581.3$ Гр. сл. = VI Точн. = П
	БПО-3043 $F \text{ см} = 1.754$ $Q \text{ кг.} = 0.475$ $D \text{ оп.мм.} = 39$ $P \text{ н.} = 139.3$ Гр. сл. = IV Точн. = П		БПО-3048 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3044 $F \text{ см} = 4.601$ $Q \text{ кг.} = 1.127$ $D \text{ оп.мм.} = 125$ $P \text{ н.} = 374.5$ Гр. сл. = IV Точн. = П		БПО-3049 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3045 $F \text{ см}^2 = 2.883$ $Q \text{ кг.} = 0.781$ $D \text{ оп.мм.} = 52$ $P \text{ н.} = 248$ Гр. сл. = V Точн. = П		БПО-3050 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0








	БПО-3051		БПО-3056
	$F \text{ см}^2 = 5.087$ $Q \text{ кг.} = 1.379$ $D \text{ оп.мм.} = 75$ $P \text{ н.} = 300.8$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3052		БПО-3057
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3053		БПО-3058
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3054		БПО-3059
	$F \text{ см} = 4.18$ $Q \text{ кг.} = 1.133$ $D \text{ оп.мм.} = 69$ $P \text{ н.} = 251.6$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3055		БПО-3060
	$F \text{ см}^2 = 4.265$ $Q \text{ кг.} = 1.156$ $D \text{ оп.мм.} = 80$ $P \text{ н.} = 243.3$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$











	БПО-3061		БПО-3066
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3062		БПО-3067
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3063		БПО-3068
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3064		БПО-3069
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 3.34$ $Q \text{ кг.} = 0.91$ $D \text{ оп.мм.} = 75$ $P \text{ н.} = 355.1$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3065		БПО-3070
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 4.516$ $Q \text{ кг.} = 1.22$ $D \text{ оп.мм.} = 82.5$ $P \text{ н.} = 447.7$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$





	БПО-3071		БПО-3076
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.467$ $Q \text{ кг.} = 0.127$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 64.6$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$
	БПО-3072		БПО-3077
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.699$ $Q \text{ кг.} = 0.189$ $D \text{ оп.мм.} = 40$ $P \text{ н.} = 83.9$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$
	БПО-3073		БПО-3078
	$F \text{ см} = 3.373$ $Q \text{ кг.} = 0.914$ $D \text{ оп.мм.} = 82$ $P \text{ н.} = 350.5$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0.996$ $Q \text{ кг.} = 0.27$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 121$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$
	БПО-3074		БПО-3079
	$F \text{ см} = 1.545$ $Q \text{ кг.} = 0.419$ $D \text{ оп.мм.} = 80$ $P \text{ н.} = 185.6$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0.76$ $Q \text{ кг.} = 0.206$ $D \text{ оп.мм.} = 35$ $P \text{ н.} = 105.3$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$
	БПО-3075		БПО-3080
	$F \text{ см}^2 = 1.096$ $Q \text{ кг.} = 0.297$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 137.1$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 1.078$ $Q \text{ кг.} = 0.292$ $D \text{ оп.мм.} = 46$ $P \text{ н.} = 127.6$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$


	БПО-3081		БПО-3086
	$F \text{ см}^2 = 0.999$ $Q \text{ кг.} = 0.271$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 165.8$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3082		БПО-3087
	$F \text{ см} = 0.582$ $Q \text{ кг.} = 0.158$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 96.8$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = П$		$F \text{ см} = 0.43$ $Q \text{ кг.} = 0.117$ $D \text{ оп.мм.} = 23$ $P \text{ н.} = 83.4$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$
	БПО-3083		БПО-3088
	$F \text{ см} = 0.61$ $Q \text{ кг.} = 0.165$ $D \text{ оп.мм.} = 29.9$ $P \text{ н.} = 72.6$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = П$		$F \text{ см} = 6.33$ $Q \text{ кг.} = 1.716$ $D \text{ оп.мм.} = 137$ $P \text{ н.} = 426.6$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$
	БПО-3084		БПО-3089
	$F \text{ см} = 0.8$ $Q \text{ кг.} = 0.217$ $D \text{ оп.мм.} = 40.8$ $P \text{ н.} = 99.5$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = П$		$F \text{ см} = 23.25$ $Q \text{ кг.} = 6.3$ $D \text{ оп.мм.} = 182$ $P \text{ н.} = 409$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
	БПО-3085		БПО-3090
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 3.133$ $Q \text{ кг.} = 0.849$ $D \text{ оп.мм.} = 64$ $P \text{ н.} = 152.7$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = П$









	БПО-3091		БПО-3096
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3092		БПО-3097
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 2.17$ $Q \text{ кг.} = 0.588$ $D \text{ оп.мм.} = 57$ $P \text{ н.} = 149$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$
	БПО-3093		БПО-3098
	$F \text{ см} = 1.503$ $Q \text{ кг.} = 0.407$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 145.9$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 3.61$ $Q \text{ кг.} = 0.979$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 249$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-3094		БПО-3099
	$F \text{ см} = 2.47$ $Q \text{ кг.} = 0.67$ $D \text{ оп.мм.} = 69$ $P \text{ н.} = 349.3$ $\Gamma \text{р. сл.} = \text{Особ.}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 1.086$ $Q \text{ кг.} = 0.294$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 113.1$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3095		БПО-3100
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.375$ $Q \text{ кг.} = 0.102$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 79.3$ $\Gamma \text{р. сл.} = \text{II}$ $\text{Точн.} = \text{H}$









	БПО-3101 $F \text{ см}^2 = 1.383$ $Q \text{ кг.} = 0.375$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 137.4$ Гр. сл. = IV Точн. = □		БПО-3106 $F \text{ см} = 4.68$ $Q \text{ кг.} = 1.268$ $D \text{ оп.мм.} = 89.3$ $P \text{ н.} = 356.1$ Гр. сл. = Особ. Точн. = □
	БПО-3102 $F \text{ см} = 8.99$ $Q \text{ кг.} = 2.436$ $D \text{ оп.мм.} = 161$ $P \text{ н.} = 863.9$ Гр. сл. = Особ. Точн. = □		БПО-3107 $F \text{ см} = 0.363$ $Q \text{ кг.} = 0.098$ $D \text{ оп.мм.} = 18.5$ $P \text{ н.} = 48.8$ Гр. сл. = III Точн. = □
	БПО-3103 $F \text{ см} = 5.646$ $Q \text{ кг.} = 1.53$ $D \text{ оп.мм.} = 148$ $P \text{ н.} = 517.7$ Гр. сл. = Особ. Точн. = □		БПО-3108 $F \text{ см} = 7.882$ $Q \text{ кг.} = 2.136$ $D \text{ оп.мм.} = 190$ $P \text{ н.} = 543.3$ Гр. сл. = Особ. Точн. = □
	БПО-3104 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		БПО-3109 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3105 $F \text{ см}^2 = 0.721$ $Q \text{ кг.} = 0.195$ $D \text{ оп.мм.} = 33$ $P \text{ н.} = 122.5$ Гр. сл. = V Точн. = □		БПО-3110 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0









	<p>БПО-3111</p> <p> $F \text{ см}^2 = 16$ $Q \text{ кг.} = 4.34$ $D \text{ оп.мм.} = 163$ $P \text{ н.} = 650$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3116</p> <p> $F \text{ см} = 0.979$ $Q \text{ кг.} = 0.265$ $D \text{ оп.мм.} = 40$ $P \text{ н.} = 138.3$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3112</p> <p> $F \text{ см} = 2.595$ $Q \text{ кг.} = 0.703$ $D \text{ оп.мм.} = 63$ $P \text{ н.} = 139.3$ $\text{Гр. сл.} = \text{II}$ $\text{Точн.} = \square$ </p>		<p>БПО-3117</p> <p> $F \text{ см} = 1.067$ $Q \text{ кг.} = 0.29$ $D \text{ оп.мм.} = 46$ $P \text{ н.} = 164.5$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3113</p> <p> $F \text{ см} = 0.719$ $Q \text{ кг.} = 0.195$ $D \text{ оп.мм.} = 39$ $P \text{ н.} = 113.2$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-3118</p> <p> $F \text{ см} = 2.33$ $Q \text{ кг.} = 0.631$ $D \text{ оп.мм.} = 54$ $P \text{ н.} = 246$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3114</p> <p> $F \text{ см} = 0.681$ $Q \text{ кг.} = 0.185$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 111$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>		<p>БПО-3119</p> <p> $F \text{ см} = 0.569$ $Q \text{ кг.} = 0.154$ $D \text{ оп.мм.} = 25.5$ $P \text{ н.} = 67.5$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3115</p> <p> $F \text{ см}^2 = 0.91$ $Q \text{ кг.} = 0.247$ $D \text{ оп.мм.} = 48$ $P \text{ н.} = 157.2$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3120</p> <p> $F \text{ см} = 0.86$ $Q \text{ кг.} = 0.233$ $D \text{ оп.мм.} = 36.7$ $P \text{ н.} = 168$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>










	БПО-3121		БПО-3126
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3122		БПО-3127
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.979$ $Q \text{ кг.} = 0.265$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 151.1$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3123		БПО-3128
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.657$ $Q \text{ кг.} = 0.178$ $D \text{ оп.мм.} = 40$ $P \text{ н.} = 133.5$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3124		БПО-3129
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.758$ $Q \text{ кг.} = 0.205$ $D \text{ оп.мм.} = 42$ $P \text{ н.} = 98.8$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = 0$
	БПО-3125		БПО-3130
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$








	БПО-0		БПО-0
	F см ² = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-0		БПО-0
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-0		БПО-0
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-0		БПО-0
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-0		БПО-3140
	F см ² = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		<div>  </div> F см = 3.28 Q кз. = 0.889 D оп.мм.= 66 P н. = 282.2 Гр. сл. = VI Точн. = П






	БПО-3141 $F \text{ см}^2 = 3.832$ $Q \text{ кг.} = 1.038$ $D \text{ оп.мм.} = 46$ $P \text{ н.} = 193.6$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		БПО-3146 $F \text{ см} = 0.578$ $Q \text{ кг.} = 0.157$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 80$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$
	БПО-3142 $F \text{ см} = 20.758$ $Q \text{ кг.} = 5.625$ $D \text{ оп.мм.} = 121$ $P \text{ н.} = 949.5$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		БПО-0 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3143 $F \text{ см} = 11.8$ $Q \text{ кг.} = 3.198$ $D \text{ оп.мм.} = 57$ $P \text{ н.} = 148.5$ $\text{Гр. сл.} = \text{I}$ $\text{Точн.} = \text{П}$		БПО-0 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3144 $F \text{ см} = 3.326$ $Q \text{ кг.} = 0.901$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 306$ $\text{Гр. сл.} = \text{Особая}$ $\text{Точн.} = \text{Н}$		БПО-3149 $F \text{ см} = 0.953$ $Q \text{ кг.} = 0.258$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 148.9$ $\text{Гр. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$
	БПО-3145 $F \text{ см}^2 = 0.93$ $Q \text{ кг.} = 0.252$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 89.1$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3150 $F \text{ см} = 4.949$ $Q \text{ кг.} = 1.341$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 427.3$ $\text{Гр. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$





	БПО-3151 $F \text{ см}^2 = 3.13$ $Q \text{ кг.} = 0.848$ $D \text{ оп.мм.} = 22$ $P \text{ н.} = 65.8$ $\Gamma \text{р. сл.} = \text{I}$ $\text{Точн.} = \text{П}$		БПО-3156 $F \text{ см} = 1.835$ $Q \text{ кг.} = 0.497$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 258.3$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3152 $F \text{ см} = 1.849$ $Q \text{ кг.} = 0.501$ $D \text{ оп.мм.} = 80$ $P \text{ н.} = 269.6$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{Особой}$		БПО-3157 $F \text{ см} = 4.93$ $Q \text{ кг.} = 1.336$ $D \text{ оп.мм.} = 180$ $P \text{ н.} = 510$ $\Gamma \text{р. сл.} = \text{Особой}$ $\text{Точн.} = \text{П}$
	БПО-3153 $F \text{ см} = 1.065$ $Q \text{ кг.} = 0.289$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 182.3$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3158 $F \text{ см} = 7.29$ $Q \text{ кг.} = 1.976$ $D \text{ оп.мм.} = 150$ $P \text{ н.} = 628$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-3154 $F \text{ см} = 2.719$ $Q \text{ кг.} = 0.737$ $D \text{ оп.мм.} = 84$ $P \text{ н.} = 270.4$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		БПО-0 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3155 $F \text{ см}^2 = 4.79$ $Q \text{ кг.} = 1.298$ $D \text{ оп.мм.} = 180$ $P \text{ н.} = 798.6$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$		БПО-0 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$





	БПО-3161 $F \text{ см}^2 = 6.668$ $Q \text{ кг.} = 1.807$ $D \text{ оп.мм.} = 165$ $P \text{ н.} = 646$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		БПО-3166 $F \text{ см} = 1.095$ $Q \text{ кг.} = 0.297$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 157.3$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3162 $F \text{ см} = 1.686$ $Q \text{ кг.} = 0.457$ $D \text{ оп.мм.} = 40$ $P \text{ н.} = 124.6$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3167 $F \text{ см} = 1.762$ $Q \text{ кг.} = 0.478$ $D \text{ оп.мм.} = 33.4$ $P \text{ н.} = 187.3$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-0 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		БПО-3168 $F \text{ см} = 3.049$ $Q \text{ кг.} = 0.826$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 148.6$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-0 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		БПО-3169 $F \text{ см} = 5.66$ $Q \text{ кг.} = 1.534$ $D \text{ оп.мм.} = 55$ $P \text{ н.} = 134.7$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} =$
	БПО-3165 $F \text{ см}^2 = 2.774$ $Q \text{ кг.} = 0.752$ $D \text{ оп.мм.} = 46$ $P \text{ н.} = 170.6$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3170 $F \text{ см} = 4.726$ $Q \text{ кг.} = 1.28$ $D \text{ оп.мм.} = 153$ $P \text{ н.} = 477.6$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$







	БПО-3171 $F \text{ см}^2 = 0.697$ $Q \text{ кг.} = 0.189$ $D \text{ оп.мм.} = 40$ $P \text{ н.} = 118.7$ Гр. сл. = IV Точн. = П		БПО-3176 $F \text{ см} = 2.968$ $Q \text{ кг.} = 0.804$ $D \text{ оп.мм.} = 106$ $P \text{ н.} = 317.8$ Гр. сл. = VI Точн. = П
	БПО-3172 $F \text{ см} = 4.204$ $Q \text{ кг.} = 1.139$ $D \text{ оп.мм.} = 38.5$ $P \text{ н.} = 95.7$ Гр. сл. = III Точн. = П		БПО-0 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3173 $F \text{ см} = 1.71$ $Q \text{ кг.} = 0.463$ $D \text{ оп.мм.} = 19$ $P \text{ н.} = 73.6$ Гр. сл. = V Точн. = П		БПО-3178 $F \text{ см} = 2.07$ $Q \text{ кг.} = 0.561$ $D \text{ оп.мм.} = 76$ $P \text{ н.} = 159.9$ Гр. сл. = II Точн. = Особой
	БПО-3174 $F \text{ см} = 2.588$ $Q \text{ кг.} = 0.701$ $D \text{ оп.мм.} = 75$ $P \text{ н.} = 285.3$ Гр. сл. = V Точн. = П		БПО-3179 $F \text{ см} = 3.833$ $Q \text{ кг.} = 1.039$ $D \text{ оп.мм.} = 140$ $P \text{ н.} = 296.5$ Гр. сл. = Особой Точн. = П
	БПО-3175 $F \text{ см}^2 = 1.64$ $Q \text{ кг.} = 0.444$ $D \text{ оп.мм.} = 64$ $P \text{ н.} = 223.8$ Гр. сл. = VI Точн. = П		БПО-3180 $F \text{ см} = 5.33$ $Q \text{ кг.} = 1.445$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 213.5$ Гр. сл. = VI Точн. = П





	БПО-3181 $F \text{ см}^2 = 1.73$ $Q \text{ кг.} = 0.469$ $D \text{ оп.мм.} = 34$ $P \text{ н.} = 109.3$ Гр. сл. = IV Точн. = П		БПО-3186 $F \text{ см} = 0.796$ $Q \text{ кг.} = 0.216$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 91.1$ Гр. сл. = III Точн. = П
	БПО-3182 $F \text{ см} = 2.24$ $Q \text{ кг.} = 0.607$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 139$ Гр. сл. = IV Точн. = П		БПО-0 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3183 $F \text{ см} = 3.382$ $Q \text{ кг.} = 0.917$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 181.7$ Гр. сл. = V Точн. = П		БПО-3188 $F \text{ см} = 1.847$ $Q \text{ кг.} = 0.5$ $D \text{ оп.мм.} = 65$ $P \text{ н.} = 313.6$ Гр. сл. = IV Точн. = П
	БПО-0 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		БПО-3189 $F \text{ см} = 1.263$ $Q \text{ кг.} = 0.342$ $D \text{ оп.мм.} = 69$ $P \text{ н.} = 167.6$ Гр. сл. = V Точн. = П
	БПО-0 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		БПО-3190 $F \text{ см} = 0.363$ $Q \text{ кг.} = 0.099$ $D \text{ оп.мм.} = 11$ $P \text{ н.} = 35.2$ Гр. сл. = IV Точн. = П









	<p>БПО-3191</p> <p> $F \text{ см}^2 = 5.474$ $Q \text{ кг.} = 1.484$ $D \text{ оп.мм.} = 38$ $P \text{ н.} = 96.2$ Гр. сл. = III Точн. = П </p>		<p>БПО-0</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-0</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>		<p>БПО-0</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-3193</p> <p> $F \text{ см} = 0.671$ $Q \text{ кг.} = 0.182$ $D \text{ оп.мм.} = 21$ $P \text{ н.} = 62.8$ Гр. сл. = IV Точн. = П </p>		<p>БПО-3198</p> <p> $F \text{ см} = 2.54$ $Q \text{ кг.} = 0.688$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 204$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-3194</p> <p> $F \text{ см} = 31.325$ $Q \text{ кг.} = 8.49$ $D \text{ оп.мм.} = 120$ $P \text{ н.} = 1439$ Гр. сл. = Особая Точн. = П </p>		<p>БПО-0</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-0</p> <p> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>		<p>БПО-3200</p> <p> $F \text{ см} = 2.21$ $Q \text{ кг.} = 0.599$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 198$ Гр. сл. = IV Точн. = П </p>







	БПО-3201		БПО-3206
	<p> $F \text{ см}^2 = 1.92$ $Q \text{ кг.} = 0.52$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 196$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>		<p> $F \text{ см} = 1.525$ $Q \text{ кг.} = 0.413$ $D \text{ оп.мм.} = 76$ $P \text{ н.} = 205.1$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p>
	БПО-3202		БПО-3207
	<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p> $F \text{ см} = 1.48$ $Q \text{ кг.} = 0.401$ $D \text{ оп.мм.} = 81$ $P \text{ н.} = 215.3$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p>
	БПО-3203		БПО-3208
	<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p> $F \text{ см} = 2.363$ $Q \text{ кг.} = 0.641$ $D \text{ оп.мм.} = 105$ $P \text{ н.} = 317.3$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	БПО-3204		БПО-3209
	<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>
	БПО-3205		БПО-3210
	<p> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>




	<p>БПО-3211</p> <p> $F \text{ см}^2 = 2.288$ $Q \text{ кг.} = 0.62$ $D \text{ оп.мм.} = 65$ $P \text{ н.} = 298.6$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3216</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>
	<p>БПО-3212</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3217</p> <p> $F \text{ см} = 2.694$ $Q \text{ кг.} = 0.73$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 272.9$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3213</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3218</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>
	<p>БПО-3214</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3219</p> <p> $F \text{ см} = 4.736$ $Q \text{ кг.} = 1.283$ $D \text{ оп.мм.} = 135$ $P \text{ н.} = 550.3$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3215</p> <p> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3220</p> <p> $F \text{ см} = 0.82$ $Q \text{ кг.} = 0.222$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 94.3$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>










	БПО-3221		БПО-3226
	<p> $F \text{ см}^2 = 0.751$ $Q \text{ кг.} = 0.204$ $D \text{ оп.мм.} = 28$ $P \text{ н.} = 87.8$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$ </p>		<p> $F \text{ см} = 12.49$ $Q \text{ кг.} = 3.386$ $D \text{ оп.мм.} = 89$ $P \text{ н.} = 210.5$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = Н$ </p>
	БПО-3222		БПО-3227
	<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$ </p>
	БПО-3223		БПО-3228
	<p> $F \text{ см} = 1.62$ $Q \text{ кг.} = 0.439$ $D \text{ оп.мм.} = 102$ $P \text{ н.} = 251.6$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$ </p>		<p> $F \text{ см} = 19.045$ $Q \text{ кг.} = 5.16$ $D \text{ оп.мм.} = 157$ $P \text{ н.} = 740.1$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$ </p>
	БПО-3224		БПО-3228
	<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p> $F \text{ см} = 0.427$ $Q \text{ кг.} = 0.116$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 65.7$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$ </p>
	БПО-3225		БПО-3230
	<p> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p> $F \text{ см} = 0.595$ $Q \text{ кг.} = 0.161$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 110.5$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$ </p>







	БПО-3231		БПО-3236
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 6.28$ $Q \text{ кг.} = 1.702$ $D \text{ оп.мм.} = 141$ $P \text{ н.} = 493$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
	БПО-3232		БПО-3237
	$F \text{ см} = 2.7$ $Q \text{ кг.} = 0.732$ $D \text{ оп.мм.} = 91$ $P \text{ н.} = 186$ $\Gamma \text{р. сл.} = II$ $\text{Точн.} = П$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3233		БПО-3238
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3234		БПО-3239
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 11.19$ $Q \text{ кг.} = 3.032$ $D \text{ оп.мм.} = 155$ $P \text{ н.} = 737.6$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$
	БПО-3235		БПО-3240
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 4.61$ $Q \text{ кг.} = 1.249$ $D \text{ оп.мм.} = 102$ $P \text{ н.} = 499.4$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$









	<p>БПО-3241</p> <p> $F \text{ см}^2 = 6.707$ $Q \text{ кг.} = 1.818$ $D \text{ оп.мм.} = 151$ $P \text{ н.} = 651.7$ Гр. сл. = IV Точн. = П </p>		<p>БПО-3246</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-3242</p> <p> $F \text{ см} = 1.604$ $Q \text{ кг.} = 0.435$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 202.5$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3247</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-3243</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>		<p>БПО-3248</p> <p> $F \text{ см} = 16.16$ $Q \text{ кг.} = 4.38$ $D \text{ оп.мм.} = 147$ $P \text{ н.} = 754$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-3244</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>		<p>БПО-3249</p> <p> $F \text{ см} = 1.885$ $Q \text{ кг.} = 0.511$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 130.4$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-3245</p> <p> $F \text{ см}^2 = 3.914$ $Q \text{ кг.} = 1.061$ $D \text{ оп.мм.} = 48$ $P \text{ н.} = 164.7$ Гр. сл. = III Точн. = П </p>		<p>БПО-3250</p> <p> $F \text{ см} = 3.565$ $Q \text{ кг.} = 0.97$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 171.8$ Гр. сл. = V Точн. = П </p>










	<p>БПО-3251</p> <p> $F \text{ см}^2 = 4.547$ $Q \text{ кг.} = 1.23$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 268.9$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-3256</p> <p> $F \text{ см} = 7.43$ $Q \text{ кг.} = 2$ $D \text{ оп.мм.} = 96$ $P \text{ н.} = 483$ Гр. сл. = V Точн. = П </p>
	<p>БПО-3252</p> <p> $F \text{ см} = 1.041$ $Q \text{ кг.} = 0.282$ $D \text{ оп.мм.} = 24.5$ $P \text{ н.} = 56.7$ Гр. сл. = III Точн. = П </p>		<p>БПО-3257</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-3253</p> <p> $F \text{ см} = 13.37$ $Q \text{ кг.} = 3.623$ $D \text{ оп.мм.} = 106$ $P \text{ н.} = 781.1$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3258</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-3254</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>		<p>БПО-3259</p> <p> $F \text{ см} = 1.033$ $Q \text{ кг.} = 0.28$ $D \text{ оп.мм.} = 19$ $P \text{ н.} = 70.6$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-3255</p> <p> $F \text{ см}^2 = 3.675$ $Q \text{ кг.} = 0.996$ $D \text{ оп.мм.} = 114$ $P \text{ н.} = 478.8$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3260</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>








	БПО-3261		БПО-3266
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3262		БПО-3267
	$F \text{ см} = 1.025$ $Q \text{ кг.} = 0.278$ $D \text{ оп.мм.} = 48$ $P \text{ н.} = 114.1$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3263		БПО-3268
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 1.488$ $Q \text{ кг.} = 0.403$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 196.9$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
	БПО-3264		БПО-3269
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3265		БПО-3270
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 3.08$ $Q \text{ кг.} = 0.835$ $D \text{ оп.мм.} = 116$ $P \text{ н.} = 370$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = П$





	БПО-3271 $F \text{ см}^2 = 1.853$ $Q \text{ кг.} = 0.503$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 226.1$ Гр. сл. = VI Точн. = П		БПО-3276 $F \text{ см} = 10.43$ $Q \text{ кг.} = 2.83$ $D \text{ оп.мм.} = 187$ $P \text{ н.} = 992.3$ Гр. сл. = Особая Точн. = П
	БПО-3272 $F \text{ см} = 0.471$ $Q \text{ кг.} = 0.128$ $D \text{ оп.мм.} = 21$ $P \text{ н.} = 73.6$ Гр. сл. = IV Точн. = П		БПО-3277 $F \text{ см} = 1.02$ $Q \text{ кг.} = 0.276$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 172.7$ Гр. сл. = Особая Точн. = П
	БПО-3273 $F \text{ см} = 2.401$ $Q \text{ кг.} = 0.651$ $D \text{ оп.мм.} = 54$ $P \text{ н.} = 121.4$ Гр. сл. = III Точн. = П		БПО-3278 $F \text{ см} = 6.89$ $Q \text{ кг.} = 1.867$ $D \text{ оп.мм.} = 166$ $P \text{ н.} = 847.9$ Гр. сл. = VI Точн. = П
	БПО-3274 $F \text{ см} = 1.370$ $Q \text{ кг.} = 0.371$ $D \text{ оп.мм.} = 24$ $P \text{ н.} = 78.5$ Гр. сл. = III Точн. = П		БПО-3059 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3275 $F \text{ см}^2 = 19.331$ $Q \text{ кг.} = 5.24$ $D \text{ оп.мм.} = 152$ $P \text{ н.} = 1177$ Гр. сл. = Особая Точн. = П		БПО-3280 $F \text{ см} = 16.967$ $Q \text{ кг.} = 4.598$ $D \text{ оп.мм.} = 111$ $P \text{ н.} = 764.2$ Гр. сл. = VI Точн. = П










	<p>БПО-3281</p> <p> $F \text{ см}^2 = 0.6$ $Q \text{ кг.} = 0.163$ $D \text{ оп.мм.} = 13$ $P \text{ н.} = 34$ Гр. сл. = III Точн. = П </p>		<p>БПО-3286</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-3282</p> <p> $F \text{ см} = 0.475$ $Q \text{ кг.} = 0.129$ $D \text{ оп.мм.} = 25$ $P \text{ н.} = 79.1$ Гр. сл. = IV Точн. = П </p>		<p>БПО-3287</p> <p> $F \text{ см} = 3.34$ $Q \text{ кг.} = 0.905$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 108.5$ Гр. сл. = III Точн. = Ос. </p>
	<p>БПО-3283</p> <p> $F \text{ см} = 3.095$ $Q \text{ кг.} = 0.838$ $D \text{ оп.мм.} = 58$ $P \text{ н.} = 228.3$ Гр. сл. = V Точн. = П </p>		<p>БПО-3288</p> <p> $F \text{ см} = 0.278$ $Q \text{ кг.} = 0.075$ $D \text{ оп.мм.} = 14$ $P \text{ н.} = 48.2$ Гр. сл. = V Точн. = П </p>
	<p>БПО-3054</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>		<p>БПО-3289</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-3285</p> <p> $F \text{ см}^2 = 0.352$ $Q \text{ кг.} = 0.096$ $D \text{ оп.мм.} = 9$ $P \text{ н.} = 39.5$ Гр. сл. = IV Точн. = П </p>		<p>БПО-3290</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>







	<p>БПО-3291</p> <p> $F \text{ см}^2 = 5.12$ $Q \text{ кг.} = 1.388$ $D \text{ оп.мм.} = 113$ $P \text{ н.} = 264$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>		<p>БПО-3296</p> <p> $F \text{ см} = 0.273$ $Q \text{ кг.} = 0.074$ $D \text{ оп.мм.} = 12.6$ $P \text{ н.} = 39.4$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = П$ </p>
	<p>БПО-3292</p> <p> $F \text{ см} = 4.27$ $Q \text{ кг.} = 1.157$ $D \text{ оп.мм.} = 62$ $P \text{ н.} = 224.2$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$ </p>		<p>БПО-3297</p> <p> $F \text{ см} = 1.067$ $Q \text{ кг.} = 0.289$ $D \text{ оп.мм.} = 38$ $P \text{ н.} = 163.7$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>
	<p>БПО-3293</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3298</p> <p> $F \text{ см} = 1.018$ $Q \text{ кг.} = 0.279$ $D \text{ оп.мм.} = 37$ $P \text{ н.} = 106.4$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$ </p>
	<p>БПО-3294</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3299</p> <p> $F \text{ см} = 1.7590$ $Q \text{ кг.} = 0.477$ $D \text{ оп.мм.} = 44$ $P \text{ н.} = 154.1$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$ </p>
	<p>БПО-3295</p> <p> $F \text{ см}^2 = 1.21$ $Q \text{ кг.} = 0.328$ $D \text{ оп.мм.} = 52$ $P \text{ н.} = 173.8$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$ </p>		<p>БПО-3300</p> <p> $F \text{ см} = 0,252$ $Q \text{ кг.} = 0,068$ $D \text{ оп.мм.} = 34,6$ $P \text{ н.} = 34,6$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = П$ </p>




	<p>БПО-3301</p> <p> $F \text{ см}^2 = 0.24$ $Q \text{ кг.} = 0.065$ $D \text{ оп.мм.} = 9$ $P \text{ н.} = 22$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3306</p> <p> $F \text{ см} = 1.72$ $Q \text{ кг.} = 0.466$ $D \text{ оп.мм.} = 118$ $P \text{ н.} = 336.4$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3302</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3307</p> <p> $F \text{ см} = 13.43$ $Q \text{ кг.} = 3.64$ $D \text{ оп.мм.} = 181$ $P \text{ н.} = 805.4$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3303</p> <p> $F \text{ см} = 14.43$ $Q \text{ кг.} = 3.91$ $D \text{ оп.мм.} = 137$ $P \text{ н.} = 457$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3308</p> <p> $F \text{ см} = 2.019$ $Q \text{ кг.} = 0.547$ $D \text{ оп.мм.} = 84$ $P \text{ н.} = 325.4$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3304</p> <p> $F \text{ см} = 5.03$ $Q \text{ кг.} = 1.36$ $D \text{ оп.мм.} = 167$ $P \text{ н.} = 502.8$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3309</p> <p> $F \text{ см} = 2.18$ $Q \text{ кг.} = 0.591$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 227.1$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3305</p> <p> $F \text{ см}^2 = 0.872$ $Q \text{ кг.} = 0.236$ $D \text{ оп.мм.} = 17$ $P \text{ н.} = 38.7$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3310</p> <p> $F \text{ см} = 0.639$ $Q \text{ кг.} = 0.173$ $D \text{ оп.мм.} = 28$ $P \text{ н.} = 108.2$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>








	БПО-3311		БПО-3316
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 17.965$ $Q \text{ кг.} = 4.869$ $D \text{ оп.мм.} = 156$ $P \text{ н.} = 566$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3312		БПО-3317
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 1.138$ $Q \text{ кг.} = 0.308$ $D \text{ оп.мм.} = 37$ $P \text{ н.} = 96.4$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3313		БПО-3318
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 1.696$ $Q \text{ кг.} = 0.46$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 146.9$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3314		БПО-3319
	$F \text{ см} = 22.84$ $Q \text{ кг.} = 6.19$ $D \text{ оп.мм.} = 173$ $P \text{ н.} = 758.9$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 21.36$ $Q \text{ кг.} = 5.79$ $D \text{ оп.мм.} = 160$ $P \text{ н.} = 730.5$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3315		БПО-3320
	$F \text{ см}^2 = 0.836$ $Q \text{ кг.} = 0.227$ $D \text{ оп.мм.} = 27$ $P \text{ н.} = 69.4$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0.81$ $Q \text{ кг.} = 0.22$ $D \text{ оп.мм.} = 19$ $P \text{ н.} = 70.5$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$









	БПО-3321 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		БПО-3326 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3322 $F \text{ см} = 2.211$ $Q \text{ кг.} = 0.599$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 183.5$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		БПО-3327 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3323 $F \text{ см} = 1.237$ $Q \text{ кг.} = 0.335$ $D \text{ оп.мм.} = 55$ $P \text{ н.} = 178.3$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$		БПО-3328 $F \text{ см} = 1.791$ $Q \text{ кг.} = 0.485$ $D \text{ оп.мм.} = 57$ $P \text{ н.} = 260.5$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$
	БПО-3324 $F \text{ см} = 0,814$ $Q \text{ кг.} = 0,221$ $D \text{ оп.мм.} = 24$ $P \text{ н.} = 118,4$ $\Gamma \text{р. сл.} = M$ $\text{Точн.} = П$		БПО-3329 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3325 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		БПО-3330 $F \text{ см} = 4.354$ $Q \text{ кг.} = 1.18$ $D \text{ оп.мм.} = 62$ $P \text{ н.} = 231.3$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$







	БПО-3331 $F \text{ см}^2 = 9.259$ $Q \text{ кг.} = 2.509$ $D \text{ оп.мм.} = 175$ $P \text{ н.} = 612.9$ Гр. сл. = VI Точн. = П		БПО-3336 $F \text{ см} = 3.968$ $Q \text{ кг.} = 1.075$ $D \text{ оп.мм.} = 88$ $P \text{ н.} = 270$ Гр. сл. = VI Точн. = 0
	БПО-3332 $F \text{ см} = 10.222$ $Q \text{ кг.} = 2.77$ $D \text{ оп.мм.} = 167$ $P \text{ н.} = 726.9$ Гр. сл. = особая Точн. = П		БПО-3337 $F \text{ см} = 9.127$ $Q \text{ кг.} = 2.473$ $D \text{ оп.мм.} = 161$ $P \text{ н.} = 447.2$ Гр. сл. = VI Точн. = П
	БПО-3333 $F \text{ см} = 3.842$ $Q \text{ кг.} = 1.041$ $D \text{ оп.мм.} = 71$ $P \text{ н.} = 226.7$ Гр. сл. = V Точн. = П		БПО-3338 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3334 $F \text{ см} = 8.63$ $Q \text{ кг.} = 2.34$ $D \text{ оп.мм.} = 126$ $P \text{ н.} = 564.2$ Гр. сл. = особая Точн. = П		БПО-3339 $F \text{ см} = 19.87$ $Q \text{ кг.} = 5.385$ $D \text{ оп.мм.} = 151$ $P \text{ н.} = 690.4$ Гр. сл. = IV Точн. = П
	БПО-3335 $F \text{ см}^2 = 11.233$ $Q \text{ кг.} = 3.044$ $D \text{ оп.мм.} = 166$ $P \text{ н.} = 747.7$ Гр. сл. = особая Точн. = П		БПО-3340 $F \text{ см} = 2.34$ $Q \text{ кг.} = 0.634$ $D \text{ оп.мм.} = 76$ $P \text{ н.} = 315$ Гр. сл. = III Точн. = П







	<p>БПО-3341</p> <p> $F \text{ см}^2 = 2.973$ $Q \text{ кг.} = 0.805$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 204.9$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3346</p> <p> $F \text{ см} = 10.392$ $Q \text{ кг.} = 2.82$ $D \text{ оп.мм.} = 180$ $P \text{ н.} = 492.9$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3342</p> <p> $F \text{ см} = 9.107$ $Q \text{ кг.} = 2.468$ $D \text{ оп.мм.} = 161$ $P \text{ н.} = 529.1$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3347</p> <p> $F \text{ см} = 4.064$ $Q \text{ кг.} = 1.101$ $D \text{ оп.мм.} = 42$ $P \text{ н.} = 114.9$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3343</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3348</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>
	<p>БПО-3344</p> <p> $F \text{ см} = 9.978$ $Q \text{ кг.} = 2.704$ $D \text{ оп.мм.} = 136$ $P \text{ н.} = 471.2$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3349</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>
	<p>БПО-3345</p> <p> $F \text{ см}^2 = 2.57$ $Q \text{ кг.} = 0.696$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 139$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3350</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>








	БПО-3351		БПО-3356
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3352		БПО-3357
	$F \text{ см} = 10.74$ $Q \text{ кг.} = 2.91$ $D \text{ оп.мм.} = 181$ $P \text{ н.} = 451.6$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \Pi$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3353		БПО-3358
	$F \text{ см} = 6$ $Q \text{ кг.} = 1.626$ $D \text{ оп.мм.} = 110$ $P \text{ н.} = 236$ $\Gamma \text{р. сл.} = \text{I}$ $\text{Точн.} = \Pi$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3354		БПО-3359
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3355		БПО-3360
	$F \text{ см}^2 = 0.52$ $Q \text{ кг.} = 0.14$ $D \text{ оп.мм.} = 25$ $P \text{ н.} = 73$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \Pi$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$







	БПО-3361		БПО-3366
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 8.471$ $Q \text{ кг.} = 2.296$ $D \text{ оп.мм.} = 139$ $P \text{ н.} = 882.1$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	БПО-3362		БПО-3367
	$F \text{ см} = 1.18$ $Q \text{ кг.} = 0.32$ $D \text{ оп.мм.} = 37$ $P \text{ н.} = 173.6$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0.433$ $Q \text{ кг.} = 0.117$ $D \text{ оп.мм.} = 22$ $P \text{ н.} = 73.9$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3363		БПО-3368
	$F \text{ см} = 0.63$ $Q \text{ кг.} = 0.171$ $D \text{ оп.мм.} = 15$ $P \text{ н.} = 41.5$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0.555$ $Q \text{ кг.} = 0.151$ $D \text{ оп.мм.} = 20$ $P \text{ н.} = 77$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3364		БПО-3369
	$F \text{ см} = 10.315$ $Q \text{ кг.} = 2.795$ $D \text{ оп.мм.} = 167$ $P \text{ н.} = 463.5$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3365		БПО-3370
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 2.699$ $Q \text{ кг.} = 0.731$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 354.7$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$









	БПО-3371 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		БПО-3376 $F \text{ см} = 0.77$ $Q \text{ кг.} = 0.209$ $D \text{ оп.мм.} = 13$ $P \text{ н.} = 36$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{П}$
	БПО-3372 $F \text{ см} = 6.69$ $Q \text{ кг.} = 1.81$ $D \text{ оп.мм.} = 152$ $P \text{ н.} = 389.5$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3377 $F \text{ см} = 7.88$ $Q \text{ кг.} = 2.14$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 187.3$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3373 $F \text{ см} = 18.627$ $Q \text{ кг.} = 5.048$ $D \text{ оп.мм.} = 147$ $P \text{ н.} = 847.5$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$		БПО-3378 $F \text{ см} = 15.08$ $Q \text{ кг.} = 4.09$ $D \text{ оп.мм.} = 106$ $P \text{ н.} = 253.7$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{П}$
	БПО-3374 $F \text{ см} = 8.235$ $Q \text{ кг.} = 2.232$ $D \text{ оп.мм.} = 158$ $P \text{ н.} = 787.6$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$		БПО-3379 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3375 $F \text{ см}^2 = 1.04$ $Q \text{ кг.} = 0.282$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 210$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		БПО-3380 $F \text{ см} = 8.103$ $Q \text{ кг.} = 2.196$ $D \text{ оп.мм.} = 176$ $P \text{ н.} = 503.9$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$











	БПО-3381 $F \text{ см}^2 = 1.68$ $Q \text{ кг.} = 0.455$ $D \text{ оп.мм.} = 74$ $P \text{ н.} = 242.5$ Гр. сл. = VI Точн. = П		БПО-3386 $F \text{ см} = 11.34$ $Q \text{ кг.} = 3.074$ $D \text{ оп.мм.} = 154$ $P \text{ н.} = 401.6$ Гр. сл. = IV Точн. = П
	БПО-3382 $F \text{ см} = 3.26$ $Q \text{ кг.} = 0.884$ $D \text{ оп.мм.} = 130$ $P \text{ н.} = 360.4$ Гр. сл. = IV Точн. = П		БПО-3387 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3383 $F \text{ см} = 9.826$ $Q \text{ кг.} = 2.663$ $D \text{ оп.мм.} = 92$ $P \text{ н.} = 335.3$ Гр. сл. = V Точн. = П		БПО-3388 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3384 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		БПО-3389 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3385 $F \text{ см}^2 = 5.106$ $Q \text{ кг.} = 1.384$ $D \text{ оп.мм.} = 96$ $P \text{ н.} = 261.8$ Гр. сл. = III Точн. = П		БПО-3390 $F \text{ см} = 0.93$ $Q \text{ кг.} = 0.252$ $D \text{ оп.мм.} = 48$ $P \text{ н.} = 144.6$ Гр. сл. = IV Точн. = П









	БПО-3391		БПО-3396
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.838$ $Q \text{ кг.} = 0.227$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 142.9$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3392		БПО-3397
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.666$ $Q \text{ кг.} = 0.18$ $D \text{ оп.мм.} = 49$ $P \text{ н.} = 102.9$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3393		БПО-3398
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.921$ $Q \text{ кг.} = 0.25$ $D \text{ оп.мм.} = 46$ $P \text{ н.} = 186.4$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$
	БПО-3394		БПО-3399
	$F \text{ см} = 1.897$ $Q \text{ кг.} = 0.514$ $D \text{ оп.мм.} = 49$ $P \text{ н.} = 172.6$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0.532$ $Q \text{ кг.} = 0.144$ $D \text{ оп.мм.} = 33$ $P \text{ н.} = 107$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$
	БПО-3395		БПО-3400
	$F \text{ см}^2 = 4.9$ $Q \text{ кг.} = 1.328$ $D \text{ оп.мм.} = 66$ $P \text{ н.} = 299.3$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$









	БПО-3401		БПО-3406
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 1.82$ $Q \text{ кг.} = 0.493$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 186$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3402		БПО-3407
	$F \text{ см} = 2.151$ $Q \text{ кг.} = 0.583$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 168.7$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{особой}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3403		БПО-3408
	$F \text{ см} = 3.314$ $Q \text{ кг.} = 0.898$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 213.6$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3404		БПО-3409
	$F \text{ см} = 1.52$ $Q \text{ кг.} = 0.412$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 156$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 4.633$ $Q \text{ кг.} = 1.256$ $D \text{ оп.мм.} = 162$ $P \text{ н.} = 517.5$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3405		БПО-3410
	$F \text{ см}^2 = 2.91$ $Q \text{ кг.} = 0.79$ $D \text{ оп.мм.} = 140$ $P \text{ н.} = 327.8$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 3.724$ $Q \text{ кг.} = 1.009$ $D \text{ оп.мм.} = 77$ $P \text{ н.} = 248.3$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$








	БПО-3411 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		БПО-3416 $F \text{ см} = 0.404$ $Q \text{ кг.} = 0.109$ $D \text{ оп.мм.} = 15$ $P \text{ н.} = 56.5$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3412 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		БПО-3417 $F \text{ см} = 1.032$ $Q \text{ кг.} = 0.28$ $D \text{ оп.мм.} = 35$ $P \text{ н.} = 151.7$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3413 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		БПО-3418 $F \text{ см} = 6.37$ $Q \text{ кг.} = 1.73$ $D \text{ оп.мм.} = 63$ $P \text{ н.} = 254.9$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$
	БПО-3414 $F \text{ см} = 2.59$ $Q \text{ кг.} = 0.702$ $D \text{ оп.мм.} = 88$ $P \text{ н.} = 427.9$ $\Gamma \text{ р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$		БПО-3419 $F \text{ см} = 3.166$ $Q \text{ кг.} = 0.858$ $D \text{ оп.мм.} = 120$ $P \text{ н.} = 385.7$ $\Gamma \text{ р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	БПО-3415 $F \text{ см}^2 = 1.259$ $Q \text{ кг.} = 0.341$ $D \text{ оп.мм.} = 33$ $P \text{ н.} = 155$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3420 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$








	БПО-3421 $F \text{ см}^2 = 1.624$ $Q \text{ кг.} = 0.44$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 125.7$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		БПО-3426 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3422 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		БПО-3427 $F \text{ см} = 2.834$ $Q \text{ кг.} = 0.768$ $D \text{ оп.мм.} = 65$ $P \text{ н.} = 233.6$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	БПО-3423 $F \text{ см} = 4.56$ $Q \text{ кг.} = 1.24$ $D \text{ оп.мм.} = 120$ $P \text{ н.} = 456.2$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		БПО-3428 $F \text{ см} = 8.29$ $Q \text{ кг.} = 2.25$ $D \text{ оп.мм.} = 157$ $P \text{ н.} = 404.8$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-3424 $F \text{ см} = 1.578$ $Q \text{ кг.} = 0.428$ $D \text{ оп.мм.} = 71$ $P \text{ н.} = 175.6$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3429 $F \text{ см} = 13.42$ $Q \text{ кг.} = 3.64$ $D \text{ оп.мм.} = 179$ $P \text{ н.} = 565.8$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3425 $F \text{ см}^2 = 17.809$ $Q \text{ кг.} = 4.826$ $D \text{ оп.мм.} = 160$ $P \text{ н.} = 522.8$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$		БПО-3430 $F \text{ см} = 5.63$ $Q \text{ кг.} = 1.53$ $D \text{ оп.мм.} = 120$ $P \text{ н.} = 397.1$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$






	<p>БПО-3431</p> <p> $F \text{ см}^2 = 0.566$ $Q \text{ кг.} = 0.154$ $D \text{ оп.мм.} = 24$ $P \text{ н.} = 97.4$ Гр. сл. = IV Точн. = П </p>		<p>БПО-3436</p> <p> $F \text{ см} = 11.093$ $Q \text{ кг.} = 3.01$ $D \text{ оп.мм.} = 195$ $P \text{ н.} = 533.8$ Гр. сл. = особая Точн. = Н </p>
	<p>БПО-3432</p> <p> $F \text{ см} = 1.24$ $Q \text{ кг.} = 0.336$ $D \text{ оп.мм.} = 51$ $P \text{ н.} = 176$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3437</p> <p> $F \text{ см} = 2.774$ $Q \text{ кг.} = 0.742$ $D \text{ оп.мм.} = 68$ $P \text{ н.} = 237$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-3433</p> <p> $F \text{ см} = 3.14$ $Q \text{ кг.} = 0.851$ $D \text{ оп.мм.} = 54$ $P \text{ н.} = 189.3$ Гр. сл. = IV Точн. = П </p>		<p>БПО-3438</p> <p> $F \text{ см} = 1.034$ $Q \text{ кг.} = 0.28$ $D \text{ оп.мм.} = 67$ $P \text{ н.} = 169.2$ Гр. сл. = V Точн. = П </p>
	<p>БПО-3434</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>		<p>БПО-3439</p> <p> $F \text{ см} = 2$ $Q \text{ кг.} = 0.543$ $D \text{ оп.мм.} = 42$ $P \text{ н.} = 219.3$ Гр. сл. = V Точн. = П </p>
	<p>БПО-3435</p> <p> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>		<p>БПО-3440</p> <p> $F \text{ см} = 5.384$ $Q \text{ кг.} = 1.46$ $D \text{ оп.мм.} = 175$ $P \text{ н.} = 533$ Гр. сл. = особая Точн. = П </p>


	БПО-3441 $F \text{ см}^2 = 5.672$ $Q \text{ кг.} = 1.537$ $D \text{ оп.мм.} = 75$ $P \text{ н.} = 358.2$ Гр. сл. = VI Точн. = П		БПО-3446 $F \text{ см} = 0.56$ $Q \text{ кг.} = 0.152$ $D \text{ оп.мм.} = 22$ $P \text{ н.} = 76.6$ Гр. сл. = IV Точн. = П
	БПО-3442 $F \text{ см} = 3.235$ $Q \text{ кг.} = 0.877$ $D \text{ оп.мм.} = 63$ $P \text{ н.} = 174$ Гр. сл. = IV Точн. = П		БПО-3447 $F \text{ см} = 0.636$ $Q \text{ кг.} = 0.172$ $D \text{ оп.мм.} = 42$ $P \text{ н.} = 90.3$ Гр. сл. = III Точн. = Н
	БПО-3443 $F \text{ см} = 0.557$ $Q \text{ кг.} = 0.151$ $D \text{ оп.мм.} = 20$ $P \text{ н.} = 76.3$ Гр. сл. = VI Точн. = Н		БПО-3448 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3444 $F \text{ см} = 2.603$ $Q \text{ кг.} = 0.705$ $D \text{ оп.мм.} = 110$ $P \text{ н.} = 300$ Гр. сл. = V Точн. = П		БПО-3449 $F \text{ см} = 3.98$ $Q \text{ кг.} = 1.079$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 186.8$ Гр. сл. = III Точн. = П
	БПО-3445 $F \text{ см}^2 = 1.898$ $Q \text{ кг.} = 0.514$ $D \text{ оп.мм.} = 54$ $P \text{ н.} = 122.1$ Гр. сл. = IV Точн. = П		БПО-3450 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0









	<p>БПО-3451</p> <p> $F \text{ см}^2 = 5.464$ $Q \text{ кг.} = 1.481$ $D \text{ оп.мм.} = 174$ $P \text{ н.} = 374$ Гр. сл. = V Точн. = П </p>		<p>БПО-3456</p> <p> $F \text{ см} = 3.97$ $Q \text{ кг.} = 1.076$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 197.5$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-3452</p> <p> $F \text{ см} = 5.152$ $Q \text{ кг.} = 1.396$ $D \text{ оп.мм.} = 166$ $P \text{ н.} = 348.4$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3457</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-3453</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>		<p>БПО-3458</p> <p> $F \text{ см} = 5.813$ $Q \text{ кг.} = 1.575$ $D \text{ оп.мм.} = 73$ $P \text{ н.} = 159.8$ Гр. сл. = II Точн. = П </p>
	<p>БПО-3454</p> <p> $F \text{ см} = 6.163$ $Q \text{ кг.} = 1.67$ $D \text{ оп.мм.} = 100$ $P \text{ н.} = 306.3$ Гр. сл. = IV Точн. = П </p>		<p>БПО-3459</p> <p> $F \text{ см} = 3.0$ $Q \text{ кг.} = 0.813$ $D \text{ оп.мм.} = 111$ $P \text{ н.} = 304$ Гр. сл. = V Точн. = П </p>
	<p>БПО-3455</p> <p> $F \text{ см}^2 = 3.515$ $Q \text{ кг.} = 0.953$ $D \text{ оп.мм.} = 66$ $P \text{ н.} = 211.3$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3460</p> <p> $F \text{ см} = 2.958$ $Q \text{ кг.} = 0.802$ $D \text{ оп.мм.} = 133$ $P \text{ н.} = 458$ Гр. сл. = IV Точн. = П </p>









	<p>БПО-3461</p> <p> $F \text{ см}^2 = 1.08$ $Q \text{ кг.} = 0.292$ $D \text{ оп.мм.} = 47$ $P \text{ н.} = 156.9$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-3466</p> <p> $F \text{ см} = 9.32$ $Q \text{ кг.} = 2.526$ $D \text{ оп.мм.} = 51$ $P \text{ н.} = 269.9$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-3462</p> <p> $F \text{ см} = 3.728$ $Q \text{ кг.} = 1.01$ $D \text{ оп.мм.} = 140$ $P \text{ н.} = 337.6$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3467</p> <p> $F \text{ см} = 1.694$ $Q \text{ кг.} = 0.459$ $D \text{ оп.мм.} = 65$ $P \text{ н.} = 303.4$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-3463</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>		<p>БПО-3468</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-3464</p> <p> $F \text{ см} = 0.907$ $Q \text{ кг.} = 0.246$ $D \text{ оп.мм.} = 34$ $P \text{ н.} = 123.6$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-3469</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-3465</p> <p> $F \text{ см}^2 = 0.964$ $Q \text{ кг.} = 0.261$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 112$ Гр. сл. = V Точн. = П </p>		<p>БПО-3470</p> <p> $F \text{ см} = 9.456$ $Q \text{ кг.} = 2.563$ $D \text{ оп.мм.} = 120$ $P \text{ н.} = 380$ Гр. сл. = V Точн. = П </p>











	<p>БПО-3471</p> <p> $F \text{ см}^2 = 12.13$ $Q \text{ кг.} = 3.287$ $D \text{ оп.мм.} = 99$ $P \text{ н.} = 456.8$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3476</p> <p> $F \text{ см} = 5.202$ $Q \text{ кг.} = 1.41$ $D \text{ оп.мм.} = 66$ $P \text{ н.} = 146.2$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3472</p> <p> $F \text{ см} = 15.685$ $Q \text{ кг.} = 4.25$ $D \text{ оп.мм.} = 150$ $P \text{ н.} = 744.6$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{Особой}$ </p>		<p>БПО-3477</p> <p> $F \text{ см} = 0.43$ $Q \text{ кг.} = 0.12$ $D \text{ оп.мм.} = 27$ $P \text{ н.} = 74$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3473</p> <p> $F \text{ см} = 3.163$ $Q \text{ кг.} = 0.857$ $D \text{ оп.мм.} = 74$ $P \text{ н.} = 353.8$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3478</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>
	<p>БПО-3474</p> <p> $F \text{ см} = 10.14$ $Q \text{ кг.} = 2.748$ $D \text{ оп.мм.} = 96$ $P \text{ н.} = 278.3$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3479</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>
	<p>БПО-3475</p> <p> $F \text{ см}^2 = 7.43$ $Q \text{ кг.} = 2.01$ $D \text{ оп.мм.} = 91$ $P \text{ н.} = 194.3$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3480</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>






	БПО-3481		БПО-3486
	$F \text{ см}^2 = 1.624$ $Q \text{ кг.} = 0.44$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 134.3$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3482		БПО-3487
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.88$ $Q \text{ кг.} = 0.238$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 74$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$
	БПО-3483		БПО-3488
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3484		БПО-3489
	$F \text{ см} = 0.577$ $Q \text{ кг.} = 0.157$ $D \text{ оп.мм.} = 19$ $P \text{ н.} = 75.2$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = Н$		$F \text{ см} = 7.36$ $Q \text{ кг.} = 1.995$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 272$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
	БПО-3485		БПО-3490
	$F \text{ см}^2 = 0.46$ $Q \text{ кг.} = 0.125$ $D \text{ оп.мм.} = 19.3$ $P \text{ н.} = 80.5$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$







	БПО-3491		БПО-3496
	F см ² = 9 Q кг. = 2.439 D оп.мм.= 187 P н. = 460 Гр. сл. = V Точн. = Н		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3492		БПО-3497
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3493		БПО-3498
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3494		БПО-3499
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3495		БПО-3500
	F см ² = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0



	БПО-3501		БПО-3506
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3502		БПО-3507
	$F \text{ см} = 0.547$ $Q \text{ кг.} = 0.148$ $D \text{ оп.мм.} = 22$ $P \text{ н.} = 50$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см} = 1.113$ $Q \text{ кг.} = 0.302$ $D \text{ оп.мм.} = 67$ $P \text{ н.} = 191.3$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$
	БПО-3503		БПО-3508
	$F \text{ см} = 0.25$ $Q \text{ кг.} = 0.068$ $D \text{ оп.мм.} = 11$ $P \text{ н.} = 43$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$		$F \text{ см} = 0.426$ $Q \text{ кг.} = 0.115$ $D \text{ оп.мм.} = 15$ $P \text{ н.} = 73.5$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
	БПО-3504		БПО-3509
	$F \text{ см} = 1.695$ $Q \text{ кг.} = 0.46$ $D \text{ оп.мм.} = 64$ $P \text{ н.} = 197$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см} = 0.757$ $Q \text{ кг.} = 0.205$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 93.2$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
	БПО-3505		БПО-3510
	$F \text{ см}^2 = 2.305$ $Q \text{ кг.} = 0.625$ $D \text{ оп.мм.} = 38$ $P \text{ н.} = 117.9$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$		$F \text{ см} = 1.080$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 151$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$






	<p>БПО-3511</p> <p> $F \text{ см}^2 = 1.461$ $Q \text{ кг.} = 0.396$ $D \text{ оп.мм.} = 52$ $P \text{ н.} = 161$ $\text{Гр. сл.} = V$ $\text{Точн.} = П$ </p>		<p>БПО-3516</p> <p> $F \text{ см} = 1.246$ $Q \text{ кг.} = 0.338$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 120.5$ $\text{Гр. сл.} = IV$ $\text{Точн.} = П$ </p>
	<p>БПО-3512</p> <p> $F \text{ см} = 3.63$ $Q \text{ кг.} = 0.984$ $D \text{ оп.мм.} = 124$ $P \text{ н.} = 352.6$ $\text{Гр. сл.} = VI$ $\text{Точн.} = П$ </p>		<p>БПО-3517</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>
	<p>БПО-3513</p> <p> $F \text{ см} = 5.317$ $Q \text{ кг.} = 1.441$ $D \text{ оп.мм.} = 149$ $P \text{ н.} = 465.3$ $\text{Гр. сл.} = VI$ $\text{Точн.} = П$ </p>		<p>БПО-3518</p> <p> $F \text{ см} = 1.164$ $Q \text{ кг.} = 0.315$ $D \text{ оп.мм.} = 34$ $P \text{ н.} = 166.3$ $\text{Гр. сл.} = V$ $\text{Точн.} = П$ </p>
	<p>БПО-3514</p> <p> $F \text{ см} = 2.244$ $Q \text{ кг.} = 0.608$ $D \text{ оп.мм.} = 57.5$ $P \text{ н.} = 250.4$ $\text{Гр. сл.} = IV$ $\text{Точн.} = П$ </p>		<p>БПО-3519</p> <p> $F \text{ см} = 2.092$ $Q \text{ кг.} = 0.567$ $D \text{ оп.мм.} = 87$ $P \text{ н.} = 264.7$ $\text{Гр. сл.} = VI$ $\text{Точн.} = П$ </p>
	<p>БПО-3515</p> <p> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3520</p> <p> $F \text{ см} = 3.051$ $Q \text{ кг.} = 0.827$ $D \text{ оп.мм.} = 28$ $P \text{ н.} = 69.7$ $\text{Гр. сл.} = III$ $\text{Точн.} = П$ </p>







	БПО-3521 $F \text{ см}^2 = 2.414$ $Q \text{ кг.} = 0.654$ $D \text{ оп.мм.} = 39$ $P \text{ н.} = 169.3$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3526 $F \text{ см} = 2.247$ $Q \text{ кг.} = 0.609$ $D \text{ оп.мм.} = 34$ $P \text{ н.} = 155.7$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-3522 $F \text{ см} = 2.393$ $Q \text{ кг.} = 0.649$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 159.8$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		БПО-3527 $F \text{ см} = 4.526$ $Q \text{ кг.} = 1.227$ $D \text{ оп.мм.} = 51$ $P \text{ н.} = 339.4$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$
	БПО-3523 $F \text{ см} = 1.42$ $Q \text{ кг.} = 0.385$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 106.8$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3528 $F \text{ см} = 2.092$ $Q \text{ кг.} = 0.567$ $D \text{ оп.мм.} = 34$ $P \text{ н.} = 140.5$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$
	БПО-3524 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		БПО-3529 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3525 $F \text{ см}^2 = 3.31$ $Q \text{ кг.} = 0.897$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 181.2$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		БПО-3530 $F \text{ см} = 2.247$ $Q \text{ кг.} = 0.609$ $D \text{ оп.мм.} = 35$ $P \text{ н.} = 166.6$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$










	БПО-3531		БПО-3536
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 2.145$ $Q \text{ кг.} = 0.581$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 116.8$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$
	БПО-3532		БПО-3537
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 3.499$ $Q \text{ кг.} = 0.948$ $D \text{ оп.мм.} = 138$ $P \text{ н.} = 469.5$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$
	БПО-3533		БПО-3538
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 17.87$ $Q \text{ кг.} = 4.84$ $D \text{ оп.мм.} = 128$ $P \text{ н.} = 528.1$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$
	БПО-3534		БПО-3539
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 2.516$ $Q \text{ кг.} = 0.681$ $D \text{ оп.мм.} = 125$ $P \text{ н.} = 352.7$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$
	БПО-3535		БПО-3540
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 1.072$ $Q \text{ кг.} = 0.291$ $D \text{ оп.мм.} = 52$ $P \text{ н.} = 166.7$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$









	БПО-3541 $F \text{ см}^2 = 1.04$ $Q \text{ кг.} = 0.281$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 157.8$ Гр. сл. = IV Точн. = П		БПО-3546 $F \text{ см} = 3.046$ $Q \text{ кг.} = 0.825$ $D \text{ оп.мм.} = 94$ $P \text{ н.} = 327.7$ Гр. сл. = V Точн. = П
	БПО-3542 $F \text{ см} = 4.35$ $Q \text{ кг.} = 1.18$ $D \text{ оп.мм.} = 88$ $P \text{ н.} = 290$ Гр. сл. = IV Точн. = П		БПО-3547 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = IV Точн. = П
	БПО-3543 $F \text{ см} = 8.73$ $Q \text{ кг.} = 2.366$ $D \text{ оп.мм.} = 156$ $P \text{ н.} = 588$ Гр. сл. = IV Точн. = П		БПО-3548 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3544 $F \text{ см} = 4.72$ $Q \text{ кг.} = 1.279$ $D \text{ оп.мм.} = 160$ $P \text{ н.} = 476$ Гр. сл. = V Точн. = П		БПО-3549 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3545 $F \text{ см}^2 = 6.674$ $Q \text{ кг.} = 1.81$ $D \text{ оп.мм.} = 67$ $P \text{ н.} = 253.8$ Гр. сл. = V Точн. = П		БПО-3550 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0







	БПО-3551		БПО-3556
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3552		БПО-3557
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3553		БПО-3558
	$F \text{ см} = 8.995$ $Q \text{ кг.} = 2.438$ $D \text{ оп.мм.} = 180$ $P \text{ н.} = 497.3$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3554		БПО-3559
	$F \text{ см} = 10.838$ $Q \text{ кг.} = 2.937$ $D \text{ оп.мм.} = 123$ $P \text{ н.} = 577.4$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3555		БПО-3560
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$


	БПО-3561		БПО-3566
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 2.382$ $Q \text{ кг.} = 0.646$ $D \text{ оп.мм.} = 153$ $P \text{ н.} = 345$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3562		БПО-3567
	$F \text{ см} = 4.663$ $Q \text{ кг.} = 1.264$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 373.8$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3563		БПО-3568
	$F \text{ см} = 2.782$ $Q \text{ кг.} = 0.754$ $D \text{ оп.мм.} = 80$ $P \text{ н.} = 281.4$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3564		БПО-3569
	$F \text{ см} = 8.73$ $Q \text{ кг.} = 2.37$ $D \text{ оп.мм.} = 173$ $P \text{ н.} = 458.1$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3565		БПО-3570
	$F \text{ см}^2 = 9.53$ $Q \text{ кг.} = 2.583$ $D \text{ оп.мм.} = 191$ $P \text{ н.} = 498.1$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$






	БПО-3571		БПО-3576
	F см ² = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 1.81 Q кг. = 0.491 D оп.мм.= 42 P н. = 222.7 Гр. сл. = V Точн. = П
	БПО-3572		БПО-3577
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 8.34 Q кг. = 2.26 D оп.мм.= 120 P н. = 612 Гр. сл. = IV Точн. = П
	БПО-3573		БПО-3578
	F см = 0.525 Q кг. = 0.142 D оп.мм.= 38 P н. = 81.4 Гр. сл. = III Точн. = П		F см = 4.42 Q кг. = 1.198 D оп.мм.= 130 P н. = 335 Гр. сл. = IV Точн. = П
	БПО-3574		БПО-3579
	F см = 0.334 Q кг. = 0.091 D оп.мм.= 26 P н. = 55.5 Гр. сл. = III Точн. = П		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3575		БПО-3580
	F см ² = 0.93 Q кг. = 0.252 D оп.мм.= 35 P н. = 152.4 Гр. сл. = VI Точн. = П		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0











	БПО-3581		БПО-3586
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 3.242$ $Q \text{ кг.} = 0.878$ $D \text{ оп.мм.} = 64$ $P \text{ н.} = 268.6$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3582		БПО-3587
	$F \text{ см} = 2.31$ $Q \text{ кг.} = 0.626$ $D \text{ оп.мм.} = 58$ $P \text{ н.} = 204$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 1.918$ $Q \text{ кг.} = 0.52$ $D \text{ оп.мм.} = 100$ $P \text{ н.} = 223$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-3583		БПО-3588
	$F \text{ см} = 6.92$ $Q \text{ кг.} = 1.875$ $D \text{ оп.мм.} = 110$ $P \text{ н.} = 455.8$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 2.804$ $Q \text{ кг.} = 0.76$ $D \text{ оп.мм.} = 118$ $P \text{ н.} = 325.1$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-3584		БПО-3589
	$F \text{ см} = 5.676$ $Q \text{ кг.} = 1.538$ $D \text{ оп.мм.} = 84$ $P \text{ н.} = 393.7$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0.773$ $Q \text{ кг.} = 0.209$ $D \text{ оп.мм.} = 41$ $P \text{ н.} = 156.4$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-3585		БПО-3590
	$F \text{ см}^2 = 5.17$ $Q \text{ кг.} = 1.4$ $D \text{ оп.мм.} = 74$ $P \text{ н.} = 358.1$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 1.558$ $Q \text{ кг.} = 0.43$ $D \text{ оп.мм.} = 95$ $P \text{ н.} = 286.6$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$











	БПО-3591 $F \text{ см}^2 = 0.885$ $Q \text{ кг.} = 0.24$ $D \text{ оп.мм.} = 48$ $P \text{ н.} = 178.8$ Гр. сл. = V Точн. = П		БПО-3596 $F \text{ см} = 1.59$ $Q \text{ кг.} = 0.431$ $D \text{ оп.мм.} = 44$ $P \text{ н.} = 173.9$ Гр. сл. = V Точн. = П
	БПО-3592 $F \text{ см} = 0.446$ $Q \text{ кг.} = 0.121$ $D \text{ оп.мм.} = 33.8$ $P \text{ н.} = 76$ Гр. сл. = VI Точн. = П		БПО-3597 $F \text{ см} = 2.276$ $Q \text{ кг.} = 0.617$ $D \text{ оп.мм.} = 69$ $P \text{ н.} = 279.3$ Гр. сл. = VI Точн. = П
	БПО-3593 $F \text{ см} = 0.33$ $Q \text{ кг.} = 0.089$ $D \text{ оп.мм.} = 18$ $P \text{ н.} = 39.2$ Гр. сл. = III Точн. = П		БПО-3058 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3594 $F \text{ см} = 0.873$ $Q \text{ кг.} = 0.237$ $D \text{ оп.мм.} = 64$ $P \text{ н.} = 157.4$ Гр. сл. = V Точн. = П		БПО-3599 $F \text{ см} = 3.006$ $Q \text{ кг.} = 0.815$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 311.5$ Гр. сл. = IV Точн. = П
	БПО-3055 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		БПО-3600 $F \text{ см} = 0.714$ $Q \text{ кг.} = 0.193$ $D \text{ оп.мм.} = 25$ $P \text{ н.} = 85.6$ Гр. сл. = III Точн. = П











	БПО-3601		БПО-3606
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 2.62$ $Q \text{ кг.} = 0.71$ $D \text{ оп.мм.} = 72$ $P \text{ н.} = 223.6$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3602		БПО-3607
	$F \text{ см} = 2.513$ $Q \text{ кг.} = 0.681$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 229.2$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 1.26$ $Q \text{ кг.} = 0.342$ $D \text{ оп.мм.} = 53$ $P \text{ н.} = 152.9$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3603		БПО-3608
	$F \text{ см} = 1.743$ $Q \text{ кг.} = 0.473$ $D \text{ оп.мм.} = 42$ $P \text{ н.} = 179.3$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 2.32$ $Q \text{ кг.} = 0.629$ $D \text{ оп.мм.} = 102$ $P \text{ н.} = 311$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3604		БПО-3609
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 2.346$ $Q \text{ кг.} = 0.636$ $D \text{ оп.мм.} = 105$ $P \text{ н.} = 315$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3605		БПО-3610
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$











	БПО-3611		БПО-3616
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3612		БПО-3617
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3613		БПО-3618
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3614		БПО-3619
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3615		БПО-3620
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 6.816$ $Q \text{ кг.} = 1.847$ $D \text{ оп.мм.} = 71$ $P \text{ н.} = 264.4$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$











	<div>БПО-3621</div> <div><div>Ф см² = 0</div><div>Q кг. = 0</div><div>D оп.мм.= 0</div><div>Р н. = 0</div><div>Гр. сл. = 0</div><div>Точн. = 0</div></div>		<div>БПО-3626</div> <div><div>Ф см = 1.439</div><div>Q кг. = 0.39</div><div>D оп.мм.= 38</div><div>Р н. = 116.4</div><div>Гр. сл. = III</div><div>Точн. = П</div></div>
	<div>БПО-3622</div> <div><div>Ф см = 0</div><div>Q кг. = 0</div><div>D оп.мм.= 0</div><div>Р н. = 0</div><div>Гр. сл. = 0</div><div>Точн. = 0</div></div>		<div>БПО-3627</div> <div><div>Ф см = 1.358</div><div>Q кг. = 0.368</div><div>D оп.мм.= 86</div><div>Р н. = 206.2</div><div>Гр. сл. = VI</div><div>Точн. = П</div></div>
	<div>БПО-3623</div> <div><div>Ф см = 0</div><div>Q кг. = 0</div><div>D оп.мм.= 0</div><div>Р н. = 0</div><div>Гр. сл. = 0</div><div>Точн. = 0</div></div>		<div>БПО-3628</div> <div><div>Ф см = 3.549</div><div>Q кг. = 0.962</div><div>D оп.мм.= 109</div><div>Р н. = 319.1</div><div>Гр. сл. = VI</div><div>Точн. = П</div></div>
	<div>БПО-3624</div> <div><div>Ф см = 0</div><div>Q кг. = 0</div><div>D оп.мм.= 0</div><div>Р н. = 0</div><div>Гр. сл. = 0</div><div>Точн. = 0</div></div>		<div>БПО-3629</div> <div><div>Ф см = 1.849</div><div>Q кг. = 0.501</div><div>D оп.мм.= 60</div><div>Р н. = 236.8</div><div>Гр. сл. = VI</div><div>Точн. = П</div></div>
	<div>БПО-3625</div> <div><div>Ф см² = 0</div><div>Q кг. = 0</div><div>D оп.мм.= 0</div><div>Р н. = 0</div><div>Гр. сл. = 0</div><div>Точн. = 0</div></div>		<div>БПО-3630</div> <div><div>Ф см = 2.118</div><div>Q кг. = 0.574</div><div>D оп.мм.= 73</div><div>Р н. = 272.5</div><div>Гр. сл. = VI</div><div>Точн. = П</div></div>







	<p>БПО-3631</p> <p> $F \text{ см}^2 = 2.24$ $Q \text{ кг.} = 0.607$ $D \text{ оп.мм.} = 76$ $P \text{ н.} = 288.4$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3636</p> <p> $F \text{ см} = 5.177$ $Q \text{ кг.} = 1.403$ $D \text{ оп.мм.} = 161$ $P \text{ н.} = 520.1$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3632</p> <p> $F \text{ см} = 2.36$ $Q \text{ кг.} = 0.64$ $D \text{ оп.мм.} = 79$ $P \text{ н.} = 304$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3637</p> <p> $F \text{ см} = 5.402$ $Q \text{ кг.} = 1.464$ $D \text{ оп.мм.} = 139$ $P \text{ н.} = 541.9$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3633</p> <p> $F \text{ см} = 2.601$ $Q \text{ кг.} = 0.705$ $D \text{ оп.мм.} = 82$ $P \text{ н.} = 337.7$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3638</p> <p> $F \text{ см} = 0.597$ $Q \text{ кг.} = 0.162$ $D \text{ оп.мм.} = 35$ $P \text{ н.} = 100.5$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3634</p> <p> $F \text{ см} = 3.521$ $Q \text{ кг.} = 0.954$ $D \text{ оп.мм.} = 55$ $P \text{ н.} = 215.9$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3639</p> <p> $F \text{ см} = 1.16$ $Q \text{ кг.} = 0.314$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 157.2$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3635</p> <p> $F \text{ см}^2 = 4.483$ $Q \text{ кг.} = 1.215$ $D \text{ оп.мм.} = 69$ $P \text{ н.} = 161.6$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3640</p> <p> $F \text{ см} = 0.276$ $Q \text{ кг.} = 0.075$ $D \text{ оп.мм.} = 11$ $P \text{ н.} = 30$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>





	<p>БПО-3641</p> <p> $F \text{ см}^2 = 1.218$ $Q \text{ кг.} = 0.33$ $D \text{ оп.мм.} = 21$ $P \text{ н.} = 88.7$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>		<p>БПО-3646</p> <p> $F \text{ см} = 2.398$ $Q \text{ кг.} = 0.65$ $D \text{ оп.мм.} = 80$ $P \text{ н.} = 224.3$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$ </p>
	<p>БПО-3642</p> <p> $F \text{ см} = 0.562$ $Q \text{ кг.} = 0.152$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 93.6$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>		<p>БПО-3647</p> <p> $F \text{ см} = 1.82$ $Q \text{ кг.} = 0.493$ $D \text{ оп.мм.} = 82$ $P \text{ н.} = 237$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$ </p>
	<p>БПО-3643</p> <p> $F \text{ см} = 0.913$ $Q \text{ кг.} = 0.247$ $D \text{ оп.мм.} = 49$ $P \text{ н.} = 155.8$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>		<p>БПО-3648</p> <p> $F \text{ см} = 1.931$ $Q \text{ кг.} = 0.523$ $D \text{ оп.мм.} = 61$ $P \text{ н.} = 194$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$ </p>
	<p>БПО-3644</p> <p> $F \text{ см} = 4.036$ $Q \text{ кг.} = 1.09$ $D \text{ оп.мм.} = 135$ $P \text{ н.} = 451.7$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = \text{Особой}$ </p>		<p>БПО-3649</p> <p> $F \text{ см} = 2.561$ $Q \text{ кг.} = 0.694$ $D \text{ оп.мм.} = 59$ $P \text{ н.} = 271.4$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>
	<p>БПО-3645</p> <p> $F \text{ см}^2 = 6.99$ $Q \text{ кг.} = 1.894$ $D \text{ оп.мм.} = 179$ $P \text{ н.} = 579$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = \text{Особая}$ </p>		<p>БПО-3650</p> <p> $F \text{ см} = 1.204$ $Q \text{ кг.} = 0.326$ $D \text{ оп.мм.} = 42$ $P \text{ н.} = 171$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$ </p>









	<p>БПО-3651</p> <p> $F \text{ см}^2 = 2.83$ $Q \text{ кг.} = 0.767$ $D \text{ оп.мм.} = 135$ $P \text{ н.} = 404.6$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3656</p> <p> $F \text{ см} = 0.584$ $Q \text{ кг.} = 0.158$ $D \text{ оп.мм.} = 17$ $P \text{ н.} = 74.1$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p>
	<p>БПО-3652</p> <p> $F \text{ см} = 0.587$ $Q \text{ кг.} = 0.159$ $D \text{ оп.мм.} = 21$ $P \text{ н.} = 83.8$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3657</p> <p> $F \text{ см} = 1.301$ $Q \text{ кг.} = 0.353$ $D \text{ оп.мм.} = 33$ $P \text{ н.} = 111.3$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3653</p> <p> $F \text{ см} = 2.27$ $Q \text{ кг.} = 0.615$ $D \text{ оп.мм.} = 53$ $P \text{ н.} = 292.3$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3658</p> <p> $F \text{ см} = 14.98$ $Q \text{ кг.} = 4.06$ $D \text{ оп.мм.} = 166$ $P \text{ н.} = 490.3$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3654</p> <p> $F \text{ см} = 1.01$ $Q \text{ кг.} = 0.274$ $D \text{ оп.мм.} = 59$ $P \text{ н.} = 165.7$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3659</p> <p> $F \text{ см} = 1.026$ $Q \text{ кг.} = 0.278$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 164$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3655</p> <p> $F \text{ см}^2 = 0.959$ $Q \text{ кг.} = 0.26$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 162.6$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3660</p> <p> $F \text{ см} = 0.77$ $Q \text{ кг.} = 0.209$ $D \text{ оп.мм.} = 26$ $P \text{ н.} = 120.8$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>










	БПО-3671 $F \text{ см}^2 = 1.291$ $Q \text{ кг.} = 0.35$ $D \text{ оп.мм.} = 383$ $P \text{ н.} = 172.1$ Гр. сл. = VI Точн. = особая		БПО-3676 $F \text{ см} = 3.755$ $Q \text{ кг.} = 1.02$ $D \text{ оп.мм.} = 145$ $P \text{ н.} = 351.3$ Гр. сл. = V Точн. = П
	БПО-3672 $F \text{ см} = 2.37$ $Q \text{ кг.} = 0.642$ $D \text{ оп.мм.} = 75$ $P \text{ н.} = 211.1$ Гр. сл. = V Точн. = П		БПО-3677 $F \text{ см} = 0.684$ $Q \text{ кг.} = 0.185$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 92$ Гр. сл. = V Точн. = П
	БПО-3673 $F \text{ см} = 1.385$ $Q \text{ кг.} = 0.375$ $D \text{ оп.мм.} = 35$ $P \text{ н.} = 153.4$ Гр. сл. = V Точн. = П		БПО-3678 $F \text{ см} = 1.684$ $Q \text{ кг.} = 0.456$ $D \text{ оп.мм.} = 48$ $P \text{ н.} = 219.2$ Гр. сл. = V Точн. = П
	БПО-3674 $F \text{ см} = 9.038$ $Q \text{ кг.} = 2.45$ $D \text{ оп.мм.} = 67$ $P \text{ н.} = 282.2$ Гр. сл. = IV Точн. = П		БПО-3679 $F \text{ см} = 3.219$ $Q \text{ кг.} = 0.872$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 173$ Гр. сл. = III Точн. = П
	БПО-3675 $F \text{ см}^2 = 6.803$ $Q \text{ кг.} = 1.84$ $D \text{ оп.мм.} = 63$ $P \text{ н.} = 264.9$ Гр. сл. = VI Точн. = П		БПО-3680 $F \text{ см} = 1.969$ $Q \text{ кг.} = 0.534$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 118.9$ Гр. сл. = IV Точн. = П





	<p>БПО-3681</p> <p> $F \text{ см}^2 = 1.33$ $Q \text{ кг.} = 0.36$ $D \text{ оп.мм.} = 18$ $P \text{ н.} = 46.9$ $\Gamma \text{ р. сл.} = \text{II}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3686</p> <p> $F \text{ см} = 1.852$ $Q \text{ кг.} = 0.502$ $D \text{ оп.мм.} = 54$ $P \text{ н.} = 230.8$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3682</p> <p> $F \text{ см} = 4.19$ $Q \text{ кг.} = 1.135$ $D \text{ оп.мм.} = 41$ $P \text{ н.} = 186.7$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3687</p> <p> $F \text{ см} = 3.8$ $Q \text{ кг.} = 1.03$ $D \text{ оп.мм.} = 182$ $P \text{ н.} = 390$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3683</p> <p> $F \text{ см} = 8.55$ $Q \text{ кг.} = 2.317$ $D \text{ оп.мм.} = 150$ $P \text{ н.} = 623.9$ $\Gamma \text{ р. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3688</p> <p> $F \text{ см} = 2.783$ $Q \text{ кг.} = 0.754$ $D \text{ оп.мм.} = 28$ $P \text{ н.} = 106.8$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3684</p> <p> $F \text{ см} = 1.514$ $Q \text{ кг.} = 0.411$ $D \text{ оп.мм.} = 73$ $P \text{ н.} = 235.3$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3689</p> <p> $F \text{ см} = 0.55$ $Q \text{ кг.} = 0.149$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 90.3$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3685</p> <p> $F \text{ см}^2 = 0.709$ $Q \text{ кг.} = 0.191$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 99$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3690</p> <p> $F \text{ см} = 1.45$ $Q \text{ кг.} = 0.393$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 132.7$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>





	БПО-3691		БПО-3696
	<p> $F \text{ см}^2 = 2.641$ $Q \text{ кг.} = 0.716$ $D \text{ оп.мм.} = 112$ $P \text{ н.} = 302.1$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>		<p> $F \text{ см} = 2.934$ $Q \text{ кг.} = 0.795$ $D \text{ оп.мм.} = 140$ $P \text{ н.} = 323.4$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$ </p>
	БПО-3692		БПО-3697
	<p> $F \text{ см} = 15.48$ $Q \text{ кг.} = 4.195$ $D \text{ оп.мм.} = 87$ $P \text{ н.} = 278.5$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$ </p>		<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>
	БПО-3693		БПО-3698
	<p> $F \text{ см} = 0.52$ $Q \text{ кг.} = 0.141$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 106$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$ </p>		<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>
	БПО-3694		БПО-3699
	<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p> $F \text{ см} = 0.629$ $Q \text{ кг.} = 0.17$ $D \text{ оп.мм.} = 11$ $P \text{ н.} = 86.2$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>
	БПО-3695		БПО-3700
	<p> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p> $F \text{ см} = 0.765$ $Q \text{ кг.} = 0.207$ $D \text{ оп.мм.} = 21$ $P \text{ н.} = 113$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>



	БПО-3701		БПО-3706
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3702		БПО-3707
	$F \text{ см} = 2.941$ $Q \text{ кг.} = 0.797$ $D \text{ оп.мм.} = 39$ $P \text{ н.} = 107.1$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 24.32$ $Q \text{ кг.} = 6.59$ $D \text{ оп.мм.} = 179$ $P \text{ н.} = 624$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$
	БПО-3703		БПО-3708
	$F \text{ см} = 3.475$ $Q \text{ кг.} = 0.942$ $D \text{ оп.мм.} = 47$ $P \text{ н.} = 138$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 1.373$ $Q \text{ кг.} = 0.372$ $D \text{ оп.мм.} = 53$ $P \text{ н.} = 137.6$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$
	БПО-3704		БПО-3709
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3705		БПО-3710
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$









	БПО-3711		БПО-3716
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 1.157$ $Q \text{ кг.} = 0.314$ $D \text{ оп.мм.} = 15$ $P \text{ н.} = 50.5$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{П}$
	БПО-3712		БПО-3717
	$F \text{ см} = 2.15$ $Q \text{ кг.} = 0.583$ $D \text{ оп.мм.} = 55$ $P \text{ н.} = 252$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0.655$ $Q \text{ кг.} = 0.178$ $D \text{ оп.мм.} = 19$ $P \text{ н.} = 69.9$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3713		БПО-3718
	$F \text{ см} = 1.694$ $Q \text{ кг.} = 0.459$ $D \text{ оп.мм.} = 44$ $P \text{ н.} = 133.5$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 2.7$ $Q \text{ кг.} = 0.732$ $D \text{ оп.мм.} = 78$ $P \text{ н.} = 269.7$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-3714		БПО-3719
	$F \text{ см} = 1.23$ $Q \text{ кг.} = 0.337$ $D \text{ оп.мм.} = 23$ $P \text{ н.} = 94.4$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 2.06$ $Q \text{ кг.} = 0.558$ $D \text{ оп.мм.} = 31.5$ $P \text{ н.} = 113.2$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-3715		БПО-3720
	$F \text{ см}^2 = 0.58$ $Q \text{ кг.} = 0.157$ $D \text{ оп.мм.} = 18.5$ $P \text{ н.} = 60.4$ $\text{Гр. сл.} = \text{II}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$










	<p>БПО-3721</p> <p> $F \text{ см}^2 = 1.108$ $Q \text{ кг.} = 0.3$ $D \text{ оп.мм.} = 76$ $P \text{ н.} = 162.3$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3726</p> <p> $F \text{ см} = 1.162$ $Q \text{ кг.} = 0.315$ $D \text{ оп.мм.} = 28$ $P \text{ н.} = 137.8$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-3722</p> <p> $F \text{ см} = 1.17$ $Q \text{ кг.} = 0.318$ $D \text{ оп.мм.} = 76$ $P \text{ н.} = 167.1$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3727</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-3723</p> <p> $F \text{ см} = 1.31$ $Q \text{ кг.} = 0.355$ $D \text{ оп.мм.} = 34.5$ $P \text{ н.} = 179.6$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3728</p> <p> $F \text{ см} = 2.31$ $Q \text{ кг.} = 0.626$ $D \text{ оп.мм.} = 83$ $P \text{ н.} = 311$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-3724</p> <p> $F \text{ см} = 2.494$ $Q \text{ кг.} = 0.677$ $D \text{ оп.мм.} = 87$ $P \text{ н.} = 386.2$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3729</p> <p> $F \text{ см} = 1.602$ $Q \text{ кг.} = 0.434$ $D \text{ оп.мм.} = 25$ $P \text{ н.} = 112.5$ Гр. сл. = VI Точн. = П </p>
	<p>БПО-3725</p> <p> $F \text{ см}^2 = 1.283$ $Q \text{ кг.} = 0.348$ $D \text{ оп.мм.} = 59.8$ $P \text{ н.} = 215.2$ Гр. сл. = VI Точн. = П </p>		<p>БПО-3730</p> <p> $F \text{ см} = 5.236$ $Q \text{ кг.} = 1.42$ $D \text{ оп.мм.} = 162$ $P \text{ н.} = 494.8$ Гр. сл. = VI Точн. = П </p>









	БПО-3731		БПО-3736
	F см ² = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 2.07 Q кг. = 0.561 D оп.мм.= 38 P н. = 141 Гр. сл. = V Точн. = П
	БПО-3732		БПО-3737
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 3.955 Q кг. = 1.072 D оп.мм.= 52 P н. = 185 Гр. сл. = V Точн. = П
	БПО-3733		БПО-3738
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 2.335 Q кг. = 0.633 D оп.мм.= 29 P н. = 141.8 Гр. сл. = V Точн. = П
	БПО-3734		БПО-3739
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 1.82 Q кг. = 0.493 D оп.мм.= 37 P н. = 118 Гр. сл. = IV Точн. = П
	БПО-3735		БПО-3740
	F см ² = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0



	БПО-3741		БПО-3746
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3742		БПО-3747
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 1.775$ $Q \text{ кг.} = 0.481$ $D \text{ оп.мм.} = 61$ $P \text{ н.} = 220.1$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3743		БПО-3748
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3744		БПО-3749
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 1.51$ $Q \text{ кг.} = 0.4$ $D \text{ оп.мм.} = 48$ $P \text{ н.} = 168$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
	БПО-3745		БПО-3750
	$F \text{ см}^2 = 2.338$ $Q \text{ кг.} = 0.634$ $D \text{ оп.мм.} = 52$ $P \text{ н.} = 226.4$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 2.1$ $Q \text{ кг.} = 0.569$ $D \text{ оп.мм.} = 27$ $P \text{ н.} = 71.6$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$

	БПО-3751		БПО-3756
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3752		БПО-3757
	$F \text{ см} = 5.902$ $Q \text{ кг.} = 1.6$ $D \text{ оп.мм.} = 61$ $P \text{ н.} = 159.2$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3753		БПО-3758
	$F \text{ см} = 17$ $Q \text{ кг.} = 4.607$ $D \text{ оп.мм.} = 67$ $P \text{ н.} = 190$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3754		БПО-3759
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3755		БПО-3760
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$

	БПО-3761		БПО-3766
	$F \text{ см}^2 = 0.729$ $Q \text{ кг.} = 0.198$ $D \text{ оп.мм.} = 20$ $P \text{ н.} = 83.1$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3762		БПО-3767
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 1.999$ $Q \text{ кг.} = 0.542$ $D \text{ оп.мм.} = 64$ $P \text{ н.} = 203.1$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{особая}$
	БПО-3763		БПО-3768
	$F \text{ см} = 0.565$ $Q \text{ кг.} = 0.153$ $D \text{ оп.мм.} = 20$ $P \text{ н.} = 48.4$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 8.33$ $Q \text{ кг.} = 2.26$ $D \text{ оп.мм.} = 98$ $P \text{ н.} = 374.9$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{особая}$
	БПО-3764		БПО-3769
	$F \text{ см} = 0.275$ $Q \text{ кг.} = 0.075$ $D \text{ оп.мм.} = 17$ $P \text{ н.} = 48$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0.82$ $Q \text{ кг.} = 0.222$ $D \text{ оп.мм.} = 20$ $P \text{ н.} = 82.7$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3765		БПО-3770
	$F \text{ см}^2 = 2.56$ $Q \text{ кг.} = 0.694$ $D \text{ оп.мм.} = 21$ $P \text{ н.} = 211$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 3.873$ $Q \text{ кг.} = 1.05$ $D \text{ оп.мм.} = 100$ $P \text{ н.} = 389.8$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{особая}$





	БПО-3771 $F \text{ см}^2 = 2.661$ $Q \text{ кг.} = 0.721$ $D \text{ оп.мм.} = 39$ $P \text{ н.} = 246.8$ Гр. сл. = VI Точн. = П		БПО-3776 $F \text{ см} = 10.55$ $Q \text{ кг.} = 2.859$ $D \text{ оп.мм.} = 105$ $P \text{ н.} = 556.5$ Гр. сл. = VI Точн. = П
	БПО-3772 $F \text{ см} = 3.335$ $Q \text{ кг.} = 0.904$ $D \text{ оп.мм.} = 53$ $P \text{ н.} = 169.8$ Гр. сл. = IV Точн. = П		БПО-3777 $F \text{ см} = 4.818$ $Q \text{ кг.} = 1.306$ $D \text{ оп.мм.} = 133$ $P \text{ н.} = 529.7$ Гр. сл. = особая Точн. = П
	БПО-3773 $F \text{ см} = 2.67$ $Q \text{ кг.} = 0.724$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 344.4$ Гр. сл. = VI Точн. = П		БПО-3778 $F \text{ см} = 7.661$ $Q \text{ кг.} = 2.076$ $D \text{ оп.мм.} = 144$ $P \text{ н.} = 412$ Гр. сл. = VI Точн. = П
	БПО-3774 $F \text{ см} = 1.273$ $Q \text{ кг.} = 0.345$ $D \text{ оп.мм.} = 21$ $P \text{ н.} = 116.2$ Гр. сл. = IV Точн. = П		БПО-3779 $F \text{ см} = 1.67$ $Q \text{ кг.} = 0.453$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 180.5$ Гр. сл. = VI Точн. = П
	БПО-3775 $F \text{ см}^2 = 1.67$ $Q \text{ кг.} = 0.453$ $D \text{ оп.мм.} = 44$ $P \text{ н.} = 187$ Гр. сл. = особая Точн. = П		БПО-3780 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0








	БПО-3781 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		БПО-3786 $F \text{ см} = 0.548$ $Q \text{ кг.} = 0.149$ $D \text{ оп.мм.} = 19$ $P \text{ н.} = 43.7$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{П}$
	БПО-3782 $F \text{ см} = 1.768$ $Q \text{ кг.} = 0.48$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 240.4$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		БПО-3787 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3783 $F \text{ см} = 0.845$ $Q \text{ кг.} = 0.229$ $D \text{ оп.мм.} = 33$ $P \text{ н.} = 116.6$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		БПО-3788 $F \text{ см} = 0.269$ $Q \text{ кг.} = 0.073$ $D \text{ оп.мм.} = 11$ $P \text{ н.} = 29.6$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	БПО-3784 $F \text{ см} = 1.723$ $Q \text{ кг.} = 0.467$ $D \text{ оп.мм.} = 52$ $P \text{ н.} = 249.1$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		БПО-3789 $F \text{ см} = 1.119$ $Q \text{ кг.} = 0.303$ $D \text{ оп.мм.} = 22$ $P \text{ н.} = 93.5$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3785 $F \text{ см}^2 = 1.696$ $Q \text{ кг.} = 0.46$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 207$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		БПО-3790 $F \text{ см} = 1.479$ $Q \text{ кг.} = 0.401$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 203.8$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$





	БПО-3791		БПО-3796
	F см ² = 0.678 Q кг. = 0.184 D оп.мм.= 42 P н. = 103 Гр. сл. = V Точн. = П		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3792		БПО-3797
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3793		БПО-3798
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3794		БПО-3799
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3795		БПО-3800
	F см ² = 2.235 Q кг. = 0.606 D оп.мм.= 70 P н. = 328.2 Гр. сл. = особая Точн. = П		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0


	БПО-3801		БПО-3806
	F см ² = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3802		БПО-3807
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3803		БПО-3808
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3804		БПО-3809
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3805		БПО-3810
	F см ² = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0








	БПО-3811		БПО-3816
	F см ² = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3812		БПО-3817
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3813		БПО-3818
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3814		БПО-3819
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3815		БПО-3820
	F см ² = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0


	БПО-3821		БПО-3826
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 3.331$ $Q \text{ кг.} = 0.903$ $D \text{ оп.мм.} = 151$ $P \text{ н.} = 377.2$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$
	БПО-3822		БПО-3827
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 7$ $Q \text{ кг.} = 1.897$ $D \text{ оп.мм.} = 116$ $P \text{ н.} = 290$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = Н$
	БПО-3823		БПО-3828
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.6$ $Q \text{ кг.} = 0.163$ $D \text{ оп.мм.} = 26$ $P \text{ н.} = 64$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = П$
	БПО-3824		БПО-3829
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3825		БПО-3830
	$F \text{ см}^2 = 3.79$ $Q \text{ кг.} = 1.03$ $D \text{ оп.мм.} = 151$ $P \text{ н.} = 416.5$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$

	БПО-3831 $F \text{ см}^2 = 4.529$ $Q \text{ кг.} = 1.227$ $D \text{ оп.мм.} = 141$ $P \text{ н.} = 341.2$ Гр. сл. = VI Точн. = П		БПО-3836 $F \text{ см} = 0.771$ $Q \text{ кг.} = 0.209$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 144.7$ Гр. сл. = VI Точн. = Н
	БПО-3832 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		БПО-3837 $F \text{ см} = 0.846$ $Q \text{ кг.} = 0.229$ $D \text{ оп.мм.} = 42$ $P \text{ н.} = 152.1$ Гр. сл. = VI Точн. = Н
	БПО-3833 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		БПО-3838 $F \text{ см} = 0.881$ $Q \text{ кг.} = 0.239$ $D \text{ оп.мм.} = 31$ $P \text{ н.} = 155.2$ Гр. сл. = VI Точн. = Н
	БПО-3834 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		БПО-3839 $F \text{ см} = 1.093$ $Q \text{ кг.} = 0.297$ $D \text{ оп.мм.} = 58$ $P \text{ н.} = 161.8$ Гр. сл. = VI Точн. = П
	БПО-3835 $F \text{ см}^2 = 1.215$ $Q \text{ кг.} = 0.329$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 178$ Гр. сл. = VI Точн. = П		БПО-3840 $F \text{ см} = 2.01$ $Q \text{ кг.} = 0.55$ $D \text{ оп.мм.} = 61$ $P \text{ н.} = 261.8$ Гр. сл. = особая Точн. = П


	БПО-3841		БПО-3846
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 1.889$ $Q \text{ кг.} = 0.512$ $D \text{ оп.мм.} = 41$ $P \text{ н.} = 132.6$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3842		БПО-3847
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.458$ $Q \text{ кг.} = 0.124$ $D \text{ оп.мм.} = 24$ $P \text{ н.} = 86$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{Н}$
	БПО-3843		БПО-3848
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 12.254$ $Q \text{ кг.} = 3.321$ $D \text{ оп.мм.} = 147$ $P \text{ н.} = 498.9$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$
	БПО-3844		БПО-3849
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3845		БПО-3850
	$F \text{ см}^2 = 16.48$ $Q \text{ кг.} = 4.47$ $D \text{ оп.мм.} = 181$ $P \text{ н.} = 577.5$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{Н}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$






	БПО-3851		БПО-3856
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3852		БПО-3857
	$F \text{ см} = 0.9$ $Q \text{ кг.} = 0.244$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 123$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3853		БПО-3858
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3854		БПО-3859
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3855		БПО-3860
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$






	БПО-3861		БПО-3866
	F см ² = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 3.2 Q кг. = 0.867 D оп.мм.= 38 P н. = 111.1 Гр. сл. = III Точн. = П
	БПО-3862		БПО-3867
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 3.77 Q кг. = 1.02 D оп.мм.= 58 P н. = 191.4 Гр. сл. = V Точн. = П
	БПО-3863		БПО-3868
	F см = 5.12 Q кг. = 1.39 D оп.мм.= 107 P н. = 309.8 Гр. сл. = VI Точн. = П		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3864		БПО-3869
	F см = 0.858 Q кг. = 0.233 D оп.мм.= 49 P н. = 137.6 Гр. сл. = VI Точн. = П		F см = 0.643 Q кг. = 0.174 D оп.мм.= 22 P н. = 80 Гр. сл. = VI Точн. = П
	БПО-3865		БПО-3870
	F см ² = 4.75 Q кг. = 1.29 D оп.мм.= 46 P н. = 133.2 Гр. сл. = III Точн. = П		F см = 0.416 Q кг. = 0.113 D оп.мм.= 12 P н. = 45.1 Гр. сл. = особая Точн. = Н






	БПО-3871		БПО-3876
	F см ² = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3872		БПО-3877
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3873		БПО-3878
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3874		БПО-3879
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3875		БПО-3880
	F см ² = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 3.634 Q кз. = 0.985 D оп.мм.= 74 P н. = 314.9 Гр. сл. = VI Точн. = П

	БПО-3881		БПО-3886
	F см ² = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3882		БПО-3887
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3883		БПО-3888
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3884		БПО-3889
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3885		БПО-3890
	F см ² = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0





	БПО-3891		БПО-3896
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3892		БПО-3897
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3893		БПО-3898
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3894		БПО-3899
	$F \text{ см} = 13.42$ $Q \text{ кг.} = 3.64$ $D \text{ оп.мм.} = 173$ $P \text{ н.} = 1139$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \Pi$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3895		БПО-3900
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$









	БПО-3901 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		БПО-3906 $F \text{ см} = 2.6$ $Q \text{ кг.} = 0.705$ $D \text{ оп.мм.} = 72$ $P \text{ н.} = 313.6$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3902 $F \text{ см} = 0.526$ $Q \text{ кг.} = 0.143$ $D \text{ оп.мм.} = 28$ $P \text{ н.} = 90$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		БПО-3907 $F \text{ см} = 2.28$ $Q \text{ кг.} = 0.618$ $D \text{ оп.мм.} = 65$ $P \text{ н.} = 257.3$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3903 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		БПО-3908 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3904 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		БПО-3909 $F \text{ см} = 2.03$ $Q \text{ кг.} = 0.55$ $D \text{ оп.мм.} = 51$ $P \text{ н.} = 151.1$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-3905 $F \text{ см}^2 = 2.722$ $Q \text{ кг.} = 0.738$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 242.8$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \text{Н}$		БПО-3910 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$









	БПО-3911		БПО-3916
	F см ² = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0.782 Q кг. = 0.212 D оп.мм.= 51 P н. = 143.2 Гр. сл. = VI Точн. = П
	БПО-3912		БПО-3917
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3913		БПО-3918
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0.639 Q кг. = 0.173 D оп.мм.= 31 P н. = 86.5 Гр. сл. = VI Точн. = П
	БПО-3914		БПО-3919
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0.59 Q кг. = 0.16 D оп.мм.= 31 P н. = 96.4 Гр. сл. = VI Точн. = П
	БПО-3915		БПО-3920
	F см ² = 0.228 Q кг. = 0.062 D оп.мм.= 15 P н. = 40.4 Гр. сл. = особая Точн. = П		F см = 25.11 Q кг. = 6.81 D оп.мм.= 184 P н. = 880.5 Гр. сл. = VI Точн. = П






	БПО-3921		БПО-3926
	$F \text{ см}^2 = 1.956$ $Q \text{ кг.} = 0.53$ $D \text{ оп.мм.} = 38$ $P \text{ н.} = 178$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3922		БПО-3927
	$F \text{ см} = 3.424$ $Q \text{ кг.} = 0.928$ $D \text{ оп.мм.} = 63$ $P \text{ н.} = 174.8$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3923		БПО-3928
	$F \text{ см} = 2.381$ $Q \text{ кг.} = 0.645$ $D \text{ оп.мм.} = 77$ $P \text{ н.} = 325.5$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3924		БПО-3929
	$F \text{ см} = 1.303$ $Q \text{ кг.} = 0.353$ $D \text{ оп.мм.} = 82$ $P \text{ н.} = 182.7$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3925		БПО-3930
	$F \text{ см}^2 = 0.686$ $Q \text{ кг.} = 0.186$ $D \text{ оп.мм.} = 41$ $P \text{ н.} = 89$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$








	БПО-3931		БПО-3936
	F см ² = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3932		БПО-3937
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3933		БПО-3938
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3934		БПО-3939
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-3935		БПО-3940
	F см ² = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0







	БПО-3941		БПО-3946
	$F \text{ см}^2 = 1.425$ $Q \text{ кг.} = 0.386$ $D \text{ оп.мм.} = 55$ $P \text{ н.} = 130.5$ Гр. сл. = VI Точн. = П		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3942		БПО-3947
	$F \text{ см} = 3.258$ $Q \text{ кг.} = 0.883$ $D \text{ оп.мм.} = 90$ $P \text{ н.} = 386.1$ Гр. сл. = V Точн. = П		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3943		БПО-3948
	$F \text{ см} = 3.905$ $Q \text{ кг.} = 1.058$ $D \text{ оп.мм.} = 82$ $P \text{ н.} = 456.8$ Гр. сл. = V Точн. = П		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-3944		БПО-3949
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		$F \text{ см} = 1$ $Q \text{ кг.} = 0.271$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 110.3$ Гр. сл. = IV Точн. = П
	БПО-3945		БПО-3950
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0











	<p>БПО-3951</p> <p> $F \text{ см}^2 = 12.31$ $Q \text{ кг.} = 3.336$ $D \text{ оп.мм.} = 178$ $P \text{ н.} = 420$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3956</p> <p> $F \text{ см} = 0.372$ $Q \text{ кг.} = 0.1$ $D \text{ оп.мм.} = 18$ $P \text{ н.} = 45.1$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3952</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3957</p> <p> $F \text{ см} = 4.193$ $Q \text{ кг.} = 1.136$ $D \text{ оп.мм.} = 137$ $P \text{ н.} = 446.5$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3953</p> <p> $F \text{ см} = 2.36$ $Q \text{ кг.} = 0.64$ $D \text{ оп.мм.} = 28$ $P \text{ н.} = 203.7$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3958</p> <p> $F \text{ см} = 0.376$ $Q \text{ кг.} = 0.102$ $D \text{ оп.мм.} = 10$ $P \text{ н.} = 41.1$ $\text{Гр. сл.} = 0$ $\text{Точн.} = \text{H}$ </p>
	<p>БПО-3954</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3959</p> <p> $F \text{ см} = 1.01$ $Q \text{ кг.} = 0.274$ $D \text{ оп.мм.} = 46$ $P \text{ н.} = 142.8$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-3955</p> <p> $F \text{ см}^2 = 4.948$ $Q \text{ кг.} = 1.341$ $D \text{ оп.мм.} = 139$ $P \text{ н.} = 520.8$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-3960</p> <p> $F \text{ см} = 3.303$ $Q \text{ кг.} = 0.895$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 246.3$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>





	<p>БПО-3961</p> <p> $F \text{ см}^2 = 1.768$ $Q \text{ кг.} = 0.479$ $D \text{ оп.мм.} = 46$ $P \text{ н.} = 164.6$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$ </p>		<p>БПО-3966</p> <p> $F \text{ см} = 0.316$ $Q \text{ кг.} = 0.086$ $D \text{ оп.мм.} = 21.5$ $P \text{ н.} = 45.2$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = П$ </p>
	<p>БПО-3962</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3967</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$ </p>
	<p>БПО-3963</p> <p> $F \text{ см} = 0.72$ $Q \text{ кг.} = 0.195$ $D \text{ оп.мм.} = 26$ $P \text{ н.} = 107.7$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = H$ </p>		<p>БПО-3968</p> <p> $F \text{ см} = 9.11$ $Q \text{ кг.} = 2.47$ $D \text{ оп.мм.} = 140$ $P \text{ н.} = 602.5$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$ </p>
	<p>БПО-3964</p> <p> $F \text{ см} = 7.117$ $Q \text{ кг.} = 1.929$ $D \text{ оп.мм.} = 149$ $P \text{ н.} = 790.6$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$ </p>		<p>БПО-3969</p> <p> $F \text{ см} = 1.705$ $Q \text{ кг.} = 0.462$ $D \text{ оп.мм.} = 80$ $P \text{ н.} = 170.3$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = П$ </p>
	<p>БПО-3965</p> <p> $F \text{ см}^2 = 0.384$ $Q \text{ кг.} = 0.104$ $D \text{ оп.мм.} = 26$ $P \text{ н.} = 54.2$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = П$ </p>		<p>БПО-3970</p> <p> $F \text{ см} = 7.246$ $Q \text{ кг.} = 1.964$ $D \text{ оп.мм.} = 46$ $P \text{ н.} = 140.8$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = H$ </p>






	БПО-3971 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		БПО-3976 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3972 $F \text{ см} = 2.05$ $Q \text{ кг.} = 0.56$ $D \text{ оп.мм.} = 49$ $P \text{ н.} = 156$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3977 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3973 $F \text{ см} = 1.233$ $Q \text{ кг.} = 0.334$ $D \text{ оп.мм.} = 46$ $P \text{ н.} = 155$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$		БПО-3978 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3974 $F \text{ см} = 0.892$ $Q \text{ кг.} = 0.242$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 141$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		БПО-3979 $F \text{ см} = 1.26$ $Q \text{ кг.} = 0.341$ $D \text{ оп.мм.} = 34$ $P \text{ н.} = 130$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПО-3975 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		БПО-3980 $F \text{ см} = 2.341$ $Q \text{ кг.} = 0.634$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 214.1$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$










	БПО-3981 $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		БПО-3986 $F \text{ см} = 2.228$ $Q \text{ кг.} = 0.604$ $D \text{ оп.мм.} = 41$ $P \text{ н.} = 156.8$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-3982 $F \text{ см} = 4.74$ $Q \text{ кг.} = 1.285$ $D \text{ оп.мм.} = 65$ $P \text{ н.} = 322.6$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3987 $F \text{ см} = 1.588$ $Q \text{ кг.} = 0.43$ $D \text{ оп.мм.} = 64$ $P \text{ н.} = 180$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
	БПО-3983 $F \text{ см} = 3.201$ $Q \text{ кг.} = 0.868$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 246$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3988 $F \text{ см} = 2.308$ $Q \text{ кг.} = 0.625$ $D \text{ оп.мм.} = 83$ $P \text{ н.} = 260$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
	БПО-3984 $F \text{ см} = 2.12$ $Q \text{ кг.} = 0.575$ $D \text{ оп.мм.} = 51$ $P \text{ н.} = 278.1$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = \text{П}$		БПО-3989 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-3985 $F \text{ см}^2 = 1.433$ $Q \text{ кг.} = 0.388$ $D \text{ оп.мм.} = 44$ $P \text{ н.} = 109.6$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		БПО-3990 $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$









	<p>БПО-3991</p> <p> $F \text{ см}^2 = 1.347$ $Q \text{ кг.} = 0.365$ $D \text{ оп.мм.} = 29$ $P \text{ н.} = 107.6$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$ </p>		<p>БПО-3996</p> <p> $F \text{ см} = 4.643$ $Q \text{ кг.} = 1.258$ $D \text{ оп.мм.} = 118$ $P \text{ н.} = 340.6$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = П$ </p>
	<p>БПО-3992</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3997</p> <p> $F \text{ см} = 8.726$ $Q \text{ кг.} = 2.365$ $D \text{ оп.мм.} = 173$ $P \text{ н.} = 492.1$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = П$ </p>
	<p>БПО-3993</p> <p> $F \text{ см} = 3.89$ $Q \text{ кг.} = 1.054$ $D \text{ оп.мм.} = 137$ $P \text{ н.} = 407.2$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$ </p>		<p>БПО-3998</p> <p> $F \text{ см} = 4.565$ $Q \text{ кг.} = 1.237$ $D \text{ оп.мм.} = 62$ $P \text{ н.} = 132.4$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = Н$ </p>
	<p>БПО-3994</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-3999</p> <p> $F \text{ см} = 6.635$ $Q \text{ кг.} = 1.798$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 137.1$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = Н$ </p>
	<p>БПО-3995</p> <p> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-4000</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$ </p>







	<p>БПО-4001</p> <p> $F \text{ см}^2 = 0.514$ $Q \text{ кг.} = 0.139$ $D \text{ оп.мм.} = 15$ $P \text{ н.} = 62.9$ Гр. сл. = IV Точн. = Н </p>		<p>БПО-4006</p> <p> $F \text{ см} = 0.516$ $Q \text{ кг.} = 0.14$ $D \text{ оп.мм.} = 18$ $P \text{ н.} = 38.4$ Гр. сл. = III Точн. = П </p>
	<p>БПО-4002</p> <p> $F \text{ см} = 1.811$ $Q \text{ кг.} = 0.491$ $D \text{ оп.мм.} = 42$ $P \text{ н.} = 398.3$ Гр. сл. = VI Точн. = П </p>		<p>БПО-4007</p> <p> $F \text{ см} = 1.235$ $Q \text{ кг.} = 0.335$ $D \text{ оп.мм.} = 16.7$ $P \text{ н.} = 102.3$ Гр. сл. = III Точн. = П </p>
	<p>БПО-4003</p> <p> $F \text{ см} = 1.453$ $Q \text{ кг.} = 0.394$ $D \text{ оп.мм.} = 42$ $P \text{ н.} = 240$ Гр. сл. = VI Точн. = П </p>		<p>БПО-4008</p> <p> $F \text{ см} = 0,645$ $Q \text{ кг.} = 0,175$ $D \text{ оп.мм.} = 16,7$ $P \text{ н.} = 69,6$ Гр. сл. = V Точн. = П </p>
	<p>БПО-4004</p> <p> $F \text{ см} = 1.096$ $Q \text{ кг.} = 0.297$ $D \text{ оп.мм.} = 35$ $P \text{ н.} = 181.5$ Гр. сл. = VI Точн. = П </p>		<p>БПО-4009</p> <p> $F \text{ см} = 1.695$ $Q \text{ кг.} = 0.459$ $D \text{ оп.мм.} = 39$ $P \text{ н.} = 137.2$ Гр. сл. = III Точн. = П </p>
	<p>БПО-4005</p> <p> $F \text{ см}^2 = 0.746$ $Q \text{ кг.} = 0.202$ $D \text{ оп.мм.} = 26$ $P \text{ н.} = 53.9$ Гр. сл. = III Точн. = П </p>		<p>БПО-4010</p> <p> $F \text{ см} = 0.851$ $Q \text{ кг.} = 0.231$ $D \text{ оп.мм.} = 23$ $P \text{ н.} = 128.2$ Гр. сл. = VI Точн. = П </p>





	БПО-4011		БПО-4016
	$F \text{ см}^2 = 1.594$ $Q \text{ кг.} = 0.432$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 216.9$ Гр. сл. = VI Точн. = П		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-4012		БПО-4017
	$F \text{ см} = 1.463$ $Q \text{ кг.} = 0.389$ $D \text{ оп.мм.} = 54$ $P \text{ н.} = 230.9$ Гр. сл. = 0 Точн. = П		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-4013		БПО-4018
	$F \text{ см} = 0.829$ $Q \text{ кг.} = 0.225$ $D \text{ оп.мм.} = 47$ $P \text{ н.} = 132.2$ Гр. сл. = VI Точн. = П		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-4014		БПО-4019
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0
	БПО-4015		БПО-4020
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0		$F \text{ см} = 7.04$ $Q \text{ кг.} = 1.908$ $D \text{ оп.мм.} = 146$ $P \text{ н.} = 360$ Гр. сл. = IV Точн. = Н









	БПО-4021		БПО-4026
	<p> $F \text{ см}^2 = 7.84$ $Q \text{ кг.} = 2.125$ $D \text{ оп.мм.} = 166$ $P \text{ н.} = 400$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p>		<p> $F \text{ см} = 7.042$ $Q \text{ кг.} = 1.908$ $D \text{ оп.мм.} = 123$ $P \text{ н.} = 454$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>
	БПО-4022		БПО-4027
	<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>
	БПО-4023		БПО-4028
	<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p> $F \text{ см} = 0.55$ $Q \text{ кг.} = 0.149$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 94$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	БПО-4024		БПО-4029
	<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>		<p> $F \text{ см} = 0.796$ $Q \text{ кг.} = 0.216$ $D \text{ оп.мм.} = 37$ $P \text{ н.} = 134.6$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	БПО-4025		БПО-4030
	<p> $F \text{ см}^2 = 11.664$ $Q \text{ кг.} = 3.161$ $D \text{ оп.мм.} = 109$ $P \text{ н.} = 404.7$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{П}$ </p>		<p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$ </p>






	БПО-4031		БПО-4036
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 2.364 Q кг. = 0.641 D оп.мм.= 51 P н. = 216.8 Гр. сл. = VI Точн. = П
	БПО-4032		БПО-4037
	F см = 3.325 Q кг. = 0.901 D оп.мм.= 60 P н. = 248 Гр. сл. = IV Точн. = П		F см = 8.351 Q кг. = 2.263 D оп.мм.= 106 P н. = 481 Гр. сл. = IV Точн. = П
	БПО-4033		БПО-4038
	F см = 27.07 Q кг. = 7.336 D оп.мм.= 178 P н. = 689.9 Гр. сл. = III Точн. = Особая		F см = 1.665 Q кг. = 0.451 D оп.мм.= 51 P н. = 179.1 Гр. сл. = IV Точн. = П
	БПО-4034		БПО-4039
	F см = 1.351 Q кг. = 0.366 D оп.мм.= 51 P н. = 115.3 Гр. сл. = IV Точн. = П		F см = 1.41 Q кг. = 0.382 D оп.мм.= 51 P н. = 155.3 Гр. сл. = IV Точн. = П
	БПО-4035		БПО-4040
	F см = 1.326 Q кг. = 0.359 D оп.мм.= 50 P н. = 113.3 Гр. сл. = IV Точн. = П		F см = 1,9 Q кг. = 0,515 D оп.мм.= 47 P н. = 189,2 Гр. сл. = IV Точн. = П





	<p>БПО-4041</p> <p> $F \text{ см} = 2.3$ $Q \text{ кг.} = 0.623$ $D \text{ оп.мм.} = 39$ $P \text{ н.} = 175.4$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-4046</p> <p> $F \text{ см} = 3.74$ $Q \text{ кг.} = 1.01$ $D \text{ оп.мм.} = 107$ $P \text{ н.} = 369.8$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-4042</p> <p> $F \text{ см} = 1.71$ $Q \text{ кг.} = 0.463$ $D \text{ оп.мм.} = 39$ $P \text{ н.} = 157.6$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-4047</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>
	<p>БПО-4043</p> <p> $F \text{ см} = 1.963$ $Q \text{ кг.} = 0.532$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 166.1$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-4048</p> <p> $F \text{ см} = 8.69$ $Q \text{ кг.} = 2.36$ $D \text{ оп.мм.} = 84$ $P \text{ н.} = 702.9$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-4044</p> <p> $F \text{ см} = 0.29$ $Q \text{ кг.} = 0.079$ $D \text{ оп.мм.} = 17$ $P \text{ н.} = 50.8$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-4049</p> <p> $F \text{ см} = 24.926$ $Q \text{ кг.} = 6.755$ $D \text{ оп.мм.} = 194$ $P \text{ н.} = 705$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-4045</p> <p> $F \text{ см} = 4.463$ $Q \text{ кг.} = 1.209$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 366.7$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-4050</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$ </p>







	БПО-4051 F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		БПО-4056 F см = 1.813 Q кз. = 0.491 D оп.мм.= 62 P н. = 262.8 Гр. сл. = VI Точн. = П
	БПО-4052 F см = 1.472 Q кз. = 0.399 D оп.мм.= 61 P н. = 193.1 Гр. сл. = VI Точн. = П		БПО-4057 F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-4053 F см = 0.514 Q кз. = 0.139 D оп.мм.= 19 P н. = 63 Гр. сл. = IV Точн. = П		БПО-4058 F см = 2.598 Q кз. = 0.704 D оп.мм.= 92 P н. = 362.8 Гр. сл. = VI Точн. = П
	БПО-4054 F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		БПО-4059 F см = 1.577 Q кз. = 0.427 D оп.мм.= 25 P н. = 96.9 Гр. сл. = IV Точн. = Н
	БПО-4055 F см = 4.137 Q кз. = 1.12 D оп.мм.= 90 P н. = 336 Гр. сл. = IV Точн. = П		БПО-4060 F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0






	БПО-4061		БПО-4066
	$F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$		$F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$
	БПО-4062		БПО-4067
	$F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$		$F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$
	БПО-4063		БПО-4068
	$F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$		$F_{\text{см}} = 2.128$ $Q_{\text{кз.}} = 0.577$ $D_{\text{оп.мм.}} = 73$ $P_{\text{н.}} = 240$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{H}$
	БПО-4064		БПО-4069
	$F_{\text{см}} = 0.945$ $Q_{\text{кз.}} = 0.256$ $D_{\text{оп.мм.}} = 30$ $P_{\text{н.}} = 130$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{П}$		$F_{\text{см}} = 0.493$ $Q_{\text{кз.}} = 0.134$ $D_{\text{оп.мм.}} = 17$ $P_{\text{н.}} = 66.4$ $\Gamma_{\text{р. сл.}} = \text{Особая}$ $\text{Точн.} = \text{П}$
	БПО-4065		БПО-4070
	$F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$		$F_{\text{см}} = 14.72$ $Q_{\text{кз.}} = 3.989$ $D_{\text{оп.мм.}} = 184$ $P_{\text{н.}} = 384$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{П}$




	<p>БПО-4071</p> <p> $F \text{ см} = 2.208$ $Q \text{ кг.} = 0.598$ $D \text{ оп.мм.} = 37$ $P \text{ н.} = 214.4$ Гр. сл. = VI Точн. = П </p>		<p>БПО-4076</p> <p> $F \text{ см} = 14.2$ $Q \text{ кг.} = 3.848$ $D \text{ оп.мм.} = 102$ $P \text{ н.} = 479.6$ Гр. сл. = V Точн. = П </p>
	<p>БПО-4072</p> <p> $F \text{ см} = 1.33$ $Q \text{ кг.} = 0.36$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 171.2$ Гр. сл. = VI Точн. = П </p>		<p>БПО-4077</p> <p> $F \text{ см} = 4.75$ $Q \text{ кг.} = 1.287$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 160$ Гр. сл. = IV Точн. = П </p>
	<p>БПО-4073</p> <p> $F \text{ см} = 1.3$ $Q \text{ кг.} = 0.352$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 191.1$ Гр. сл. = V Точн. = П </p>		<p>БПО-4078</p> <p> $F \text{ см} = 1.145$ $Q \text{ кг.} = 0.31$ $D \text{ оп.мм.} = 37.5$ $P \text{ н.} = 168.2$ Гр. сл. = V Точн. = П </p>
	<p>БПО-4074</p> <p> $F \text{ см} = 12.323$ $Q \text{ кг.} = 3.34$ $D \text{ оп.мм.} = 127$ $P \text{ н.} = 408.4$ Гр. сл. = IV Точн. = П </p>		<p>БПО-4079</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>
	<p>БПО-4075</p> <p> $F \text{ см} = 2.1$ $Q \text{ кг.} = 0.569$ $D \text{ оп.мм.} = 34$ $P \text{ н.} = 146$ Гр. сл. = III Точн. = П </p>		<p>БПО-4080</p> <p> $F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0 </p>










	БПО-4081		БПО-4086
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 1.061 Q кз. = 0.288 D оп.мм.= 60 P н. = 172.9 Гр. сл. = VI Точн. = П
	БПО-4082		БПО-4087
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0.738 Q кз. = 0.2 D оп.мм.= 33 P н. = 124.5 Гр. сл. = V Точн. = П
	БПО-4083		БПО-4088
	F см = 2.364 Q кз. = 0.641 D оп.мм.= 56 P н. = 223.8 Гр. сл. = VI Точн. = П		F см = 1.096 Q кз. = 0.297 D оп.мм.= 28 P н. = 112.7 Гр. сл. = IV Точн. = П
	БПО-4084		БПО-4089
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-4085		БПО-4090
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 9.39 Q кз. = 2.54 D оп.мм.= 159 P н. = 973.7 Гр. сл. = Особая Точн. = П





	БПО-4091		БПО-4096
	$F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$		$F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$
	БПО-4092		БПО-4097
	$F_{\text{см}} = 1.572$ $Q_{\text{кз.}} = 0.426$ $D_{\text{оп.мм.}} = 51$ $P_{\text{н.}} = 165$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{П}$		$F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$
	БПО-4093		БПО-4098
	$F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$		$F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$
	БПО-4094		БПО-4099
	$F_{\text{см}} = 1.01$ $Q_{\text{кз.}} = 0.274$ $D_{\text{оп.мм.}} = 30$ $P_{\text{н.}} = 95.3$ $\Gamma_{\text{р. сл.}} = \text{Особая}$ $\text{Точн.} = \text{П}$		$F_{\text{см}} = 8.6$ $Q_{\text{кз.}} = 2.331$ $D_{\text{оп.мм.}} = 64$ $P_{\text{н.}} = 526.4$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-4095		БПО-4100
	$F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$		$F_{\text{см}} = 1.74$ $Q_{\text{кз.}} = 0.472$ $D_{\text{оп.мм.}} = 47$ $P_{\text{н.}} = 247.5$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{П}$






	<p>БПО-4101</p> <p> $F_{\text{см}} = 1.82$ $Q_{\text{кз.}} = 0.5$ $D_{\text{оп.мм.}} = 57$ $P_{\text{н.}} = 261.5$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-4106</p> <p> $F_{\text{см}} = 0.79$ $Q_{\text{кз.}} = 0.22$ $D_{\text{оп.мм.}} = 20$ $P_{\text{н.}} = 103.9$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-4102</p> <p> $F_{\text{см}} = 0.73$ $Q_{\text{кз.}} = 0.2$ $D_{\text{оп.мм.}} = 26$ $P_{\text{н.}} = 100$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>		<p>БПО-4107</p> <p> $F_{\text{см}} = 0.449$ $Q_{\text{кз.}} = 0.122$ $D_{\text{оп.мм.}} = 30$ $P_{\text{н.}} = 56.4$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p>
	<p>БПО-4103</p> <p> $F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-4108</p> <p> $F_{\text{см}} = 4.36$ $Q_{\text{кз.}} = 1.2$ $D_{\text{оп.мм.}} = 33$ $P_{\text{н.}} = 192$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>
	<p>БПО-4104</p> <p> $F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-4109</p> <p> $F_{\text{см}} = 1.55$ $Q_{\text{кз.}} = 0.42$ $D_{\text{оп.мм.}} = 28$ $P_{\text{н.}} = 101.5$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{Н}$ </p>
	<p>БПО-4105</p> <p> $F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$ </p>		<p>БПО-4110</p> <p> $F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$ </p>





	БПО-4111		БПО-4116
	F см = 3.24 Q кз. = 0.878 D оп.мм.= 91 P н. = 294.3 Гр. сл. = IV Точн. = П		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-4112		БПО-4117
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-4113		БПО-4118
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-4114		БПО-4119
	F см = 1.052 Q кз. = 0.285 D оп.мм.= 26 P н. = 61.7 Гр. сл. = IV Точн. = П		F см = 5.37 Q кз. = 1.455 D оп.мм.= 63 P н. = 287.8 Гр. сл. = III Точн. = П
	БПО-4115		БПО-4120
	F см = 6.84 Q кз. = 1.8 D оп.мм.= 64 P н. = 155.6 Гр. сл. = IV Точн. = П		F см = 5.542 Q кз. = 1.502 D оп.мм.= 65 P н. = 303.8 Гр. сл. = III Точн. = П

	БПО-4121		БПО-4126
	F см = 1.463 Q кг. = 0.395 D оп.мм.= 34 P н. = 83.4 Гр. сл. = II Точн. = П		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-4122		БПО-4127
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 17.36 Q кг. = 4.7 D оп.мм.= 152 P н. = 615.4 Гр. сл. = V Точн. = П
	БПО-4123		БПО-4128
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-4124		БПО-4129
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0
	БПО-4125		БПО-4130
	F см = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 3.721 Q кг. = 1.0 D оп.мм.= 92 P н. = 380.6 Гр. сл. = IV Точн. = П

	БПО-4131		БПО-4136
	F см = 0 Q кз. = 0 D оп.мм.= 0 P н. = 0 Гр. сл. = 0 Точн. = 0		F см = 6.17 Q кз. = 1.68 D оп.мм.= 105 P н. = 418 Гр. сл. = VI Точн. = Н
	БПО-4132		БПО-4137
	F см = 0.956 Q кз. = 0.26 D оп.мм.= 58 P н. = 156.3 Гр. сл. = VI Точн. = П		F см = 4.1 Q кз. = 1.11 D оп.мм.= 72 P н. = 268 Гр. сл. = IV Точн. = П
	БПО-4133		БПО-4138
	F см = 5.83 Q кз. = 1.58 D оп.мм.= 56 P н. = 198.5 Гр. сл. = III Точн. = П		F см = 4.36 Q кз. = 1.19 D оп.мм.= 92 P н. = 303 Гр. сл. = IV Точн. = П
	БПО-4134		БПО-4139
	F см = 25.11 Q кз. = 6.805 D оп.мм.= 107 P н. = 381.8 Гр. сл. = VI Точн. = П		F см = 6.29 Q кз. = 1.7 D оп.мм.= 132 P н. = 468.3 Гр. сл. = IV Точн. = П
	БПО-4135		БПО-4140
	F см = 6.55 Q кз. = 1.78 D оп.мм.= 115 P н. = 453 Гр. сл. = VI Точн. = Н		F см = 3.13 Q кз. = 0.85 D оп.мм.= 68 P н. = 256 Гр. сл. = IV Точн. = Н

	БПО-4141		БПО-4146
	<p> $F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = \text{П}$ </p>		<p> $F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$ </p>
	БПО-4142		БПО-4147
	<p> $F_{\text{см}} = 0.557$ $Q_{\text{кз.}} = 0.151$ $D_{\text{оп.мм.}} = 27$ $P_{\text{н.}} = 89.6$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p> $F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$ </p>
	БПО-4143		БПО-4148
	<p> $F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$ </p>		<p> $F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$ </p>
	БПО-4144		БПО-4149
	<p> $F_{\text{см}} = 1.42$ $Q_{\text{кз.}} = 0.39$ $D_{\text{оп.мм.}} = 67$ $P_{\text{н.}} = 237.5$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p> $F_{\text{см}} = 0.819$ $Q_{\text{кз.}} = 0.222$ $D_{\text{оп.мм.}} = 21$ $P_{\text{н.}} = 84.9$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{П}$ </p>
	БПО-4145		БПО-4150
	<p> $F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$ </p>		<p> $F_{\text{см}} = 0$ $Q_{\text{кз.}} = 0$ $D_{\text{оп.мм.}} = 0$ $P_{\text{н.}} = 0$ $\Gamma_{\text{р. сл.}} = 0$ $\text{Точн.} = 0$ </p>

	БПО-4151		БПО-4156
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-4152		БПО-4157
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 7.73$ $Q \text{ кг.} = 2.1$ $D \text{ оп.мм.} = 179$ $P \text{ н.} = 792.2$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-4153		БПО-4158
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 6.88$ $Q \text{ кг.} = 1.87$ $D \text{ оп.мм.} = 130$ $P \text{ н.} = 838.1$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-4154		БПО-4159
	$F \text{ см} = 1.12$ $Q \text{ кг.} = 0.31$ $D \text{ оп.мм.} = 40$ $P \text{ н.} = 148.4$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 1.08$ $Q \text{ кг.} = 0.3$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 169.2$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-4155		БПО-4160
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.71$ $Q \text{ кг.} = 0.2$ $D \text{ оп.мм.} = 26$ $P \text{ н.} = 120.7$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$

	БПО-4161		БПО-4166
	$F \text{ см}^2 = 0.56$ $Q \text{ кг.} = 0.152$ $D \text{ оп.мм.} = 20$ $P \text{ н.} = 90.5$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-4162		БПО-4167
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.631$ $Q \text{ кг.} = 0.171$ $D \text{ оп.мм.} = 39.2$ $P \text{ н.} = 107.3$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПО-4163		БПО-4168
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 2.96$ $Q \text{ кг.} = 0.802$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 115.1$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПО-4164		БПО-4169
	$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПО-4165		БПО-4170
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см} = 0.8$ $Q \text{ кг.} = 0.217$ $D \text{ оп.мм.} = 33$ $P \text{ н.} = 124.9$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$