



















































	OK-1	(РОСТ-23)	OK-6
	$F \text{ см}^2 = 5,44$ $Q \text{ кг} = 1,474$ $D \text{ оп.мм} = 107,7$ $P \text{ н.мм} = 280$ Гр. сл. = III Точн. = Н		$F \text{ см}^2 = 2,42$ $Q \text{ кг} = 0,656$ $D \text{ оп.мм} = 38,2$ $P \text{ н.мм} = 168,3$ Гр. сл. = V Точн. = Н
	OK-2	(РОСТ-22)	OK-7
	$F \text{ см}^2 = 6,24$ $Q \text{ кг} = 1,691$ $D \text{ оп.мм} = 126,5$ $P \text{ н.мм} = 320$ Гр. сл. = III Точн. = Н		$F \text{ см}^2 = 4,269$ $Q \text{ кг} = 1,157$ $D \text{ оп.мм} = 60,2$ $P \text{ н.мм} = 224,2$ Гр. сл. = VI Точн. = Н
	OK-3		OK-8
	$F \text{ см}^2 = 3,84$ $Q \text{ кг} = 1,041$ $D \text{ оп.мм} = 72,1$ $P \text{ н.мм} = 200$ Гр. сл. = III Точн. = Н		$F \text{ см}^2 = 0,463$ $Q \text{ кг} = 0,125$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 63,2$ Гр. сл. = IV Точн. = Н
	OK-4		OK-9
	$F \text{ см}^2 = 0,6248$ $Q \text{ кг} = 0,1693$ $D \text{ оп.мм} = 34,9$ $P \text{ н.мм} = 93,95$ Гр. сл. = V Точн. = Н		$F \text{ см}^2 = 0,408$ $Q \text{ кг} = 0,111$ $D \text{ оп.мм} = 26$ $P \text{ н.мм} = 56,7$ Гр. сл. = IV Точн. = Н
	OK-5		OK-10
	$F \text{ см}^2 = 0,791$ $Q \text{ кг} = 0,215$ $D \text{ оп.мм} = 37,1$ $P \text{ н.мм} = 133,7$ Гр. сл. = V Точн. = Н		$F \text{ см}^2 = 6,81$ $Q \text{ кг} = 1,846$ $D \text{ оп.мм} = 149,5$ $P \text{ н.мм} = 590$ Гр. сл. = VII Точн. = Н











	<p>OK-11</p>		<p>OK-16</p>
	<p> $F \text{ см}^2 = 1.9$ $Q \text{ кг} = 0.515$ $D \text{ оп.мм} = 61$ $P \text{ н.мм} = 186.5$ Гр. сл. = V Точн. = Н </p>		<p> $F \text{ см}^2 = 3.7$ $Q \text{ кг} = 1.002$ $D \text{ оп.мм} = 51$ $P \text{ н.мм} = 222$ Гр. сл. = V Точн. = Н </p>
	<p>OK-12</p>		<p>OK-17</p>
	<p> $F \text{ см}^2 = 9.07$ $Q \text{ кг} = 2.46$ $D \text{ оп.мм} = 183$ $P \text{ н.мм} = 737$ Гр. сл. = VII Точн. = Н </p>		<p> $F \text{ см}^2 = 18.32$ $Q \text{ кг} = 4.96$ $D \text{ оп.мм} = 186$ $P \text{ н.мм} = 514.6$ Гр. сл. = V Точн. = П </p>
	<p>OK-13</p>		<p>OK-18</p>
	<p> $F \text{ см}^2 = 4.28$ $Q \text{ кг} = 1.16$ $D \text{ оп.мм} = 63.6$ $P \text{ н.мм} = 175.7$ Гр. сл. = II Точн. = Н </p>		<p> $F \text{ см}^2 = 7.074$ $Q \text{ кг} = 2.088$ $D \text{ оп.мм} = 124$ $P \text{ н.мм} = 371.1$ Гр. сл. = IV Точн. = П </p>
	<p>OK-14</p>		<p>OK-19</p>
	<p> $F \text{ см}^2 = 1.72$ $Q \text{ кг} = 0.466$ $D \text{ оп.мм} = 42.4$ $P \text{ н.мм} = 117.4$ Гр. сл. = II Точн. = Н </p>		<p> $F \text{ см}^2 = 3.984$ $Q \text{ кг} = 1.08$ $D \text{ оп.мм} = 107$ $P \text{ н.мм} = 331$ Гр. сл. = IV Точн. = П </p>
	<p>OK-15</p>		<p>OK-20</p>
	<p> $F \text{ см}^2 = 1.3$ $Q \text{ кг} = 0.352$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 161$ Гр. сл. = IV Точн. = П </p>		<p> $F \text{ см}^2 = 0.865$ $Q \text{ кг} = 0.234$ $D \text{ оп.мм} = 31.4$ $P \text{ н.мм} = 71.7$ Гр. сл. = III Точн. = Н </p>











	<p>OK-21</p> <p>(801008)</p> <p>OK-26</p>		
	<p>$F \text{ см}^2 = 4,574$</p> <p>$Q \text{ кг} = 1,24$</p> <p>$D \text{ оп.мм} = 53,3$</p> <p>$P \text{ н.мм} = 424,8$</p> <p>Гр. сл. = VII</p> <p>Точн. = Н</p>		<p>$F \text{ см}^2 = 1,249$</p> <p>$Q \text{ кг} = 0,338$</p> <p>$D \text{ оп.мм} = 52,2$</p> <p>$P \text{ н.мм} = 208,2$</p> <p>Гр. сл. = ОСОБ.</p> <p>Точн. = П</p>
<p>(100023)</p>	<p>OK-22</p> <p>(801009)</p> <p>OK-27</p>		
	<p>$F \text{ см}^2 = 2,13$</p> <p>$Q \text{ кг} = 0,577$</p> <p>$D \text{ оп.мм} = 50,2$</p> <p>$P \text{ н.мм} = 212,6$</p> <p>Гр. сл. = V</p> <p>Точн. = П</p>		<p>$F \text{ см}^2 = 2,803$</p> <p>$Q \text{ кг} = 0,76$</p> <p>$D \text{ оп.мм} = 100,5$</p> <p>$P \text{ н.мм} = 415,3$</p> <p>Гр. сл. = ОСОБ.</p> <p>Точн. = П</p>
<p>(100024)</p>	<p>OK-23</p> <p>(801010)</p> <p>OK-28</p>		
	<p>$F \text{ см}^2 = 3,467$</p> <p>$Q \text{ кг} = 0,94$</p> <p>$D \text{ оп.мм} = 51,8$</p> <p>$P \text{ н.мм} = 317,2$</p> <p>Гр. сл. = V</p> <p>Точн. = П</p>		<p>$F \text{ см}^2 = 1,582$</p> <p>$Q \text{ кг} = 0,429$</p> <p>$D \text{ оп.мм} = 66,5$</p> <p>$P \text{ н.мм} = 261,5$</p> <p>Гр. сл. = ОСОБ.</p> <p>Точн. = П</p>
<p>(100055)</p>	<p>OK-24</p> <p>(ЯВ45.85050х)</p> <p>OK-29</p>		
	<p>$F \text{ см}^2 = 1,585$</p> <p>$Q \text{ кг} = 0,43$</p> <p>$D \text{ оп.мм} = 48$</p> <p>$P \text{ н.мм} = 164,7$</p> <p>Гр. сл. = V</p> <p>Точн. = П</p>		<p>$F \text{ см}^2 = 1,967$</p> <p>$Q \text{ кг} = 0,533$</p> <p>$D \text{ оп.мм} = 50$</p> <p>$P \text{ н.мм} = 179,5$</p> <p>Гр. сл. = VI</p> <p>Точн. = Н</p>
<p>(100056XX)</p>	<p>OK-25</p> <p>(ЯВ-3)</p> <p>OK-30</p>		
	<p>$F \text{ см}^2 = 1,648$</p> <p>$Q \text{ кг} = 0,446$</p> <p>$D \text{ оп.мм} = 50$</p> <p>$P \text{ н.мм} = 127$</p> <p>Гр. сл. = IV</p> <p>Точн. = П</p>		<p>$F \text{ см}^2 = 13$</p> <p>$Q \text{ кг} = 3,523$</p> <p>$D \text{ оп.мм} = 102$</p> <p>$P \text{ н.мм} = 444,3$</p> <p>Гр. сл. = V</p> <p>Точн. = Н</p>











(ЯВ-4)	□К-31	(Р96.001-134.60227)	□К-36
	<p> $F \text{ см}^2 = 14,77$ $Q \text{ кг} = 4$ $D \text{ оп.мм} = 180$ $P \text{ н.мм} = 458,5$ Гр. сл. = V Точн. = Н </p>		<p> $F \text{ см}^2 = 6,591$ $Q \text{ кг} = 1,786$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 105,3$ Гр. сл. = I Точн. = Н </p>
(ЯВ-5)	□К-32	(РОСТ-01)	□К-37
	<p> $F \text{ см}^2 = 1,923$ $Q \text{ кг} = 0,521$ $D \text{ оп.мм} = 31$ $P \text{ н.мм} = 82,2$ Гр. сл. = III Точн. = Н </p>		<p> $F \text{ см}^2 = 6,734$ $Q \text{ кг} = 1,825$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 144,3$ Гр. сл. = III Точн. = П </p>
(Г96.002-222.60.207)	□К-33	(РОСТ-02)	□К-38
	<p> $F \text{ см}^2 = 5,66$ $Q \text{ кг} = 1,534$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 92,4$ Гр. сл. = II Точн. = Н </p>		<p> $F \text{ см}^2 = 3,051$ $Q \text{ кг} = 0,827$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 69,7$ Гр. сл. = III Точн. = Н </p>
(Г96.002-222.60.214)	□К-34	(РОСТ-03)	□К-39
	<p> $F \text{ см}^2 = 5,576$ $Q \text{ кг} = 1,511$ $D \text{ оп.мм} = 29$ $P \text{ н.мм} = 91,5$ Гр. сл. = II Точн. = Н </p>		<p> $F \text{ см}^2 = 1,398$ $Q \text{ кг} = 0,379$ $D \text{ оп.мм} = 36$ $P \text{ н.мм} = 137,4$ Гр. сл. = IV Точн. = Н </p>
(Г96.002-222.60.215)	□К-35	(РОСТ-04)	□К-40
	<p> $F \text{ см}^2 = 12,56$ $Q \text{ кг} = 3,404$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 125,7$ Гр. сл. = I Точн. = Н </p>		<p> $F \text{ см}^2 = 1,498$ $Q \text{ кг} = 0,406$ $D \text{ оп.мм} = 43$ $P \text{ н.мм} = 147,4$ Гр. сл. = IV Точн. = Н </p>











(РОСТ-05)	□К-41	(РОСТ-11)	□К-46
	<p> $F \text{ см}^2 = 2.721$ $Q \text{ кг} = 0.737$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 101.4$ Гр. сл. = IV Точн. = Н </p>		<p> $F \text{ см}^2 = 0.72$ $Q \text{ кг} = 0.195$ $D \text{ оп.мм} = 31$ $P \text{ н.мм} = 76$ Гр. сл. = II Точн. = Н </p>
(РОСТ-06)	□К-42	(РОСТ-12)	□К-47
	<p> $F \text{ см}^2 = 3.57$ $Q \text{ кг} = 0.967$ $D \text{ оп.мм} = 27$ $P \text{ н.мм} = 73.1$ Гр. сл. = III Точн. = Н </p>		<p> $F \text{ см}^2 = 0.52$ $Q \text{ кг} = 0.141$ $D \text{ оп.мм} = 21.5$ $P \text{ н.мм} = 56$ Гр. сл. = II Точн. = Н </p>
(РОСТ-07)	□К-43	(РОСТ-17)	□К-48
	<p> $F \text{ см}^2 = 1.17$ $Q \text{ кг} = 0.317$ $D \text{ оп.мм} = 31.6$ $P \text{ н.мм} = 102$ Гр. сл. = III Точн. = Н </p>		<p> $F \text{ см}^2 = 1.416$ $Q \text{ кг} = 0.384$ $D \text{ оп.мм} = 31$ $P \text{ н.мм} = 105.5$ Гр. сл. = III Точн. = Н </p>
(РОСТ-08)	□К-44	(РОСТ-18)	□К-49
	<p> $F \text{ см}^2 = 2.671$ $Q \text{ кг} = 0.734$ $D \text{ оп.мм} = 57$ $P \text{ н.мм} = 194.1$ Гр. сл. = V Точн. = П </p>		<p> $F \text{ см}^2 = 2.393$ $Q \text{ кг} = 0.649$ $D \text{ оп.мм} = 36$ $P \text{ н.мм} = 159.8$ Гр. сл. = V Точн. = Н </p>
(РОСТ-9)	□К-45	(РДГ-180)	□К-50
	<p> $F \text{ см}^2 = 1.999$ $Q \text{ кг} = 0.542$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 141.6$ Гр. сл. = IV Точн. = П </p>		<p> $F \text{ см}^2 = 7.308$ $Q \text{ кг} = 1.98$ $D \text{ оп.мм} = 181$ $P \text{ н.мм} = 705.6$ Гр. сл. = V Точн. = П </p>











(Г-130)	OK-51		OK-56
	<p> $F \text{ см}^2 = 7,425$ $Q \text{ кг} = 2,12$ $D \text{ оп.мм} = 154$ $P \text{ н.мм} = 463,3$ Гр. сл. = V Точн. = П </p>		<p> $F \text{ см}^2 = 3,437$ $Q \text{ кг} = 0,932$ $D \text{ оп.мм} = 51$ $P \text{ н.мм} = 211,1$ Гр. сл. = V Точн. = П </p>
(Т-2)	OK-52		OK-57
	<p> $F \text{ см}^2 = 0,781$ $Q \text{ кг} = 0,212$ $D \text{ оп.мм} = 29$ $P \text{ н.мм} = 104,1$ Гр. сл. = V Точн. = П </p>		<p> $F \text{ см}^2 = 2,05$ $Q \text{ кг} = 0,556$ $D \text{ оп.мм} = 62,4$ $P \text{ н.мм} = 210$ Гр. сл. = V Точн. = Н </p>
	OK-53		OK-58
	<p> $F \text{ см}^2 = 1,76$ $Q \text{ кг} = 0,477$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 180$ Гр. сл. = IV Точн. = Н </p>		<p> $F \text{ см}^2 = 1,78$ $Q \text{ кг} = 0,485$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 187,8$ Гр. сл. = V Точн. = Н </p>
	OK-54	(C1)	OK-59
	<p> $F \text{ см}^2 = 4,64$ $Q \text{ кг} = 1,257$ $D \text{ оп.мм} = 89,4$ $P \text{ н.мм} = 240$ Гр. сл. = III Точн. = Н </p>		<p> $F \text{ см}^2 = 11,891$ $Q \text{ кг} = 3,222$ $D \text{ оп.мм} = 58$ $P \text{ н.мм} = 256$ Гр. сл. = V Точн. = Н </p>
	OK-55	(C2)	OK-60
	<p> $F \text{ см}^2 = 3,16$ $Q \text{ кг} = 0,856$ $D \text{ оп.мм} = 110,2$ $P \text{ н.мм} = 320$ Гр.сл.= VII Точн. = Н </p>		<p> $F \text{ см}^2 = 10,54$ $Q \text{ кг} = 2,86$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 230,6$ Гр. сл. = IV Точн. = Н </p>











(С3)	□К-61		□К-66
	<p> $F \text{ см}^2 = 258$ $Q \text{ кг} = 0.7$ $D \text{ оп.мм} = 34$ $P \text{ н.мм} = 99$ Гр. сл. = IV Точн. = Н </p>		<p> $F \text{ см}^2 = 1176$ $Q \text{ кг} = 0.319$ $D \text{ оп.мм} = 32.7$ $P \text{ н.мм} = 85.3$ Гр. сл. = IV Точн. = Н </p>
(С4)	□К-62		□К-67
	<p> $F \text{ см}^2 = 3.42$ $Q \text{ кг} = 0.927$ $D \text{ оп.мм} = 36$ $P \text{ н.мм} = 112.4$ Гр. сл. = III Точн. = Н </p>		<p> $F \text{ см}^2 = 0.453$ $Q \text{ кг} = 0.123$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 75.25$ Гр. сл. = V Точн. = Н </p>
	□К-63		□К-68
	<p> $F \text{ см}^2 = 0.467$ $Q \text{ кг} = 0.127$ $D \text{ оп.мм} = 29.6$ $P \text{ н.мм} = 67.2$ Гр. сл. = III Точн. = Н </p>		<p> $F \text{ см}^2 = 22.57$ $Q \text{ кг} = 6.12$ $D \text{ оп.мм} = 112.3$ $P \text{ н.мм} = 367.6$ Гр. сл. = III Точн. = Н </p>
	□К-64		□К-69
	<p> $F \text{ см}^2 = 0.713$ $Q \text{ кг} = 0.193$ $D \text{ оп.мм} = 32.7$ $P \text{ н.мм} = 88.9$ Гр. сл. = IV Точн. = Н </p>		<p> $F \text{ см}^2 = 8.365$ $Q \text{ кг} = 2.27$ $D \text{ оп.мм} = 52.8$ $P \text{ н.мм} = 148.2$ Гр. сл. = II Точн. = Н </p>
	□К-65		□К-70
	<p> $F \text{ см}^2 = 1.01$ $Q \text{ кг} = 0.273$ $D \text{ оп.мм} = 32.7$ $P \text{ н.мм} = 86.4$ Гр. сл. = IV Точн. = Н </p>		<p> $F \text{ см}^2 = 3.673$ $Q \text{ кг} = 0.995$ $D \text{ оп.мм} = 36.6$ $P \text{ н.мм} = 145.1$ Гр. сл. = V Точн. = Н </p>

	<p>□К-71</p>		<p>□К-76</p>
	<p> $F \text{ см}^2 = 1.845$ $Q \text{ кг} = 0.5$ $D \text{ оп.мм} = 44.2$ $P \text{ н.мм} = 235$ Гр. сл. = VI Точн. = П </p>		<p> $F \text{ см}^2 = 2.46$ $Q \text{ кг} = 0.667$ $D \text{ оп.мм} = 98$ $P \text{ н.мм} = 252.6$ Гр. сл. = V Точн. = Н </p>
	<p>□К-72</p>		<p>□К-77</p>
	<p> $F \text{ см}^2 = 5.483$ $Q \text{ кг} = 1.486$ $D \text{ оп.мм} = 118$ $P \text{ н.мм} = 401.4$ Гр. сл. = VI Точн. = П </p>		<p> $F \text{ см}^2 = 2.29$ $Q \text{ кг} = 0.621$ $D \text{ оп.мм} = 110$ $P \text{ н.мм} = 265$ Гр. сл. = V Точн. = Н </p>
	<p>□К-73</p>		<p>□К-78</p>
	<p> $F \text{ см}^2 = 0.5345$ $Q \text{ кг} = 0.145$ $D \text{ оп.мм} = 22$ $P \text{ н.мм} = 58.65$ Гр. сл. = III Точн. = Н </p>		<p> $F \text{ см}^2 = 9.78$ $Q \text{ кг} = 2.65$ $D \text{ оп.мм} = 147$ $P \text{ н.мм} = 627$ Гр. сл. = VII Точн. = Н </p>
	<p>□К-74</p>		<p>□К-79</p>
	<p> $F \text{ см}^2 = 3.661$ $Q \text{ кг} = 0.992$ $D \text{ оп.мм} = 56.5$ $P \text{ н.мм} = 260.6$ Гр. сл. = V Точн. = П </p>		<p> $F \text{ см}^2 = 0.7062$ $Q \text{ кг} = 0.1914$ $D \text{ оп.мм} = 17.52$ $P \text{ н.мм} = 65.79$ Гр. сл. = V Точн. = Н </p>
	<p>□К-75</p>		<p>□К-80</p>
	<p> $F \text{ см}^2 = 12.63$ $Q \text{ кг} = 3.43$ $D \text{ оп.мм} = 147.5$ $P \text{ н.мм} = 683.8$ Гр. сл. = VII Точн. = Н </p>		<p> $F \text{ см}^2 = 3.002$ $Q \text{ кг} = 0.814$ $D \text{ оп.мм} = 48.7$ $P \text{ н.мм} = 220.9$ Гр. сл. = V Точн. = П </p>











	<p>□К-81</p>		<p>□К-86</p>
	<p> $F \text{ см}^2 = 8.591$ $Q \text{ кг} = 2.328$ $D \text{ оп.мм} = 133.8$ $P \text{ н.мм} = 442.1$ Гр. сл. = V Точн. = □ </p>		<p> $F \text{ см}^2 = 6.51$ $Q \text{ кг} = 1.764$ $D \text{ оп.мм} = 144.4$ $P \text{ н.мм} = 511$ Гр. сл. = VI Точн. = П </p>
	<p>□К-82</p>		<p>□К-87</p>
	<p> $F \text{ см}^2 = 6.981$ $Q \text{ кг} = 1.892$ $D \text{ оп.мм} = 105.4$ $P \text{ н.мм} = 372.5$ Гр. сл. = V Точн. = □ </p>		<p> $F \text{ см}^2 = 1.23$ $Q \text{ кг} = 0.3333$ $D \text{ оп.мм} = 51$ $P \text{ н.мм} = 207.2$ Гр. сл. = V Точн. = П </p>
	<p>□К-83</p>		<p>□К-88</p>
	<p> $F \text{ см}^2 = 2.045$ $Q \text{ кг} = 0.554$ $D \text{ оп.мм} = 61$ $P \text{ н.мм} = 200$ Гр. сл. = V Точн. = П </p>		<p> $F \text{ см}^2 = 10.55$ $Q \text{ кг} = 2.86$ $D \text{ оп.мм} = 164.9$ $P \text{ н.мм} = 503$ Гр. сл. = IV Точн. = П </p>
	<p>□К-84</p>		<p>□К-89</p>
	<p> $F \text{ см}^2 = 0.635$ $Q \text{ кг} = 0.1721$ $D \text{ оп.мм} = 40.2$ $P \text{ н.мм} = 87.75$ Гр. сл. = IV Точн. = Н </p>		<p> $F \text{ см}^2 = 2.238$ $Q \text{ кг} = 0.606$ $D \text{ оп.мм} = 98$ $P \text{ н.мм} = 278$ Гр. сл. = IV Точн. = П </p>
	<p>□К-85</p>		<p>□К-90</p>
	<p> $F \text{ см}^2 = 0.792$ $Q \text{ кг} = 0.2146$ $D \text{ оп.мм} = 40.54$ $P \text{ н.мм} = 102.5$ Гр. сл. = IV Точн. = Н </p>		<p> $F, \text{ см}^2 = 75.939$ $Q, \text{ кг} = 20.579$ $D \text{ оп.мм} = 192.4$ $P \text{ н.мм} = 2148.53$ Гр. сл. = VII Точн. = П </p>











	<p>□К-91</p>		<p>□К-96</p>
	<p> $F \text{ см}^2 = 15.885$ $Q \text{ кг} = 4.305$ $D \text{ оп.мм} = 150$ $R_{н.мм} = 743.44$ Гр. сл. = V Точн. = Осб. </p>		<p> $F \text{ см}^2 = 2.62$ $Q \text{ кг} = 0.71$ $D \text{ оп.мм} = 80.7$ $R_{н.мм} = 350$ Гр. сл. = V Точн. = П </p>
	<p>□К-92</p>		<p>□К-97</p>
	<p> $F \text{ см}^2 = 1.08$ $Q \text{ кг} = 0.293$ $D \text{ оп.мм} = 28.8$ $R_{н.мм} = 102$ Гр. сл. = VI Точн. = П </p>		<p> $F \text{ см}^2 = 0.486$ $Q \text{ кг} = 0.132$ $D \text{ оп.мм} = 29$ $R_{н.мм} = 61.6$ Гр. сл. = IV Точн. = Н </p>
	<p>□К-93</p>		<p>□К-98</p>
	<p> $F \text{ см}^2 = 7.05$ $Q \text{ кг} = 1.91$ $D \text{ оп.мм} = 226.2$ $R_{н.мм} = 568.9$ Гр. сл. = VII Точн. = П </p>		<p> $F, \text{ см}^2 = 13.484$ $Q, \text{ кг} = 3.654$ $D \text{ оп.мм} = 72.95$ $R_{н.мм} = 675.85$ Гр. сл. = Осб. Точн. = Н </p>
	<p>□К-94</p>		<p>□К-99</p>
	<p> $F \text{ см}^2 = 58.36$ $Q \text{ кг} = 15.82$ $D \text{ оп.мм} = 185.4$ $R_{н.мм} = 2473$ Гр. сл. = VII Точн. = П </p>		<p> $F, \text{ см}^2 = 11.43$ $Q, \text{ кг} = 3.098$ $D \text{ оп.мм} = 70$ $R_{н.мм} = 618.7$ Гр. сл. = Осб. Точн. = Н </p>
	<p>□К-95</p>		<p>□К-100</p>
	<p> $F \text{ см}^2 = 2.91$ $Q \text{ кг} = 0.79$ $D \text{ оп.мм} = 79$ $R_{н.мм} = 318.5$ Гр. сл. = V Точн. = П </p>		<p> $F \text{ см}^2 = 0.626$ $Q \text{ кг} = 0.167$ $D \text{ оп.мм} = 30$ $R_{н.мм} = 85.1$ Гр. сл. = IV Точн. = Н </p>











	<p>□К-101</p>		<p>□К-106</p>
	<p> $F \text{ см}^2 = 0.6$ $Q \text{ кг} = 0.163$ $D \text{ оп.мм} = 35$ $P \text{ н.мм} = 78.04$ Гр. сл. = IV Точн. = Н </p>		<p> $F \text{ см}^2 = 6$ $Q \text{ кг} = 1.626$ $D \text{ оп.мм} = 61$ $P \text{ н.мм} = 140$ Гр. сл. = I Точн. = Н </p>
	<p>□К-102</p>		<p>□К-107</p>
	<p> $F \text{ см}^2 = 25.3$ $Q \text{ кг} = 6.86$ $D \text{ оп.мм} = 209.2$ $P \text{ н.мм} = 234.85$ Гр. сл. = VII Точн. = Н </p>		<p> $F \text{ см}^2 = 14.82$ $Q \text{ кг} = 4.016$ $D \text{ оп.мм} = 106.6$ $P \text{ н.мм} = 237.4$ Гр. сл. = III Точн. = Н </p>
	<p>□К-103</p>		<p>□К-108</p>
	<p> $F \text{ см}^2 = 1.206$ $Q \text{ кг} = 0.327$ $D \text{ оп.мм} = 49$ $P \text{ н.мм} = 141.5$ Гр. сл. = V Точн. = Н </p>		<p> $F \text{ см}^2 = 26.43$ $Q \text{ кг} = 7.163$ $D \text{ оп.мм} = 116.8$ $P \text{ н.мм} = 273.4$ Гр. сл. = III Точн. = Н </p>
	<p>□К-104</p>		<p>□К-109</p>
	<p> $F \text{ см}^2 = 20.21$ $Q \text{ кг} = 5.477$ $D \text{ оп.мм} = 108.2$ $P \text{ н.мм} = 686.6$ Гр. сл. = VI Точн. = Н </p>		<p> $F \text{ см}^2 = 30.78$ $Q \text{ кг} = 8.341$ $D \text{ оп.мм} = 141.3$ $P \text{ н.мм} = 321.4$ Гр. сл. = III Точн. = Н </p>
	<p>□К-105</p>		<p>□К-110</p>
	<p> $F \text{ см}^2 = 35.495$ $Q \text{ кг} = 9.619$ $D \text{ оп.мм} = 219.3$ $P \text{ н.мм} = 718.35$ Гр. сл. = V Точн. = Н </p>		<p> $F \text{ см}^2 = 24.2$ $Q \text{ кг} = 6.558$ $D \text{ оп.мм} = 70.4$ $P \text{ н.мм} = 198$ Гр. сл. = III Точн. = Н </p>











	<p>OK-111</p>		<p>OK-116</p>
	<p> $F \text{ см}^2 = 0,623$ $Q \text{ кг} = 0,169$ $D \text{ оп.мм} = 24,7$ $P \text{ н.мм} = 81,74$ Гр. сл. = V Точн. = П </p>		<p> $F \text{ см}^2 = 1,244$ $Q \text{ кг} = 0,337$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 115,64$ Гр. сл. = IV Точн. = П </p>
	<p>OK-112</p>		<p>OK-117</p>
	<p> $F \text{ см}^2 = 0,636$ $Q \text{ кг} = 0,172$ $D \text{ оп.мм} = 27,4$ $P \text{ н.мм} = 81,38$ Гр. сл. = V Точн. = П </p>		<p> $F \text{ см}^2 = 18,711$ $Q \text{ кг} = 5,071$ $D \text{ оп.мм} = 180,3$ $P \text{ н.мм} = 434$ Гр. сл. = III Точн. = Н </p>
	<p>OK-113</p>		<p>OK-118</p>
	<p> $F \text{ см}^2 = 1,112$ $Q \text{ кг} = 0,301$ $D \text{ оп.мм} = 41,8$ $P \text{ н.мм} = 132,22$ Гр. сл. = V Точн. = П </p>		<p> $F \text{ см}^2 = 3,721$ $Q \text{ кг} = 1,008$ $D \text{ оп.мм} = 171$ $P \text{ н.мм} = 378$ Гр. сл. = 0сб. Точн. = Н </p>
	<p>OK-114</p>		<p>OK-119</p>
	<p> $F \text{ см}^2 = 2,334$ $Q \text{ кг} = 0,633$ $D \text{ оп.мм} = 53,81$ $P \text{ н.мм} = 150,75$ Гр. сл. = V Точн. = П </p>		<p> $F \text{ см}^2 = 5,046$ $Q \text{ кг} = 1,367$ $D \text{ оп.мм} = 237,3$ $P \text{ н.мм} = 521$ Гр. сл. = 0сб. Точн. = Н </p>
	<p>OK-115</p>		<p>OK-120</p>
	<p> $F \text{ см}^2 = 2,196$ $Q \text{ кг} = 0,595$ $D \text{ оп.мм} = 70,3$ $P \text{ н.мм} = 211,38$ Гр. сл. = V Точн. = П </p>		<p> $F \text{ см}^2 = 0,558$ $Q \text{ кг} = 0,151$ $D \text{ оп.мм} = 25,34$ $P \text{ н.мм} = 86,44$ Гр. сл. = V Точн. = Н </p>











	<p>ОК-121</p> <p>$F \text{ см}^2=13,362$ $Q \text{ кг} = 3,621$ $D \text{ оп.мм}=106$ $P \text{ н.мм} =782$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = \square$</p>		<p>ОК-126</p> <p>$F \text{ см}^2= 2,009$ $Q \text{ кг} = 0,544$ $D \text{ оп.мм}=36,88$ $P \text{ н.мм} =111,2$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = \Pi$</p>
	<p>ОК-122</p> <p>$F \text{ см}^2=11,798$ $Q \text{ кг} = 3,197$ $D \text{ оп.мм}=56,62$ $P \text{ н.мм} =148,5$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = \square$</p>		<p>ОК-127</p> <p>$F \text{ см}^2= 3,305$ $Q \text{ кг} = 0,896$ $D \text{ оп.мм}=91,6$ $P \text{ н.мм} = 350$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = H$</p>
	<p>ОК-123</p> <p>$F \text{ см}^2= 39,66$ $Q \text{ кг} = 10,748$ $D \text{ оп.мм}= 194$ $P \text{ н.мм} = 833$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = H$</p>		<p>ОК-128</p> <p>$F \text{ см}^2= 1,825$ $Q \text{ кг} = 0,495$ $D \text{ оп.мм}= 62$ $P \text{ н.мм} =192,5$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = H$</p>
	<p>ОК-124</p> <p>$F \text{ см}^2= 15,06$ $Q \text{ кг} = 4,08$ $D \text{ оп.мм}=93,7$ $P \text{ н.мм} =294$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = H$</p>		<p>ОК-129</p> <p>$F \text{ см} \approx 3,9672$ $Q \text{ кг} = 1,075$ $D \text{ оп.мм}= 126$ $P \text{ н.мм} =331,3$ $\Gamma \text{р. сл.} = \square \text{с}$ $\text{Точн.} = H$</p>
	<p>ОК-125</p> <p>$F \text{ см}^2= 2,593$ $Q \text{ кг} = 0,703$ $D \text{ оп.мм}=41,49$ $P \text{ н.мм} = 149$ $\Gamma \text{р.сл.} = V$ $\text{Точн.} = \Pi$</p>		<p>ОК-130</p> <p>$F \text{ см}^2= 2,678$ $Q \text{ кг} = 0,726$ $D \text{ оп.мм}=45,31$ $P \text{ н.мм} =231,3$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = \Pi$</p>











	<p>OK-131</p>		<p>OK-136</p>
	<p> $F \text{ см}^2 = 2,546$ $Q \text{ кг} = 0,69$ $D \text{ оп.мм} = 80,01$ $P \text{ н.мм} = 212$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>		<p> $F \text{ см}^2 = 3,536$ $Q \text{ кг} = 0,958$ $D \text{ оп.мм} = 127$ $P \text{ н.мм} = 328$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>
	<p>OK-132</p>		<p>OK-137</p>
	<p> $F \text{ см}^2 = 2,404$ $Q \text{ кг} = 0,651$ $D \text{ оп.мм} = 76,15$ $P \text{ н.мм} = 226$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>		<p> $F \text{ см}^2 = 8,063$ $Q \text{ кг} = 2,185$ $D \text{ оп.мм} = 160,88$ $P \text{ н.мм} = 740$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>
	<p>OK-133</p>		<p>OK-138</p>
	<p> $F \text{ см}^2 = 6,854$ $Q \text{ кг} = 1,857$ $D \text{ оп.мм} = 125$ $P \text{ н.мм} = 356,11$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$ </p>		<p> $F, \text{ см}^2 = 3,581$ $Q, \text{ кг} = 0,97$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 181,9$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = П$ </p>
	<p>OK-134</p>		<p>OK-139</p>
	<p> $F \text{ см}^2 = 0,751$ $Q \text{ кг} = 0,204$ $D \text{ оп.мм} = 24,25$ $P \text{ н.мм} = 58,11$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = П$ </p>		<p> $F, \text{ см}^2 = 0,529$ $Q, \text{ кг} = 0,143$ $D \text{ оп.мм} = 22,5$ $P \text{ н.мм} = 52,9$ $\Gamma \text{р. сл.} = II$ $\text{Точн.} = \text{ОСОБ}$ </p>
	<p>OK-135</p>		<p>OK-140</p>
	<p> $F \text{ см}^2 = 2,829$ $Q \text{ кг} = 0,766$ $D \text{ оп.мм} = 76$ $P \text{ н.мм} = 226,54$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p>		<p> $F, \text{ см}^2 = 6,131$ $Q, \text{ кг} = 1,631$ $D \text{ оп.мм} = 89,4$ $P \text{ н.мм} = 307$ $\Gamma \text{р. сл.} = I$ $\text{Точн.} = H$ </p>











	<p>□К-141</p>		<p>□К-146</p>
	<p> $F, \text{ см}^2 = 4.932$ $Q, \text{ кг} = 1.312$ $D_{\text{оп.,мм}} = 76.2$ $P_{\text{н.,мм}} = 247$ Гр. сл. = I Точн. = Н </p>		<p> $F, \text{ см}^2 = 8.828$ $Q, \text{ кг} = 2.392$ $D_{\text{оп.,мм}} = 63$ $P_{\text{н.,мм}} = 518.8$ Гр. сл. = VII Точн. = Н </p>
	<p>□К-142</p>		<p>□К-147</p>
	<p> $F, \text{ см}^2 = 3.299$ $Q, \text{ кг} = 0.878$ $D_{\text{оп.,мм}} = 62.6$ $P_{\text{н.,мм}} = 220$ Гр. сл. = I Точн. = Н </p>		<p> $F, \text{ см}^2 = 3.763$ $Q, \text{ кг} = 1.02$ $D_{\text{оп.,мм}} = 61$ $P_{\text{н.,мм}} = 198.3$ Гр. сл. = III Точн. = П </p>
	<p>□К-143</p>		<p>□К-148</p>
	<p> $F, \text{ см}^2 = 2.55$ $Q, \text{ кг} = 0.678$ $D_{\text{оп.,мм}} = 47.2$ $P_{\text{н.,мм}} = 170$ Гр. сл. = I Точн. = Н </p>		<p> $F, \text{ см}^2 = 1.449$ $Q, \text{ кг} = 0.393$ $D_{\text{оп.,мм}} = 40.7$ $P_{\text{н.,мм}} = 95.57$ Гр. сл. = III Точн. = П </p>
	<p>□К-144</p>		<p>□К-149</p>
	<p> $F, \text{ см}^2 = 1.95$ $Q, \text{ кг} = 0.519$ $D_{\text{оп.,мм}} = 36.1$ $P_{\text{н.,мм}} = 130$ Гр. сл. = I Точн. = Н </p>		<p> $F, \text{ см}^2 = 1.687$ $Q, \text{ кг} = 0.457$ $D_{\text{оп.,мм}} = 48.77$ $P_{\text{н.,мм}} = 109.7$ Гр. сл. = III Точн. = П </p>
	<p>□К-145</p>		<p>□К-150</p>
	<p> $F, \text{ см}^2 = 2.849$ $Q, \text{ кг} = 0.758$ $D_{\text{оп.,мм}} = 55.9$ $P_{\text{н.,мм}} = 190.14$ Гр. сл. = I Точн. = Н </p>		<p> $F, \text{ см}^2 = 3.721$ $Q, \text{ кг} = 1.008$ $D_{\text{оп.,мм}} = 52.6$ $P_{\text{н.,мм}} = 207.7$ Гр. сл. = III Точн. = П </p>











	<p>OK-151</p>		<p>OK-156</p>
	<p> $F, \text{cm}^2 = 0,535$ $Q, \text{кг} = 0,145$ $D_{\text{оп.,мм}} = 25,1$ $P_{\text{н.,мм}} = 30$ Гр. сл. = III Точн. = П </p>		<p> $F, \text{cm}^2 = 4,064$ $Q, \text{кг} = 1,101$ $D_{\text{оп.,мм}} = 132,3$ $P_{\text{н.,мм}} = 531,1$ Гр. сл. = VI Точн. = Н </p>
	<p>OK-152</p>		<p>OK-157</p>
	<p> $F, \text{cm}^2 = 17,837$ $Q, \text{кг} = 4,834$ $D_{\text{оп.,мм}} = 180,1$ $P_{\text{н.,мм}} = 502,6$ Гр. сл. = V Точн. = Н </p>		<p> $F, \text{cm}^2 = 2,769$ $Q, \text{кг} = 0,75$ $D_{\text{оп.,мм}} = 78,07$ $P_{\text{н.,мм}} = 291,4$ Гр. сл. = VI Точн. = О </p>
	<p>OK-153</p>		<p>OK-158</p>
	<p> $F, \text{cm}^2 = 1,25$ $Q, \text{кг} = 0,339$ $D_{\text{оп.,мм}} = 21,54$ $P_{\text{н.,мм}} = 86,52$ Гр. сл. = III Точн. = П </p>		<p> $F, \text{cm}^2 = 5,289$ $Q, \text{кг} = 1,433$ $D_{\text{оп.,мм}} = 121,26$ $P_{\text{н.,мм}} = 475$ Гр. сл. = VI Точн. = О </p>
	<p>OK-154</p>		<p>OK-159</p>
	<p> $F, \text{cm}^2 = 2,099$ $Q, \text{кг} = 0,558$ $D_{\text{оп.,мм}} = 40,3$ $P_{\text{н.,мм}} = 140,14$ Гр. сл. = I Точн. = Н </p>		<p> $F, \text{cm}^2 = 6,278$ $Q, \text{кг} = 1,701$ $D_{\text{оп.,мм}} = 92$ $P_{\text{н.,мм}} = 336$ Гр. сл. = IV Точн. = П </p>
	<p>OK-155</p>		<p>OK-160</p>
	<p> $F, \text{cm}^2 = 2,355$ $Q, \text{кг} = 0,638$ $D_{\text{оп.,мм}} = 68,13$ $P_{\text{н.,мм}} = 303,2$ Гр. сл. = VI Точн. = Н </p>		<p> $F, \text{cm}^2 = 1,014$ $Q, \text{кг} = 0,275$ $D_{\text{оп.,мм}} = 20,2$ $P_{\text{н.,мм}} = 92,95$ Гр. сл. = VII Точн. = Н </p>











	<p>□К-161</p>		<p>□К-166</p>
	<p> $F, \text{ см}^2 = 19,027$ $Q, \text{ кг} = 5,156$ $D_{\text{оп.,мм}} = 88,8$ $P_{\text{н.,мм}} = 745$ Гр. сл. = ОС. Точн. = Н </p>		<p> $F, \text{ см}^2 = 1,954$ $Q, \text{ кг} = 0,53$ $D_{\text{оп.,мм}} = 47,13$ $P_{\text{н.,мм}} = 147,3$ Гр. сл. = √ Точн. = Н </p>
	<p>□К-162</p>		<p>□К-167</p>
	<p> $F, \text{ см}^2 = 4,52$ $Q, \text{ кг} = 1,225$ $D_{\text{оп.,мм}} = 66$ $P_{\text{н.,мм}} = 256,4$ Гр. сл. = √I Точн. = Н </p>		<p> $F, \text{ см}^2 = 3,61$ $Q, \text{ кг} = 0,979$ $D_{\text{оп.,мм}} = 70$ $P_{\text{н.,мм}} = 249$ Гр. сл. = √ Точн. = Н </p>
	<p>□К-163</p>		<p>□К-168</p>
	<p> $F, \text{ см}^2 = 4,603$ $Q, \text{ кг} = 1,247$ $D_{\text{оп.,мм}} = 57$ $P_{\text{н.,мм}} = 227,6$ Гр. сл. = √I Точн. = Н </p>		<p> $F, \text{ см}^2 = 3,729$ $Q, \text{ кг} = 1,011$ $D_{\text{оп.,мм}} = 80,5$ $P_{\text{н.,мм}} = 323$ Гр. сл. = √ Точн. = Н </p>
	<p>□К-164</p>		<p>□К-169</p>
	<p> $F, \text{ см}^2 = 29,497$ $Q, \text{ кг} = 7,994$ $D_{\text{оп.,мм}} = 192,4$ $P_{\text{н.,мм}} = 2254,6$ Гр. сл. = ОСОБ. Точн. = Н </p>		<p> $F, \text{ см}^2 = 11,0$ $Q, \text{ кг} = 2,981$ $D_{\text{оп.,мм}} = 100,6$ $P_{\text{н.,мм}} = 222$ Гр. сл. = I Точн. = Н </p>
	<p>□К-165</p>		<p>□К-170</p>
	<p> $F, \text{ см}^2 = 7,52$ $Q, \text{ кг} = 2,038$ $D_{\text{оп.,мм}} = 59$ $P_{\text{н.,мм}} = 217,1$ Гр. сл. = √I Точн. = П </p>		<p> $F, \text{ см}^2 = 11,5$ $Q, \text{ кг} = 3,117$ $D_{\text{оп.,мм}} = 100,7$ $P_{\text{н.,мм}} = 223$ Гр. сл. = I Точн. = Н </p>











	□К-171		□К-176
	$F, \text{ см}^2 = 12.0$ $Q, \text{ кг} = 3.252$ $D_{\text{оп.,мм}} = 100.7$ $P_{\text{н.,мм}} = 224$ Гр. сл. = I Точн. = Н		$F, \text{ см}^2 = 14.5$ $Q, \text{ кг} = 3.93$ $D_{\text{оп.,мм}} = 101$ $P_{\text{н.,мм}} = 229$ Гр. сл. = I Точн. = Н
	□К-172		□К-177
	$F, \text{ см}^2 = 12.5$ $Q, \text{ кг} = 3.388$ $D_{\text{оп.,мм}} = 100.8$ $P_{\text{н.,мм}} = 225$ Гр. сл. = I Точн. = Н		$F, \text{ см}^2 = 15.0$ $Q, \text{ кг} = 4.065$ $D_{\text{оп.,мм}} = 101.1$ $P_{\text{н.,мм}} = 230$ Гр. сл. = I Точн. = Н
	□К-173		□К-178
	$F, \text{ см}^2 = 13.0$ $Q, \text{ кг} = 3.523$ $D_{\text{оп.,мм}} = 100.8$ $P_{\text{н.,мм}} = 226$ Гр. сл. = I Точн. = Н		$F, \text{ см}^2 = 15.5$ $Q, \text{ кг} = 4.201$ $D_{\text{оп.,мм}} = 101.2$ $P_{\text{н.,мм}} = 231$ Гр. сл. = I Точн. = Н
	□К-174		□К-179
	$F, \text{ см}^2 = 13.5$ $Q, \text{ кг} = 3.659$ $D_{\text{оп.,мм}} = 100.9$ $P_{\text{н.,мм}} = 227$ Гр. сл. = I Точн. = Н		$F, \text{ см}^2 = 16.0$ $Q, \text{ кг} = 4.336$ $D_{\text{оп.,мм}} = 101.3$ $P_{\text{н.,мм}} = 232$ Гр. сл. = I Точн. = Н
	□К-175		□К-180
	$F, \text{ см}^2 = 14.0$ $Q, \text{ кг} = 3.794$ $D_{\text{оп.,мм}} = 101$ $P_{\text{н.,мм}} = 228$ Гр. сл. = I Точн. = Н		$F, \text{ см}^2 = 16.5$ $Q, \text{ кг} = 4.472$ $D_{\text{оп.,мм}} = 101.4$ $P_{\text{н.,мм}} = 233$ Гр. сл. = I Точн. = Н











	□К-181		□К-186
	$F, \text{ см}^2 = 17.0$ $Q, \text{ кг} = 4.607$ $D_{\text{оп.,мм}} = 101.4$ $P_{\text{н.,мм}} = 234$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 4.95$ $Q, \text{ кг} = 1.341$ $D_{\text{оп.,мм}} = 46.3$ $P_{\text{н.,мм}} = 112$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-182		□К-187
	$F, \text{ см}^2 = 17.5$ $Q, \text{ кг} = 4.743$ $D_{\text{оп.,мм}} = 101.5$ $P_{\text{н.,мм}} = 235$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 5.172$ $Q, \text{ кг} = 1.402$ $D_{\text{оп.,мм}} = 46.4$ $P_{\text{н.,мм}} = 113$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-183		□К-188
	$F, \text{ см}^2 = 18.0$ $Q, \text{ кг} = 4.878$ $D_{\text{оп.,мм}} = 101.6$ $P_{\text{н.,мм}} = 236$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 5.4$ $Q, \text{ кг} = 1.463$ $D_{\text{оп.,мм}} = 46.6$ $P_{\text{н.,мм}} = 114$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-184		□К-189
	$F, \text{ см}^2 = 18.5$ $Q, \text{ кг} = 5.014$ $D_{\text{оп.,мм}} = 101.7$ $P_{\text{н.,мм}} = 237$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 5.625$ $Q, \text{ кг} = 1.524$ $D_{\text{оп.,мм}} = 46.7$ $P_{\text{н.,мм}} = 115$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-185		□К-190
	$F, \text{ см}^2 = 19.0$ $Q, \text{ кг} = 5.149$ $D_{\text{оп.,мм}} = 101.8$ $P_{\text{н.,мм}} = 238$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 5.85$ $Q, \text{ кг} = 1.585$ $D_{\text{оп.,мм}} = 46.8$ $P_{\text{н.,мм}} = 116$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$











	□К-191		□К-196
	$F, \text{ см}^2 = 6.075$ $Q, \text{ кг} = 1.646$ $D_{\text{оп.,мм}} = 47$ $P_{\text{н.,мм}} = 117$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 7.2$ $Q, \text{ кг} = 1.951$ $D_{\text{оп.,мм}} = 47.8$ $P_{\text{н.,мм}} = 122$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-192		□К-197
	$F, \text{ см}^2 = 6.3$ $Q, \text{ кг} = 1.707$ $D_{\text{оп.,мм}} = 47.1$ $P_{\text{н.,мм}} = 118$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 7.425$ $Q, \text{ кг} = 2.012$ $D_{\text{оп.,мм}} = 48$ $P_{\text{н.,мм}} = 123$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-193		□К-198
	$F, \text{ см}^2 = 6.525$ $Q, \text{ кг} = 1.768$ $D_{\text{оп.,мм}} = 47.3$ $P_{\text{н.,мм}} = 119$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 7.65$ $Q, \text{ кг} = 2.073$ $D_{\text{оп.,мм}} = 48.1$ $P_{\text{н.,мм}} = 124$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-194		□К-199
	$F, \text{ см}^2 = 6.75$ $Q, \text{ кг} = 1.829$ $D_{\text{оп.,мм}} = 47.4$ $P_{\text{н.,мм}} = 120$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 7.875$ $Q, \text{ кг} = 2.134$ $D_{\text{оп.,мм}} = 48.3$ $P_{\text{н.,мм}} = 125$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-195		□К-200
	$F, \text{ см}^2 = 6.975$ $Q, \text{ кг} = 1.89$ $D_{\text{оп.,мм}} = 47.6$ $P_{\text{н.,мм}} = 121$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 8.1$ $Q, \text{ кг} = 2.195$ $D_{\text{оп.,мм}} = 48.5$ $P_{\text{н.,мм}} = 126$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$











	<p>OK-201</p>		<p>OK-206</p>
	<p>$F, \text{cm}^2 = 8.325$ $Q, \text{кг} = 2.256$ $D_{\text{оп.,мм}} = 48.7$ $P_{\text{н.,мм}} = 127$ Гр. сл. = I Точн. = Н</p>		<p>$F, \text{cm}^2 = 3.049$ $Q, \text{кг} = 0.826$ $D_{\text{оп.,мм}} = 45.2$ $P_{\text{н.,мм}} = 187$ Гр. сл. = VII Точн. = П</p>
	<p>OK-202</p>		<p>OK-207</p>
	<p>$F, \text{cm}^2 = 8.55$ $Q, \text{кг} = 2.317$ $D_{\text{оп.,мм}} = 48.8$ $P_{\text{н.,мм}} = 128$ Гр. сл. = I Точн. = Н</p>		<p>$F, \text{cm}^2 = 8.773$ $Q, \text{кг} = 2.377$ $D_{\text{оп.,мм}} = 143.5$ $P_{\text{н.,мм}} = 473.9$ Гр. сл. = V Точн. = Н</p>
	<p>OK-203</p>		<p>OK-208</p>
	<p>$F, \text{cm}^2 = 48.64$ $Q, \text{кг} = 13.18$ $D_{\text{оп.,мм}} = 133.5$ $P_{\text{н.,мм}} = 332$ Гр. сл. = I Точн. = Н</p>		<p>$F, \text{cm}^2 = 3.763$ $Q, \text{кг} = 1.02$ $D_{\text{оп.,мм}} = 136.7$ $P_{\text{н.,мм}} = 382.1$ Гр. сл. = V Точн. = Н</p>
	<p>OK-204</p>		<p>OK-209</p>
	<p>$F, \text{cm}^2 = 57.243$ $Q, \text{кг} = 15.513$ $D_{\text{оп.,мм}} = 187.8$ $P_{\text{н.,мм}} = 2187$ Гр. сл. = Ос. Точн. = П</p>		<p>$F, \text{cm}^2 = 9.523$ $Q, \text{кг} = 2.581$ $D_{\text{оп.,мм}} = 177$ $P_{\text{н.,мм}} = 629.2$ Гр. сл. = Ос. Точн. = Н</p>
	<p>OK-205</p>		<p>OK-210</p>
	<p>$F, \text{cm}^2 = 0.696$ $Q, \text{кг} = 0.189$ $D_{\text{оп.,мм}} = 29.1$ $P_{\text{н.,мм}} = 66.4$ Гр. сл. = IV Точн. = П</p>		<p>$F, \text{cm}^2 = 0.861$ $Q, \text{кг} = 0.233$ $D_{\text{оп.,мм}} = 49$ $P_{\text{н.,мм}} = 137.6$ Гр. сл. = VI Точн. = П</p>











	<p>ОК-211</p> <p>$F, \text{ см}^2 = 4.75$ $Q, \text{ кг} = 1.29$ $D_{\text{оп.,мм}} = 46$ $P_{\text{н.,мм}} = 133.2$ Гр. сл. = III Точн. = П</p>		<p>ОК-216</p> <p>$F, \text{ см}^2 = 1.401$ $Q, \text{ кг} = 0.38$ $D_{\text{оп.,мм}} = 47.7$ $P_{\text{н.,мм}} = 165.6$ Гр. сл. = V Точн. = □с.</p>
	<p>ОК-212</p> <p>$F, \text{ см}^2 = 3.296$ $Q, \text{ кг} = 0.893$ $D_{\text{оп.,мм}} = 38$ $P_{\text{н.,мм}} = 111.3$ Гр. сл. = III Точн. = П</p>		<p>ОК-217</p> <p>$F, \text{ см}^2 = 2.121$ $Q, \text{ кг} = 0.575$ $D_{\text{оп.,мм}} = 58.8$ $P_{\text{н.,мм}} = 216.9$ Гр. сл. = V Точн. = Н</p>
	<p>ОК-213</p> <p>$F, \text{ см}^2 = 3.77$ $Q, \text{ кг} = 1.02$ $D_{\text{оп.,мм}} = 58$ $P_{\text{н.,мм}} = 191.4$ Гр. сл. = V Точн. = П</p>		<p>ОК-218</p> <p>$F, \text{ см}^2 = 1.484$ $Q, \text{ кг} = 0.402$ $D_{\text{оп.,мм}} = 41.7$ $P_{\text{н.,мм}} = 151.4$ Гр. сл. = V Точн. = Н</p>
	<p>ОК-214</p> <p>$F, \text{ см}^2 = 5.709$ $Q, \text{ кг} = 1.547$ $D_{\text{оп.,мм}} = 164$ $P_{\text{н.,мм}} = 570$ Гр. сл. = IV Точн. = Н</p>		<p>ОК-219</p> <p>$F, \text{ см}^2 = 3.415$ $Q, \text{ кг} = 0.925$ $D_{\text{оп.,мм}} = 74.4$ $P_{\text{н.,мм}} = 307$ Гр. сл. = □с. Точн. = Н</p>
	<p>ОК-215</p> <p>$F, \text{ см}^2 = 32.17$ $Q, \text{ кг} = 8.718$ $D_{\text{оп.,мм}} = 109$ $P_{\text{н.,мм}} = 1482$ Гр. сл. = VII Точн. = Н</p>		<p>ОК-220</p> <p>$F, \text{ см}^2 = 2.763$ $Q, \text{ кг} = 0.749$ $D_{\text{оп.,мм}} = 101.5$ $P_{\text{н.,мм}} = 429$ Гр. сл. = VI Точн. = Н</p>











	<p>OK-221</p>		<p>OK-226</p>
	<p> $F, \text{cm}^2 = 2.437$ $Q, \text{кг} = 0.661$ $D_{\text{оп.,мм}} = 86.3$ $R_{\text{н.,мм}} = 373.6$ Гр. сл. = VI Точн. = Н </p>		<p> $F, \text{cm}^2 = 1.404$ $Q, \text{кг} = 0.38$ $D_{\text{оп.,мм}} = 32.14$ $R_{\text{н.,мм}} = 91.05$ Гр. сл. = III Точн. = Н </p>
	<p>OK-222</p>		<p>OK-227</p>
	<p> $F, \text{cm}^2 = 1.833$ $Q, \text{кг} = 0.497$ $D_{\text{оп.,мм}} = 71.3$ $R_{\text{н.,мм}} = 251.8$ Гр. сл. = VI Точн. = Н </p>		<p> $F, \text{cm}^2 = 26.101$ $Q, \text{кг} = 7.073$ $D_{\text{оп.,мм}} = 182.25$ $R_{\text{н.,мм}} = 928.43$ Гр. сл. = VI Точн. = Н </p>
	<p>OK-223</p>		<p>OK-228</p>
	<p> $F, \text{cm}^2 = 5.715$ $Q, \text{кг} = 1.548$ $D_{\text{оп.,мм}} = 118.7$ $R_{\text{н.,мм}} = 525.1$ Гр. сл. = VI Точн. = Н </p>		<p> $F, \text{cm}^2 = 19.523$ $Q, \text{кг} = 5.291$ $D_{\text{оп.,мм}} = 150.23$ $R_{\text{н.,мм}} = 837.05$ Гр. сл. = VI Точн. = Н </p>
	<p>OK-224</p>		<p>OK-229</p>
	<p> $F, \text{cm}^2 = 2.846$ $Q, \text{кг} = 0.771$ $D_{\text{оп.,мм}} = 82.5$ $R_{\text{н.,мм}} = 295.5$ Гр. сл. = V Точн. = П </p>		<p> $F, \text{cm}^2 = 13.026$ $Q, \text{кг} = 3.579$ $D_{\text{оп.,мм}} = 183.07$ $R_{\text{н.,мм}} = 475.4$ Гр. сл. = V Точн. = Н </p>
	<p>OK-225</p>		<p>OK-230</p>
	<p> $F, \text{cm}^2 = 1.954$ $Q, \text{кг} = 0.53$ $D_{\text{оп.,мм}} = 40$ $R_{\text{н.,мм}} = 137.5$ Гр. сл. = V Точн. = Н </p>		<p> $F, \text{cm}^2 = 2.135$ $Q, \text{кг} = 0.578$ $D_{\text{оп.,мм}} = 39.8$ $R_{\text{н.,мм}} = 157.8$ Гр. сл. = V Точн. = Н </p>









	<p>□К-231</p>		<p>□К-236</p>
	<p> $F, \text{см}^2 = 4.5$ $Q, \text{кг} = 1.22$ $D_{\text{оп.мм}} = 50.8$ $P_{\text{н.мм}} = 118$ Гр. сл. = II Точн. = Н </p>		<p> $F, \text{см}^2 = 28.0$ $Q, \text{кг} = 7.588$ $D_{\text{оп.мм}} = 87.3$ $P_{\text{н.мм}} = 230$ Гр. сл. = II Точн. = Н </p>
	<p>□К-232</p>		<p>□К-237</p>
	<p> $F, \text{см}^2 = 3.85$ $Q, \text{кг} = 1.043$ $D_{\text{оп.мм}} = 55.4$ $P_{\text{н.мм}} = 124$ Гр. сл. = II Точн. = Н </p>		<p> $F, \text{см}^2 = 2.332$ $Q, \text{кг} = 0.632$ $D_{\text{оп.мм}} = 73.2$ $P_{\text{н.мм}} = 231.3$ Гр. сл. = V Точн. = □с. </p>
	<p>□К-233</p>		<p>□К-238</p>
	<p> $F, \text{см}^2 = 2.642$ $Q, \text{кг} = 0.716$ $D_{\text{оп.мм}} = 58.03$ $P_{\text{н.мм}} = 197$ Гр. сл. = V Точн. = Н </p>		<p> $F, \text{см}^2 = 4.95$ $Q, \text{кг} = 1.341$ $D_{\text{оп.мм}} = 55.7$ $P_{\text{н.мм}} = 128$ Гр. сл. = II Точн. = Н </p>
	<p>□К-234</p>		<p>□К-239</p>
	<p> $F, \text{см}^2 = 2.142$ $Q, \text{кг} = 0.58$ $D_{\text{оп.мм}} = 46.04$ $P_{\text{н.мм}} = 153.8$ Гр. сл. = V Точн. = Н </p>		<p> $F, \text{см}^2 = 7.275$ $Q, \text{кг} = 1.972$ $D_{\text{оп.мм}} = 171.2$ $P_{\text{н.мм}} = 633.7$ Гр. сл. = Ос. Точн. = Н </p>
	<p>□К-235</p>		<p>□К-240</p>
	<p> $F, \text{см}^2 = 4.75$ $Q, \text{кг} = 1.287$ $D_{\text{оп.мм}} = 66.1$ $P_{\text{н.мм}} = 271.7$ Гр. сл. = VI Точн. = П </p>		<p> $F, \text{см}^2 = 4.073$ $Q, \text{кг} = 1.104$ $D_{\text{оп.мм}} = 50.7$ $P_{\text{н.мм}} = 195$ Гр. сл. = VII Точн. = П </p>











	<p>OK-241</p>		<p>OK-246</p>
	<p> $F, \text{cm}^2 = 1.996$ $Q, \text{kg} = 0.541$ $D_{\text{оп.,мм}} = 28.1$ $P_{\text{н.,мм}} = 140$ Гр. сл. = V II Точн. = П </p>		<p> $F, \text{cm}^2 = 0.94$ $Q, \text{kg} = 0.256$ $D_{\text{оп.,мм}} = 22.1$ $P_{\text{н.,мм}} = 96$ Гр. сл. = V Точн. = П </p>
	<p>OK-242</p>		<p>OK-247</p>
	<p> $F, \text{cm}^2 = 0.8186$ $Q, \text{kg} = 0.222$ $D_{\text{оп.,мм}} = 30.9$ $P_{\text{н.,мм}} = 107.4$ Гр. сл. = V Точн. = Н </p>		<p> $F, \text{cm}^2 = 9.624$ $Q, \text{kg} = 2.608$ $D_{\text{оп.,мм}} = 186.7$ $P_{\text{н.,мм}} = 503.2$ Гр. сл. = V I Точн. = П </p>
	<p>OK-243</p>		<p>OK-248</p>
	<p> $F, \text{cm}^2 = 0.811$ $Q, \text{kg} = 0.22$ $D_{\text{оп.,мм}} = 30.9$ $P_{\text{н.,мм}} = 104.8$ Гр. сл. = V Точн. = Н </p>		<p> $F, \text{cm}^2 = 27.41$ $Q, \text{kg} = 7.428$ $D_{\text{оп.,мм}} = 140$ $P_{\text{н.,мм}} = 1184$ Гр. сл. = O c. Точн. = Н </p>
	<p>OK-244</p>		<p>OK-249</p>
	<p> $F, \text{cm}^2 = 1.76$ $Q, \text{kg} = 0.477$ $D_{\text{оп.,мм}} = 35.2$ $P_{\text{н.,мм}} = 116.7$ Гр. сл. = V II Точн. = П </p>		<p> $F, \text{cm}^2 = 3.967$ $Q, \text{kg} = 1.075$ $D_{\text{оп.,мм}} = 126$ $P_{\text{н.,мм}} = 331.3$ Гр. сл. = O c Точн. = Н </p>
	<p>OK-245</p>		<p>OK-250</p>
	<p> $F, \text{cm}^2 = 8.336$ $Q, \text{kg} = 2.26$ $D_{\text{оп.,мм}} = 158$ $P_{\text{н.,мм}} = 436$ Гр. сл. = V Точн. = Н </p>		<p> $F, \text{cm}^2 = 116.2$ $Q, \text{kg} = 31.49$ $D_{\text{оп.,мм}} = 183.7$ $P_{\text{н.,мм}} = 308.8$ Гр. сл. = III Точн. = Н </p>











	<p>OK-251</p>		<p>OK-256</p>
	<p>$F, \text{cm}^2 = 2.27$ $Q, \text{кг} = 0.615$ $D_{\text{оп.,мм}} = 44$ $P_{\text{н.,мм}} = 249$ $\Gamma_{\text{р. сл.}} = \text{OС}$ $\text{Точн.} = \text{H}$</p>		<p>$F, \text{cm}^2 = 3.258$ $Q, \text{кг} = 0.883$ $D_{\text{оп.,мм}} = 90$ $P_{\text{н.,мм}} = 386.1$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{П}$</p>
	<p>OK-252</p>		<p>OK-257</p>
	<p>$F, \text{cm}^2 = 0.5$ $Q, \text{кг} = 0.136$ $D_{\text{оп.,мм}} = 11.7$ $P_{\text{н.,мм}} = 74$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{H}$</p>		<p>$F, \text{cm}^2 = 3.095$ $Q, \text{кг} = 1.058$ $D_{\text{оп.,мм}} = 82$ $P_{\text{н.,мм}} = 456.8$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{П}$</p>
	<p>OK-253</p>		<p>OK-258</p>
	<p>$F, \text{cm}^2 = 2.393$ $Q, \text{кг} = 0.649$ $D_{\text{оп.,мм}} = 44.6$ $P_{\text{н.,мм}} = 167.5$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$</p>		<p>$F, \text{cm}^2 = 2.186$ $Q, \text{кг} = 0.592$ $D_{\text{оп.,мм}} = 41.7$ $P_{\text{н.,мм}} = 162.3$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$</p>
	<p>OK-254</p>		<p>OK-259</p>
	<p>$F, \text{cm}^2 = 1.45$ $Q, \text{кг} = 0.393$ $D_{\text{оп.,мм}} = 53.1$ $P_{\text{н.,мм}} = 178$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{H}$</p>		<p>$F, \text{cm}^2 = 12.145$ $Q, \text{кг} = 3.291$ $D_{\text{оп.,мм}} = 115.2$ $P_{\text{н.,мм}} = 539$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$</p>
	<p>OK-255</p>		<p>OK-260</p>
	<p>$F, \text{cm}^2 = 1.37$ $Q, \text{кг} = 0.377$ $D_{\text{оп.,мм}} = 52.5$ $P_{\text{н.,мм}} = 170$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{H}$</p>		<p>$F, \text{cm}^2 = 2.317$ $Q, \text{кг} = 0.629$ $D_{\text{оп.,мм}} = 53.9$ $P_{\text{н.,мм}} = 232.2$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$</p>









	<p>□К-261</p>		<p>□К-266</p>
	<p> $F, \text{см}^2 = 13.663$ $Q, \text{кг} = 3.703$ $D_{\text{оп.,мм}} = 103.6$ $P_{\text{н.,мм}} = 1021.8$ Гр. сл. = √I Точн. = Н </p>		<p> $F, \text{см}^2 = 2.247$ $Q, \text{кг} = 0.607$ $D_{\text{оп.,мм}} = 34$ $P_{\text{н.,мм}} = 155.7$ Гр. сл. = √ Точн. = П </p>
	<p>□К-262</p>		<p>□К-267</p>
	<p> $F, \text{см}^2 = 2.17$ $Q, \text{кг} = 0.588$ $D_{\text{оп.,мм}} = 51.7$ $P_{\text{н.,мм}} = 149$ Гр. сл. = III Точн. = Н </p>		<p> $F, \text{см}^2 = 2.247$ $Q, \text{кг} = 0.609$ $D_{\text{оп.,мм}} = 35$ $P_{\text{н.,мм}} = 166.6$ Гр. сл. = Ос. Точн. = П </p>
	<p>□К-263</p>		<p>□К-268</p>
	<p> $F, \text{см}^2 = 9.132$ $Q, \text{кг} = 2.475$ $D_{\text{оп.,мм}} = 161$ $P_{\text{н.,мм}} = 531.9$ Гр. сл. = √I Точн. = П </p>		<p> $F, \text{см}^2 = 2.145$ $Q, \text{кг} = 0.581$ $D_{\text{оп.,мм}} = 36$ $P_{\text{н.,мм}} = 116.8$ Гр. сл. = √ Точн. = П </p>
	<p>□К-264</p>		<p>□К-269</p>
	<p> $F, \text{см}^2 = 4.931$ $Q, \text{кг} = 1.336$ $D_{\text{оп.,мм}} = 85$ $P_{\text{н.,мм}} = 301.4$ Гр. сл. = √ Точн. = Н </p>		<p> $F, \text{см}^2 = 1.914$ $Q, \text{кг} = 0.519$ $D_{\text{оп.,мм}} = 58.4$ $P_{\text{н.,мм}} = 187.1$ Гр. сл. = I√ Точн. = Н </p>
	<p>□К-265</p>		<p>□К-270</p>
	<p> $F, \text{см}^2 = 1.928$ $Q, \text{кг} = 0.523$ $D_{\text{оп.,мм}} = 79.4$ $P_{\text{н.,мм}} = 245.2$ Гр. сл. = √ Точн. = Н </p>		<p> $F, \text{см}^2 = 2.356$ $Q, \text{кг} = 0.639$ $D_{\text{оп.,мм}} = 81.6$ $P_{\text{н.,мм}} = 260.7$ Гр. сл. = I√ Точн. = Н </p>

	<p>□К-271</p>		<p>□К-276</p>
 <p>Technical drawing of profile □К-271. It is a U-shaped profile with a total width of 28 mm and a height of 18 mm. The top edge has a chamfered corner.</p>	<p> $F, \text{ см}^2 = 1.138$ $Q, \text{ кг} = 0.308$ $D_{\text{оп, мм}} = 33$ $R_{\text{н, мм}} = 86.7$ $\Gamma_{\text{р. сл.}} = I \vee$ $\text{Точн.} = \Pi$ </p>	 <p>Technical drawing of profile □К-276. It is a wide, shallow U-shaped profile with a total width of 150 mm and a height of 41.5 mm. The top edge is rounded.</p>	<p> $F, \text{ см}^2 = 4.997$ $Q, \text{ кг} = 1.354$ $D_{\text{оп, мм}} = 152.1$ $R_{\text{н, мм}} = 501.6$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = H$ </p>
	<p>□К-272</p>		<p>□К-277</p>
 <p>Technical drawing of profile □К-272. It is a U-shaped profile with a total width of 30 mm and a height of 20 mm. The top edge has a complex, multi-lobed profile.</p>	<p> $F, \text{ см}^2 = 1.926$ $Q, \text{ кг} = 0.522$ $D_{\text{оп, мм}} = 41.2$ $R_{\text{н, мм}} = 127.4$ $\Gamma_{\text{р. сл.}} = I \vee$ $\text{Точн.} = \Pi$ </p>	 <p>Technical drawing of profile □К-277. It is a wide, shallow U-shaped profile with a total width of 141.6 mm. The top edge has a complex, multi-lobed profile.</p>	<p> $F, \text{ см}^2 = 10.516$ $Q, \text{ кг} = 2.85$ $D_{\text{оп, мм}} = 141.2$ $R_{\text{н, мм}} = 505.5$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = H$ </p>
	<p>□К-273</p>		<p>□К-278</p>
 <p>Technical drawing of profile □К-273. It is a U-shaped profile with a total width of 55 mm and a height of 37 mm. The top edge has a chamfered corner with a width of 4 mm.</p>	<p> $F, \text{ см}^2 = 4.36$ $Q, \text{ кг} = 1.182$ $D_{\text{оп, мм}} = 64.8$ $R_{\text{н, мм}} = 225$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = \Pi$ </p>	 <p>Technical drawing of profile □К-278. It is a U-shaped profile with a total width of 60.5 mm and a height of 12.5 mm. The top edge has a chamfered corner with a width of 1.3 mm.</p>	<p> $F, \text{ см}^2 = 4.036$ $Q, \text{ кг} = 1.094$ $D_{\text{оп, мм}} = 130.4$ $R_{\text{н, мм}} = 437.12$ $\Gamma_{\text{р. сл.}} = I \vee$ $\text{Точн.} = \Pi$ </p>
	<p>□К-274</p>		<p>□К-279</p>
 <p>Technical drawing of profile □К-274. It is a U-shaped profile with a total width of 55 mm and a height of 23 mm. The top edge has a chamfered corner with a width of 2.5 mm.</p>	<p> $F, \text{ см}^2 = 2.41$ $Q, \text{ кг} = 0.653$ $D_{\text{оп, мм}} = 60$ $R_{\text{н, мм}} = 195.7$ $\Gamma_{\text{р. сл.}} = I \vee$ $\text{Точн.} = \Pi$ </p>	 <p>Technical drawing of profile □К-279. It is a U-shaped profile with a total width of 20 mm and a height of 8.5 mm. The top edge has a complex, multi-lobed profile.</p>	<p> $F, \text{ см}^2 = 0.797$ $Q, \text{ кг} = 0.216$ $D_{\text{оп, мм}} = 21.4$ $R_{\text{н, мм}} = 81.6$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = H$ </p>
	<p>□К-275</p>		<p>□К-280</p>
 <p>Technical drawing of profile □К-275. It is a U-shaped profile with a total width of 31 mm and a height of B mm. The top edge has a chamfered corner with a width of 1.5 mm.</p>	<p> $F, \text{ см}^2 =$ $Q, \text{ кг} =$ $D_{\text{оп, мм}} =$ $R_{\text{н, мм}} =$ $\Gamma_{\text{р. сл.}} = I \vee$ $\text{Точн.} = \Pi$ </p>	 <p>Technical drawing of profile □К-280. It is a U-shaped profile with a total width of 31 mm and a height of B mm. The top edge has a chamfered corner with a width of 1.5 mm.</p>	<p> $F, \text{ см}^2 = 0.816$ $Q, \text{ кг} = 0.221$ $D_{\text{оп, мм}} = 33.6$ $R_{\text{н, мм}} = 110$ $\Gamma_{\text{р. сл.}} = V I$ $\text{Точн.} = \Pi$ </p>











	OK-281		OK-286
	$F, \text{ см}^2 = 1.160$ $Q, \text{ кг} = 0.314$ $D_{\text{оп, мм}} = 42.4$ $P_{\text{н, мм}} = 120$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{П}$		$F, \text{ см}^2 =$ $Q, \text{ кг} =$ $D_{\text{оп, мм}} =$ $P_{\text{н, мм}} =$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{П}$
	OK-282		OK-287
	$F, \text{ см}^2 = 1.383$ $Q, \text{ кг} = 0.375$ $D_{\text{оп, мм}} = 42$ $P_{\text{н, мм}} = 139$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{П}$		$F, \text{ см}^2 = 3.48$ $Q, \text{ кг} = 0.943$ $D_{\text{оп, мм}} = 59$ $P_{\text{н, мм}} = 150$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{П}$
	OK-283		OK-288
	$F, \text{ см}^2 = 0.56$ $Q, \text{ кг} = 0.152$ $D_{\text{оп, мм}} = 19.3$ $P_{\text{н, мм}} = 77$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{П}$		$F, \text{ см}^2 = 0.56$ $Q, \text{ кг} = 0.152$ $D_{\text{оп, мм}} = 18.5$ $P_{\text{н, мм}} = 56$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{П}$
	OK-284		OK-289
	$F, \text{ см}^2 = 10.838$ $Q, \text{ кг} = 2.937$ $D_{\text{оп, мм}} = 123$ $P_{\text{н, мм}} = 577.4$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{П}$		$F, \text{ см}^2 = 0.523$ $Q, \text{ кг} = 0.142$ $D_{\text{оп, мм}} = 23.3$ $P_{\text{н, мм}} = 53.9$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{П}$
	OK-285		OK-290
	$F, \text{ см}^2 = 5.26$ $Q, \text{ кг} = 1.425$ $D_{\text{оп, мм}} = 64.8$ $P_{\text{н, мм}} = 206$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{П}$		$F, \text{ см}^2 = 2.8$ $Q, \text{ кг} = 0.759$ $D_{\text{оп, мм}} = 53$ $P_{\text{н, мм}} = 180.7$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{П}$










	<p>□К-291</p>		<p>□К-296</p>
	<p>$F, \text{ см}^2 = 1,14$ $Q, \text{ кг} = 0,309$ $D_{\text{оп.}, \text{ мм}} = 26,3$ $P_{\text{н.}, \text{ мм}} = 62$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{П}$</p>		<p>$F, \text{ см}^2 = 8,995$ $Q, \text{ кг} = 2,438$ $D_{\text{оп.}, \text{ мм}} = 180$ $P_{\text{н.}, \text{ мм}} = 497,3$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{П}$</p>
	<p>□К-292</p>		<p>□К-297</p>
	<p>$F, \text{ см}^2 = 1,08$ $Q, \text{ кг} = 0,293$ $D_{\text{оп.}, \text{ мм}} = 54$ $P_{\text{н.}, \text{ мм}} = 112$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{П}$</p>		<p>$F, \text{ см}^2 = 10,37$ $Q, \text{ кг} = 2,81$ $D_{\text{оп.}, \text{ мм}} = 170,1$ $P_{\text{н.}, \text{ мм}} = 667,3$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{H}$</p>
	<p>□К-293</p>		<p>□К-298</p>
	<p>$F, \text{ см}^2 =$ $Q, \text{ кг} =$ $D_{\text{оп.}, \text{ мм}} =$ $P_{\text{н.}, \text{ мм}} =$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{П}$</p>		<p>$F, \text{ см}^2 = 44,309$ $Q, \text{ кг} = 12,008$ $D_{\text{оп.}, \text{ мм}} = 177,2$ $P_{\text{н.}, \text{ мм}} = 1656$ $\Gamma_{\text{р. сл.}} = \text{OC}$ $\text{Точн.} = \text{П}$</p>
	<p>□К-294</p>		<p>□К-299</p>
	<p>$F, \text{ см}^2 = 27,07$ $Q, \text{ кг} = 7,336$ $D_{\text{оп.}, \text{ мм}} = 178$ $P_{\text{н.}, \text{ мм}} = 689,9$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{OC}$</p>		<p>$F, \text{ см}^2 = 31,429$ $Q, \text{ кг} = 8,517$ $D_{\text{оп.}, \text{ мм}} = 201$ $P_{\text{н.}, \text{ мм}} = 1589$ $\Gamma_{\text{р. сл.}} = \text{OC}$ $\text{Точн.} = \text{П}$</p>
	<p>□К-295</p>		<p>□К-300</p>
	<p>$F, \text{ см}^2 = 4,866$ $Q, \text{ кг} = 1,319$ $D_{\text{оп.}, \text{ мм}} = 129$ $P_{\text{н.}, \text{ мм}} = 405,2$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{H}$</p>		<p>$F, \text{ см}^2 = 2,75$ $Q, \text{ кг} = 0,745$ $D_{\text{оп.}, \text{ мм}} = 55,2$ $P_{\text{н.}, \text{ мм}} = 120$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$</p>











	□К-301		□К-306
	<p> $F, \text{см}^2 = 2.75$ $Q, \text{кг} = 0.745$ $D_{\text{оп,мм}} = 50.3$ $P_{\text{н,мм}} = 111$ Гр. сл. = II Точн. = Н </p>		<p> $F, \text{см}^2 = 4.75$ $Q, \text{кг} = 1.287$ $D_{\text{оп,мм}} = 50.9$ $P_{\text{н,мм}} = 119$ Гр. сл. = II Точн. = Н </p>
	□К-302		□К-307
	<p> $F, \text{см}^2 = 3.25$ $Q, \text{кг} = 0.881$ $D_{\text{оп,мм}} = 50.4$ $P_{\text{н,мм}} = 113$ Гр. сл. = II Точн. = Н </p>		<p> $F, \text{см}^2 = 5.0$ $Q, \text{кг} = 1.355$ $D_{\text{оп,мм}} = 100.1$ $P_{\text{н,мм}} = 210$ Гр. сл. = II Точн. = Н </p>
	□К-303		□К-308
	<p> $F, \text{см}^2 = 3.75$ $Q, \text{кг} = 1.016$ $D_{\text{оп,мм}} = 50.6$ $P_{\text{н,мм}} = 115$ Гр. сл. = II Точн. = Н </p>		<p> $F, \text{см}^2 = 5.5$ $Q, \text{кг} = 1.491$ $D_{\text{оп,мм}} = 100.1$ $P_{\text{н,мм}} = 211$ Гр. сл. = II Точн. = Н </p>
	□К-304		□К-309
	<p> $F, \text{см}^2 = 4.0$ $Q, \text{кг} = 1.084$ $D_{\text{оп,мм}} = 50.6$ $P_{\text{н,мм}} = 116$ Гр. сл. = II Точн. = Н </p>		<p> $F, \text{см}^2 = 6.0$ $Q, \text{кг} = 1.626$ $D_{\text{оп,мм}} = 100.2$ $P_{\text{н,мм}} = 212$ Гр. сл. = II Точн. = Н </p>
	□К-305		□К-310
	<p> $F, \text{см}^2 = 4.25$ $Q, \text{кг} = 1.152$ $D_{\text{оп,мм}} = 50.7$ $P_{\text{н,мм}} = 117$ Гр. сл. = II Точн. = Н </p>		<p> $F, \text{см}^2 = 6.5$ $Q, \text{кг} = 1.762$ $D_{\text{оп,мм}} = 100.2$ $P_{\text{н,мм}} = 213$ Гр. сл. = II Точн. = Н </p>











	□К-311		□К-316
	$F, \text{ см}^2 = 7.5$ $Q, \text{ кг} = 2.033$ $D_{\text{оп.мм}} = 100.3$ $P_{\text{н.мм}} = 215$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 2.57$ $Q, \text{ кг} = 0.696$ $D_{\text{оп.мм}} = 45$ $P_{\text{н.мм}} = 139$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{П}$
	□К-312		□К-317
	$F, \text{ см}^2 = 8.5$ $Q, \text{ кг} = 2.304$ $D_{\text{оп.мм}} = 100.4$ $P_{\text{н.мм}} = 217$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 9.839$ $Q, \text{ кг} = 2.66$ $D_{\text{оп.мм}} = 119$ $P_{\text{н.мм}} = 585.8$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{П}$
	□К-313		□К-318
	$F, \text{ см}^2 = 9.5$ $Q, \text{ кг} = 2.575$ $D_{\text{оп.мм}} = 100.5$ $P_{\text{н.мм}} = 219$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 3.549$ $Q, \text{ кг} = 0.961$ $D_{\text{оп.мм}} = 140.8$ $P_{\text{н.мм}} = 355$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	□К-314		□К-319
	$F, \text{ см}^2 =$ $Q, \text{ кг} =$ $D_{\text{оп.мм}} =$ $P_{\text{н.мм}} =$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Ос}$		$F, \text{ см}^2 = 4.565$ $Q, \text{ кг} = 1.237$ $D_{\text{оп.мм}} = 62$ $P_{\text{н.мм}} = 132.4$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	□К-315		□К-320
	$F, \text{ см}^2 =$ $Q, \text{ кг} =$ $D_{\text{оп.мм}} =$ $P_{\text{н.мм}} =$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 6.635$ $Q, \text{ кг} = 1.798$ $D_{\text{оп.мм}} = 60$ $P_{\text{н.мм}} = 137.1$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$











	ОН-1	(ЭЛ-02)	ОН-6
	$F \text{ см}^2 = 2.56$ $Q_{\text{кз}} = 0.694$ $D_{\text{оп.мм}} = 82$ $P_{\text{н.мм}} = 260$ Гр. сл. = VI Точн. = Н		$F \text{ см}^2 = 6.855$ $Q_{\text{кз}} = 1.858$ $D_{\text{оп.мм}} = 83$ $P_{\text{н.мм}} = 236$ Гр. сл. = I Точн. = П
(AA2100)	ОН-2	(ЭЛ-03)	ОН-7
	$F \text{ см}^2 = 2.385$ $Q_{\text{кз}} = 0.646$ $D_{\text{оп.мм}} = 101$ $P_{\text{н.мм}} = 320.3$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 = 5.64$ $Q_{\text{кз}} = 1.528$ $D_{\text{оп.мм}} = 71$ $P_{\text{н.мм}} = 200$ Гр. сл. = I Точн. = П
(AA2140)	ОН-3	(П39.016)	ОН-8
	$F \text{ см}^2 = 5.251$ $Q_{\text{кз}} = 1.423$ $D_{\text{оп.мм}} = 141$ $P_{\text{н.мм}} = 578.2$ Гр. сл. = особ. Точн. = П		$F \text{ см}^2 = 1.75$ $Q_{\text{кз}} = 0.4743$ $D_{\text{оп.мм}} = 57.5$ $P_{\text{н.мм}} = 233.4$ Гр. сл. = IV Точн. = Н
(AA2170)	ОН-4	(П39.026)	ОН-9
	$F \text{ см}^2 = 5.7$ $Q_{\text{кз}} = 1.545$ $D_{\text{оп.мм}} = 172$ $P_{\text{н.мм}} = 644$ Гр. сл. = особ. Точн. = П		$F \text{ см}^2 = 0.9299$ $Q_{\text{кз}} = 0.252$ $D_{\text{оп.мм}} = 24.2$ $P_{\text{н.мм}} = 113.2$ Гр. сл. = III Точн. = Н
(TP-150)	ОН-5	(П39.028)	ОН-10
	$F \text{ см}^2 = 7.44$ $Q_{\text{кз}} = 2.016$ $D_{\text{оп.мм}} = 156$ $P_{\text{н.мм}} = 380$ Гр. сл. = IV Точн. = П		$F \text{ см}^2 = 9.84$ $Q_{\text{кз}} = 2.67$ $D_{\text{оп.мм}} = 164.1$ $P_{\text{н.мм}} = 340$ Гр. сл. = III Точн. = Н











<p>(П39.030)</p>	<p>ОН-11</p>	<p>(П39.038)</p>	<p>ОН-16</p>
	<p>$F_{\text{см}^2} = 1.792$ $Q_{\text{кз}} = 0.486$ $D_{\text{оп.мм}} = 74.1$ $P_{\text{н.мм}} = 278$ Гр. сл. = VII Точн. = Н</p>		<p>$F_{\text{см}^2} = 11.13$ $Q_{\text{кз}} = 2.94$ $D_{\text{оп.мм}} = 69$ $P_{\text{н.мм}} = 205.6$ Гр. сл. = II Точн. = Н</p>
<p>(П39.031)</p>	<p>ОН-12</p>	<p>(П39.039)</p>	<p>ОН-17</p>
	<p>$F_{\text{см}^2} = 2.36$ $Q_{\text{кз}} = 0.64$ $D_{\text{оп.мм}} = 76$ $P_{\text{н.мм}} = 302.3$ Гр. сл. = VI Точн. = Н</p>		<p>$F_{\text{см}^2} = 16.7$ $Q_{\text{кз}} = 4.41$ $D_{\text{оп.мм}} = 90$ $P_{\text{н.мм}} = 262.6$ Гр. сл. = III Точн. = Н</p>
<p>(П39.035)</p>	<p>ОН-13</p>	<p>(П39.040)</p>	<p>ОН-18</p>
	<p>$F_{\text{см}^2} = 16.01$ $Q_{\text{кз}} = 4.24$ $D_{\text{оп.мм}} = 120.2$ $P_{\text{н.мм}} = 333.3$ Гр. сл. = II Точн. = Н</p>		<p>$F_{\text{см}^2} = 9.495$ $Q_{\text{кз}} = 2.5$ $D_{\text{оп.мм}} = 57.3$ $P_{\text{н.мм}} = 157.3$ Гр. сл. = I Точн. = Н</p>
<p>(П39.036)</p>	<p>ОН-14</p>	<p>(П39.041)</p>	<p>ОН-19</p>
	<p>$F_{\text{см}^2} = 23.2$ $Q_{\text{кз}} = 6.12$ $D_{\text{оп.мм}} = 77$ $P_{\text{н.мм}} = 290.3$ Гр. сл. = V Точн. = Н</p>		<p>$F_{\text{см}^2} = 3.102$ $Q_{\text{кз}} = 0.82$ $D_{\text{оп.мм}} = 52$ $P_{\text{н.мм}} = 142$ Гр. сл. = II Точн. = Н</p>
<p>(П39.037)</p>	<p>ОН-15</p>	<p>(П39.042)</p>	<p>ОН-20</p>
	<p>$F_{\text{см}^2} = 24.46$ $Q_{\text{кз}} = 6.49$ $D_{\text{оп.мм}} = 104$ $P_{\text{н.мм}} = 294.3$ Гр. сл. = II Точн. = Н</p>		<p>$F_{\text{см}^2} = 6.102$ $Q_{\text{кз}} = 1.61$ $D_{\text{оп.мм}} = 68$ $P_{\text{н.мм}} = 190.8$ Гр. сл. = II Точн. = Н</p>











(П39.043))	ОН-21	(П39.052)	ОН-26
	$F \text{ см}^2 = 3.094$ $Q_{\text{кз}} = 0.817$ $D_{\text{оп.мм}} = 55.9$ $P_{\text{н.мм}} = 146.3$ Гр. сл. = II Точн. = Н		$F \text{ см}^2 = 1.59$ $Q_{\text{кз}} = 0.42$ $D_{\text{оп.мм}} = 21$ $P_{\text{н.мм}} = 56.67$ Гр. сл. = II Точн. = Н
(П39.045)	ОН-22	(П39.057)	ОН-27
	$F \text{ см}^2 = 1.02$ $Q_{\text{кз}} = 0.278$ $D_{\text{оп.мм}} = 18$ $P_{\text{н.мм}} = 46$ Гр. сл. = I Точн. = Н		$F \text{ см}^2 = 28.8$ $Q_{\text{кз}} = 7.8$ $D_{\text{оп.мм}} = 240$ $P_{\text{н.мм}} = 504$ Гр. сл. = II Точн. = Н
(П39.046)	ОН-23	(П39.061)	ОН-28
	$F \text{ см}^2 = 4.82$ $Q_{\text{кз}} = 1.31$ $D_{\text{оп.мм}} = 83.2$ $P_{\text{н.мм}} = 292.3$ Гр. сл. = IV Точн. = Н		$F \text{ см}^2 = 10.5$ $Q_{\text{кз}} = 2.846$ $D_{\text{оп.мм}} = 46.1$ $P_{\text{н.мм}} = 130.0$ Гр. сл. = I Точн. = Н
(П39.048)	ОН-24	(П39.062)	ОН-29
	$F \text{ см}^2 = 0.785$ $Q_{\text{кз}} = 0.213$ $D_{\text{оп.мм}} = 10$ $P_{\text{н.мм}} = 31.42$ Гр. сл. = I Точн. = Н		$F \text{ см}^2 = 39$ $Q_{\text{кз}} = 10.57$ $D_{\text{оп.мм}} = 133.5$ $P_{\text{н.мм}} = 380$ Гр. сл. = I Точн. = Н
(П39.051)	ОН-25	(П39.066)	ОН-30
	$F \text{ см}^2 = 1.61$ $Q_{\text{кз}} = 0.43$ $D_{\text{оп.мм}} = 18$ $P_{\text{н.мм}} = 56.24$ Гр. сл. = II Точн. = Н		$F \text{ см}^2 = 3.6$ $Q_{\text{кз}} = 0.976$ $D_{\text{оп.мм}} = 60.3$ $P_{\text{н.мм}} = 132$ Гр. сл. = I Точн. = Н











(П39.069)	ОН-31	(П39.076)	ОН-36
	$F \text{ см}^2 = 10.0$ $Q_{\text{кз}} = 2.71$ $D_{\text{оп.мм}} = 53.8$ $P_{\text{н.мм}} = 140$ Гр. сл. = I Точн. = Н		$F \text{ см}^2 = 52.81$ $Q_{\text{кз}} = 14.312$ $D_{\text{оп.мм}} = 82$ $P_{\text{н.мм}} = 257.6$ Гр. сл. = I Точн. = Н
(П39.070)	ОН-32	(П39.077)	ОН-37
	$F \text{ см}^2 = 40$ $Q_{\text{кз}} = 10.84$ $D_{\text{оп.мм}} = 201$ $P_{\text{н.мм}} = 440$ Гр. сл. = I Точн. = Н		$F \text{ см}^2 = 15.9$ $Q_{\text{кз}} = 4.3$ $D_{\text{оп.мм}} = 45$ $P_{\text{н.мм}} = 141.4$ Гр. сл. = I Точн. = Н
(П39.071)	ОН-33	(П39.007)	ОН-38
	$F \text{ см}^2 = 30$ $Q_{\text{кз}} = 8.13$ $D_{\text{оп.мм}} = 151.3$ $P_{\text{н.мм}} = 340$ Гр. сл. = I Точн. = Н		$F \text{ см}^2 = 0.82$ $Q_{\text{кз}} = 0.222$ $D_{\text{оп.мм}} = 28$ $P_{\text{н.мм}} = 164$ Гр. сл. = VI Точн. = II
(П39.074)	ОН-34	(П39.010)	ОН-39
	$F \text{ см}^2 = 6.22$ $Q_{\text{кз}} = 1.68$ $D_{\text{оп.мм}} = 37$ $P_{\text{н.мм}} = 103.9$ Гр. сл. = II Точн. = Н		$F \text{ см}^2 = 0.554$ $Q_{\text{кз}} = 0.15$ $D_{\text{оп.мм}} = 18.1$ $P_{\text{н.мм}} = 48.83$ Гр. сл. = III Точн. = Н
(П39.075)	ОН-35	(П39.011)	ОН-40
	$F \text{ см}^2 = 4.224$ $Q_{\text{кз}} = 1.145$ $D_{\text{оп.мм}} = 50$ $P_{\text{н.мм}} = 113.0$ Гр. сл. = II Точн. = Н		$F \text{ см}^2 = 0.593$ $Q_{\text{кз}} = 0.16$ $D_{\text{оп.мм}} = 30$ $P_{\text{н.мм}} = 87$ Гр. сл. = VI Точн. = Н











<p>(П39.014)</p>	<p>ОН-41</p>	<p>ОН-46</p>
	<p> $F_{\text{см}^2} = 1.804$ $Q_{\text{кз}} = 0.499$ $D_{\text{оп.мм}} = 90.5$ $P_{\text{н.мм}} = 211.6$ Гр. сл. = V Точн. = Н </p>	
<p>(П39.015)</p>	<p>ОН-42</p>	<p>ОН-47</p>
	<p> $F_{\text{см}^2} = 0.625$ $Q_{\text{кз}} = 0.17$ $D_{\text{оп.мм}} = 24.5$ $P_{\text{н.мм}} = 85.3$ Гр. сл. = III Точн. = Н </p>	
<p>(П39.017)</p>	<p>ОН-43</p>	<p>ОН-48</p>
	<p> $F_{\text{см}^2} = 11.54$ $Q_{\text{кз}} = 3.12$ $D_{\text{оп.мм}} = 142$ $P_{\text{н.мм}} = 543$ Гр. сл. = IV Точн. = Н </p>	
<p>(П39.018)</p>	<p>ОН-44</p>	<p>ОН-49</p>
	<p> $F_{\text{см}^2} = 12.41$ $Q_{\text{кз}} = 3.363$ $D_{\text{оп.мм}} = 150$ $P_{\text{н.мм}} = 515.3$ Гр. сл. = IV Точн. = Н </p>	
<p>(П39.019)</p>	<p>ОН-45</p>	<p>ОН-50</p>
	<p> $F_{\text{см}^2} = 10.0$ $Q_{\text{кз}} = 2.71$ $D_{\text{оп.мм}} = 100.5$ $P_{\text{н.мм}} = 220$ Гр. сл. = I Точн. = Н </p>	










	ОН-51		ОН-56
 <p>Technical drawing of profile ОН-51 showing a cross-section with a total width of 46 mm and a height of 12.9 mm.</p>	<p> $F \text{ см}^2 = 1.688$ $Q_{к2} = 0.4575$ $D_{оп.мм} = 45.3$ $P_{н.мм} = 145.6$ Гр. сл. = VI Точн. = Н </p>	 <p>Technical drawing of profile ОН-56 showing a cross-section with a total width of 36.5 mm and a height of 28 mm.</p>	<p> $F \text{ см}^2 = 3.211$ $Q_{к2} = 0.87$ $D_{оп.мм} = 41.8$ $P_{н.мм} = 189.6$ Гр. сл. = V Точн. = Н </p>
	ОН-52		ОН-57
 <p>Technical drawing of profile ОН-52 showing a cross-section with a total width of 35 mm and a height of 27 mm.</p>	<p> $F \text{ см}^2 = 2.153$ $Q_{к2} = 0.583$ $D_{оп.мм} = 42.6$ $P_{н.мм} = 162$ Гр. сл. = III Точн. = Н </p>	 <p>Technical drawing of profile ОН-57 showing a cross-section with a total width of 37.5 mm and a height of 25 mm.</p>	<p> $F \text{ см}^2 = 3.316$ $Q_{к2} = 0.899$ $D_{оп.мм} = 44.5$ $P_{н.мм} = 203.5$ Гр. сл. = V Точн. = Н </p>
	ОН-53		ОН-58
 <p>Technical drawing of profile ОН-53 showing a cross-section with a total width of 34 mm and a height of 29 mm.</p>	<p> $F \text{ см}^2 = 3.441$ $Q_{к2} = 0.933$ $D_{оп.мм} = 39.8$ $P_{н.мм} = 210.1$ Гр. сл. = IV Точн. = Н </p>	 <p>Technical drawing of profile ОН-58 showing a cross-section with a total width of 28 mm and a height of 10 mm.</p>	<p> $F \text{ см}^2 = 1.060$ $Q_{к2} = 0.287$ $D_{оп.мм} = 29.7$ $P_{н.мм} = 110.4$ Гр. сл. = III Точн. = Н </p>
	ОН-54		ОН-59
 <p>Technical drawing of profile ОН-54 showing a cross-section with a total width of 34 mm and a height of 25.5 mm.</p>	<p> $F \text{ см}^2 = 2.61$ $Q_{к2} = 0.707$ $D_{оп.мм} = 36.7$ $P_{н.мм} = 173.7$ Гр. сл. = IV Точн. = Н </p>	 <p>Technical drawing of profile ОН-59 showing a cross-section with a total width of 28 mm and a height of 10 mm.</p>	<p> $F \text{ см}^2 = 0.996$ $Q_{к2} = 0.27$ $D_{оп.мм} = 28.8$ $P_{н.мм} = 104.3$ Гр. сл. = III Точн. = Н </p>
	ОН-55		ОН-60
 <p>Technical drawing of profile ОН-55 showing a cross-section with a total width of 29 mm and a height of 18.5 mm.</p>	<p> $F \text{ см}^2 = 2.293$ $Q_{к2} = 0.621$ $D_{оп.мм} = 33.7$ $P_{н.мм} = 148.6$ Гр. сл. = IV Точн. = Н </p>	 <p>Technical drawing of profile ОН-60 showing a cross-section with a total width of 38 mm and a height of 8.5 mm.</p>	<p> $F \text{ см}^2 = 1.21$ $Q_{к2} = 0.328$ $D_{оп.мм} = 38.1$ $P_{н.мм} = 125.5$ Гр. сл. = IV Точн. = Н </p>









	ОН-61		ОН-66
	$F \text{ см}^2 = 1.15$ $Q_{к2} = 0.312$ $D_{оп.мм} = 34.1$ $P_{н.мм} = 101.3$ Гр. сл. = IV Точн. = Н		$F \text{ см}^2 = 3.233$ $Q_{к2} = 0.876$ $D_{оп.мм} = 47$ $P_{н.мм} = 199.22$ Гр. сл. = V Точн. = Н
	ОН-62		ОН-67
	$F \text{ см}^2 = 8.07$ $Q_{к2} = 2.187$ $D_{оп.мм} = 79$ $P_{н.мм} = 305.3$ Гр. сл. = VII Точн. = II		$F \text{ см}^2 = 3.337$ $Q_{к2} = 0.904$ $D_{оп.мм} = 50$ $P_{н.мм} = 204.7$ Гр. сл. = V Точн. = Н
	ОН-63		ОН-68
	$F \text{ см}^2 = 0.965$ $Q_{к2} = 0.262$ $D_{оп.мм} = 31$ $P_{н.мм} = 90.1$ Гр. сл. = III Точн. = Н		$F \text{ см}^2 = 10.18$ $Q_{к2} = 2.759$ $D_{оп.мм} = 36$ $P_{н.мм} = 113.1$ Гр. сл. = I Точн. = Н
	ОН-64		ОН-69
	$F \text{ см}^2 = 0.725$ $Q_{к2} = 0.196$ $D_{оп.мм} = 24$ $P_{н.мм} = 77$ Гр. сл. = IV Точн. = II		$F \text{ см}^2 = 0.434$ $Q_{к2} = 0.118$ $D_{оп.мм} = 21$ $P_{н.мм} = 51.1$ Гр. сл. = IV Точн. = Н
	ОН-65		ОН-70
	$F \text{ см}^2 = 3.187$ $Q_{к2} = 0.8637$ $D_{оп.мм} = 46.6$ $P_{н.мм} = 194.7$ Гр. сл. = V Точн. = Н		$F \text{ см}^2 = 2.5$ $Q_{к2} = 0.678$ $D_{оп.мм} = 50.3$ $P_{н.мм} = 110$ Гр. сл. = I Точн. = Н






	ОН-71		ОН-76
	$F \text{ см}^2 = 7.863$ $Q_{\text{кз}} = 2.131$ $D_{\text{оп.мм}} = 100$ $P_{\text{н.мм}} = 209$ Гр. сл. = I Точн. = Н		$F \text{ см}^2 = 7.998$ $Q_{\text{кз}} = 2.167$ $D_{\text{оп.мм}} = 80.5$ $P_{\text{н.мм}} = 179.1$ Гр. сл. = I Точн. = Н
(П39.027)	ОН-72		ОН-77
	$F \text{ см}^2 = 0.714$ $Q_{\text{кз}} = 0.194$ $D_{\text{оп.мм}} = 17.5$ $P_{\text{н.мм}} = 42.4$ Гр. сл. = II Точн. = Н		$F \text{ см}^2 = 2.011$ $Q_{\text{кз}} = 0.545$ $D_{\text{оп.мм}} = 16$ $P_{\text{н.мм}} = 50.26$ Гр. сл. = I Точн. = Н
	ОН-73		ОН-78
	$F \text{ см}^2 = 1.037$ $Q_{\text{кз}} = 0.281$ $D_{\text{оп.мм}} = 32.13$ $P_{\text{н.мм}} = 97.64$ Гр. сл. = В Точн. = Н		$F \text{ см}^2 = 2.545$ $Q_{\text{кз}} = 0.69$ $D_{\text{оп.мм}} = 18$ $P_{\text{н.мм}} = 56.55$ Гр. сл. = I Точн. = Н
	ОН-74		ОН-79
	$F \text{ см}^2 = 55.504$ $Q_{\text{кз}} = 15.042$ $D_{\text{оп.мм}} = 148.7$ $P_{\text{н.мм}} = 1875$ Гр. сл. = особая Точн. = II		$F \text{ см}^2 = 96.23$ $Q_{\text{кз}} = 26.08$ $D_{\text{оп.мм}} = 183$ $P_{\text{н.мм}} = 457.4$ Гр. сл. = I Точн. = Н
	ОН-75		ОН-80
	$F \text{ см}^2 = 57.908$ $Q_{\text{кз}} = 15.7$ $D_{\text{оп.мм}} = 148.7$ $P_{\text{н.мм}} = 1810$ Гр. сл. = особая Точн. = II		$F \text{ см}^2 = 3.14$ $Q_{\text{кз}} = 0.851$ $D_{\text{оп.мм}} = 20$ $P_{\text{н.мм}} = 62.83$ Гр. сл. = I Точн. = Н











	ОН-81		ОН-86
	$F_{\text{см}^2} = 11$ $Q_{\text{кз}} = 2.981$ $D_{\text{оп.мм}} = 89.4$ $P_{\text{н.мм}} = 240$ Гр. сл. = II Точн. = Н		$F_{\text{см}^2} = 1.103$ $Q_{\text{кз}} = 0.299$ $D_{\text{оп.мм}} = 45.2$ $P_{\text{н.мм}} = 114$ Гр. сл. = IV Точн. = Н
	ОН-82		ОН-87
	$F_{\text{см}^2} = 15,394$ $Q_{\text{кз}} = 4.172$ $D_{\text{оп.мм}} = 128$ $P_{\text{н.мм}} = 1056$ Гр. сл. = С Точн. = Н		$F_{\text{см}^2} = 4.07$ $Q_{\text{кз}} = 1.103$ $D_{\text{оп.мм}} = 62$ $P_{\text{н.мм}} = 189.8$ Гр. сл. = VI Точн. = Н
	ОН-83		ОН-88
	$F_{\text{см}^2} = 0.76$ $Q_{\text{кз}} = 0.206$ $D_{\text{оп.мм}} = 28.28$ $P_{\text{н.мм}} = 80$ Гр. сл. = II Точн. = Н		$F_{\text{см}^2} = 4.212$ $Q_{\text{кз}} = 1.142$ $D_{\text{оп.мм}} = 40$ $P_{\text{н.мм}} = 136.4$ Гр. сл. = V Точн. = Н
	ОН-84		ОН-89
	$F_{\text{см}^2} = 2.31$ $Q_{\text{кз}} = 0.626$ $D_{\text{оп.мм}} = 56.56$ $P_{\text{н.мм}} = 160$ Гр. сл. = III Точн. = Н		$F_{\text{см}^2} = 0.96$ $Q_{\text{кз}} = 0.26$ $D_{\text{оп.мм}} = 35.36$ $P_{\text{н.мм}} = 100$ Гр. сл. = III Точн. = Н
	ОН-85		ОН-90
	$F_{\text{см}^2} = 33.183$ $Q_{\text{кз}} = 8.993$ $D_{\text{оп.мм}} = 65$ $P_{\text{н.мм}} = 204$ Гр. сл. = I Точн. = Н		$F_{\text{см}^2} = 13$ $Q_{\text{кз}} = 3.52$ $D_{\text{оп.мм}} = 100.5$ $P_{\text{н.мм}} = 223.4$ Гр. сл. = I Точн. = Н










	ОН-91		ОН-96
	$F_{\text{см}^2} = 5.309$ $Q_{\text{кз}} = 1.439$ $D_{\text{оп.,мм}} = 26$ $P_{\text{н.,мм}} = 81.68$ Гр. сл. = I Точн. = Н		$F_{\text{см}^2} = 5.505$ $Q_{\text{кз}} = 1.492$ $D_{\text{оп.,мм}} = 118$ $P_{\text{н.,мм}} = 401.7$ Гр. сл. = VI Точн. = Н
	ОН-92		ОН-97
	$F_{\text{см}^2} = 7.069$ $Q_{\text{кз}} = 1.916$ $D_{\text{оп.,мм}} = 30$ $P_{\text{н.,мм}} = 94.25$ Гр. сл. = I Точн. = Н		$F_{\text{см}^2} = 363.1$ $Q_{\text{кз}} = 98.4$ $D_{\text{оп.,мм}} = 215$ $P_{\text{н.,мм}} = 675.5$ Гр. сл. = I Точн. = Н
	ОН-93		ОН-98
	$F_{\text{см}^2} = 12$ $Q_{\text{кз}} = 3.252$ $D_{\text{оп.,мм}} = 120.4$ $P_{\text{н.,мм}} = 260$ Гр. сл. = III Точн. = Н		$F_{\text{см}^2} = 19.635$ $Q_{\text{кз}} = 5.321$ $D_{\text{оп.,мм}} = 50$ $P_{\text{н.,мм}} = 157.1$ Гр. сл. = I Точн. = Н
	ОН-94		ОН-99
	$F_{\text{см}^2} = 4.91$ $Q_{\text{кз}} = 1.33$ $D_{\text{оп.,мм}} = 25$ $P_{\text{н.,мм}} = 78.54$ Гр. сл. = I Точн. = Н		$F_{\text{см}^2} = 1.244$ $Q_{\text{кз}} = 0.337$ $D_{\text{оп.,мм}} = 28$ $P_{\text{н.,мм}} = 90.2$ Гр. сл. = III Точн. = Н
	ОН-95		ОН-100
	$F_{\text{см}^2} = 0.832$ $Q_{\text{кз}} = 0.2256$ $D_{\text{оп.,мм}} = 23.33$ $P_{\text{н.,мм}} = 82.33$ Гр. сл. = III Точн. = Н		$F_{\text{см}^2} = 9.152$ $Q_{\text{кз}} = 2.48$ $D_{\text{оп.,мм}} = 98.08$ $P_{\text{н.,мм}} = 637$ Гр. сл. = VI Точн. = II











	ОН-101		ОН-106
	$F, \text{см}^2 = 4.656$ $Q, \text{кг} = 1.262$ $D_{\text{оп.мм}} = 68.4$ $P_{\text{н.мм}} = 219.11$ Гр. сл. = IV Точн. = П		$F, \text{см}^2 = 1.6$ $Q, \text{кг} = 0.434$ $D_{\text{оп.мм}} = 40.2$ $P_{\text{н.мм}} = 88$ Гр. сл. = II Точн. = Н
	ОН-102		ОН-107
	$F, \text{см}^2 = 6.4$ $Q, \text{кг} = 1.734$ $D_{\text{оп.мм}} = 80.4$ $P_{\text{н.мм}} = 176$ Гр. сл. = I Точн. = Н		$F, \text{см}^2 = 4.8$ $Q, \text{кг} = 1.301$ $D_{\text{оп.мм}} = 80.2$ $P_{\text{н.мм}} = 172$ Гр. сл. = II Точн. = Н
	ОН-103		ОН-108
	$F, \text{см}^2 = 4.098$ $Q, \text{кг} = 1.111$ $D_{\text{оп.мм}} = 58$ $P_{\text{н.мм}} = 232.4$ Гр. сл. = VI Точн. = Н		$F, \text{см}^2 = 4.8$ $Q, \text{кг} = 1.301$ $D_{\text{оп.мм}} = 60.5$ $P_{\text{н.мм}} = 136$ Гр. сл. = II Точн. = Н
	ОН-104		ОН-109
	$F, \text{см}^2 = 1.341$ $Q, \text{кг} = 0.363$ $D_{\text{оп.мм}} = 39$ $P_{\text{н.мм}} = 95.4$ Гр. сл. = III Точн. = Н		$F, \text{см}^2 = -$ $Q, \text{кг} = -$ $D_{\text{оп.мм}} = -$ $P_{\text{н.мм}} = -$ Гр. сл. = - Точн. = -
	ОН-105		ОН-110
	$F, \text{см}^2 = 1.298$ $Q, \text{кг} = 0.352$ $D_{\text{оп.мм}} = 33$ $P_{\text{н.мм}} = 102.7$ Гр. сл. = IV Точн. = П		$F, \text{см}^2 = 4.132$ $Q, \text{кг} = 1.12$ $D_{\text{оп.мм}} = 58.3$ $P_{\text{н.мм}} = 206.9$ Гр. сл. = V Точн. = Н











	ОН-111		ОН-116
	$F, \text{см}^2 = 5.548$ $Q, \text{кг} = 1.504$ $D_{\text{оп.мм}} = 171.2$ $P_{\text{н.мм}} = 654.7$ Гр. сл. = Ос. Точн. = Н		$F, \text{см}^2 = 0.8$ $Q, \text{кг} = 0.217$ $D_{\text{оп.мм}} = 20.4$ $P_{\text{н.мм}} = 48$ Гр. сл. = II Точн. = Н
	ОН-112		ОН-117
	$F, \text{см}^2 = 2.0$ $Q, \text{кг} = 0.542$ $D_{\text{оп.мм}} = 40.3$ $P_{\text{н.мм}} = 90$ Гр. сл. = II Точн. = Н		$F, \text{см}^2 = 1.0$ $Q, \text{кг} = 0.271$ $D_{\text{оп.мм}} = 20.6$ $P_{\text{н.мм}} = 50.0$ Гр. сл. = II Точн. = Н
БПО-915	ОН-113		ОН-118
	$F, \text{см}^2 = 0.86$ $Q, \text{кг} = 0.233$ $D_{\text{оп.мм}} = 33.5$ $P_{\text{н.мм}} = 90$ Гр. сл. = III Точн. = Н		$F, \text{см}^2 = 0.75$ $Q, \text{кг} = 0.203$ $D_{\text{оп.мм}} = 25.2$ $P_{\text{н.мм}} = 56$ Гр. сл. = II Точн. = Н
	ОН-114		ОН-119
	$F, \text{см}^2 = 0.96$ $Q, \text{кг} = 0.26$ $D_{\text{оп.мм}} = 36.1$ $P_{\text{н.мм}} = 100$ Гр. сл. = III Точн. = Н		$F, \text{см}^2 = 3.0$ $Q, \text{кг} = 0.813$ $D_{\text{оп.мм}} = 50.4$ $P_{\text{н.мм}} = 112$ Гр. сл. = II Точн. = Н
	ОН-115		ОН-120
	$F, \text{см}^2 = 1.5$ $Q, \text{кг} = 0.407$ $D_{\text{оп.мм}} = 30.4$ $P_{\text{н.мм}} = 70$ Гр. сл. = III Точн. = Н		$F, \text{см}^2 = 14.346$ $Q, \text{кг} = 3.888$ $D_{\text{оп.мм}} = 120.2$ $P_{\text{н.мм}} = 259.7$ Гр. сл. = II Точн. = Н











	ОН-121		ОН-126
	$F, \text{см}^2 = -$ $Q, \text{кз} = -$ $D_{\text{оп.мм}} = -$ $P_{\text{н.мм}} = -$ Гр. сл. = - Точн. = -		$F, \text{см}^2 = 1.2$ $Q, \text{кз} = 0.325$ $D_{\text{оп.мм}} = 40.1$ $P_{\text{н.мм}} = 86$ Гр. сл. = II Точн. = Н
	ОН-122		ОН-127
	$F, \text{см}^2 = 3.2$ $Q, \text{кз} = 0.867$ $D_{\text{оп.мм}} = 40.8$ $P_{\text{н.мм}} = 96$ Гр. сл. = II Точн. = Н		$F, \text{см}^2 = 1.2$ $Q, \text{кз} = 0.325$ $D_{\text{оп.мм}} = 30.3$ $P_{\text{н.мм}} = 68$ Гр. сл. = II Точн. = Н
	ОН-123		ОН-128
	$F, \text{см}^2 = 3.0$ $Q, \text{кз} = 0.813$ $D_{\text{оп.мм}} = 60.2$ $P_{\text{н.мм}} = 130$ Гр. сл. = II Точн. = Н		$F, \text{см}^2 = 0.56$ $Q, \text{кз} = 0.152$ $D_{\text{оп.мм}} = 21.2$ $P_{\text{н.мм}} = 60$ Гр. сл. = III Точн. = Н
БПО-1908	ОН-124		ОН-129
	$F, \text{см}^2 = 12.38$ $Q, \text{кз} = 3.355$ $D_{\text{оп.мм}} = 125$ $P_{\text{н.мм}} = 744.3$ Гр. сл. = V Точн. = Н		$F, \text{см}^2 = -$ $Q, \text{кз} = -$ $D_{\text{оп.мм}} = -$ $P_{\text{н.мм}} = -$ Гр. сл. = - Точн. = -
	ОН-125		ОН-130
	$F, \text{см}^2 = 2.0$ $Q, \text{кз} = 0.542$ $D_{\text{оп.мм}} = 50.2$ $P_{\text{н.мм}} = 108$ Гр. сл. = II Точн. = Н		$F, \text{см}^2 = -$ $Q, \text{кз} = -$ $D_{\text{оп.мм}} = -$ $P_{\text{н.мм}} = -$ Гр. сл. = - Точн. = -










	<p>ПО-01</p> <p>$F \text{ см}^2 = 0.870$ $Q \text{ кг.} = 0.236$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 118.3$ Гр. сл. = IV Точн. = Н</p>		<p>ПО-06</p> <p>$F \text{ см}^2 = 0.667$ $Q \text{ кг.} = 0.181$ $D \text{ оп.мм} = 35.5$ $P \text{ н.мм} = 111.2$ Гр. сл. = VI Точн. = Н</p>
	<p>ПО-02</p> <p>$F \text{ см}^2 = 1.924$ $Q \text{ кг.} = 0.521$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 259.2$ Гр. сл. = 0соб. Точн. = П</p>		<p>ПО-07</p> <p>$F \text{ см}^2 = 0.190$ $Q \text{ кг.} = 0.051$ $D \text{ оп.мм} = 7.0$ $P \text{ н.мм} = 17.4$ Гр. сл. = 0соб. Точн. = П</p>
	<p>ПО-03</p> <p>$F \text{ см}^2 = 3.592$ $Q \text{ кг.} = 0.973$ $D \text{ оп.мм} = 110.0$ $P \text{ н.мм} = 321.0$ Гр. сл. = IV Точн. = П</p>		<p>ПО-08</p> <p>$F \text{ см}^2 = 3.401$ $Q \text{ кг.} = 0.922$ $D \text{ оп.мм} = 101.0$ $P \text{ н.мм} = 338.9$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-04</p> <p>$F \text{ см}^2 = 2.143$ $Q \text{ кг.} = 0.581$ $D \text{ оп.мм} = 62.0$ $P \text{ н.мм} = 288.8$ Гр. сл. = 0соб. Точн. = Н</p>		<p>ПО-09</p> <p>$F \text{ см}^2 = 5.507$ $Q \text{ кг.} = 1.492$ $D \text{ оп.мм} = 118.0$ $P \text{ н.мм} = 401.7$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-05</p> <p>$F \text{ см}^2 = 5.817$ $Q \text{ кг.} = 1.576$ $D \text{ оп.мм} = 132.0$ $P \text{ н.мм} = 497.6$ Гр. сл. = IV Точн. = П</p>		<p>ПО-10</p> <p>$F \text{ см}^2 = 0.949$ $Q \text{ кг.} = 0.257$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 121.7$ Гр. сл. = VI Точн. = П</p>











	<p>ПЮ-11</p> <p>$F \text{ см}^2 = 8.236$ $Q \text{ кг.} = 2.232$ $D \text{ оп.мм} = 180.0$ $P \text{ н.мм} = 730.7$ $\text{Гр. сл.} = \text{Особ.}$ $\text{Точн.} = \text{Н}$</p>		<p>ПЮ-16</p> <p>$F \text{ см}^2 = 0.835$ $Q \text{ кг.} = 0.226$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 141.1$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{Н}$</p>
	<p>ПЮ-12</p> <p>$F \text{ см}^2 = 5.100$ $Q \text{ кг.} = 1.382$ $D \text{ оп.мм} = 129.0$ $P \text{ н.мм} = 434.2$ $\text{Гр. сл.} = \text{Особ.}$ $\text{Точн.} = \text{Н}$</p>		<p>ПЮ-17</p> <p>$F \text{ см}^2 = 2.631$ $Q \text{ кг.} = 0.713$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 323.0$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$</p>
	<p>ПЮ-13</p> <p>$F \text{ см}^2 = 1.793$ $Q \text{ кг.} = 0.486$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 185.9$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{Н}$</p>		<p>ПЮ-18</p>
	<p>ПЮ-14</p> <p>$F \text{ см}^2 = 2.220$ $Q \text{ кг.} = 0.602$ $D \text{ оп.мм} = 81.0$ $P \text{ н.мм} = 267.9$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$</p>		<p>ПЮ-19</p> <p>$F \text{ см}^2 = 2.940$ $Q \text{ кг.} = 0.797$ $D \text{ оп.мм} = 143.4$ $P \text{ н.мм} = 378.2$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{Н}$</p>
	<p>ПЮ-15</p> <p>$F \text{ см}^2 = 0.516$ $Q \text{ кг.} = 0.140$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 85.6$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$</p>		<p>ПЮ-20</p> <p>$F \text{ см}^2 = 4.410$ $Q \text{ кг.} = 1.195$ $D \text{ оп.мм} = 15.0$ $P \text{ н.мм} = 156.3$ $\text{Гр. сл.} = \text{III}$ $\text{Точн.} = \text{П}$</p>

	<p>ПО-21</p> <p>$F \text{ см}^2 = 5.959$ $Q \text{ кг.} = 1.615$ $D \text{ оп.мм} = 171.0$ $P \text{ н.мм} = 579.3$ Гр. сл. = VI Точн. = Н</p>		<p>ПО-26</p> <p>$F \text{ см}^2 = 7.877$ $Q \text{ кг.} = 2.135$ $D \text{ оп.мм} = 121.0$ $P \text{ н.мм} = 586.5$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-22</p> <p>$F \text{ см}^2 = 3.795$ $Q \text{ кг.} = 1.028$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 214.4$ Гр. сл. = IV Точн. = П</p>		<p>ПО-27</p> <p>$F \text{ см}^2 = 1.025$ $Q \text{ кг.} = 0.278$ $D \text{ оп.мм} = 23.4$ $P \text{ н.мм} = 99.0$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-23</p> <p>$F \text{ см}^2 = 3.472$ $Q \text{ кг.} = 0.941$ $D \text{ оп.мм} = 94.0$ $P \text{ н.мм} = 461.9$ Гр. сл. = VI Точн. = Н</p>		<p>ПО-28</p> <p>$F \text{ см}^2 = 16.750$ $Q \text{ кг.} = 4.539$ $D \text{ оп.мм} = 114.0$ $P \text{ н.мм} = 289.9$ Гр. сл. = IV Точн. = Н</p>
	<p>ПО-24</p> <p>$F \text{ см}^2 = 1.728$ $Q \text{ кг.} = 0.468$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 228.6$ Гр. сл. = V Точн. = Н</p>		<p>ПО-29</p> <p>$F \text{ см}^2 = 29.860$ $Q \text{ кг.} = 8.092$ $D \text{ оп.мм} = 101.0$ $P \text{ н.мм} = 301.2$ Гр. сл. = IV Точн. = Н</p>
	<p>ПО-25</p> <p>$F \text{ см}^2 = 1.250$ $Q \text{ кг.} = 0.339$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 86.5$ Гр. сл. = IV Точн. = Н</p>		<p>ПО-30</p> <p>$F \text{ см}^2 = 1.373$ $Q \text{ кг.} = 0.372$ $D \text{ оп.мм} = 21.0$ $P \text{ н.мм} = 104.4$ Гр. сл. = VI Точн. = П</p>

	<p>ПО-31</p> <p>$F \text{ см}^2 = 1.390$ $Q \text{ кг.} = 0.377$ $D \text{ оп.мм} = 58.9$ $P \text{ н.мм} = 164.2$ Гр. сл. = IV Точн. = П</p>		<p>ПО-36</p> <p>$F \text{ см}^2 = 7.510$ $Q \text{ кг.} = 2.035$ $D \text{ оп.мм} = 170.0$ $P \text{ н.мм} = 734.3$ Гр. сл. = 0соб. Точн. = П</p>
	<p>ПО-32</p> <p>$F \text{ см}^2 = 2.020$ $Q \text{ кг.} = 0.547$ $D \text{ оп.мм} = 62.9$ $P \text{ н.мм} = 270.0$ Гр. сл. = V Точн. = П</p>		<p>ПО-37</p> <p>$F \text{ см}^2 = 2.216$ $Q \text{ кг.} = 0.601$ $D \text{ оп.мм} = 44.7$ $P \text{ н.мм} = 153.1$ Гр. сл. = V Точн. = П</p>
	<p>ПО-33</p> <p>$F \text{ см}^2 = 6.175$ $Q \text{ кг.} = 1.673$ $D \text{ оп.мм} = 162.0$ $P \text{ н.мм} = 463.3$ Гр. сл. = 0соб. Точн. = П</p>		<p>ПО-38</p> <p>$F \text{ см}^2 = 0.996$ $Q \text{ кг.} = 0.270$ $D \text{ оп.мм} = 28.9$ $P \text{ н.мм} = 131.1$ Гр. сл. = III Точн. = П</p>
	<p>ПО-34</p> <p>$F \text{ см}^2 = 6.354$ $Q \text{ кг.} = 1.722$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 489.1$ Гр. сл. = 0соб. Точн. = П</p>		<p>ПО-39</p> <p>$F \text{ см}^2 = 1.050$ $Q \text{ кг.} = 0.285$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 119.2$ Гр. сл. = ШМ Точн. = П</p>
	<p>ПО-35</p> <p>$F \text{ см}^2 = 1.520$ $Q \text{ кг.} = 0.412$ $D \text{ оп.мм} = 53.0$ $P \text{ н.мм} = 226.1$ Гр. сл. = VI Точн. = Н</p>		<p>ПО-40</p> <p>$F \text{ см}^2 = 1.284$ $Q \text{ кг.} = 0.348$ $D \text{ оп.мм} = 18.5$ $P \text{ н.мм} = 64.0$ Гр. сл. = III Точн. = П</p>











	<p>ПО-41</p> <p>$F \text{ см}^2 = 1.243$ $Q \text{ кг.} = 0.337$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 137.1$ Гр. сл. = IV Точн. = П</p>		<p>ПО-46</p> <p>$F \text{ см}^2 = 7.393$ $Q \text{ кг.} = 2.004$ $D \text{ оп.мм} = 112.3$ $P \text{ н.мм} = 256.7$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-42</p> <p>$F \text{ см}^2 = 0.735$ $Q \text{ кг.} = 0.199$ $D \text{ оп.мм} = 14.0$ $P \text{ н.мм} = 50.4$ Гр. сл. = IV Точн. = П</p>		<p>ПО-47</p> <p>$F \text{ см}^2 = 5.355$ $Q \text{ кг.} = 1.451$ $D \text{ оп.мм} = 181.5$ $P \text{ н.мм} = 533.4$ Гр. сл. = 0соб. Точн. = П</p>
	<p>ПО-43</p> <p>$F \text{ см}^2 = 5.430$ $Q \text{ кг.} = 1.472$ $D \text{ оп.мм} = 86.8$ $P \text{ н.мм} = 266.3$ Гр. сл. = III Точн. = П</p>		<p>ПО-48</p> <p>$F \text{ см}^2 = 5.755$ $Q \text{ кг.} = 1.56$ $D \text{ оп.мм} = 91.0$ $P \text{ н.мм} = 483.4$ Гр. сл. = 0соб. Точн. = П</p>
	<p>ПО-44</p> <p>$F \text{ см}^2 = 0.443$ $Q \text{ кг.} = 0.120$ $D \text{ оп.мм} = 12.8$ $P \text{ н.мм} = 40.2$ Гр. сл. = III Точн. = П</p>		<p>ПО-49</p> <p>$F \text{ см}^2 = 0.769$ $Q \text{ кг.} = 0.208$ $D \text{ оп.мм} = 21.2$ $P \text{ н.мм} = 51.7$ Гр. сл. = III Точн. = П</p>
	<p>ПО-45</p> <p>$F \text{ см}^2 = 1.834$ $Q \text{ кг.} = 0.497$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 187.6$ Гр. сл. = VI Точн. = П</p>		<p>ПО-50</p> <p>$F \text{ см}^2 = 3.794$ $Q \text{ кг.} = 1.03$ $D \text{ оп.мм} = 86.0$ $P \text{ н.мм} = 428.8$ Гр. сл. = 0соб. Точн. = П</p>











	<p>ПО-51</p> <p>$F \text{ см}^2 = 2.250$ $Q \text{ кг.} = 0.610$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 112.2$ Гр. сл. = IV Точн. = П</p>		<p>ПО-56</p> <p>$F \text{ см}^2 = 31.500$ $Q \text{ кг.} = 8.537$ $D \text{ оп.мм} = 143.0$ $P \text{ н.мм} = 1260.0$ Гр. сл. = 0соб. Точн. = Н</p>
	<p>ПО-52</p> <p>$F \text{ см}^2 = 2.060$ $Q \text{ кг.} = 0.558$ $D \text{ оп.мм} = 41.6$ $P \text{ н.мм} = 106.5$ Гр. сл. = IV Точн. = П</p>		<p>ПО-57</p> <p>$F \text{ см}^2 = 2.874$ $Q \text{ кг.} = 0.779$ $D \text{ оп.мм} = 90.5$ $P \text{ н.мм} = 346.5$ Гр. сл. = 0соб. Точн. = П</p>
	<p>ПО-53</p> <p>$F \text{ см}^2 = 5.55$ $Q \text{ кг.} = 1.51$ $D \text{ оп.мм} = 172.0$ $P \text{ н.мм} = 654.7$ Гр. сл. = 0соб. Точн. = П</p>		
	<p>ПО-54</p> <p>$F \text{ см}^2 = 8.850$ $Q \text{ кг.} = 2.398$ $D \text{ оп.мм} = 139.8$ $P \text{ н.мм} = 703.7$ Гр. сл. = VI Точн. = П</p>		<p>ПО-59</p> <p>$F \text{ см}^2 = 1.578$ $Q \text{ кг.} = 0.428$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 220.0$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-55</p> <p>$F \text{ см}^2 = 1.630$ $Q \text{ кг.} = 0.442$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 161.0$ Гр. сл. = 0соб. Точн. = П</p>		<p>ПО-60</p> <p>$F \text{ см}^2 = 5.456$ $Q \text{ кг.} = 1.479$ $D \text{ оп.мм} = 141.0$ $P \text{ н.мм} = 718.8$ Гр. сл. = 0соб. Точн. = П</p>











	<p>ПО-61</p> <p>$F \text{ см}^2 = 0.537$ $Q \text{ кг.} = 0.146$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 92.3$ Гр. сл. = V Точн. = П</p>		<p>ПО-66</p> <p>$F \text{ см}^2 = 6.040$ $Q \text{ кг.} = 1.637$ $D \text{ оп.мм} = 132.0$ $P \text{ н.мм} = 602.7$ Гр. сл. = V Точн. = П</p>
	<p>ПО-62</p> <p>$F \text{ см}^2 = 2.205$ $Q \text{ кг.} = 0.598$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 173.3$ Гр. сл. = IV Точн. = П</p>		<p>ПО-67</p> <p>$F \text{ см}^2 = 0.777$ $Q \text{ кг.} = 0.211$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 122.6$ Гр. сл. = 0соб. Точн. = П</p>
	<p>ПО-63</p> <p>$F \text{ см}^2 = 1.694$ $Q \text{ кг.} = 0.459$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 172.7$ Гр. сл. = V Точн. = П</p>		<p>ПО-68</p> <p>$F \text{ см}^2 = 1.015$ $Q \text{ кг.} = 0.275$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 147.2$ Гр. сл. = V Точн. = П</p>
	<p>ПО-64</p> <p>$F \text{ см}^2 = 1.239$ $Q \text{ кг.} = 0.336$ $D \text{ оп.мм} = 62.9$ $P \text{ н.мм} = 187.8$ Гр. сл. = IV Точн. = П</p>		<p>ПО-69</p> <p>$F \text{ см}^2 = 1.169$ $Q \text{ кг.} = 0.317$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 173.5$ Гр. сл. = V Точн. = П</p>
	<p>ПО-65</p> <p>$F \text{ см}^2 = 2.680$ $Q \text{ кг.} = 0.726$ $D \text{ оп.мм} = 75.0$ $P \text{ н.мм} = 271.2$ Гр. сл. = V Точн. = П</p>		<p>ПО-70</p> <p>$F \text{ см}^2 = 1.442$ $Q \text{ кг.} = 0.391$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 165.0$ Гр. сл. = V Точн. = П</p>











	<p>ПО-71</p> <p>$F \text{ см}^2 = 2.130$ $Q \text{ кг.} = 0.577$ $D \text{ оп.мм} = 50.2$ $P \text{ н.мм} = 212.6$ Гр. сл. = V Точн. = П</p>		<p>ПО-76</p> <p>$F \text{ см}^2 = 3.149$ $Q \text{ кг.} = 0.853$ $D \text{ оп.мм} = 61.8$ $P \text{ н.мм} = 250.3$ Гр. сл. = 0соб. Точн. = П</p>
	<p>ПО-72</p> <p>$F \text{ см}^2 = 3.467$ $Q \text{ кг.} = 0.940$ $D \text{ оп.мм} = 51.8$ $P \text{ н.мм} = 317.2$ Гр. сл. = V Точн. = П</p>		<p>ПО-77</p> <p>$F \text{ см}^2 = 1.012$ $Q \text{ кг.} = 0.274$ $D \text{ оп.мм} = 26.8$ $P \text{ н.мм} = 105.2$ Гр. сл. = II Точн. = H</p>
	<p>ПО-73</p> <p>$F \text{ см}^2 = 1.054$ $Q \text{ кг.} = 0.286$ $D \text{ оп.мм} = 37.5$ $P \text{ н.мм} = 82.5$ Гр. сл. = V Точн. = H</p>		<p>ПО-78</p> <p>$F \text{ см}^2 = 3.303$ $Q \text{ кг.} = 0.895$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 239.0$ Гр. сл. = III Точн. = П</p>
	<p>ПО-74</p> <p>$F \text{ см}^2 = 0.520$ $Q \text{ кг.} = 0.141$ $D \text{ оп.мм} = 14.5$ $P \text{ н.мм} = 73.6$ Гр. сл. = V Точн. = П</p>		<p>ПО-79</p> <p>$F \text{ см}^2 = 1.110$ $Q \text{ кг.} = 0.301$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 128.0$ Гр. сл. = III Точн. = П</p>
	<p>ПО-75</p> <p>$F \text{ см}^2 = 2.100$ $Q \text{ кг.} = 0.569$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 199.8$ Гр. сл. = VI Точн. = П</p>		<p>ПО-80</p> <p>$F \text{ см}^2 = 2.798$ $Q \text{ кг.} = 0.758$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 241.1$ Гр. сл. = IV Точн. = П</p>











	<p>ПО-81</p> <p>$F \text{ см}^2 = 1.583$ $Q \text{ кг.} = 0.429$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 220.5$ Гр. сл. = IV Точн. = П</p>		<p>ПО-86</p> <p>$F \text{ см}^2 = 5.031$ $Q \text{ кг.} = 1.363$ $D \text{ оп.мм} = 140.0$ $P \text{ н.мм} = 476.7$ Гр. сл. = V Точн. = Н</p>
	<p>ПО-82</p> <p>$F \text{ см}^2 = 1.614$ $Q \text{ кг.} = 0.437$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 213.9$ Гр. сл. = IV Точн. = П</p>		<p>ПО-87</p> <p>$F \text{ см}^2 = 6.610$ $Q \text{ кг.} = 1.791$ $D \text{ оп.мм} = 141.0$ $P \text{ н.мм} = 610.5$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-83</p> <p>$F \text{ см}^2 = 0.579$ $Q \text{ кг.} = 0.157$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 105.0$ Гр. сл. = IV Точн. = П</p>		<p>ПО-88</p> <p>$F \text{ см}^2 = 3.867$ $Q \text{ кг.} = 1.048$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 213.9$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-84</p> <p>$F \text{ см}^2 = 0.618$ $Q \text{ кг.} = 0.167$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 112.0$ Гр. сл. = IV Точн. = П</p>		<p>ПО-89</p> <p>$F \text{ см}^2 = 8.258$ $Q \text{ кг.} = 2.238$ $D \text{ оп.мм} = 148.4$ $P \text{ н.мм} = 706.5$ Гр. сл. = 0соб. Точн. = Н</p>
	<p>ПО-85</p> <p>$F \text{ см}^2 = 15.000$ $Q \text{ кг.} = 4.065$ $D \text{ оп.мм} = 142.0$ $P \text{ н.мм} = 608.5$ Гр. сл. = IV Точн. = Н</p>		<p>ПО-90</p> <p>$F \text{ см}^2 = 3.040$ $Q \text{ кг.} = 0.824$ $D \text{ оп.мм} = 132.0$ $P \text{ н.мм} = 294.0$ Гр. сл. = 0соб. Точн. = Н</p>











	<p>ПО-91</p> <p>$F \text{ см}^2 = 1.835$ $Q \text{ кг.} = 0.497$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 219.5$ Гр. сл. = 0соб. Точн. = П</p>		<p>ПО-96</p> <p>$F \text{ см}^2 = 0.285$ $Q \text{ кг.} = 0.077$ $D \text{ оп.мм} = 20.2$ $P \text{ н.мм} = 50.8$ Гр. сл. = Точн. = Н</p>
	<p>ПО-92</p> <p>$F \text{ см}^2 = 2.923$ $Q \text{ кг.} = 0.792$ $D \text{ оп.мм} = 105.0$ $P \text{ н.мм} = 337.1$ Гр. сл. = 0соб. Точн. = П</p>		<p>ПО-97</p> <p>$F \text{ см}^2 = 4.040$ $Q \text{ кг.} = 1.095$ $D \text{ оп.мм} = 106.0$ $P \text{ н.мм} = 479.0$ Гр. сл. = 0соб. Точн. =</p>
	<p>ПО-93</p> <p>$F \text{ см}^2 = 3.535$ $Q \text{ кг.} = 0.958$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 408.1$ Гр. сл. = 0соб. Точн. = П</p>		<p>ПО-98</p> <p>$F \text{ см}^2 = 4.560$ $Q \text{ кг.} = 1.236$ $D \text{ оп.мм} = 152.0$ $P \text{ н.мм} = 510.6$ Гр. сл. = 0соб. Точн. = Н</p>
	<p>ПО-94</p> <p>$F \text{ см}^2 = 0.860$ $Q \text{ кг.} = 0.233$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 115.8$ Гр. сл. = IV Точн. = Н</p>		<p>ПО-99</p> <p>$F \text{ см}^2 = 0.806$ $Q \text{ кг.} = 0.218$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 135.2$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-95</p> <p>$F \text{ см}^2 = 0.525$ $Q \text{ кг.} = 0.142$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 75.4$ Гр. сл. = IV Точн. = Н</p>		<p>ПО-100</p> <p>$F \text{ см}^2 = 0.579$ $Q \text{ кг.} = 0.157$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 98.1$ Гр. сл. = V Точн. = П</p>











	<p>ПО-101</p> <p>$F \text{ см}^2 = 2.195$ $Q \text{ кг.} = 0.595$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 286.5$ Гр. сл. = III Точн. = П</p>		<p>ПО-106</p> <p>$F \text{ см}^2 = 3.797$ $Q \text{ кг.} = 1.029$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 242.9$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-102</p> <p>$F \text{ см}^2 = 1.654$ $Q \text{ кг.} = 0.448$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 232.4$ Гр. сл. = III Точн. = П</p>		<p>ПО-107</p> <p>$F \text{ см}^2 = 0.971$ $Q \text{ кг.} = 0.263$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 161.4$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-103</p> <p>$F \text{ см}^2 = 0.791$ $Q \text{ кг.} = 0.214$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 142.5$ Гр. сл. = V Точн. = П</p>		<p>ПО-108</p> <p>$F \text{ см}^2 = 1.999$ $Q \text{ кг.} = 0.542$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 178.8$ Гр. сл. = V Точн. = П</p>
	<p>ПО-104</p> <p>$F \text{ см}^2 = 0.540$ $Q \text{ кг.} = 0.146$ $D \text{ оп.мм} = 23.0$ $P \text{ н.мм} = 81.0$ Гр. сл. = IV Точн. = П</p>		<p>ПО-109</p> <p>$F \text{ см}^2 = 0.370$ $Q \text{ кг.} = 0.100$ $D \text{ оп.мм} = 12.5$ $P \text{ н.мм} = 61.4$ Гр. сл. = V Точн. = П</p>
	<p>ПО-105</p> <p>$F \text{ см}^2 = 1.369$ $Q \text{ кг.} = 0.371$ $D \text{ оп.мм} = 94.0$ $P \text{ н.мм} = 211.7$ Гр. сл. = V Точн. = П</p>		<p>ПО-110</p> <p>$F \text{ см}^2 = 0.391$ $Q \text{ кг.} = 0.106$ $D \text{ оп.мм} = 13.4$ $P \text{ н.мм} = 63.6$ Гр. сл. = V Точн. = П</p>











	<p>ПО-111</p> <p>$F \text{ см}^2 = 0.422$ $Q \text{ кг.} = 0.114$ $D \text{ оп.мм} = 14.6$ $P \text{ н.мм} = 67.6$ Гр. сл. = V Точн. = П</p>		<p>ПО-116</p> <p>$F \text{ см}^2 = 1.853$ $Q \text{ кг.} = 0.502$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 150.1$ Гр. сл. = V Точн. = П</p>
	<p>ПО-112</p> <p>$F \text{ см}^2 = 0.463$ $Q \text{ кг.} = 0.125$ $D \text{ оп.мм} = 15.7$ $P \text{ н.мм} = 70.2$ Гр. сл. = V Точн. = П</p>		<p>ПО-117</p> <p>$F \text{ см}^2 = 5.833$ $Q \text{ кг.} = 1.581$ $D \text{ оп.мм} = 152.0$ $P \text{ н.мм} = 587.3$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-113</p> <p>$F \text{ см}^2 = 0.856$ $Q \text{ кг.} = 0.232$ $D \text{ оп.мм} = 25.8$ $P \text{ н.мм} = 111.7$ Гр. сл. = V Точн. = П</p>		<p>ПО-118</p> <p>$F \text{ см}^2 = 0.940$ $Q \text{ кг.} = 0.255$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 118.4$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-114</p> <p>$F \text{ см}^2 = 1.474$ $Q \text{ кг.} = 0.399$ $D \text{ оп.мм} = 48.1$ $P \text{ н.мм} = 170.7$ Гр. сл. = V Точн. = П</p>		<p>ПО-119</p> <p>$F \text{ см}^2 = 0.408$ $Q \text{ кг.} = 0.111$ $D \text{ оп.мм} = 17.8$ $P \text{ н.мм} = 69.0$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-115</p> <p>$F \text{ см}^2 = 1.599$ $Q \text{ кг.} = 0.433$ $D \text{ оп.мм} = 48.1$ $P \text{ н.мм} = 186.3$ Гр. сл. = V Точн. = П</p>		<p>ПО-120</p> <p>$F \text{ см}^2 = 6.154$ $Q \text{ кг.} = 1.668$ $D \text{ оп.мм} = 142.0$ $P \text{ н.мм} = 601.4$ Гр. сл. = 0соб. Точн. = Н</p>









	<p>ПЮ-121</p> <p>$F \text{ см}^2 = 0.562$ $Q \text{ кг.} = 0.152$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 96.7$ Гр. сл. = IV Точн. = Н</p>		<p>ПЮ-126</p> <p>$F \text{ см}^2 = 0.688$ $Q \text{ кг.} = 0.186$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 73.0$ Гр. сл. = III Точн. = П</p>
	<p>ПЮ-122</p> <p>$F \text{ см}^2 = 0.996$ $Q \text{ кг.} = 0.270$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 54.8$ Гр. сл. = II Точн. = Н</p>		<p>ПЮ-127</p> <p>$F \text{ см}^2 = 6.098$ $Q \text{ кг.} = 1.653$ $D \text{ оп.мм} = 180.0$ $P \text{ н.мм} = 663.6$ Гр. сл. = V Точн. = Н</p>
	<p>ПЮ-123</p> <p>$F \text{ см}^2 = 1.050$ $Q \text{ кг.} = 0.285$ $D \text{ оп.мм} = 20.6$ $P \text{ н.мм} = 60.8$ Гр. сл. = II Точн. = Н</p>		<p>ПЮ-128</p> <p>$F \text{ см}^2 = 5.648$ $Q \text{ кг.} = 1.531$ $D \text{ оп.мм} = 180.0$ $P \text{ н.мм} = 621.6$ Гр. сл. = V Точн. = Н</p>
	<p>ПЮ-124</p> <p>$F \text{ см}^2 = 1.479$ $Q \text{ кг.} = 0.4008$ $D \text{ оп.мм} = 40.5$ $P \text{ н.мм} = 196.1$ Гр. сл. = V Точн. = П</p>		<p>ПЮ-129</p> <p>$F \text{ см}^2 = 5.524$ $Q \text{ кг.} = 1.497$ $D \text{ оп.мм} = 170.0$ $P \text{ н.мм} = 590.2$ Гр. сл. = Особ. Точн. = П</p>
	<p>ПЮ-125</p> <p>$F \text{ см}^2 = 1.648$ $Q \text{ кг.} = 0.447$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 230.0$ Гр. сл. = iv Точн. = П</p>		<p>ПЮ-130</p> <p>$F \text{ см}^2 = 3.165$ $Q \text{ кг.} = 0.858$ $D \text{ оп.мм} = 93.0$ $P \text{ н.мм} = 344.7$ Гр. сл. = Особ. Точн. = П</p>











	<p>ПЮ-131</p> <p>$F \text{ см}^2 = 9.023$ $Q \text{ кг.} = 2.445$ $D \text{ оп.мм} = 191.0$ $P \text{ н.мм} = 584.7$ Гр. сл. = 0соб. Точн. = Н</p>		<p>ПЮ-136</p> <p>$F \text{ см}^2 = 1.038$ $Q \text{ кг.} = 0.281$ $D \text{ оп.мм} = 52.9$ $P \text{ н.мм} = 151.4$ Гр. сл. = V Точн. = П</p>
	<p>ПЮ-132</p> <p>$F \text{ см}^2 = 0.981$ $Q \text{ кг.} = 0.266$ $D \text{ оп.мм} = 26.8$ $P \text{ н.мм} = 149.5$ Гр. сл. = III Точн. = П</p>		<p>ПЮ-137</p> <p>$F \text{ см}^2 = 0.909$ $Q \text{ кг.} = 0.246$ $D \text{ оп.мм} = 51.9$ $P \text{ н.мм} = 129.0$ Гр. сл. = V Точн. = П</p>
	<p>ПЮ-133</p> <p>$F \text{ см}^2 = 0.836$ $Q \text{ кг.} = 0.227$ $D \text{ оп.мм} = 29.4$ $P \text{ н.мм} = 150.9$ Гр. сл. = V Точн. = П</p>		<p>ПЮ-138</p> <p>$F \text{ см}^2 = 0.742$ $Q \text{ кг.} = 0.201$ $D \text{ оп.мм} = 17.4$ $P \text{ н.мм} = 58.8$ Гр. сл. = V Точн. = Н</p>
	<p>ПЮ-134</p> <p>$F \text{ см}^2 = 1.414$ $Q \text{ кг.} = 0.383$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 166.3$ Гр. сл. = V Точн. = П</p>		<p>ПЮ-139</p> <p>$F \text{ см}^2 = 1.078$ $Q \text{ кг.} = 0.292$ $D \text{ оп.мм} = 61.4$ $P \text{ н.мм} = 154.9$ Гр. сл. = V Точн. = Н</p>
	<p>ПЮ-135</p> <p>$F \text{ см}^2 = 0.926$ $Q \text{ кг.} = 0.251$ $D \text{ оп.мм} = 32.1$ $P \text{ н.мм} = 107.2$ Гр. сл. = V Точн. = П</p>		<p>ПЮ-140</p> <p>$F \text{ см}^2 = 0.694$ $Q \text{ кг.} = 0.188$ $D \text{ оп.мм} = 27.7$ $P \text{ н.мм} = 62.2$ Гр. сл. = V Точн. = Н</p>











	<p>ПЮ-141</p> <p>$F \text{ см}^2 = 1.294$ $Q \text{ кг.} = 0.351$ $D \text{ оп.мм} = 47.4$ $P \text{ н.мм} = 102.2$ Гр. сл. = V Точн. = Н</p>		<p>ПЮ-146</p> <p>$F \text{ см}^2 = 4.066$ $Q \text{ кг.} = 1.102$ $D \text{ оп.мм} = 145.0$ $P \text{ н.мм} = 439.9$ Гр. сл. = VI Точн. = Н</p>
	<p>ПЮ-142</p> <p>$F \text{ см}^2 = 6.715$ $Q \text{ кг.} = 1.820$ $D \text{ оп.мм} = 154.0$ $P \text{ н.мм} = 384.8$ Гр. сл. = III Точн. = Н</p>		<p>ПЮ-147</p> <p>$F \text{ см}^2 = 2.554$ $Q \text{ кг.} = 0.692$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 182.7$ Гр. сл. = V Точн. = П</p>
	<p>ПЮ-143</p> <p>$F \text{ см}^2 = 1.988$ $Q \text{ кг.} = 0.539$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 333.6$ Гр. сл. = IV Точн. = Н</p>		<p>ПЮ-148</p> <p>$F \text{ см}^2 = 2.790$ $Q \text{ кг.} = 0.756$ $D \text{ оп.мм} = 60.8$ $P \text{ н.мм} = 276.3$ Гр. сл. = VI Точн. = П</p>
	<p>ПЮ-144</p> <p>$F \text{ см}^2 = 1.303$ $Q \text{ кг.} = 0.353$ $D \text{ оп.мм} = 77$ $P \text{ н.мм} = 217.6$ Гр. сл. = VI Точн. = Н</p>		<p>ПЮ-149</p> <p>$F \text{ см}^2 = 0.436$ $Q \text{ кг.} = 0.118$ $D \text{ оп.мм} = 19.0$ $P \text{ н.мм} = 63.6$ Гр. сл. = IV Точн. = П</p>
	<p>ПЮ-145</p> <p>$F \text{ см}^2 = 8.487$ $Q \text{ кг.} = 2.300$ $D \text{ оп.мм} = 154.0$ $P \text{ н.мм} = 844.1$ Гр. сл. = 0соб. Точн. = П</p>		<p>ПЮ-150</p> <p>$F \text{ см}^2 = 1.284$ $Q \text{ кг.} = 0.348$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 199.0$ Гр. сл. = VI Точн. = П</p>











	<p>ПО-151</p> <p>$F \text{ см}^2 = 0.973$ $Q \text{ кг.} = 0.264$ $D \text{ оп.мм} = 42.8$ $P \text{ н.мм} = 151.1$ Гр. сл. = VI Точн. = П</p>		<p>ПО-156</p> <p>$F \text{ см}^2 = 0.371$ $Q \text{ кг.} = 0.101$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 64.1$ Гр. сл. = IV Точн. = Н</p>
	<p>ПО-152</p> <p>$F \text{ см}^2 = 2.055$ $Q \text{ кг.} = 0.557$ $D \text{ оп.мм} = 66.5$ $P \text{ н.мм} = 281.6$ Гр. сл. = 0соб. Точн. = П</p>		<p>ПО-157</p> <p>$F \text{ см}^2 = 0.609$ $Q \text{ кг.} = 0.165$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 103.8$ Гр. сл. = IV Точн. = Н</p>
	<p>ПО-153</p> <p>$F \text{ см}^2 = 0.723$ $Q \text{ кг.} = 0.196$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 112.3$ Гр. сл. = V Точн. = П</p>		<p>ПО-158</p> <p>$F \text{ см}^2 = 0.666$ $Q \text{ кг.} = 0.180$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 105.9$ Гр. сл. = IV Точн. = Н</p>
	<p>ПО-154</p> <p>$F \text{ см}^2 = 0.799$ $Q \text{ кг.} = 0.217$ $D \text{ оп.мм} = 31.3$ $P \text{ н.мм} = 110.0$ Гр. сл. = 0соб. Точн. = П</p>		<p>ПО-159</p> <p>$F \text{ см}^2 = 3.661$ $Q \text{ кг.} = 0.992$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 361.1$ Гр. сл. = 0соб. Точн. = П</p>
	<p>ПО-155</p> <p>$F \text{ см}^2 = 0.551$ $Q \text{ кг.} = 0.149$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 94.1$ Гр. сл. = IV Точн. = П</p>		<p>ПО-160</p> <p>$F \text{ см}^2 = 1.683$ $Q \text{ кг.} = 0.456$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 80.3$ Гр. сл. = I Точн. = П</p>










	<p>ПО-161</p> <p>$F \text{ см}^2 = 1.101$ $Q \text{ кг.} = 0.298$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 93.9$ Гр. сл. = III Точн. = П</p>		<p>ПО-166</p> <p>$F \text{ см}^2 = 0.840$ $Q \text{ кг.} = 0.228$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 139.5$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-162</p> <p>$F \text{ см}^2 = 6.200$ $Q \text{ кг.} = 1.680$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 141.4$ Гр. сл. = I Точн. = П</p>		<p>ПО-167</p> <p>$F \text{ см}^2 = 1.487$ $Q \text{ кг.} = 0.403$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 248.1$ Гр. сл. = Особая Точн. = П</p>
	<p>ПО-163</p> <p>$F \text{ см}^2 = 6.734$ $Q \text{ кг.} = 1.825$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 144.3$ Гр. сл. = I Точн. = П</p>		<p>ПО-168</p> <p>$F \text{ см}^2 = 1.567$ $Q \text{ кг.} = 0.425$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 261.5$ Гр. сл. = Особ. Точн. = П</p>
	<p>ПО-164</p> <p>$F \text{ см}^2 = 2.910$ $Q \text{ кг.} = 0.789$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 175.0$ Гр. сл. = III Точн. = П</p>		<p>ПО-169</p> <p>$F \text{ см}^2 = 2.624$ $Q \text{ кг.} = 0.711$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 231.1$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-165</p> <p>$F \text{ см}^2 = 2.860$ $Q \text{ кг.} = 0.775$ $D \text{ оп.мм} = 38.4$ $P \text{ н.мм} = 102.0$ Гр. сл. = II Точн. = П</p>		<p>ПО-170</p> <p>$F \text{ см}^2 = 0.883$ $Q \text{ кг.} = 0.239$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 137.0$ Гр. сл. = IV Точн. = П</p>










	<p>ПО-171</p> <p>$F \text{ см}^2 = 1.156$ $Q \text{ кг.} = 0.313$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 179.0$ Гр. сл. = IV Точн. = П</p>		<p>ТО-176</p>
	<p>ПО-172</p> <p>$F \text{ см}^2 = 3.010$ $Q \text{ кг.} = 0.816$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 252.0$ Гр. сл. = IV Точн. = П</p>		<p>ПО-177</p> <p>$F \text{ см}^2 = 17.837$ $Q \text{ кг.} = 4.834$ $D \text{ оп.мм} = 180.1$ $P \text{ н.мм} = 502.6$ Гр. сл. = V Точн. = П</p>
	<p>ПО-173</p> <p>$F \text{ см}^2 = 4.830$ $Q \text{ кг.} = 1.309$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 560.3$ Гр. сл. = VI Точн. = П</p>		<p>ПО-178</p> <p>$F \text{ см}^2 = 1.355$ $Q \text{ кг.} = 0.367$ $D \text{ оп.мм} = 30.4$ $P \text{ н.мм} = 79.5$ Гр. сл. = IV Точн. = Н</p>
	<p>ПО-174</p> <p>$F \text{ см}^2 = 1.320$ $Q \text{ кг.} = 0.358$ $D \text{ оп.мм} = 85.2$ $P \text{ н.мм} = 198.0$ Гр. сл. = 0соб. Точн. = Н</p>		<p>ПО-178</p> <p>$F \text{ см}^2 = 1.445$ $Q \text{ кг.} = 0.392$ $D \text{ оп.мм} = 40.7$ $P \text{ н.мм} = 176.9$ Гр. сл. = IV Точн. = Н</p>
			<p>ПО-180</p> <p>$F \text{ см}^2 = 1.392$ $Q \text{ кг.} = 0.377$ $D \text{ оп.мм} = 116.0$ $P \text{ н.мм} = 179.8$ Гр. сл. = IV Точн. = П</p>







	<p>ПО-181</p> <p>$F \text{ см}^2 = 1.737$ $Q \text{ кг.} = 0.471$ $D \text{ оп.мм} = 62.0$ $P \text{ н.мм} = 225.2$ Гр. сл. = V Точн. = П</p>		<p>ПО-186</p> <p>$F \text{ см}^2 = 0.672$ $Q \text{ кг.} = 0.182$ $D \text{ оп.мм} = 25.6$ $P \text{ н.мм} = 93.7$ Гр. сл. = V Точн. = П</p>
	<p>ПО-182</p> <p>$F \text{ см}^2 = 6.280$ $Q \text{ кг.} = 1.702$ $D \text{ оп.мм} = 181.0$ $P \text{ н.мм} = 678.3$ Гр. сл. = 0соб. Точн. = П</p>		<p>ПО-187</p> <p>$F \text{ см}^2 = 0.433$ $Q \text{ кг.} = 0.117$ $D \text{ оп.мм} = 21.3$ $P \text{ н.мм} = 65.7$ Гр. сл. = V Точн. = П</p>
	<p>ПО-183</p> <p>$F \text{ см}^2 = 3.792$ $Q \text{ кг.} = 1.028$ $D \text{ оп.мм} = 163.0$ $P \text{ н.мм} = 428.0$ Гр. сл. = IV Точн. = П</p>		<p>ПО-188</p> <p>$F \text{ см}^2 = 1.324$ $Q \text{ кг.} = 0.359$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 145.0$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-184</p> <p>$F \text{ см}^2 = 1.427$ $Q \text{ кг.} = 0.387$ $D \text{ оп.мм} = 48.1$ $P \text{ н.мм} = 124.1$ Гр. сл. = V Точн. = П</p>		<p>ПО-189</p> <p>$F \text{ см}^2 = 1.720$ $Q \text{ кг.} = 0.466$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 165.0$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-185</p> <p>$F \text{ см}^2 = 1.000$ $Q \text{ кг.} = 0.271$ $D \text{ оп.мм} = 34.5$ $P \text{ н.мм} = 174.4$ Гр. сл. = V Точн. = П</p>		<p>ПО-190</p> <p>$F \text{ см}^2 = 1.701$ $Q \text{ кг.} = 0.461$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 261.3$ Гр. сл. = 0соб. Точн. = Н</p>










	<p>ПО-191</p> <p>$F \text{ см}^2 = 10.217$ $Q \text{ кг.} = 2.769$ $D \text{ оп.мм} = 190.0$ $P \text{ н.мм} = 659.1$ Гр. сл. = 0соб. Точн. = Н</p>		<p>ПО-196</p> <p>$F \text{ см}^2 = 1.164$ $Q \text{ кг.} = 0.315$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 163.0$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-192</p> <p>$F \text{ см}^2 = 8.643$ $Q \text{ кг.} = 2.342$ $D \text{ оп.мм} = 126.0$ $P \text{ н.мм} = 594.0$ Гр. сл. = 0соб. Точн. = Н</p>		<p>ПО-197</p> <p>$F \text{ см}^2 = 2.141$ $Q \text{ кг.} = 0.580$ $D \text{ оп.мм} = 86.0$ $P \text{ н.мм} = 285$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-193</p> <p>$F \text{ см}^2 = 9.504$ $Q \text{ кг.} = 2.576$ $D \text{ оп.мм} = 152.0$ $P \text{ н.мм} = 651.3$ Гр. сл. = V Точн. = Н</p>		<p>ПО-198</p> <p>$F \text{ см}^2 = 1.478$ $Q \text{ кг.} = 0.401$ $D \text{ оп.мм} = 87.0$ $P \text{ н.мм} = 201.0$ Гр. сл. = IV Точн. = Н</p>
	<p>ПО-194</p> <p>$F \text{ см}^2 = 2.458$ $Q \text{ кг.} = 0.666$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 250.3$ Гр. сл. = 0соб. Точн. = Н</p>		<p>ПО-199</p> <p>$F \text{ см}^2 = 2.978$ $Q \text{ кг.} = 0.807$ $D \text{ оп.мм} = 174.0$ $P \text{ н.мм} = 401.0$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-195</p> <p>$F \text{ см}^2 = 1.725$ $Q \text{ кг.} = 0.467$ $D \text{ оп.мм} = 87.0$ $P \text{ н.мм} = 237.0$ Гр. сл. = IV Точн. = П</p>		<p>ПО-200</p> <p>$F \text{ см}^2 = 0.772$ $Q \text{ кг.} = 0.209$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 128.9$ Гр. сл. = 0соб. Точн. = Н</p>

	<p>ПО-201</p> <p>$F \text{ см}^2 = 1.064$ $Q \text{ кг.} = 0.288$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 176.4$ Гр. сл. = VI Точн. = П</p>		<p>ПО-206</p> <p>$F \text{ см}^2 = 3.428$ $Q \text{ кг.} = 0.929$ $D \text{ оп.мм} = 101.0$ $P \text{ н.мм} = 318.8$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-202</p> <p>$F \text{ см}^2 = 7.117$ $Q \text{ кг.} = 1.929$ $D \text{ оп.мм} = 190.0$ $P \text{ н.мм} = 630.3$ Гр. сл. = 0соб. Точн. = Н</p>		<p>ПО-207</p> <p>$F \text{ см}^2 = 1.144$ $Q \text{ кг.} = 0.310$ $D \text{ оп.мм} = 33.1$ $P \text{ н.мм} = 102.6$ Гр. сл. = IV Точн. = Н</p>
	<p>ПО-203</p> <p>$F \text{ см}^2 = 1.111$ $Q \text{ кг.} = 0.301$ $D \text{ оп.мм} = 25.5$ $P \text{ н.мм} = 75.6$ Гр. сл. = IV Точн. = Н</p>		<p>ПО-208</p> <p>$F \text{ см}^2 = 2.931$ $Q \text{ кг.} = 0.794$ $D \text{ оп.мм} = 106.0$ $P \text{ н.мм} = 348.1$ Гр. сл. = V Точн. = П</p>
	<p>ПО-204</p> <p>$F \text{ см}^2 = 0.531$ $Q \text{ кг.} = 0.144$ $D \text{ оп.мм} = 12.3$ $P \text{ н.мм} = 31.3$ Гр. сл. = I Точн. = Н</p>		<p>ПО-209</p> <p>$F \text{ см}^2 = 3.778$ $Q \text{ кг.} = 1.024$ $D \text{ оп.мм} = 121.0$ $P \text{ н.мм} = 301.6$ Гр. сл. = V Точн. = П</p>
	<p>ПО-205</p> <p>$F \text{ см}^2 = 2.367$ $Q \text{ кг.} = 0.641$ $D \text{ оп.мм} = 65.0$ $P \text{ н.мм} = 240.3$ Гр. сл. = VI Точн. = 0соб.</p>		<p>ПО-210</p> <p>$F \text{ см}^2 = 4.382$ $Q \text{ кг.} = 1.188$ $D \text{ оп.мм} = 53.3$ $P \text{ н.мм} = 409.1$ Гр. сл. = VI Точн. = Н</p>

	<p>ПО-211</p> <p>$F \text{ см}^2 = 4.956$ $Q \text{ кг.} = 1.343$ $D \text{ оп.мм} = 95.0$ $P \text{ н.мм} = 269.0$ Гр. сл. = IV Точн. = П</p>		<p>ПО-216</p> <p>$F \text{ см}^2 = 4.230$ $Q \text{ кг.} = 1.146$ $D \text{ оп.мм} = 158.3$ $P \text{ н.мм} = 410.4$ Гр. сл. = 0соб. Точн. = П</p>
	<p>ПО-212</p> <p>$F \text{ см}^2 = 1.107$ $Q \text{ кг.} = 0.300$ $D \text{ оп.мм} = 37.6$ $P \text{ н.мм} = 192.7$ Гр. сл. = V Точн. = П</p>		<p>ПО-217</p> <p>$F \text{ см}^2 = 5.853$ $Q \text{ кг.} = 1.586$ $D \text{ оп.мм} = 131.0$ $P \text{ н.мм} = 567.0$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-213</p> <p>$F \text{ см}^2 = 0.820$ $Q \text{ кг.} = 0.222$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 50.0$ Гр. сл. = III Точн. = П</p>		<p>ПО-218</p> <p>$F \text{ см}^2 = 1.162$ $Q \text{ кг.} = 0.315$ $D \text{ оп.мм} = 55.5$ $P \text{ н.мм} = 172.2$ Гр. сл. = V Точн. = П</p>
	<p>ПО-214</p> <p>$F \text{ см}^2 = 0.570$ $Q \text{ кг.} = 0.154$ $D \text{ оп.мм} = 22.4$ $P \text{ н.мм} = 84.0$ Гр. сл. = IV Точн. = П</p>		<p>ПО-219</p> <p>$F \text{ см}^2 = 0.305$ $Q \text{ кг.} = 0.083$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 42.0$ Гр. сл. = V Точн. = П</p>
	<p>ПО-215</p> <p>$F \text{ см}^2 = 4.950$ $Q \text{ кг.} = 1.341$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 494.3$ Гр. сл. = V Точн. = П</p>		

			<p>ПО-226</p> <p>$F \text{ см}^2 = 0.614$ $Q \text{ кг.} = 0.166$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 95.0$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-222</p> <p>$F \text{ см}^2 = 1.892$ $Q \text{ кг.} = 0.513$ $D \text{ оп.мм} = 44.3$ $P \text{ н.мм} = 221.0$ Гр. сл. = V Точн. = П</p>		<p>ПО-227</p> <p>$F \text{ см}^2 = 2.920$ $Q \text{ кг.} = 0.791$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 379.9$ Гр. сл. = 0соб. Точн. = П</p>
	<p>ПО-223</p> <p>$F \text{ см}^2 = 1.921$ $Q \text{ кг.} = 0.521$ $D \text{ оп.мм} = 61.2$ $P \text{ н.мм} = 221.2$ Гр. сл. = V Точн. = П</p>		<p>ПО-228</p> <p>$F \text{ см}^2 = 1.899$ $Q \text{ кг.} = 0.515$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 143.6$ Гр. сл. = VI Точн. = П</p>
	<p>ПО-224</p> <p>$F \text{ см}^2 = 0.652$ $Q \text{ кг.} = 0.177$ $D \text{ оп.мм} = 18.6$ $P \text{ н.мм} = 77.5$ Гр. сл. = V Точн. = П</p>		<p>ПО-229</p> <p>$F \text{ см}^2 = 2.303$ $Q \text{ кг.} = 0.624$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 159.0$ Гр. сл. = III Точн. = П</p>
	<p>ПО-225</p> <p>$F \text{ см}^2 = 0.852$ $Q \text{ кг.} = 0.231$ $D \text{ оп.мм} = 30.5$ $P \text{ н.мм} = 101.1$ Гр. сл. = V Точн. = П</p>		<p>ПО-230</p> <p>$F \text{ см}^2 = 0.905$ $Q \text{ кг.} = 0.245$ $D \text{ оп.мм} = 20.5$ $P \text{ н.мм} = 51.7$ Гр. сл. = III Точн. = Н</p>

	<p>ПО-231</p> <p>$F \text{ см}^2 = 9.200$ $Q \text{ кг.} = 2.493$ $D \text{ оп.мм} = 121.2$ $P \text{ н.мм} = 451.8$ Гр. сл. = VI Точн. = П</p>		<p>ПО-236</p> <p>$F \text{ см}^2 = 1.821$ $Q \text{ кг.} = 0.493$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 254.0$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-232</p> <p>$F \text{ см}^2 = 21.640$ $Q \text{ кг.} = 5.864$ $D \text{ оп.мм} = 95.0$ $P \text{ н.мм} = 418.0$ Гр. сл. = IV Точн. = H</p>		
	<p>ПО-233</p> <p>$F \text{ см}^2 = 18.180$ $Q \text{ кг.} = 4.927$ $D \text{ оп.мм} = 94.9$ $P \text{ н.мм} = 370.7$ Гр. сл. = IV Точн. = H</p>		
	<p>ПО-234</p> <p>$F \text{ см}^2 = 0.814$ $Q \text{ кг.} = 0.221$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 151.0$ Гр. сл. = V Точн. = П</p>		
	<p>ПО-235</p> <p>$F \text{ см}^2 = 0.970$ $Q \text{ кг.} = 0.263$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 166.0$ Гр. сл. = 0соб. Точн. = П</p>		

	<p>ПО-241</p> <p>$F \text{ см}^2 = 3.981$ $Q \text{ кг.} = 1.079$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 374.5$ Гр. сл. = VI Точн. = П</p>		<p>ПО-246</p> <p>$F \text{ см}^2 = 0.575$ $Q \text{ кг.} = 0.156$ $D \text{ оп.мм} = 17.6$ $P \text{ н.мм} = 74.7$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-242</p> <p>$F \text{ см}^2 = 3.154$ $Q \text{ кг.} = 0.855$ $D \text{ оп.мм} = 75.2$ $P \text{ н.мм} = 270.5$ Гр. сл. = VI Точн. = П</p>		<p>ПО-247</p> <p>$F \text{ см}^2 = 0.438$ $Q \text{ кг.} = 0.119$ $D \text{ оп.мм} = 19.7$ $P \text{ н.мм} = 79.0$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-243</p> <p>$F \text{ см}^2 = 1.785$ $Q \text{ кг.} = 0.484$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 276.0$ Гр. сл. = IV Точн. = П</p>		<p>ПО-248</p> <p>$F \text{ см}^2 = 1.495$ $Q \text{ кг.} = 0.405$ $D \text{ оп.мм} = 38.7$ $P \text{ н.мм} = 126.0$ Гр. сл. = III Точн. = П</p>
	<p>ПО-244</p> <p>$F \text{ см}^2 = 2.541$ $Q \text{ кг.} = 0.689$ $D \text{ оп.мм} = 52.4$ $P \text{ н.мм} = 280.0$ Гр. сл. = IV Точн. = П</p>		<p>ПО-249</p> <p>$F \text{ см}^2 = 1.399$ $Q \text{ кг.} = 0.379$ $D \text{ оп.мм} = 55.7$ $P \text{ н.мм} = 189.0$ Гр. сл. = IV Точн. = П</p>
	<p>ПО-245</p> <p>$F \text{ см}^2 = 2.221$ $Q \text{ кг.} = 0.602$ $D \text{ оп.мм} = 52.7$ $P \text{ н.мм} = 278.0$ Гр. сл. = IV Точн. = П</p>		